# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #07-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Date: 28 Sep 2018

## **Preliminary Advice**

Vehicle No : SLW1123J **Accident Date** : 22/09/2018 Make : AUDI A3 Policy No. : 1800007169 **Assignment Date** : 27/09/2018 **Excess** : S\$0.00 Est. Duration of Repair Date of Inspection : 27/09/2018 : 5 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,352.00
Revised Amount	:S\$	11,469.00
Check Items (Estimated)	:S\$	623.00
Total	:S\$	12,092.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 115,000.00 COE / PARF Rebate :S\$ 58,584.00

Salvage Value :S\$

Margin for Repair :S\$ 56,416.00

### Remarks

X	( )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
	)	Other comments: