mumen :	Tr. 11		NMENT (Office)		3	
		of	Mslh	Da	te/Time: 17092018	3.51 pm
Estimated Cos			Bill to:			
	TTP RES / OD R	ES/EVA/INV/N SMC 4249D	AV / CS	Insured:		
at Workshop n	u/s	Perturnance		Tel:	916 5200	
of		303 Alexandra	£d			
	AUTO DE MUC	Y	Claim No:		100 mm	
Sum Insured:			Excess:	4 01110	.00	
Make of Veh:					DA 35092018	
Date/Time:	7092018 4.41		28092018 cted:	Vehi	I.O.D. Endorsement:	
Date/Time	Action/Instruction	( V) Estiv				
28.9.2018	Pavert IA.	thm menimen	n ; seek mano	late		
\$ .9.2018	Ming shao	authorise up	ni'r			
810c.p.Bc	Shirle h	bym enter	to proced	перит.		

ASSIGNMENT

	4331	CHAINTEINT		
From:	Date: 28/9/18		490 Yr Regn: 2018	Jun
Estimated Cost:		Type: M.Car / M.Cycle / Bus / \	/an / Lorry / Taxi / Prime Mover /	
OD/TP/WS/TP RES	/ OD RES / EVA / INV / MV	Truck / Trailer or		
To Inspect Vehicle No:	SMC 4249D	Make: B.M.w	2161 00 14	99
at Workshop m/s	Performance	Colour BLACK	A/C: Insured / Std / I	
of	303 Alexandra	Sp.Reading 01115	T/Radio: Insured / Std /	NI / NA
Insured.		Eng/No:	2 12 199	
Policy No.			920505LS3 199	
Claims No.		Gen. Cond: Good / Poor		
Sum Insured:	Excess: \$2000.00	Steering: morder / Jammed / L		
(Client's Record)		Brake: (norder / Jammed / L		
Make of Veh:	chua	Modi: Nil / (IRT) / STD A		
		Tyre Size: F:	205/60R16	
(Policy Condition)		R:	1.	
Remark: The veh had		BS / DUN / EXNOVA / GY / FS	/ LIZA / MIC / OHTSU / PIR / SUM	17
repair at the	time of inspection.	TOYO/YOKO or	CONTINENTAL	
Bal. or Market Value:	133 K	Front	Rear	
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. b mm	R/Bal.	mm
GIA / PR Seen:	Consistent?: Yes or No	L/Bal. mm	0 1	mm
Est. Repairs:	days Res.: Yes or No	D.O.A. 25/09/18	D.O.I. 28/69/0	8
Lum Sum:	% 3 Val.: Yes or No	Survey held at	PERFORMANCE	
CA / REV / REP.			OS I NIS I UIC I Rooftop or	
Date:	Vehicle: IN / OUT Person Contacted:		/ Body Structure affected due to	collision.
Date / Time Action	on /-Instruction			
		THE A A OUT 1019		
	RECE	EIVED 2 2 OCT 2018		
	-			
Date/Time. File Pass to?	: Preli. Report	Days Of Repair: 6		
1)		Resurvey No. of Trip:	Survey Fee:	200
Date/Time, File Return to?			Transportation	
2) 22/10- +	ypist Add Fee	: Site Insp (\$	)S + RS,SI	
1	1	: Interview (\$	) Photes	
Report Format :	merimen	: Tech. Invs (\$	) Others	10
Lump Sum / I.B.I:	(\$. 10, 331.20	: Weekend (\$	El	

# ...CLAIM SUBFOLDER...(New Assignment)

ase	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
in	27 Sep 2018 09:48		27 Sep 2018 15:51 Assign		7.00	ing right co	New Assignment Cancel Case

Main	Reference	Clair	m Details		Documents		Show All
CLAIM SUBFOLDER DETAILS				10.00	[Created	d by insurer	1
Insured:	PERFORMANCE MOTORS	LTD, Co. Reg	. No.: 1974015	59W	Lorenter	a by msurer	ı
Vehicle Reg. No.:	SMC4249D		e of Loss:		[2 Months	18 07:00 - :5 s and <b>27</b> Day (Man Yr)]	9 s From LTA
Claim Type:	OD	Polic	Policy/Cover Note No.:		29040254 Coverage 30/09/20	040254MCY (Comprehensive yerage: 01/10/2017 -	
		Exce			5\$2,000.0	00	
Repairer:	Performance Motors Limi Alexandra - Tel: 63190172/	ited (Alexand 63190174	ra) 303 Alexand	Ira Road, Sime	Darby Perfor	mance Centre	, 159941
Handling Insurer:	MSIG Insurance (Singapo 6594 2554]	ore) Pte. Ltd.	(HQ) - Tel: +6	5 6827 7888	[Handled by	Eliza Ho Te	ng Boon -
Adjuster:	0334 2334]						ng Boon -
TO THE RESIDENCE OF THE PROPERTY OF THE PARTY OF THE PART	LKK Auto Consultants Pte	e Ltd (HQ) - Te	el: 6256-3561	. [Imm.Advi	ce due 28		ng Boon -
Adjuster:	0334 2334]	e Ltd (HQ) - To 6 / Male), NR	el: 6256-3561	. [Imm.Advi	ce due 28		ng Boon -
Adjuster: Driver/Custodian:	LKK Auto Consultants Pte	e Ltd (HQ) - To 6 / Male), NR	el: 6256-3561	. [Imm.Advi	ce due 28 76229	/09/2018]	
Adjuster: Driver/Custodian: Adj Asg. Remarks:	LKK Auto Consultants Pte	e Ltd (HQ) - To 6 / Male), NR	el: 6256-3561	. [Imm.Advi	ce due 28		
Adjuster: Driver/Custodian: Adj Asg. Remarks:  ASSOCIATED MAIL RECEIVED There are no mail for this case.	LKK Auto Consultants Pte	e Ltd (HQ) - To 6 / Male), NR	el: 6256-3561	. [Imm.Advi	ce due 28 76229	/09/2018]	
Adjuster: Driver/Custodian: Adj Asg. Remarks:  ASSOCIATED MAIL RECEIVED There are no mail for this case.	LKK Auto Consultants Pte	e Ltd (HQ) - To 6 / Male), NR	el: 6256-3561	. [Imm.Advi	ce due 28 76229 View All	/09/2018]	

# View Received Message

This mail is associated with :

\*SMC4249D (571641)

OD
Sep 25 2018 7:00AM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

Reply	Reply All   Mark as Unread   Print Message   Delete Message   Forward
From	MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/10/2018 11:57 AM.
То	LKK_HQ
Subject	Alert - Adj Mandate Approved (S\$10331.20) - SMC4249D - Claim Handler: Eliza Ho Teng Boon
DOCUM	ENTS SUMMARY
There a	e no documents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Eliza Ho Teng Boon

Date: 17 Oct 2018

# Preliminary Advice

Vehicle No	: SMC4249D	Accident Date	: 25/09/2018
Make	: BMW 216I	Policy No.	: 29040254MCY
Assignment Date	: 27/09/2018	Excess	: S\$2,000.00
Date of Inspection	: 28/09/2018	Est. Duration of Repair	: 6.00
Inspection At	: PERFORMANCE MOTORS L 303 ALEXANDRA ROAD, SIM SINGAPORE 159941	IMITED (ALEXANDRA) IE DARBY PERFORMANCE CENTF	RE

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,215.70	(incl.supplementary \$1103.65)	
Revised Amount	:S\$	10,331.20	(incl.supplementary \$1103.65)	
Check Items (Estimated)	:S\$	0.00		
Total	:S\$	10,331.20		
Lump Sum Repair	:S\$			

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	133,000.00
COE / PARF Rebate	:S\$	63,638.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,362.00

#### Remarks

(X) The vehicle is economical for repair.

The above survey was conducted on a 'without prejudice' basis.

# Janice Lee (LKKAuto)

From:

Shirley Hiew (LKK Auto)

Sent:

Friday, September 28, 2018 5:02 PM

To:

chua.kee.sin@simedarby.com.sg

Cc:

han.kwan.yong@simedarby.com.sg; SUR

Subject:

SMC 4249D OD (MSIG)

Dear Kee Sin,

As instructed by our client, please proceed to repair the insured vehicle SMC 4249D (Excess \$ 2,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler (on behalf Veron)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# **Print Received Message**

This mail is associated with:

\*SMC4249D (571641)
OD
Sep 25 2018 7:00AM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

From

MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 28/09/2018 16:50 PM.

To

LKK\_HQ

Subject

Alert - Adj Mandate Approved (S\$9828.90) - SMC4249D - Claim Handler: Eliza Ho Teng Boon

Approved:9828.90:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.		

## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. To:

> 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn:

Eliza Ho Teng Boon

Date:

28 Sep 2018

# **Preliminary Advice**

Vehicle No

: SMC4249D

Accident Date

: 25/09/2018

Make

Policy No.

: BMW 216I

: 29040254MCY

Assignment Date

: 27/09/2018

Excess

: \$\$2,000.00

Date of Inspection

: 28/09/2018

Est. Duration of Repair

: 6.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA)

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,112.05
Revised Amount	:S\$	9,828.90
Check Items (Estimated)	:S\$	3,580.75
Total	:S\$	13,409.65

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	133,000.00
COE / PARF Rebate	:S\$	63,638.00
Salvage Value	:S\$	

Margin for Repair :S\$ 69,362.00

### Remarks

(	X	)	The	veh	cle	IS	economical	for	repair.
---	---	---	-----	-----	-----	----	------------	-----	---------

) The above survey was conducted on a 'without prejudice' basis.

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	1559W
Vehicle No.:	SMC4249D
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Sep 2018
Vehicle Make:	B.M.W.
Vehicle Model:	216I GT LED
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	34195262B38A15A
Chassis No.:	WBA2D920505L53199
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$30,479.00
Original Registration Date:	29 Jun 2018
First Registration Date:	29 Jun 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$34,671.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2028
PARF Rebate Amount: Intended COE Rebate Details	\$26,003.00
COE Expiry Date:	28 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,600.00
COE Rebate Amount:	\$37,635.00
Total Rebate Amount:	\$63,638.00

The information contained herein is correct as at 28 Sep 2018

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	26/09/2018 14:49
Date Of Accident	25/09/2018 07:15
Exact Location Of Accident	2 SUFFOLK ROAD S(307780) CARPARK
Country/State of Loss	SINGAPORE
D. C.	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMC4249D
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE MOTORS LTD
Co Reg No	197401559W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97276229
Vehicle Particulars	
Manufacturer	BMW
Model	216GT
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	13203504
Cover Note Number	
Driver	
Name of Driver	LEE SHUO HONG SHAUN
NIDIO No.	004074548

 NRIC No
 \$8137151B

 Date Of Birth
 28/11/1981

 Occupation
 INDOOR

 Date Of Driving Pass
 01/11/2001

Driving Experience 16 YEARS AND 10 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97276229

Fax Number

Contact Number

EMail Address SHAUN7LEE@GMAIL.COM

Address

2 SUFFOLK ROAD #16-03

OTHER - LOAN CAR

Postcode

307780

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident? Was any injured conveyed to hospital by NO NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any willful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Name:

NRIC/FIN No.:

## Sketch Plan Pg. 2

O pillar (2) direction (3) pillar (armo)

Car was parked besidenthe pillar car

pillar

pillar tarmoving cut of impact car park on the rear left passenger door

DESCRIBE CIRCUMSTANC	CES OF THE ACCIDENT	
1 Car was parte	ed at the basement car park	of 2 Suffork Road, S(307780)
@ The car was po	arked beside the pillar Pillar	was on the left side of the car
6) At O715hrs on 2	5/9/18, I drove the car out of	the parking lot.
1 misjudged +	he turning radius of the car	. I turned left too soon . As
I turned to see	in, the rear left passenger	door side swiped the pillar.
DECLARATION		
/We declare the foregoing par	ticulars are true in every respect.	(Je) 2
olicyholder's Signature iate & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Sentre Personnel's Signature Name: NRIC/FIN No.: 26692aG
		@ 1306 ha



MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Tel: (65) 6827 7888 Fax: (65) 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

# MOTOR INSURANCE COVER NOTE Cover Note No. 13203504

The Insured named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

### SCHEDULE

Agent No.

: 212668

Name of Insured

: Performance Motors Ltd

Make and Description of Vehicle: BMW 2161

Vehicle Registration No.

Year of Manufacture

: 2018

Engine No.

: 34195262B38A15A

Chassis No.

: WBA2D920505L53199

Capacity

: 1,499 Cubic Capacity

Cover Type

: Comprehensive

Sum Insured (SGD)

: Market Value

Period of Insurance

: One year from Date of Registration of the vehicle with

Excess (SGD)

: As Agreed

I/We hereby certify that this Cover Note is issued in accordance with the Provisions of the Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

Not valid unless countersigned by the Company's Authorised Representative


MSIG Insurance (Singapore) Pte. Ltd. Authorised Insurers


Sime Darby Insurance Brokers (Singapore) Pte. Ltd.

Katherine Yeo Senior Vice President, Brokers

Date of Issue: 28/06/2018

This Cover Note is valid for 30 days from the date of issue.









### LEE SHUO HONG SHAUN

CHINESE

李

Date of Birth 28-11-1981 M

Country of Birth SINGAPORE

Blood Group Date of resue 30-05-2002

2 SUFFOLK ROAD #16-03 SINGAPORE 307780

NRIC No: \$8137,151B

Date: 14/08/2015

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

01 Nov 2001

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road '
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSal

(AfterSales) 63190533/530



GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Estimate No.

: b1 48563 Page No. : 1 of 6

Date Estimated

: 26/09/2018

Prepared By

: Chua Kee Sin

ESTIMATE REPAIR FOR -

Performance Motors Limited

303 Alexandra Road

Sime Darby Performance Centre

ACCOUNT 66

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

Singapore 159941

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SMC4249D

5L53199

29/06/2018

216i GT

DESCRIPTION

Replace left rear side fender, left rear door, left lower side skirting and remove attachment etc and include knock on accid

ent dent

Spray painting left rear side fender, left both door, left lower side skirting ,b pillar trunk floor and tail end panel

To check steering geometry and conduct wheel alignment according to BMW specification (1x)

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

To replace tyre and wheel rim including balancing. (1x).

To transfer lock mechanism from old to new door including conduct checks on new door power window system for proper function. (1 door).left

To carry out body cavity preservation. (For cut panel).

To carry out body cavity preservation. (Per panel).

Sundries.

To supply and install rear left window glass quoter solar film.

To supply and install rear left window glass door quater

94.00

150.00

425.00

425.00



A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 436180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

Estimate No. Date Estimated Prepared By	: b1 4856 : 26/09/2018 : Chua Kee S	3	MATE	Page No. :	2 of 6
REGN. NO. SMC4249D	CHASSIS NO. 5L53199	REGN. DATE 29/06/2018	MODEL 216i GT		MILEAGE 0
DESCE solar fi	RIPTION lm.				VALUE
				Total Labour 1	17,853.00
PLAST ALLOY HUB C REAR Positio	RIPTION TIC NUT FOR COARSE OF RIM 7JX16 DOUBLE	SPK 473 DGE		OTY PRIC 0.80 1 738.55 1 35.75 1 1,360.75 1 5.60	VALUE 4.80 500 738.55 738.55 74 25 75 74 25 75 75 75 75 75

DESCRIPTION         QTY         PRIO         VALUE           PLASTIC NUT FOR COARSE THREADED PIN         6         0.80         A.A. 4.80           ALLOY RIM 7JX16 DOUBLE SPK 473         1         738.55         A.A. 3.55           HUB CAP WITH CHROME EDGE         1         35.75         A.A. 3.575           FEAR LH SIDE PANEL         1         1,380.75         7.560           Positionieru         1         5,600         7.560           REINFORCEMENT PLATE UNIVERSAL         1         27.75         7.27.75           Positionieru         1         49.20         7.49.20           Reinforcemen         1         49.20         7.49.20           Reinforcemen         1         49.20         7.49.20           TWELD BOLT LES MM         10         2.55         7.25.50           TH LOWER REAR DOOR HINGE         1         57.15         7.515           LH LOWER REAR DOOR HINGE         1         57.15         7.515           LH SUPPORT SILL         1         12.295         7.12.95           PLASTIC NUT         4         0.85         7.340           LH SILL TRIM PRIMED         1         278.65         7.72.05           REAR LH DOOR WINDOW FRAME COVER (AL         1				
ALLOY RIM 7JX16 DOUBLE SPK 473 1 738.55	DESCRIPTION	QTY	PRIC	
HUB CAP WITH CHROME EDGE REAR LH SIDE PANEL Positionieru 1 1,360.75 Positionieru 1 5,50 REINFORCEMENT PLATE UNIVERSAL 1 27.75 Reinforcemen 1 49.20 Reinforce	PLASTIC NUT FOR COARSE THREADED PIN	6	0.80	AA : 4.80 ×
REAR LH SIDE PANEL Positionieru Positionieru REINFORCEMENT PLATE UNIVERSAL 1 27.75 Reinforcemen 1 49.20 Reinforcemen 1 57.15 Reinforcemen 1 1 49.20 Reinforcemen 1 1 49.20 Reinforcemen 1 1 49.20 Reinforcemen 1 1 49.20 Reinforcemen 1 1 57.15 Reinforcemen 1 1 27.85 Reinforce	ALLOY RIM 7JX16 DOUBLE SPK 473	1	738.55	738.55
Positionieru 1 5.60 7.560 7.560 7.560 REINFORCEMENT PLATE UNIVERSAL 1 27.75 7.75 Reinforcemen 1 49.20 7.49.20	HUB CAP WITH CHROME EDGE	1	35.75	1 A ME X 35.75 X
REINFORCEMENT PLATE UNIVERSAL Reinforcemen 1 49.20 Reinforcemen 1 57.15 Reinforcemen 1 12.95	REAR LH SIDE PANEL	1	1,360.75	
Reinforcemen	Positionieru	1	5.60	? 5.60
Reinforcemen 1 1 49.20	REINFORCEMENT PLATE UNIVERSAL	1	27.75	. 21.13
Reinforcemen 1 1 49.20	Reinforcemen	1	49.20	<b>?</b> 49.20
T WELD BOLT L=5.4MM  10	Reinforcemen	1	49.20	49.20
LH LOWER REAR DOOR HINGE 1 57.15 LH UPPER REAR DOOR HINGE 1 57.15 LH SUPPORT SILL LH SUPPORT SILL LH SULP SILL LH SILL SILL SILL SILL SILL SILL SILL SILL	Reinforcemen	1	49.20	- 10.20
LH LOWER REAR DOOR HINGE LH UPPER REAR DOOR HINGE LH UPPER REAR DOOR HINGE LH SUPPORT SILL LH SUPPORT SILL LH SULT RIM PRIMED LH SILL TRIM PRIMED LH SOAN SE REAR LH DOOR WINDOW FRAME COVER (AL LH SEALING COLUMN B BOTTOM LH SEALING COLUMN B COVER LH GE.45 LH SEALING COLUMN B COVER LH GE.45 LH SEALING COLUMN B COVER LH SIDE WINDOW GUIDE LH SIDE WINDOW GUIDE LH SIDE WINDOW GUIDE LH SIDE WINDOW FRAME COVER LH	T WELD BOLT L=5.4MM	10	2.55	? 25.50
LH LOWER REAR DOOR HINGE LH UPPER REAR DOOR HINGE LH UPPER REAR DOOR HINGE LH SUPPORT SILL LH SUPPORT SILL LH SULT RIM PRIMED LH SILL TRIM PRIMED LH SOAN SE REAR LH DOOR WINDOW FRAME COVER (AL LH SEALING COLUMN B BOTTOM LH SEALING COLUMN B COVER LH GE.45 LH SEALING COLUMN B COVER LH GE.45 LH SEALING COLUMN B COVER LH SIDE WINDOW GUIDE LH SIDE WINDOW GUIDE LH SIDE WINDOW GUIDE LH SIDE WINDOW FRAME COVER LH	LH LOWER REAR DOOR HINGE	1	57.15	· 57.15
LH SUPPORT SILL PLASTIC NUT 4 0.85 PLASTIC NUT 7 2.05 PEAR DOOR BRAKE 7 72.05 REAR DOOR BRAKE 1 72.05 PEAR LH DOOR WINDOW FRAME COVER (AL 1 59.75 PEAR LH DOOR COLUMN B BOTTOM 1 50.85 PEAR LH DOOR COLUMN B COVER 1 60.85 PEAR LH DOOR COLUMN B COVER 1 62.45 PEAR LH DOOR COLUMN B COVER 1 62.45 PEAR LH DOOR COLUMN B COVER 1 1 21.25 PEAR LH DOOR OUTER WEATHERSTRIP (AL 1 91.80 PEAR LH DOOR WINDOW GUIDE 1 119.65 PEAR LH DOOR WINDOW GUIDE 1 119.65 PEAR LH DOOR WINDOW FIXED (ALU HOCH 1 270.25 PEAR LH DOOR WINDOW FIXED (ALU HOCH 1 270.25 PEAR LH DOOR WINDOW FRAME COVER 1 135.05 PEAR LH DOOR WINDOW FRAME COVER 1 135.05 PEAR DOOR JOINT SEAL PEAR DOOR JOINT SEAL PEAR DOOR EDGE PROTECTION 1 153.10 PET LH RETAINING STRIP SILL 1 20.80 PET LH RETAINING STRIP SILL 1 20.80 PET LH RETAINING STRIP SILL 1 15.85 PET LH RETAINING STRIP SILL 1 15.85 PET LH APERTURE COVER 1 15.85 PET LH COVER APERTURE 1	LH LOWER REAR DOOR HINGE	1	57.15	7 57.15
PLASTIC NUT  LH SILL TRIM PRIMED  REAR DOOR BRAKE  REAR LH DOOR WINDOW FRAME COVER (AL  LH SEALING COLUMN B BOTTOM  1 50.85  REAR LH DOOR COLUMN B COVER  REAR LH DOOR COLUMN B COVER  1 60.85  REAR LH DOOR COLUMN B COVER  1 121.25  Seal, door w  1 21.25  Seal, door w  1 21.25  REAR LH DOOR OUTER WEATHERSTRIP (AL  REAR LH DOOR WINDOW GUIDE  1 119.65  REAR LH SIDE WINDOW GUIDE  1 119.65  REAR LH SIDE WINDOW FIXED (ALU HOCH  1 270.25  REAR LH DOOR WINDOW  1 127.30  REAR LH DOOR WINDOW FRAME COVER  1 59.75  REAR DOOR JOINT SEAL  1 30.35  REAR DOOR JOINT SEAL  1 30.35  REAR DOOR JOINT SEAL  1 30.35  REAR DOOR STRIP SILL  1 20.80  2 20.80  REAR LH RETAINING STRIP SILL  1 45.00  1 45.00  REAR LH RETAINING STRIP SILL  1 45.00  REAR LH RETAINING STRIP SILL  1 45.00  REAR LH RETAINING STRIP SILL  1 15.85  REAR LH COVER APERTURE  1 15.85  REAR LH COVER APERTURE  1 15.85  ADrasion-res  CAVITY PROTECTION WAX REMOVER 500ML  BLIND RIVET AVIBVLB  SCREW (SF PLUS M5X15)  1 281.55  ROBERT STRIPS SILL  1 281.55  REAR SA.55  R	LH UPPER REAR DOOR HINGE	1	57.15	? 57.15
LH SILL TRIM PRIMED  REAR DOOR BRAKE  REAR LH DOOR WINDOW FRAME COVER (AL  LH SEALING COLUMN B BOTTOM  REAR LH DOOR COLUMN B COVER  REAR LH DOOR OUTER WEATHERSTRIP (AL  REAR LH DOOR WINDOW GUIDE  REAR LH DOOR WINDOW GUIDE  REAR LH DOOR WINDOW FIXED (ALU HOCH  LI STORY WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR DOOR STRIP SILL  REAR LH RETAINING STRIP SILL  REAR LH SIDE STRIP SILL  REAR	LH SUPPORT SILL	1	12.95	. 12.90
REAR DOOR BRAKE REAR LH DOOR WINDOW FRAME COVER (AL LH SEALING COLUMN B BOTTOM 1 50.85 REAR LH DOOR COLUMN B COVER 1 60.85 Inner weathe 1 62.45 Seal, trim, 1 21.25 Seal, door w REAR LH DOOR OUTER WEATHERSTRIP (AL REAR LH DOOR WINDOW GUIDE REAR LH DOOR WINDOW GUIDE REAR LH DOOR WINDOW FIXED (ALU HOCH 1 270.25 LH FIXED DOOR WINDOW FRAME COVER REAR LH DOOR BOOR FRAME COVER REAR LH WHEEL HOUSING COVER 1 135.05 REAR DOOR JOINT SEAL 1 30.35 REAR DOOR JOINT SEAL 1 20.80 REAR LH RETAINING STRIP SIDE SILL MID RT LH APERTURE RC LH COVER APERTURE RC LH C	PLASTIC NUT	4	0.85	?. 3.40
REAR LH DOOR WINDOW FRAME COVER (AL  LH SEALING COLUMN B BOTTOM  1 50.85  REAR LH DOOR COLUMN B COVER  1 60.85  Inner weathe  1 62.45  Seal, trim,  1 21.25  Seal, door w  1 21.25  REAR LH DOOR OUTER WEATHERSTRIP (AL  REAR LH DOOR WINDOW GUIDE  REAR LH SIDE WINDOW FIXED (ALU HOCH  LI 191.80  REAR LH SIDE WINDOW FIXED (ALU HOCH  LI 270.25  LH FIXED DOOR WINDOW  1 127.30  REAR LH DOOR WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR	LH SILL TRIM PRIMED	1	278.65	repent 278.65
LH SEALING COLUMN B BOTTOM  REAR LH DOOR COLUMN B COVER  Inner weathe  Seal, trim,  Seal, door w  REAR LH DOOR OUTER WEATHERSTRIP (AL  REAR LH DOOR WINDOW GUIDE  REAR LH DOOR WINDOW GUIDE  REAR LH DOOR WINDOW FIXED (ALU HOCH  I 191.85  REAR LH SIDE WINDOW FIXED (ALU HOCH  I 270.25  C 270.25  LH FIXED DOOR WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR LH WHEEL HOUSING COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR LH COVER APERTURE  REAR LH RETAINING STRIP SILL  REAR LH COVER APERTURE  REAR LH RETAINING STRIP SILL  REAR LH COVER APERTURE  REAR LH RETAINING STRIP SILL  REAR LH REAR LH DOOR WINDOW  REAR LH SOOR SOOR SOOR SOOR SOOR S	REAR DOOR BRAKE	1	72.05	
REAR LH DOOR COLUMN B COVER  Inner weathe  Seal, trim,  S	REAR LH DOOR WINDOW FRAME COVER (AL	1	59.75	? 59.75 \ \
Inner weathe  Seal, trim,  Seal, door w  REAR LH DOOR OUTER WEATHERSTRIP (AL  REAR LH DOOR WINDOW GUIDE  REAR LH SIDE WINDOW FIXED (ALU HOCH  SEAR LH DOOR WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR LH WHEEL HOUSING COVER  REAR DOOR JOINT SEAL  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR DOOR JOINT SEAL  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR LH SEAL STRIP  REAR LH SEAL STRIP  REAR LH SEAL STRIP  REAR	LH SEALING COLUMN B BOTTOM	1	50.85	. 00.00
Seal, trim,       1       21.25       21.25         Seal, door w       1       21.25       21.25         REAR LH DOOR OUTER WEATHERSTRIP (AL       1       91.80       91.80         REAR LH DOOR WINDOW GUIDE       1       119.65       119.65         REAR LH SIDE WINDOW FIXED (ALU HOCH       1       270.25       270.25         LH FIXED DOOR WINDOW       1       127.30       7.127.30         REAR LH DOOR WINDOW FRAME COVER       1       59.75       7.59.75         RR LH WHEEL HOUSING COVER       1       135.05       135.05         REAR DOOR JOINT SEAL       1       30.35       7.153.10         REAR DOOR EDGE PROTECTION       1       153.10       7.153.10         FRI LH RETAINING STRIP SILL       1       20.80       7.20.80         RR LH RETAINING STRIP SILL MID       1       20.30       7.20.30         REAR LH RETAINING STRIP SILL HAPERTURE COVER       1       15.05       7.15.85         RR LH COVER APERTURE       1       15.85       7.15.85         RR LH COVER APERTURE       1       15.85       7.15.85         RR LH COVER APERTURE       1       1.5.85       7.15.85         RA LH COVER APERTURE       1       4.75       7.4.75	REAR LH DOOR COLUMN B COVER	1	60.85	- 00.00
Seal, trim, Seal, door w REAR LH DOOR OUTER WEATHERSTRIP (AL REAR LH DOOR WINDOW GUIDE REAR LH SIDE WINDOW FIXED (ALU HOCH 1 270.25  LH FIXED DOOR WINDOW 1 127.30  REAR LH DOOR WINDOW FRAME COVER REAR LH DOOR WINDOW FRAME COVER REAR LH OOR WINDOW FRAME COVER REAR LH WHEEL HOUSING COVER REAR DOOR JOINT SEAL REAR DOOR EDGE PROTECTION FRT LH RETAINING STRIP SILL REAR LH RETAINING STRIP SILL REAR LH RETAINING STRIP SIDE SILL MID REAR LH RETAINING STRIP SIDE SILL MID REAR LH RETAINING STRIP SIDE REAR LH COVER APERTURE 1 15.85 RR LH COVER APERTURE Abrasion-res CAVITY PROTECTION WAX REMOVER 500ML BLIND RIVET AVIBVLB SCREW (SF PLUS M5X15) (DG/SL) BODY ADHESIVE K5B (195ML)  1 21.25 21	Inner weathe	1	62.45	
REAR LH DOOR OUTER WEATHERSTRIP (AL REAR LH DOOR WINDOW GUIDE REAR LH SIDE WINDOW FIXED (ALU HOCH 1 270.25 1 19.65 REAR LH SIDE WINDOW FIXED (ALU HOCH 1 127.30 REAR LH DOOR WINDOW REAR LH DOOR WINDOW REAR LH DOOR WINDOW FRAME COVER REAR LH DOOR WINDOW FRAME COVER REAR DOOR JOINT SEAL REAR DOOR JOINT SEAL REAR DOOR EDGE PROTECTION REAR DOOR EDGE PROTECTION REAR LH RETAINING STRIP SILL REAR LH SOON SOON SOON SOON SOON SOON SOON SOO	Seal, trim,	1	21.25	21.25
REAR LH DOOR WINDOW GUIDE  REAR LH SIDE WINDOW FIXED (ALU HOCH  I 270.25  LH FIXED DOOR WINDOW  REAR LH DOOR WINDOW FRAME COVER  REAR LH DOOR WINDOW FRAME COVER  REAR LH WHEEL HOUSING COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR LH RETAINING STRIP SILL MID  REAR LH RETAINING STRIP SILL  REAR LH SLOOS  REAR LH WHEEL LHOUSING  REAR LH WHEEL LHOUSING  REAR LH SLOOS  REAR LH WHEEL LHO	Seal, door w	1	21.25	
REAR LH SIDE WINDOW FIXED (ALU HOCH  LH FIXED DOOR WINDOW  REAR LH DOOR WINDOW FRAME COVER  REAR LH WHEEL HOUSING COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  FRI LH RETAINING STRIP SILL  REAR LH COVER APERTURE  REAR LH COV	REAR LH DOOR OUTER WEATHERSTRIP (AL	1	91.80	91.80 X
REAR LH SIDE WINDOW FIXED (ALU HOCH  LH FIXED DOOR WINDOW  REAR LH DOOR WINDOW FRAME COVER  REAR LH WHEEL HOUSING COVER  REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  FRI LH RETAINING STRIP SILL  REAR LH COVER APERTURE  REAR LH COV	REAR LH DOOR WINDOW GUIDE	1	119.65	7 119.65
REAR LH DOOR WINDOW FRAME COVER       1       59.75         RR LH WHEEL HOUSING COVER       1       135.05         REAR DOOR JOINT SEAL       1       30.35         REAR DOOR EDGE PROTECTION       1       153.10         FRT LH RETAINING STRIP SILL       1       20.80         RR LH RETAINING STRIP SIDE SILL MID       1       20.30         REAR LH RETAINING STRIP SILL       1       45.00         FRT LH APERTURE COVER       1       15.05         RR LH COVER APERTURE       1       15.85         RR LH COVER APERTURE       1       15.85         Abrasion-res       1       4.75         CAVITY PROTECTION WAX REMOVER 500ML       1       18.45         BLIND RIVET AVIBVLB       8       0.55         SCREW (SF PLUS M5X15)       3       0.55         (DG/SL) BODY ADHESIVE K5B (195ML)       1       281.55	REAR LH SIDE WINDOW FIXED (ALU HOCH	1	270.25	
RR LH WHEEL HOUSING COVER RR LH WHEEL HOUSING COVER REAR DOOR JOINT SEAL REAR DOOR EDGE PROTECTION 1 153.10 1 1	LH FIXED DOOR WINDOW	1	127.30	7 127.30
REAR DOOR JOINT SEAL  REAR DOOR EDGE PROTECTION  REAR DOOR EDGE PROTECTION  REAR LH RETAINING STRIP SILL  REAR LH COVER APERTURE  RE	REAR LH DOOR WINDOW FRAME COVER	1	59.75	. 59.75
REAR DOOR EDGE PROTECTION       1       153.10       153.10         FRT LH RETAINING STRIP SILL       1       20.80       20.80         RR LH RETAINING STRIP SIDE SILL MID       1       20.30       20.30         REAR LH RETAINING STRIP SILL       1       45.00       45.00         FRT LH APERTURE COVER       1       15.05       15.05         RR LH COVER APERTURE       1       15.85       15.85         RR LH COVER APERTURE       1       15.85       15.85         Abrasion-res       1       4.75       4.75         CAVITY PROTECTION WAX REMOVER 500ML       1       18.45       4.40         BLIND RIVET AVIBVLB       8       0.55       4.40         SCREW (SF PLUS M5X15)       3       0.55       1.65         (DG/SL) BODY ADHESIVE K5B (195ML)       1       281.55       281.55	RR LH WHEEL HOUSING COVER	1	135.05	135.05
FRT LH RETAINING STRIP SILL       1       20.80       7. 20.80         RR LH RETAINING STRIP SIDE SILL MID       1       20.30       20.30         REAR LH RETAINING STRIP SILL       1       45.00       45.00         FRT LH APERTURE COVER       1       15.05       15.05         RR LH COVER APERTURE       1       15.85       15.85         RR LH COVER APERTURE       1       15.85       15.85         Abrasion-res       1       4.75       4.75         CAVITY PROTECTION WAX REMOVER 500ML       1       18.45       4.40         BLIND RIVET AVIBVLB       8       0.55       4.40         SCREW (SF PLUS M5X15)       3       0.55       1.65         (DG/SL) BODY ADHESIVE K5B (195ML)       1       281.55       281.55	REAR DOOR JOINT SEAL	1	30.35	12 MX 30.35 X
RR LH RETAINING STRIP SIDE SILL MID  REAR LH RETAINING STRIP SILL  1 45.00  FRT LH APERTURE COVER  1 15.05  RR LH COVER APERTURE  1 15.85  RR LH COVER APERTURE  1 15.85  RR LH COVER APERTURE  1 15.85  Abrasion-res  1 4.75  CAVITY PROTECTION WAX REMOVER 500ML  BLIND RIVET AVIBVLB  SCREW (SF PLUS M5X15)  (DG/SL) BODY ADHESIVE K5B (195ML)  1 20.30  20.30  45.00  1 15.05  1 15.05  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 4.75  2 4.75  2 4.75  2 4.75  2 4.75  2 4.60  3 0.55  3 0.55  2 81.55	REAR DOOR EDGE PROTECTION	1	153.10	153.10
REAR LH RETAINING STRIP SILL  1 45.00 FRT LH APERTURE COVER 1 15.05 RR LH COVER APERTURE 1 15.85 RR LH COVER APERTURE 1 15.85 RR LH COVER APERTURE 1 15.85 Abrasion-res 1 4.75 CAVITY PROTECTION WAX REMOVER 500ML BLIND RIVET AVIBVLB SCREW (SF PLUS M5X15) (DG/SL) BODY ADHESIVE K5B (195ML)  1 45.00 1 45.00 1 15.05 1 15.05 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 1 15.85 2 15.85 2 15.85 2 15.85 2 15.85 2 15.85	FRT LH RETAINING STRIP SILL	1	20.80	
FRT LH APERTURE COVER 1 15.05  RR LH COVER APERTURE 1 15.85  RR LH COVER APERTURE 1 15.85  RR LH COVER APERTURE 1 15.85  Abrasion-res 1 4.75  CAVITY PROTECTION WAX REMOVER 500ML 1 18.45  BLIND RIVET AVIBVLB 8 0.55  SCREW (SF PLUS M5X15) 3 0.55  (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55	RR LH RETAINING STRIP SIDE SILL MID	1	20.30	, 20.00
RR LH COVER APERTURE  RR LH COVER APERTURE  1 15.85  RR LH COVER APERTURE  1 15.85  Abrasion-res  1 4.75  CAVITY PROTECTION WAX REMOVER 500ML  BLIND RIVET AVIBVLB  SCREW (SF PLUS M5X15)  (DG/SL) BODY ADHESIVE K5B (195ML)  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  1 15.85  2 15.85  1 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  2 15.85  3 15.85  2 15.85  2 15.85  3 15.85  2 15.85  3 15.85  3 15.85  3 15.85  4.75  4.75  4.75  4.75  5 15.85  7 15.85	REAR LH RETAINING STRIP SILL	1	45.00	. 45.00
RR LH COVER APERTURE  Abrasion-res  CAVITY PROTECTION WAX REMOVER 500ML  BLIND RIVET AVIBVLB  SCREW (SF PLUS M5X15)  (DG/SL) BODY ADHESIVE K5B (195ML)  1 15.85  1 4.75  1 4.75  1 15.85  1 4.75  2 4.75  3 0.55  1 65  2 81.55	FRT LH APERTURE COVER	1	15.05	
Abrasion-res 1 4.75 2.4.75 CAVITY PROTECTION WAX REMOVER 500ML 1 18.45 BLIND RIVET AVIBVLB 8 0.55 2.4.40 SCREW (SF PLUS M5X15) 3 0.55 (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55	RR LH COVER APERTURE	1	15.85	7. 15.85
CAVITY PROTECTION WAX REMOVER 500ML 1 18.45  BLIND RIVET AVIBVLB 8 0.55  \$CREW (SF PLUS M5X15) 3 0.55  (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55	RR LH COVER APERTURE	1	15.85	7 15.85
BLIND RIVET AVIBVLB 8 0.55 4.40 SCREW (SF PLUS M5X15) 3 0.55 1.65 (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55 281.55	Abrasion-res	1	4.75	
SCREW (SF PLUS M5X15) 3 0.55 - 1.65 (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55 - 281.55	CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	
SCREW (SF PLUS M5X15) 3 0.55 - 1.65 (DG/SL) BODY ADHESIVE K5B (195ML) 1 281.55 - 281.55	BLIND RIVET AVIBVLB	8	0.55	3 4.40
[1980년에서 1985년에 제공에 제공에 제공에 제공에 대통에 대통에 대통에 대통에 대통에 대통에 대통에 대통에 대통에 대통		3		- 1.65
(DG) BODYWORK ADHESIVE K5A (50ML) 1 118.35 118.35	[	1		
	(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35

Performance Motors Limited
A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x BMW Dealer

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road Bast Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Date Estimate Prepared By	: b1 48563 d : 26/09/2018 : Chua Kee Si			Pag	e No.	: 3 of 6	5
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL			MILEA	AGE
SMC4249D	5153199	29/06/2018	216i GT			0	
(DG (DG (DG (DG (DG PUN (DG	SCRIPTION  6) CLEANER R1 (100ML) 6) CLEANER R1 (100ML) 6) CLEANER R1 (100ML) 6/SL) W/SCREEN SEALAN 6/SL) W/SCREEN SEALAN NCH RIVET N4 6/SL) GLASS PRIMER 30MI 6/SL) GLASS PRIMER 30MI	(COLD 1 HOUR)		1 26 1 26 1 26 1 131 2 131 36 0 1 27		× 9	VALUE 26.15 26.15 26.15 131.55 263.10 19.80 27.85 27.85
				Total Pa	arts	:	5,259.05
LKK Auto	Regn No. Date&Time 28 Surveyor's Name Surveyor's Tel Authorised Date RESURVEY PARTS Surveyor's E-mail No. of Working Days	PASUL SINGER PHOTO BY SURVEYOR MON @ IKKA	iaim No	REVENT	Magazin S.	ho/18.	
	Surveyor's Name Surveyor's Tel Authorised Date RESURVEY PARTS Surveyor's E-mail	PASUL SIPOTO BY SURVEYOR MOUNT & IKKA	iaim No.  xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	REVENT	June States	10/18. 110/18.	
the Repai  To resurve  To display.  Parts price  Third party	Regn No.  Date&Time 2b  Surveyor's Name  Surveyor's Tel  Authorised Date  RESURVEY PARTS  Surveyor's E-mail  No. of Working Days  Consultants hence notify rer of the following:  syclete/after spray painting  temperature parts of the parts of the following:  syclete/after spray painting  temperature parts of the parts of the following:  syclete/after spray painting  temperature parts of the parts of the parts of the following:  syclete/after spray painting  temperature parts of the	PASUL SURVEYOR AND EXPROSE RECOmmend 5-6	iaim No.  xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	REVENT	Supple States	10/18. 14, 215.70	17,853.00 5,259.05
the Repai  To resurve  To display.  Parts price  Third party  No flegal r  Supplement	Regn No.  Date&Time 2b  Surveyor's Name Surveyor's Tel  Authorised Date  RESURVEY PARTS Surveyor's E-mail  No. of Working Days  Consultants hence notify rer of the following:  Excelderafter spray painting themselve the properties of the survey particular themselve themselve the survey particular themselve themselve the survey particular themselve the survey particular themselve the survey particular themselve themselve themselve the survey particular themselve the survey particular themselve the survey particular themselve the survey particular themselve themselve the	PASUL SH PODIOO68 AL SPHOTO BY SURVEYOR MANIE (RECOmmend 5-6 Resurveyor)	iaim No. xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	Perent No	June 3	10/18 ··	5,259.05 0.00
the Repair To resurve To display. Parts price Third party No Illegal r Supplements subject t	Regn No.  Date&Time 2b  Surveyor's Name  Surveyor's Tel  Authorised Date  RESURVEY PARTS  Surveyor's E-mail  No. of Working Days  Consultants hence notify rer of the following:  sycelete/after spray painting  transport parts; thirting resurvey es are subject to confirmation / survey is on a "Without Prejudice" be modification(s) is allowed  ntary itsm(s) must be resurveyed and	PASUL SH PODIOO68 AL SPHOTO BY SURVEYOR MANIE (RECOmmend 5-6 Resurveyor)	iaim No.  xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx	bour 1		:	

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*



A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770 Tel.

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSa: 63190533/530 (Motorra:

(AfterSales)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 48563 Page No. : 4 of 6

Date Estimated : 26/09/2018

: Chua Kee Sin Prepared By

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SMC4249D 5L53199 29/06/2018 216i GT 0

#### Terms & Conditions of Service

- 1. All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- 2. The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed \$\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- 3. Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail
- 4. The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- 5. The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge
- 6. PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- 7. Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle
- 8. Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsnever
- 9. The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- 10. If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- 11. If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- 12. PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- 13. These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer
- 14. If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.



A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road

Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

### ESTIMATE

Estimate No. : b1 48563 Page No. : 5 of 6

Date Estimated : 26/09/2018

Prepared By : Chua Kee Sin

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

29/06/2018 SMC4249D 5L53199 216i GT 0

- 15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
- 16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
- 17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
  - The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
    - (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority.
    - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
    - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
    - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
    - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
    - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
  - 17.2 The Vendor shall also disclose the Customer's personal data:
    - (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
    - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides:
    - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
    - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
    - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
    - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
    - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
  - The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
  - If the Vendor amends any provision in this clause17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the 17.4 Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
  - 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
  - The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
    - (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
    - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
    - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.



A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
(Motorrad)



GST REG. NO : M2 - 0020081 - X

### ESTIMATE

Estimate No. : b1

48563

Date Estimated Prepared By

: Chua Kee Sin

: 26/09/2018

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SMC4249D

5L53199

29/06/2018

216i GT

0

Page No. : 6 of 6

- The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
  - (a) put his request in writing;
  - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
  - (c) specify the information that is incorrect and what it should be replaced with.

The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.

- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or.
  - (a) put his request in writing by way of an email sent to the Vendor;
  - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer, and
  - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer Performance Motors Limited

Address: Sime Darby Performance Centre 303 Alexandra Road Singapore 159941

Email address:

dataprotection@pml.com.sg

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



#### FINAL REPORT

Estimate No. Date Estimated b1 48563

Prepared By

26/09/2018 Chua Kee Sin

REPAIR FOR -

- ACCOUNT -

- 66

ORIGINAL PRICE

2550.00

3801.00

451.00

742.00

150.00

94.00

451.00

Page No. :

Performance Motors Limited

MSIG Insurance (S) Pte Ltd

303 Alexandra Road

4 Shenton Way

Sime Darby Performance Centre

#21-01 SGX Centre 2 Singapore 068807

Singapore 159941

REGN NO

CHASSIS NO.

REGN DATE

MODEL

M LEAŒ

SMC4249D

5L53199

29/06/2018

216i GT

0

NETT

2,550.00

3,801.00

451.00

742.00

150.00

94.00

451.00

100.00

DISC. %

DESCRIPTION

To repalce rear LH door include making good the rear LH fender, front LH door, LH side skirting and knocking out dents caused by the accident

To spray paint rear LH fender, both LH doors and LH side

skirting

To check steering geometry and conduct wheel alignment in accordance with BMW specifications (1x)

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs

To check electrical wiring systems and lightings at the rear section for proper function,

To replace rear LH wheel rim include balancing (1x)

To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function (1x)

To carry out body cavity preservation. (Per panel).

Sundries.

150.00

QTY

DISC. %

100.00

150.00

DESCRIPTION

ALLOY RIM 7JX16 DOUBLE SPK 473
# RR LH DOOR \*

738.55 1.00 1,103.65 1.00

UNIT PRICE

738.55 1,103.65

NETT

# SUPPLEMENTARY ITEMS

Total Labour:	8,489.00
Total Parts:	1,842.20
Total Labour & Parts :	10,331.20
Deduction for Excess :	2,000.00
Total Repair Costs less Excess:	8,331.20
GST @7%:	583.18
Grand Total;	8,914.38

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



### SUPPLEMENTARY

Estimate No.

b1 48563

Date Estimated

26/09/2018

Prepared By

Chua Kee Sin

REPAIR FOR -

- ACCOUNT -

66

Page No. :

Performance Motors Limited

MSIG Insurance (S) Pte Ltd

303 Alexandra Road

Sime Darby Performance Centre

4 Shenton Way #21-01 SGX Centre 2

Singapore 068807

Singapore 159941

REGN NO

CHASSIS NO.

REGN DATE

MODEL

M LEAGE

SMC4249D

5L53199

29/06/2018

216i GT

0

DESCRIPTION

ORIGINAL PRICE

DISC. %

NETT

DESCRIPTION

UNIT PRICE

QTY DISC. %

NETT

# RR LH DOOR \*

1,103.65

1.00

1,103.65

Total Labour:

1,103.65

Total Parts : Total Labour & Parts :

1,103.65

# Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 22 October 2018 11:32 AM

To:

'Keith Leo Chi Yung'; PBSP

Cc:

Rasul (LKKAuto); SUR

Subject:

RE: FINAL REPORT / SMC4249D

Dear Caroline,

Confirm \$10,331.20 before excess \$2000 and GST

Repair days: 6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>

Sent: Friday, 19 October 2018 4:09 PM

To: Veron Chen (LKKAuto) < veronchen@lkkauto.com>; PBSP < pml-pbsp@simedarby.com.sg>

Cc: Rasul (LKKAuto) < Rasul@lkkauto.com>; SUR < sur@lkkauto.com>

Subject: RE: FINAL REPORT / SMC4249D

Dear Veron

We only have before paint photo

Warm Regards

Keith Leo Body & Paint DDI: 6319 0172 FAX: 6479 4601



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising

from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Friday, 19 October, 2018 11:23 AM

To: PBSP <pml-pbsp@simedarby.com.sg>; Keith Leo Chi Yung <keith.leo.chiyung@simedarby.com.sg>
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

Dear Keith,

Kindly forward us after paint photos.

Subject: FW: FINAL REPORT / SMC4249D

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 15 October 2018 3:06 PM

To: Rasul (LKKAuto) < Rasul@lkkauto.com >; SUR < sur@lkkauto.com >

Subject: FINAL REPORT / SMC4249D

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 8,489.00 Total Parts : 1,842.20

Total Labour & Parts: 10,331.20

Repair days: 6

Thank you.

Regards,

Caroline C/o Performance Motors Limited - Body and Paint 303 Alexandra Road Singapore 159941 DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Votified	Est Submitted	Adj Assigned	Adj Rpt	A	dj Submitted	Ins Auth'ed	Status	
Main	27 Sep 2018 27 Sep 2018 15:51 S\$10,331.20 S\$10,331.20 View Rpt Pending for Sur Report Cancel Case				Survey				
ŀ	lain	R	eference		Claim Detail	s	Documents		Show All
CLAIM SUE	FOLDER DE	TAILS				[Created	d by insurer]		
Insured:	PERFORM	ANCE MOTORS I	TD, Co. Reg. No.:	19740155	9W				
Vehicle Reg. No.:	SMC424	9D			Date of Los		18 07:00 - :59 s and <b>27</b> Days From LT	A Reg Date (M	an Yr)]
Claim Type:	OD / 571	1641			Policy/Cove Note No.:		4MCY (Comprehensive) : 01/10/2017 - 30/09/		
					Excess:	S\$2,000.0	00		
Repairer:	Performa 63190172/		ted (Alexandra) 3	03 Alexand	Ira Road, Sim	ne Darby Perfo	ormance Centre, 15994	1 Alexandra -	Tel:
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +6	5 6827 7888	[Handled b	y Eliza Ho Teng Boor	- 6594 2554]	
Adjuster:	LKK Auto	<b>Consultants Pte</b>	Ltd (HQ) - Tel: 62	56-3561	. [Handled b	Y MOHD RAS	UL] [Final Rpt d	ue 27/10/20	18]
Driver/Custo dian:	LEE SHUO	HONG SHAUN (36	5 / Male), NRIC: S	8137151B	, Tel: +659	7276229			
Adj Asg. Remarks:	CAR IN. SU	JRVEY & REVERT.							
ASSOCIAT	ED MAIL RE	CEIVED					View A	II Compose	Case Mai
MSIG_SG     MSIG_SG	(19/10/2018 (28/09/2018	3): Alert - Adj Ma 3): Alert - Adj Ma	andate Approved ( andate Approved (	S\$10331 S\$9828.9	.20) - SMC4 00) - SMC42	249D - Claim 49D - Claim	Handler: Eliza Ho T. Handler: Eliza Ho Te.		
ALL ASSO	CIATED TAS	iks⊡				View All	Search Tasks Crea	te New Task	Complete
Due Date	Priority	Type Task	Group Subject	ct Hand	dler Ass	igned By	Completed On	Created On	Done

## Claim Documents

\*SMC4249D (571641)
OD
Sep 25 2018 7:00AM
[PERFORMANCE MOTORS LTD]
Performance Motors Limited

Ass	essment Reports		1 per pa	age 🗸	V
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	28/09/18 16:00	Adjuster Immediate Advice	0	Load HTM	
2	17/10/18 10:49	Adjuster Immediate Advice	0	Load HTM	
Pho	otos/Images		3 per pa	age 🔻	<b>√</b>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/10/18 10:55	General View	0	Load JPG	<b>✓</b>
2	03/10/18 10:55	General View	0	Load JPG	✓
3	03/10/18 10:55	General View	0	Load JPG	V
4	03/10/18 10:55	General View	0	Load JPG	<b>✓</b>
5	03/10/18 10:55	General View	0	Load JPG	✓
6	03/10/18 10:55	General View	0	Load JPG	~
7	03/10/18 10:55	General View	0	Load JPG	~
8	03/10/18 10:55	General View	0	Load JPG	~
9	03/10/18 10:55	General View	0	Load JPG	<b>√</b>
10	03/10/18 10:55	General View	0	Load JPG	<b>✓</b>
11	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
12	03/10/18 10:55	General View	0	Load JPG	~
13	03/10/18 10:55	General View	0	Load JPG	~
14	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
15	03/10/18 10:55	General View	0	Load JPG	~
16	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
17	03/10/18 10:55	General View	0	Load JPG	~
18	03/10/18 10:55	General View	0	Load JPG	~
19	03/10/18 10:55	General View	0	Load JPG	~
20	03/10/18 10:55	General View	0	Load JPG	~
21	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
22	03/10/18 10:55	General View	0	Load JPG	~
23	03/10/18 10:55	General View	0	Load JPG	V
24	03/10/18 10:55	General View	0	Load JPG	V
25	03/10/18 10:55	General View	0	Load JPG	~
26	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
27	03/10/18 10:55	General View	0	Load JPG	V
28	03/10/18 10:55	General View	0	Load JPG	V
29	03/10/18 10:55	General View	0	Load JPG	V
30	03/10/18 10:55	General View	0	Load JPG	<b>V</b>
234	03/10/18 10:55	General View	0	Load JPG	V
31			0	Load JPG	<b>▼</b>
32	03/10/18 10:55	General View General View	0	Load JPG	V
33	03/10/18 10:55	General View	0	Load JPG	<b>∀</b>

Ass	essment Reports		1 per p	oage 🔻	4
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
35	03/10/18 10:55	General View	0	Load JPG	<b>✓</b>
36	03/10/18 10:55	General View	0	Load JPG	✓
37	03/10/18 10:55	General View	Ð	Load JPG	$\overline{\mathbf{Z}}$
38	03/10/18 10:55	General View	0	Load JPG	<b>✓</b>
39	17/10/18 10:40	Reinspection Photo	0	Load JPG	V
40	17/10/18 10:40	Reinspection Photo	0	Load JPG	<b>✓</b>
41	17/10/18 10:40	Reinspection Photo	0	Load JPG	<b>V</b>
42	17/10/18 10:40	Reinspection Photo	0	Load JPG	<b>V</b>
43	17/10/18 10:40	Reinspection Photo	0	Load JPG	V
44	17/10/18 10:40	Reinspection Photo	0	Load JPG	<b>V</b>
45	22/10/18 11:29	Reinspection Photo	0	Load JPG	✓
Doc	umentation		1 per j	page V	<b>V</b>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/09/18 09:49	ESTIMATE + DL	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/09/18 16:09	SMC 4249D ESTIMATE	0	Load PDF	
2	17/10/18 10:41	1ST MARKING	0	Load PDF	
3	17/10/18 10:42	SUPPLEMENTARY	0	Load PDF	

# **Linked Accident Report Documents**

			View View in Bro	wser 🗸
Ass	essment Reports		1 per page	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbna	il Print
1	26/09/18 14:59	Accident Statement	■ Load HTM	1
Pho	tos/Images		3 per page	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbna	il Print
1	26/09/18 14:56	Accident Photo	1 Load JPC	~
2	26/09/18 14:56	Accident Photo	1 Load JPC	V
3	26/09/18 14:56	Accident Photo	1 Load JPC	✓
4	26/09/18 14:56	Accident Photo	1 Load JPC	~
5	26/09/18 14:56	Accident Photo	1 Load JPC	✓
6	26/09/18 14:56	Accident Photo	1 Load JPC	<b>✓</b>
7	26/09/18 14:56	Accident Photo	1 Load JPC	<b>✓</b>
8	26/09/18 14:56	Accident Photo	1 Load JPC	✓
9	26/09/18 14:56	Accident Photo	■ Load JPC	V
10	26/09/18 14:56	Accident Photo	1 Load JPC	<b>☑</b>
11	26/09/18 14:56	Accident Photo	1 Load JPC	<b>✓</b>
12	26/09/18 14:56	Accident Photo	■ Load JPC	<b>✓</b>
13	26/09/18 14:56	Accident Photo	■ Load JPC	<b>✓</b>
14	26/09/18 14:56	Accident Photo	■ Load JPC	<b>✓</b>
15	26/09/18 14:56	Accident Photo	1 Load JPC	<b>✓</b>
16	26/09/18 14:56	Accident Photo	1 Load JPC	~
17	26/09/18 14:56	Accident Photo	1 Load JPC	<b>✓</b>
18	26/09/18 14:56	Accident Photo	1 Load JPC	~
19	26/09/18 14:56	Accident Photo	1 Load JPC	<b>▼</b>
20	26/09/18 14:56	Accident Photo	1 Load JPC	$\overline{\mathbf{Z}}$
Doc	cumentation		1 per page	
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbn	il Prin

Ass	essment Reports		1 per page	V
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	26/09/18 14:53	Sketch Plan	■ Load TIF	

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save	Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
		-
		~

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25. Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG18017617/R1VBE2

Date:

23/10/2018

REFERENCE

Date of Loss:

Insured/Claimant:

PERFORMANCE MOTORS LTD

Policy No: Nature of Claim: 29040254MCY

OD

Claim No: 571641

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

25/09/2018

Reg No:

SMC4249D

Make & Model:

BMW 216I, 1.5 D GT LED (A) 29/06/2018 (Man. Year: 2018) Engine No: Chassis No: 34195262B38A15A

Reg. Date: Colour:

Odometer:

WBA2D920505L53199 1115 km

Engine Capacity:

1499 cc

Market Value/New Car Price: S\$133,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

205/60 R16

Rear Tyre Size:

205/60 R16

Front Tyre Size: Front Left Side:

Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side:

Continental 6 mm The above values represent the remaining tyre treads depth

Continental 6 mm Rear Right Side:

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,512.70	1,992.20	4,520.50	69.41
Miscellaneous Items		0.00	0.00	0.00	
Labour		17,703.00	8,339.00	9,364.00	52.89
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	24,215.70	10,331.20	13,884.50	57.34
	- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
	(S\$)	22,215.70	8,331.20	13,884.50	62.50
	+ GST 7.00/7.00% (S\$)	1,555.10	583.18	971.92	62.50
	Nett Amount (S\$)	23,770.80	8,914.38	14,856.42	62.50

INSPECTION

Date of Assignment:

27/09/2018

Date Inspected:

28/09/2018 Inspected At:

Performance Motors Limited (Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

6.0 days

Adjuster Report Page 2 of 5

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

# REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Oct 2018)

Parts: M1-MPV BMW 216I 1.5 D GT LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC4249D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty Pa	art No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS
)	6	*PLASTIC NUT FOR COARSE THREADED PI	N Not Necessary	4.80 FS	*- FS
3	1	*ALLOY RIM 7JX16 DOUBLE SPK 473	Scratched	738.55 FS	*738.55 FS
1	1	*HUB CAP WITH CHROME EDGE	Not Necessary	35.75 FS	*- FS
5	1	*REAR LH SIDE PANEL	Repair	1,360.75 FS	*- FS
3	1	*POSITIONIERU	Not Necessary	5.60 FS	*- FS
7	1	*REINFORCEMENT PLATE UNIVERSAL	Not Necessary	27.75FS	*- FS
3	1	*REINFORCEMEN	Not Necessary	49.20 FS	*- FS
9	1	*REINFORCEMEN	Not Necessary	49.20 FS	*- FS
10	1	*REINFORCEMEN	Not Necessary	49.20 FS	*- FS
11	10	*T WELD BOLT L=5.4MM	Not Necessary	25.50 FS	*- FS
12	1	*LH LOWER REAR DOOR HINGE	Not Necessary	57.15 FS	*- FS
13	1	*LH LOWER REAR DOOR HINGE	Not Necessary	57.15FS	*- FS
14	1	*LH UPPER REAR DOOR HINGE	Not Necessary	57.15 FS	*- FS
15	1	*LH SUPPORT SILL	Not Necessary	12.95 FS	*- F8
16	4	*PLASTIC NUT	Not Necessary	3.40 FS	*- FS
7	1	*LH SILL TRIM PRIMED	Repair	278.65 FS	*- FS
8	1	*REAR DOOR BRAKE	Not Necessary	72.05 FS	*- FS
9	1	*REAR LH DOOR WINDOW FRAME COVER (	AL Not Necessary	59.75 FS	*- F8
20	1	*LH SEALING COLUMN B BOTTOM	Not Necessary	50.85 FS	*- FS
21	1	*REAR LH DOOR COLUMN B COVER	Not Necessary	60.85 FS	*- F8
22	1	*INNER WEATHE	Not Necessary	62.45 FS	*- F8
23	1	*SEAL, TRIM	Not Necessary	21.25 FS	*- F8
24	1	*SEAL, DOOR W	Not Necessary	21.25 FS	*- F8
25	1	*REAR LH DOOR OUTER WEATHERSTRIP (A	AL Not Necessary	91.80 FS	*- F8
26	1	*REAR LH DOOR WINDOW GUIDE	Not Necessary	119.65 FS	*- FS
27	1	*REAR LH SIDE WINDOW FIXED (ALU HOCH	Not Necessary	270.25 FS	*- FS
28	1	*LH FIXED DOOR WINDOW	Not Necessary	127.30 FS	*- FS
29	1	*REAR LH DOOR WINDOW FRAME COVER	Not Necessary	59.75 FS	*- F8
30	1	*RR LH WHEEL HOUSING LINER	Not Necessary	135.05 FS	*- FS
31	1	*REAR DOOR JOINT SEAL	Not Necessary	30.35 FS	*- F8
32	1	*REAR DOOR EDGE PROTECTION	Not Necessary	153.10 FS	*- FS
33	1	*FRT LH RETAINING STRIP SILL	Not Necessary	20.80 FS	*- F8
34	1	*RR LH RETAINING STRIP SIDE SILL MID	Not Necessary	20.30 FS	*- FS
35	1	*REAR LH RETAINING STRIP SILL	Not Necessary	45.00 FS	*- FS
36	1	*FRT LH APERTURE COVER	Not Necessary	15.05 FS	*- FS
37	1	*RR LH COVER APERTURE	Not Necessary	15.85 FS	*- FS
38	1	*RR LH COVER APERTURE	Not Necessary	15.85 FS	*- F8
39	1	*ABRASION-RES	Not Necessary	4.75 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*-FS
41	8		*BLIND RIVET AVIBVLB	Not Necessary	4.40 FS	*-FS
42	3		*SCREW (SF PLUS M5X15)	Not Necessary	1.65 FS	*-FS
43	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*-FS
44	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Not Necessary	118.35 FS	*-FS
45	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*-FS
46	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*-FS
47	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS
48	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	131.55 FS	*-FS
49	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*-FS
50	1		*PUNCH RIVET N4 (36PCS)	Not Necessary	19.80 FS	*-FS
51	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*-FS
52	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*-FS
53	1		*RR LH DOOR	Bent	1,103.65 FS	*1,103.65 FS
F=Fra	F=Franchise part. S=SpcNett.		Nett.	Total Parts (S\$)	6,512.70	1,992.20

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACE LEFT REAR SIDE FENDER, LEFT REAR DOOR, LEFT LOWER SIDE SKIRTING AND REMOVE ATTACHMENT ETC AND INCLUDE KNOCK ON ACCIDENT DENT	New	8,500.00	2,550.00
2	SPRAY PAINTING LEFT REAR SIDE FENDER, LEFT BOTH DOOR, LEFT LOWER SIDE SKIRTING, B PILLAR TRUNK FLOOR AND TAIL END PANEL	New	5,498.00	3,801.00
3	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION (1x)	New	531.00	451.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (1x). LEFT REAR	New	94.00	94.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR) LEFT	New	531.00	451.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
10	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS QUOTER SOLAR FILM	New	425.00	0.00
11	TO SUPPLY AND INSTALL REAR LEFT WINDOW GLASS DOOR QUATER SOLAR FILM	New	425.00	0.00
	Gross Labour	r Cost (S\$)	17,703.00	8,339.00

< END OF ESTIMATES >