

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 02 Oct 2018

## **Preliminary Advice**

Insured Vehicle No : GBG8060M

TP Vehicle No : SDS88A

Make : NISSAN GTR

Date of Inspection : 28/09/2018

Inspection At : Maximus Racing Pte Ltd (HQ)  
7 Soon Lee Street, #05-05 MR Performance Centre  
Singapore 627608

Accident Date : 23/09/2018

Assignment Date : 27/09/2018

Est. Duration of Repair : 5 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,875.00
Revised Amount	:S\$	17,230.00
Check Items (Estimated)	:S\$	3,135.00
Total	:S\$	20,365.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP