





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/09/2018

User ID : TuckFoo

Section A - Accident Details	
Registration Number	SHB5611Z
Case Reference Number	TAX/09/18/2100
Registration Date	12/19/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TOH HOCK KEE
Type of Accident	Open Door Case
Accident Date and Time	9/21/2018 4:00 PM
Accident Reported Date and Time	9/22/2018 11:13 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098048
Special Instruction to ARC, if any	
Prepared Date and Time	9/26/2018 8:53 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota Prius

Section B - Summary of Repair Estimates		
Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$1,314.00	\$200.00
Total Spare Part Cost	\$6,603.32	\$2,303.01
Total Other Cost	\$460.00	\$60.00
TOTAL COST	\$9,222.32	\$2,863.01
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5-7	2.0
Prepared / Adjusted By	Zhi Yang Phua	Naz
ARC / Surveyor Sign Off Date	26/09/2018 1:50 PM	27/09/2018 1:20 PM
Signature		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works	Quotation from AR	Adjusted by Surveyor, if applicable
Job Scope		
TO REPAIR RH PORTION	\$845.00	\$300.00
Total Labour	\$845.00	\$300.00



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Service Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/09/2018

User ID : TuckFoo

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	\$378.00	\$0.00 X M
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00 X M
TO RESPRAY RIM	\$180.00	\$0.00 X M
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$1,314.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00 X M
TO WASH AND VACUUM	\$60.00	\$0.00 X M
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00 X M
Total Other Costs	\$460.00	\$60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		6700147152	PANEL SUB-ASSY, FRONT DOOR RH	0.00	\$1,249.60	0.00	\$0.00	Replace	Not Given X SUC
			STICKER DECAL SMRT (DOOR)	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X M
		5380147080	FENDER SUB-ASSY, FR, RH	0.00	\$933.10	0.00	\$0.00	Replace	Not Given X SUC
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given X M
		5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given X SUC
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given X SUC
		5211947962	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair X R
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given X SUC
		8114547691	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace X CR
		8121047020	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given X SUC
Total					\$8,090.60		\$2,303.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

NA2 LKK
 27/9/18
 P/R
 2 DAYS
 AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: