



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : JASPAT INTERNATIONAL (S) PTE LTD
105 SIMS AVENUE
#07-01 CHANCERLODGE COMPLEX
SINGAPORE 387429

Estimate No: MC0913464
Date: 27 Sep 2018
Policy No: P2076805
Veh Reg No: SJY907J
Make/Model: TOYOTA CAMRY 2.4 A

ATTN:

Your Ref No: SJY907J
Claim Type: Third Party - *MTG 10-12*
Accident Date: 18/09/2018
TP Veh Reg No: SMC7457A

Not Notarised
Repairing 3 days

Estimate Repair Cost to Vehicle No :SJY907J

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 SIDE MIRROR LH	1 PC	926.30	?
2 SIDE MIRROR COVER	1 PC	96.30	✓
3 SIDE MIRROR SIGNAL LAMP LH - CHECK PRICE	1 PC	0.00	✓
4 FRONT FENDER LH	1 PC	798.75	✓
5 FRONT FENDER COWLING LH	1 PC	155.60	✓
6 FRONT FENDER COWLING CLIPS	8 PC	25.68	✓
7 FRONT BUMPER	1 PC	511.60	✓
8 FRONT BUMPER SIDE RETAINER LH	1 PC	60.78	✓
		2,575.01	
	Less 25%	643.75	1,931.26
LABOUR			
9 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	15/
10 TO REMOVE & REPLACE SIDE MIRROR LH	1 PC	80.00	?
11 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD . TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	300/
12 TO SPRAY FRONT FENDER LH,FRONT BUMPER,SIDE MIRROR LH.	1 PC	600.00	450/
		1,220.00	1,220.00
Total			S\$ 3,151.26
Add GST @ 7%			220.59
Total Amount Payable			S\$ 3,371.85

TOTAL: SINGAPORE DOLLAR THREE THOUSAND THREE HUNDRED SEVENTY ONE AND CENTS EIGHTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE