

INS. CASE OWNER:

CC 6, Hb 180 17646, A 403

L.A.C.

IDAC:

Surveyor:

WMP

DOI:

ASSIGNMENT

31/10/18

Date / Time:

18/09/18

Registered in Merimen:

28/09/2018

Pre-assign / CCU / FTE

TP 9986 C



Insured Vehicle No.:

Claim No.:

Name of Insured:

Lok Siah Thong

Policy No.:

1700092607

Insured Tel No.:

HP:

97579986

Make / Model:

Mazda 3

Excess Sec II :SS

D.O.A.:

26/09/2018

Place of Accident:

Commonwealth Dr

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

GI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLC 1382 H



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

X

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

13-12-18

TRANSFER: THIN 2 TO 304

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Assessed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

GST

S\$

3,584.50

Loss of Rental (LOR):

S\$

600

(C days)

x100

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.44

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

4,186.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4,185.XV

Name 1:

MODERN AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

V

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-15
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation
DATE 03.10.2018
VEH NO SLC1382H
MODEL Honda Shuttle
D O A 26.09.2018
YR REF EP9986C

Joy

Attn: Motor Claim Dept (P/s arrange vehicle survey & check liability)

RE: ESTIMATE FOR ACCIDENT REPAIR SLC1382H (HONDA SHUTTLE)

Item	Description	Qty	Amt
NO	LIST ITEMS		
1	Rear Bumper <i>Defend</i>	1	1,150.60 ✓
2	Rear Bumper Clips <i>na</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>na</i>	2	65.00 ✓
4	Rear Bumper Sponge - LH & RH <i>LH Defend</i>	2	150.40 <i>75.20</i>
5	Rear Bumper Side Garnish - LH & RH <i>LH Defend</i>	2	185.00 <i>92.50</i>
6	Rear Bumper Side Reflector - LH & RH <i>not rec</i>	2	173.20 x
7	Rear End Panel <i>Dented</i>	1	792.00 ✓
8	Rear End Panel Top Garnish <i>Defend</i>	1	187.30 ✓
9	Tailgate <i>na</i>	1	1,292.00 x
10	Tailgate Lock <i>DM</i>	1	151.70 x
11	Tailgate Weatherstrips <i>cut</i>	1	158.50 x
12	Tailgate Inner Trim Board <i>na</i>	1	320.40 x
13	Tailgate Inner Trim Board Clips <i>na</i>	1	30.00 x
14	Tailgate Glass Moulding <i>na</i>	1	138.90 x
15	Honda Logo <i>He na</i>	1	30.10 x
16	Shuttle Emblem <i>na</i>	1	55.00 ✓
17	Rear Fender Inner Trim Board - LH & RH <i>2 set</i>	2	670.00 x
18	Rear Fender Inner Trim Board Clips <i>na</i>	1	80.00 x
19	Tools Tray <i>cancel</i>	1	428.00 ✓
			6,038.10
Less 20%			(1,217.62)
			\$ 4,870.48

S/NETT ITEMS:

1	Rear Number Plate <i>2 set</i>	1	\$ 30.00 x
2	Rear Number Plate Holder <i>na</i>	1	\$ 30.00 x
3	Rear End Panel Sealant <i>na</i>	1	\$ 30.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SLC1382H (HONDA SHUTTLE)

✓ 4	Reverse Sensor <i>Damaged</i>	1	\$	230.00 <i>200</i>
✓ 5	Tailgate Glass Sealant <i>new</i>	1	\$	60.00 <i>320</i>
				<hr/>
				\$ 490.00
				<hr/>
Total Parts			\$	5,330.48

LABOUR CHARGE

✓ 1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 60
2	To putty & spray up paint works	\$	1,200.00 80
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 50
5	To remove reverse sensor	\$	100.00 50
6	To remove upholstery	\$	150.00 60
✓ 7	To transfer tailgate fittings	\$	150.00 ✗
✓ 8	To remove tailgate glass	\$	130.00 ✗
Total Labour		\$	3,180.00
Grand Total		\$	8,510.48

NOTE :-

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 420.48
3350
06 Days

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6744-4422 FAX : 6-747-6720

Email: chin@modernautomotive.com.sg

Your Ref : EP9986C

Our Ref : SLC1382H

Date : 14.02.2019

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SLC1382H & EP9986C ON 26.09.2018
AT COMMONWEALTH AVE WEST JUNCTION B/F CLEMENTI ROAD

We refer to the above matter.

We have been authorized by our client Mr Lim Soon Lee to make claim against your insured vehicle No.EP9986C in respect of the above accident for the following:

Repair Cost	\$ 3,584.50 (Incl GST)
Loss of rental (\$200 x 6 days)	\$ 1,200.00
Search fee	\$ 2.00
Total :	\$ 4,786.50

Enclosed herewith a copy each of the supporting documents for your perusal.
Kindly process the above and remit the payment to us asap

Yours faithfully


Modern Automotive Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18017646/Aja3

29 November 2018

LEK SIAH THONG
16 SUNSET CLOSE
SINGAPORE 597530

Dear Sir/Madam,

ACCIDENT INVOLVING EP 9986C AND SLC 1382H ON 26/09/18

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Joy Irene
Case Handler

DID: 6841 2409

FAX: 6741 4108

Email: joyirene@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

LETTER OF AUTHORIZATION

Date: 27/9/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLC1382 H & EP9986 C


ON 26/9/18 ALONG Commonwealth Ave West
Junction B/F Clementi Road.

This letter is to authorize MODERN AUTOMOTIVE PTE LTD at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, MODERN AUTOMOTIVE PTE LTD has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of MODERN AUTOMOTIVE PTE LTD.

MODERN AUTOMOTIVE PTE LTD is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully


Signature of Owner

Edmund Lim S8835235C
Name / NRIC

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,185.00 (Global Sum) for vehicle no. SLC 1382H that was damaged pursuant to the accident which occurred on 26/09/2018 (date) along COMMONWEALTH AVE TO CLEMENTI ROAD (location) involving vehicle no/s EP 9986C. This is pursuant to the inspection conducted on 03/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM SOON LEE (LIN SHUNLI) ("the third party claimant") of vehicle no. SLC 1382H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLC 1382H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 20 (day) of Feb (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717
TEL : 67474422, 67454422 FAX : 67476720
GST REG. NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
SINGAPORE 079120

Attention : Motor Claim Department
Contact : 6415-3727 6419-3000

Tax Invoice : TP001318

Date : 14/02/2019
Vehicle Num. : SLC 1382H
Make/Model : HONDA SHUTTLE-2016
Chassis/Eng# :
Accident Date : 26/09/2018
Claim No. :
Reference :
Policy No. : 5090057734-01

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		3,350.00
		Labour Total S\$:		3,350.00

Total S\$:	3,350.00
GST @ 7% S\$:	234.50
Amount Due S\$:	3,584.50

=====



MODERN AUTOMOTIVE PTE LTD



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1
SINGAPORE 798125
TEL: 6383 2661 FAX: 6484 2836
REG. NO. 430058/000

No. 19663

Date, 9/10/18

OFFICIAL RECEIPT

Received from

Edmund Lim Soon Lee

the sum of Dollars

One thousand two hundred only

being Payment Of

STZ 9654Z (5/10/18 - 9/10/18)

DAWN ENTERPRISES

\$

1200/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

TP
SLC1382H

Nº 35907

RENTAL AGREEMENT

DATE 03/10/18

HIRER'S PARTICULARS

Name Edmund Lim Soon Lee
Address 275A Comportvale Link
14-252
S 541275
I/C or Passport No. S7855235C Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) 98531628 (Residence) _____

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No Insurance Coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry passengers only.
3. Hirer is liable to pay first \$ 2000 as excess of all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of \$5,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

6 Day at \$200.00 per days	\$1200.00
Day at \$ per week	
Day at \$ per month	
TOTAL AMOUNT	\$1200.00
AMOUNT PAID	\$1200.00
BALANCE DUE	
Days Extension From To	
Amount Deposit (refundable) \$	

SCHEDULE

MODEL

SJZ 96542

7/with

Date Time Mileage

03/10/18 9.40 AM

9/10/18

FROM

3/10/18

TO

9/10/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-149684
Date of Request: 27/09/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date: 27/09/2018
Enquiry By: Chin Soi Shong
TP Vehicle No.: EP9986C
Accident Date: 26/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
EP9986C	AIG Asia Pacific Insurance Pte. Ltd.	13/12/2017-12/12/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-149684

Date of Request: 27/09/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd
Blk 3023A Ubi Road 1
#01-61 & #01-58
Singapore 408717

Dear Sir/Madam,

Enquiry Date 27/09/2018
Enquiry By Chin Soi Shong
TP Vehicle No. EP9986C
Accident Date 26/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Sep 2018 Edit Reg		03 Oct 2018 00:00 Edit Adj Rpt	S\$3,350.00 Edit Estimates	S\$3,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LEK SIAH THONG, ID: S01116458								
Main Claimant:	LIM SOON LEE (LIN SHUNLI), ID: S7835235C								
Vehicle Reg. No.:	SLC1382H	Date of Loss:	26/09/2018 11:00 - :59 [28 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1478982474SG	Policy/Cover Note No.:	1700092602 (Comprehensive)						
Vehicle Reg. No. (Insured):	EP9986C	Policy No. (Claimant):	5090057734-01						
		Excess:							
Repairer:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLC1382H (1478982474SG)
[EP9986C]**

TP

































LIM SOON LEE (LIN SHUNLI)

Sep 26 2018 11:00AM

[LEK SIAH THONG]

Modern Automotive Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	02/10/18 10:38	Video - Accident <small>From: SC - Reg. No: EP9986C, Claimant: LEK SIAH THONG</small>	1	Load MP4			
Letters/Correspondences						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
2	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
3	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
4	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
5	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
6	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
7	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
8	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
9	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
10	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
11	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
12	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
13	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
14	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
15	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
16	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
17	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
18	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
19	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
20	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
21	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
22	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
23	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
24	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
25	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
26	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
27	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
28	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
29	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		
30	05/11/18 10:55	General View	1	Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	05/11/18 10:55	General View	 Load JPG	<input checked="" type="checkbox"/>
32	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	05/11/18 10:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/09/18 13:38	TP GIA REPORT	 Load PDF	
2	21/02/19 13:40	WORKSHOP INVOICE	 Load PDF	
3	21/02/19 13:40	AUTHORISATION TO ACT FORM	 Load PDF	
4	21/02/19 13:40	Release Voucher	 Load PDF	
5	21/02/19 13:40	RENTAL RECEIPT	 Load PDF	
6	21/02/19 13:40	GIA SEARCH	 Load PDF	
7	21/02/19 13:40	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	01/10/18 11:42	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EP9986C (Insd veh)	Model:	HONDA SHUTTLE 1.5 G (A)
	SLC1382H (TP veh)		
Date of Accident:	26/09/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	9,106.21
Final Repair Cost	:	\$	4,185.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	6 days
LTA / GIA Search Fee	:	\$	_____
Others:	:	\$	_____
	:	\$	_____
Final Settlement Sum (Global Sum)	:	\$	4,185.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 4,185.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

21 Feb
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18017646/AJA3Q2

Date: 21/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700092602
Claimant Vehicle No : SLC1382H **Insured Vehicle No :** EP9986C
Date of Loss: 26/09/2018 **Nature of Claim:** TP **Claim No:** 1478982474SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC1382H**
 Make & Model: HONDA SHUTTLE, 1.5 G (A) Engine No: L15B3535189
 Reg. Date: 03/05/2016 (Man. Year: 2016) Chassis No: GK81004411
 Colour: White Odometer: 94886 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,330.48	2,604.48	2,726.00	51.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,590.00	1,590.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,510.48	4,194.48	4,316.00	50.71
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	8,510.48	3,350.00	5,160.48	60.64
+ GST 7.00/7.00% (S\$)	595.73	234.50	361.23	60.64
Nett Amount (S\$)	9,106.21	3,584.50	5,521.71	60.64
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,186.50		
Global Sum Settlement (S\$)		4,185.00		

INSPECTION

Date of Assignment: 03/10/2018
 Date Inspected: 03/10/2018 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,150.60 FL	*1,150.60 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	65.00 FL	*65.00 FL
4	1		*REAR BUMPER SPONGE -LH & RH	N/S Deformed	150.40 FL	*75.20 FL
5	1		*REAR BUMPER SIDE GARNISH -LH & RH	N/S Cut	185.00 FL	*92.50 FL
6	2		*REAR BUMPER SIDE REFLECTOR -LH & RH	Not Necessary	173.20 FL	*- FL
7	1		*REAR END PANEL	Dented	762.00 FL	*762.00 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	187.30 FL	*187.30 FL
9	1		*TAILGATE (Distorted)	Not Consistent With The Impact	1,292.00 FL	*- FL
10	1		*TAILGATE LOCK (DAMAGED)	Not Consistent With The Impact	181.70 FL	*- FL
11	1		*TAILGATE WEATHERSTRIPE (CUT)	Not Consistent With The Impact	168.50 FL	*- FL
12	1		*TAILGATE INNER TRIM BOARD (CRACKED)	Not Consistent With The Impact	320.40 FL	*- FL
13	1		*TAILGATE INNER TRIM BOARD CLIPS (CUT)	Not Consistent With The Impact	30.00 FL	*- FL
14	1		*TAILGATE GLASS MOULDING (NECESSARY)	Not Consistent With The Impact	138.90 FL	*- FL
15	1		*HONDA LOGO	Not Necessary	30.10 FL	*- FL
16	1		*SHUTTLE EMBLEM	Necessary	65.00 FL	*65.00 FL
17	2		*REAR FENDER INNER TRIM BOARD -LH & RH	Not Necessary	670.00 FL	*- FL
18	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FL	*- FL
19	1		*TOOLS TRAY	Cracked	428.00 FL	*428.00 FL
20	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
21	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
22	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
23	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
24	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,548.10** **3,175.60**
 - List Item Discount on L Items 20.00/20.00% (\$\$) **1,217.62** **571.12**

Total Parts (\$\$) 5,330.48 2,604.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	600.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	50.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	60.00
7	TO TRANSFER TAILGATE FITTINGS	New	150.00	0.00
8	TO REMOVE TAILGATE GLASS	New	180.00	0.00
Gross Labour Cost (\$\$)			3,180.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >