LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

4 Shenton Way 51 Ubi Ave 1 #01-25 #21-01 SGX Centre 2 Paya Ubi Industrial Park Singapore 068807 Singapore 408933

Attn: Ong Chin Kiat Date: 15 Oct 2018

Preliminary Advice

Vehicle No : SJT3305C Accident Date : 28/09/2018 Make : HYUNDAI AVANTE Policy No. : S27765039SMA **Assignment Date** : 02/10/2018 **Excess** : S\$500.00

Date of Inspection : 03/10/2018 Est. Duration of Repair : 6 days

Inspection At : SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,815.72 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	1,559.19 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	1,833.17
Total	:S\$	3,392.36

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:5\$
-------------------	------

Pre-Accident Value 13,000.00 :S\$ COE / PARF Rebate 7,645.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 5,355.00

Remarks

()	The above survey was conducted on a 'without prejudice' basis.
`	,	a p,

(X) Remarks: Supplementary amount \$30.00

(X) The vehicle is economical for repair.