

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 03 Oct 2018

Preliminary Advice

Vehicle No	: SJT3305C	Accident Date	: 28/09/2018
Make	: HYUNDAI AVANTE	Policy No.	: S27765039SMA
Assignment Date	: 02/10/2018	Excess	: S\$500.00
Date of Inspection	: 03/10/2018	Est. Duration of Repair	: 6 days
Inspection At	: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,785.72
Revised Amount	:S\$	1,529.19
Check Items (Estimated)	:S\$	1,833.17
Total	:S\$	3,362.36

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	7,645.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,355.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.