

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7105U

DATE 27/9/2018 14:54

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) X NN			\$ 1,388.00
	Front Fender (LH) ✓ DD			\$ 566.30
	Front Fender Shield (LH) X NN			\$ 175.90
	Front Bumper X repair	SUB TOTAL		\$ 2,130.20
	LH wing Mirror X repair	LESS 20%		\$ 426.04
		DISCOUNTED TOTAL		\$ 1,704.16
	Labour Charge			
	Panel Beating			\$ 440.00
	Spray Painting Charge			\$ 450.00
	Tuff Kote			\$ 50.00
		TOTAL LABOUR		\$ 710.00
		ESTIMATE TOTAL		\$ 2,414.16
	Kalur 11/18 28/9/18 no. L. 2018 PP Before Post photo	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	Acknowledged by Repairer Signature: Date:	
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			