

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 7105U

DATE 27/9/2018 14:54

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (LH) ✕			\$ 1,388.00
	Front Fender (LH) ✓			\$ 566.30
	Front Fender Shield (LH) ✕			\$ 175.90
	Front bumper ✕ repair			
	LH wing mirror ✕ repair			
	SUB TOTAL			\$ 2,130.20
	LESS 20%			\$ 426.04
	DISCOUNTED TOTAL			\$ 1,704.16
	Labour Charge			
	Panel Beating			\$ 440.00
	Spray Painting Charge			\$ 50.00
	Tuff Kote			\$ 20.00
	TOTAL LABOUR			\$ 710.00
	ESTIMATE TOTAL			\$ 2,414.16

Labour Charge

Panel Beating

Spray Painting Charge

Tuff Kote

TOTAL LABOUR

ESTIMATE TOTAL

Kalin CLK

28/9/18 11.00 L.S.

2 by 2

P.P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.