

ASS. REC. BY:

REF:

CS/FCI 18017720/Agd3/12

Special Instruction:

Surveyor

aws

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

28/9/18 @ 4:46pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 2816A

Insured:

SHC 7814L

at Workshop m/s

Modern Automotive

Tel:

6748 4422

of

Blk 3023A Ubi Rd 1 # 01-58

Policy No:

Claim No:

D18007100 MFSH

Sum Insured:

Excess:

Make of Vehl:

D.O.A.

26/09/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:01am @ 0/10/18

Person Contacted:

Grace

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SLK 2816A - X
	SHC 7814L - CS/FCI/7006540/R/H3e2 DoA: 30/3/17
1/10/18-	VNI
17/10/18-	VNI yet
2/11/18-	Vehicle still not in yet.
15/11/18-	VNI yet (pending liability)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of:

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 2816A

Yr Regn:

2017 Jan

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra. C.C. 1591

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

26716

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHD841CMH4255305

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

04/02/18

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP 1st Cap.

09/12/18 @ 6.17pm informed PC, we are pending estimate from repairer.

21/12/18 @ 12.15pm revised to PC by email.

LS @ 1900, 3 days cred B 1126-08, 37%

RECEIVED 27 DEC 2018

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.F. (\$) 7P 1900

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

) \$ - RS. \$

) Photos

) Others

TOTAL

130

50

50

16

246



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007100MFSH

Date: 27 December 2018

Our Ref: CS/FC118017720/Aqd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 2816A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/12/2018 at the premises of M/s MODERN AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,026.08</u>
Revised Estimate Amount	: S\$ <u>1,900.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the front o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	27-09-2018	Our Ref No.	D18007100MFSH
Accident Date	26-09-2018	Claim Type.	Third Party
Insured Vehicle	SHC7814L	Third Party Vehicle.	SLK2816A
Survey Location	BLK 3023A UBI ROAD 1 #01-58/61		
Contact Person.	GRACE CHIN		
Contact No.	67484422/ 0	Fax No.	67476720
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MODERN AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	LURENE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 27 December 2018 12:15 PM
To: 'Claim Workflow System'; assignments
Cc: SUR
Subject: RE: SURVEY ASSESSMENT - D18007100MFSH/1
Attachments: CSFC18017720Aqd3.pdf

Dear Sir/Madam,

Enclosed herewith preliminary advice of SLK 2816A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)

Sent: Wednesday, 5 December 2018 4:17 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007100MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLK 2816A on 04/12/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Monday, 1 October 2018 10:04 AM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18007100MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 5 December 2018 4:17 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007100MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLK 2816A on 04/12/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 1 October 2018 10:04 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007100MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 28 September 2018 4:46 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007100MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747 6720 REG NO 20050102H

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877
Tel : 6507 - 3848
Fax : 6507 - 3849

QUOTATION
DATE : 04.12.2018
VEH NO : 3LK2816A
MODEL : Hyundai Elantra
D O A : 26.09.2018
YR REF : 3HC7814L

Attn : Motor Claim Dept (Pls arrange survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR 3LK2816A (HYUNDAI ELANTRA)

Item	Description	Qty	Amt
<u>LIST ITEMS</u>			
1	Front Bumper <i>defend</i>	1	474.40 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - RH <i>new</i>	1	28.80 ✓
4	Front Bumper Lamp - RH	1	175.00 x
5	Front Bumper Lamp Cover - RH <i>3 new</i>	1	115.40 x
6	Front Bumper Fog Lamp	1	265.10 x
7	Head Lamp - RH <i>ct</i>	1	1,756.40 ✓
			\$ 2,845.10
			\$ (569.02)
			\$ 2,276.08
Total Parts			\$ 2,276.08

2289.60
1831.68

Less 20%

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew damage parts	\$ 400.00 <i>300</i>
2	To putty & spray up paint works <i>530</i>	\$ 300.00 <i>200</i>
3	To check wiring	\$ 50.00 <i>30</i>
		\$ 750.00

GRAND TOTAL

\$ 3,026.08

LKK Auto Consultants hence notify the Reparer of the following:
• To resurvey before & after repair
• To display damaged part(s) during resurvey
• Parts of **NOTE** subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

total 2361.68

4/s 1.9K

030m/s



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18017720/Aqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7814L	Veh. Inspected	SLK 2816A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007100MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	28/09/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMHU255305	Colour	BLUE	
Odometer	26716	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	HANKOOK	6 mm	
L/H Front Tyre	195/65 R15	HANKOOK	6 mm	
R/H Rear Tyre	195/65 R15	HANKOOK	6 mm	
L/H Rear Tyre	195/65 R15	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/09/2018	Inspection Date	04/12/2018	
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2816A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	474.40	474.40
1	SET FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
1	FRONT BUMPER SIDE HOLDER-RH	NECESSARY	28.80	28.80
1	FRONT BUMPER LAMP-RH	NOT NECESSARY	175.00	-
1	FRONT BUMPER LAMP COVER-RH	NOT NECESSARY	115.40	-
1	FRONT BUMPER FOG LAMP	NOT NECESSARY	265.10	-
1	HEAD LAMP-RH	CUT	1,756.40	1,756.40
	LESS 20% DISCOUNT		-569.02	-457.92
			2,276.08	1,831.68
	LABOUR			
	TO KNOCKING & PULL OUT RH SIDE PORTION & RENEW DAMAGE PARTS.		400.00	300.00
	TO PUTTY & SPRAY UP PAINT WORKS.		300.00	200.00
	TO CHECK WIRING.		50.00	30.00
			750.00	530.00
	GRAND TOTAL		3,026.08	2,361.68
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/FCI18017720/Aqd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.