

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/064/2018
DATE : 27-SEP-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : CHONG SEOW HACK
ADDRESS : 98 HUA GUAN AVENUE
S(589195)
TELEPHONE NO : 9666 0045 MR KUA

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100460170-02
VEHICLE NO : SLB4443B
MODEL CODE : SJ5DK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20Y205351
CHASSIS NO : JF1SJ5KC5GG067711
MILEAGE : 1 KM
DATE IN : 27/09/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 27/09/2018

Print Date : 27/09/2018
Print Time : 19:37:08

Taifu 97495749
'WP'
3/10/18 @ 1015
Resurvey before paint.
sur @ lkk auto.com.
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE, 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB4443B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	REVERSE2	TO SUPPLY AND INSTALL 2-POINT REVERSE SENSOR	450.00	350.00 ✓
2	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR BUMPER BEAM	2240.00	560.
3	ZZ/002	TO RESPRAY REAR BUMPER ASSY AND REAR BUMPER BEAM	1320.00	440.
4	ZZ/003	SUNDRIES	80.00	20.
5	ZZ/004	REMOVE AND REFIX EXHAUST TO FACILITATE REPAIR AND CHECKING	300.00	250.
TOTAL LABOUR CHARGES			4390.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 25 LENG KEE ROAD
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB4443B

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	GASKET (SUPP)	44011SG000	7.20 ?			
2	EXH PIPE ASSY R (SUPP)	44200SG011	720.00 ?			
3	MUFFLER ASSY RH NA (SUPP)	44300SG010	601.20 bt ✓			
4	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00 bt ✓			
5	BUMPER FACE R	57704SG012	540.00 an ✓			
6	BRKT CORNER R RH	57707SG060	18.00 ?			
7	BRKT SD R RH	57707SG080	14.40 ?			
8	BEAM COMPL R EU	57711SG0219P	288.00 ?			
9	COVER HOOK R	57731SG010NN	12.60 X			
10	COVER BMPR R (SUPP)	57731SG060	14.40 X			
SUB TOTAL			2287.80	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			457.56	0.00	0.00	0.00
GRAND TOTAL			1830.24	0.00	0.00	0.00
OVERALL TOTAL			1830.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB4443B

TOTAL LABOUR CHARGES 4390.00
TOTAL SPARE PARTS CHARGES 1830.24

GRAND TOTAL 6220.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.