



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/12/2018

### Survey Details:

Date of loss	25-Sep-18
Date of appointment	1-Oct-18
Date of survey	1-Oct-18
Location of survey	SMRT AUTOMOTIVE SERVICES PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	SHB 306M
Make and Model	TOYOTA PRIUS TAXI 1.8A - 1798cc
Date of registration	15-Jul-15
Excess	
Market Value (est)	\$0.00
Parf Rebate (est)	\$0.00
Nett Loss (est)	\$0.00

### Repair details:

Initial Estimate	\$ 4,175.18
------------------	-------------

### Proposed/Revised repair cost:

Parts	\$ 119.52
Check items (estimate)	\$ -
Labour	\$ 840.00
<b>Total</b>	<b>\$ 959.52</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 950.00</b>

Number of days for repair	<u>3 DAYS</u>
---------------------------	---------------



**Remarks:**

*We have not authorized repairs. It was reported that Insured vehicle was turning out from the minor road when collided to TP vehicle on the main road. A letter and email were sent out to the Insured to notify TP claim and NCD. TP LOD IN. For mandate approval.*

**Mandate:**

Liability(TP)		100%
Proposed Repair Cost	\$	950.00
Loss of Use	\$	-
Loss of Rental	\$	648.42
Loss of Income	\$	360.00
LTA search fees	\$	7.00
Others	\$	-
<b>Proposed Total</b>	<b>\$</b>	<b>1,965.42</b>