

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 1 December 2018 2:14 PM
To: 'Claims Dept of CTI'
Cc: Admin A; 'Ong Chin Kiat'
Subject: <SEEK MANDATE> Your ref : SNM18D04665/C01/3 *Our ref : CC6/CTI18017742/Kpa3s2 [ACCIDENT INVOLVING GT 3833E(OI) & SLP 8250R(TP) ON 27/09/2018]
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos.pdf; TP LOD_SLP8250R.pdf

Your ref : **SNM18D04665/C01/3**
Our ref : CC6/CTI18017742/Kpa3s2

Dear Sirs/Madam,

ACCIDENT INVOLVING GT 3833E(OI) & SLP 8250R(TP) ON 27/09/2018

We refer to the above matter.

The accident occurred when our insured driver turned out from minor road and collided with third party who was on main road. Liability is not in our insured driver's favour.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer "**LIM TAN MOTOR PTE LTD**" at **\$3,884.45(all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 4,477.43	\$ 3,317.00
2. Loss of Use (7days x \$80.00)	\$ 560.00	\$ 560.00 (7days x \$80.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 5,044.88	<u>\$ 3,884.45</u>

**06 days recommendation for repair + 1Sunday = 7days

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)