

ESTIMATE TO REPAIR

VEHICLE NO. : SLP 8250 R
MAKE : TOYOTA
MODEL : WISH 1.8 CVT
YEAR : 2017
CHASSIS NO : JTDGG20W90J007260

SURVEYOR NAME : Kenneth (LKK)
DATE OF SURVEY : 16 OCT 2018
TIME OF SURVEY :

DATE :
DATE OF ACCIDENT : 27-Sep-18
THIRD PARTY REF : GT 3833 E / CHINA TAIPING

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 728.50
1 pc	Rear Bumper Retainer				\$ 75.44
1 pc	O/S Rear Fender				\$ 795.68
1 pc	O/S Rear Quarter Glass Moulding				\$ 381.25
1 pc	O/S Rear Door				\$ 985.14
					\$ 2,966.01
	Less 25%				\$ 741.50
					\$ 2,224.51
1 tube	O/S Rear Quarter Glass Sealant	S.Nett			\$ 40.00
	To putty and spray painting.				\$ 800.00
	To transfer door fittings.				\$ 40.00
	To remove and refix rear quarter glass.				\$ 100.00
	To anti-rust.				\$ 80.00
	Labour Charges.				\$ 900.00
					\$ 800.00
TG-RA/-	TOTAL				\$ 4,184.51

Not Withstand
Resurvey Repaint
After
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel: 65-64520893 Fax: 65-64589127 Website: www.LTM.sg
Co.Reg No. 199307277D GST Reg No. M2-0019086-0