

Surveyor

REF: CSI / LPC 16017750 / Brbs

Special Instruction:

P/P: \$12614.96

ASSIGNMENT (Office)

From (Person): Gerald Poh of LPC Date/Time: 01-10-2018

Estimated Cost: Bill to:

Third Parties:

Claimant:

Surveyor: United Appraisal

Workshop: Team AutoPro

OD/IP Re-inspection / Evaluation

To Inspect Vehicle No: SLE 1994G

at Workshop m/s Team AutoPro

of Blk 8 Kaki Bukit Ave 4 #01-07

Policy No:

Sum Insured:

Make of Veh:

(Client's Record)

Insured: JBV 7798

Tel: 8269 9999 / 6258 1955

Claim No: 18/18/18/VP03/263932

Excess:

D.O.A. 22072018

Michelle

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 6 days)

Date/Time: 10/10/18 Submit Final Fig \$ 6284.08 , 5 days (Red \$ 6330.94 50 %; Original 6 days)

Date/Time	Action/Instruction
	Market value at the time of the accident
	SLE 1994G - X
	JBV 7798 - X
	MV: 865K, LTA: \$49,102.00, NV: \$15,898.00
	Repair days 5
	RECEIVED 11 OCT 2018

TOUIM Jim

2/10/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time File Pass to

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

Catherine Chong (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 1 October, 2018 4:50 PM
To: Catherine Chong (LKK Auto)
Cc: MT_Claim_SG
Subject: FW: Second opinion - SLE 1994 G; DOL : 22/07/2018; 18/18/18/VP02/263932
Attachments: 263932-DOCS1.pdf; 263932-DOCS2.pdf; 263932-DOCS3.pdf; 263932-ADJ RPT.pdf

Sensitivity: Confidential

Part I

Dear Catherine,

Kindly assist our Head Office to obtain the adjusted repair costs and the market value at the time of the accident.

Upon completion of the paper survey, you may forward the report directly to them.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: KO SIEW LING
Sent: Monday, 1 October, 2018 4:35 PM
To: GERALD POH WEE BIN
Subject: Second opinion - SLE 1994 G; DOL : 22/07/2018; 18/18/18/VP02/263932
Sensitivity: Confidential

Lonpac Confidential

Dear Gerald,

Would appreciate if you could help to get a second opinion from your panel adjusters on the reasonability of cost of repairs to the claimant's vehicle vis a vis the circumstances of accident as well as the **market value of the vehicle at the material time of accident**.

Attached please find the following:-

- 1) Claimant's survey report and photos.
- 2) Vehicle registration details.

3) Claimant's policy schedule.

I will split into few emails as the size is too large.

Thanks and regards,
Siew Ling

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/07/2018 11:04
Date Of Accident	22/07/2018 13:05
Exact Location Of Accident	ANAK BUKIT FLYOVER (PIE TUAS NEAR CLEMENTI AVE 6)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE1994G
Insured/Policyholder	
Name Of Registered Owner	MAHMUD BIN MOHD ARIS
NRIC No	S1643938Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83396431
Alternative Phone No	OFFICE-83396431

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00008958

Cover Note Number

Driver

Name of Driver	MAHMUD BIN MOHD ARIS
NRIC No	S1643938Z
Date Of Birth	24/02/1984
Occupation	INDOOR
Date Of Driving Pass	21/09/1988
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83396431
Fax Number	
Contact Number	OFFICE-83396431
Email Address	NOEMAIL

Address	BLK 762 BEDOK RESERVIOR VIEW #06-309
Postcode	470762
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JQV7798 (PRIVATE CAR)
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK POLICE DIVISIONAL HQ (G DIVISION)
Police Station Address	ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2440000 - FAX NO: 64443009
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JQV7798
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAU TIAN YEE
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purpose(s)
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



Amok B. last Flyover
(PLE Tuns Near Chomeng Ave 6)

Vehicle A 56E1444 G

Vehicle B 3GV 7778


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report


T/20180722/2054

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature

Date & Time:


Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No:



**SINGAPORE
POLICE FORCE**



T/20180722/2054

1 of 3

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20180722/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/07/2018 16:44		Vide Report No.: D/20180722/0063		Station Diary No.: 80	
Informant's Particulars					
Name of Informant: MAHMUD BIN MOHD ARIS			Address: APT BLK 762 BEDOK RESERVOIR VIEW #06-309 SINGAPORE 470762		
ID Type / ID No.: NRIC NO / S1643938Z			Contact No.: Home/Office: Mobile: 83396431		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 24/02/1964	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: SALES EXECUTIVE			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 22/07/2018 13:05	Type of Location: Expressway
Location: Along Road 1 PAN ISLAND EXPRESSWAY				
Before exit of Clementi Avenue 6, 26km Mark				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQV7798	Car				Seriously Damaged	0
SLE1994G	Car	HONDA	VEZEL 1.5X CVT	Blue	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLE1994G	FWD Singapore Pte. Ltd	PNPV2018-00008958	12/07/2018	11/07/2019



**SINGAPORE
POLICE FORCE**



T/20180722/2054

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

2 of 3

Report No. T/20180722/2054

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	LAU TIAN YEE	ID No.	890330015801
Related Vehicle	JQV7798 (Car)	Contact No.	85264090
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MAHMUD BIN MOHD ARIS	ID No.	S1643938Z
Related Vehicle	SLE1994G (Car)	Contact No.	83396431
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/7/2018 at about 1300hrs, I was driving my car (SLE1994G) along PIE towards Tuas on lane 4 on a 4 lane road. As I wanted to take the exit towards Clementi Avenue 6, I was driving on lane 4 at about 80km/h. Suddenly, there was a strong collision from the rear. The collision caused my car to spin towards the right and I managed to control and stop, facing the opposite direction of the road, on lane 2. I then got out from my car and saw that a Malaysian car (JQV7798) had collided onto my car. The Malaysian car was also perpendicular to the road and in between lane 2 and 3. I walked over to the said car but the driver came out from the front passenger side. I noticed that his door was stuck due to the damages to the front right from the collision. The right rear bumper of my car was also seriously damaged. When I spoke to the driver, he spoke to me in Malay. He informed that he lost control of his car, skidded and spun, thus colliding onto my car. LTA and police resources arrived at scene. I then handed over the SD card to the Traffic Police officer vide G/20180722/0063, under IO Jamie.



**SINGAPORE
POLICE FORCE**



T/20180722/2054

3 of 3

Police Station Of Origin:
Bedok North N.P.C
30 Bedok North Road SINGAPORE 469676
Tel No: 1800-2449999

Report No. T/20180722/2054

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 2 MUHAMMAD SHAHZELEEMI BIN
MOHAMAD DANEL

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
Staff Sgt MOHAMMAD ZULKARNIAN BIN
SAMSUDIN
Contact No.: 65476429

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

22/07/2018 16:44

Classification Of Case:



**SINGAPORE
POLICE FORCE**



T/20180722/2062

Police Station Of Origin
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No. 1800-6659999

1 of 3

Report No. /20180722/2062

3rd Party

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/07/2018 18:28		Vide Report No. D/20180722/0063	Station Diary No 108
Informant's Particulars			
Name of Informant: LAU TIAN YEE		Address: C/O 261C Sengkang Eastway #11-508 SINGAPORE 543261	
ID Type / ID No. FIN NO / G0569336K		Contact No. Home/Office: Mobile 85264090	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 29	Date of Birth: 30/03/1989	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: CONSTRUCTION WORKER		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident: Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 22/07/2018 13:00	Type of Location: Bend	
Location: Along Road 1 PAN ISLAND EXPRESSWAY along PIE towards Tuas, before Clementi exit				
Weather: Drizzling	Road Surface: Wet	Road Speed Limit		
Traffic Flow: Dual Carriage Way	Traffic Control: Not Controlled	Traffic Volume: Light		
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JQV7798	Car				Seriously Damaged	0
SLE1994G	Car				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180722/2062

2 of 3

Police Station Of Origin:
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No: 1800-6659999

Report No. T/20180722/2062

CONTINUATION OF REPORT

Driver			
Name	LAU TIAN YEE	ID No.	G0569336K
Related Vehicle	JQV7798 (Car)	Contact No.	85264090
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MAHMUD BIN MOHD ARIS	ID No.	S1643938Z
Related Vehicle	SLE1994G (Car)	Contact No.	83396431
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 22/07/2018 at about 1300hrs, I was driving alone along PIE towards Tuas on the first lane when I lose control of my car, JQV7798 (Toyota) when I was negotiating a corner bend as the road surface was wet. My car spin several times and I hit onto another car, SLE1994G (Honda) which was travelling on the 4th lane. My car came to a stop between lane three and two. Both drivers then got out of our cars, uninjured. We then made a check on our vehicles. My vehicle obtained some damages on the front driver door (unable to open), dents on front right bumper, dents on front right mudguard on top of the front right tyre, crack on the front right head light and slight dents on the right rear bumper. The other car have damages to its rear right bumper and dents on the bottom right bonnet. I do not have any in-built camera in my car. I am not sure about the other vehicle.

Traffic Police arrived at the accident location and advised us to lodge a police report. We then moved our vehicle once everything was settled.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Batok N P C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No 1800-6659999



T/20180722/2062

3 of 3

Report No T/20180722/2062

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
J /
Sgt 3 NUR FAIZZAHASHIKIN BINTE SUBTO

Signature Of Informant

Signature Of Interpreter:
Not applicable

Date/Time
22/07/2018 18 28

Officer In Charge Of Case
TP / AEIT /
SSI KASMAWATI BTE SAMIAN
Contact No: 65476179

Classification Of Case

Authentication Stamp
NP188

Singapore Police Force

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3938Z

Vehicle Details

Vehicle No.:	SLE1994G
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Aug 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	L15B4037616
Chassis No.:	RU11117610
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,054.00
Original Registration Date:	12 Jul 2016
First Registration Date:	12 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$10,076.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jul 2026
PARF Rebate Amount:	\$7,557.00

Intended COE Rebate Details

COE Expiry Date:	11 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$41,298.00
Total Rebate Amount:	\$48,855.00

The information contained herein is correct as at 18 Aug 2018

OK



Advanced Search

Home » Used Cars » Avil Motors Pte Ltd » Honda Vezel 1.5A X

Resources

Car Buying

Car Selling


Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



Honda Vezel 1.5A X

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$66,300	
Depreciation	\$7,900 /yr	
	View models with similar depreciation	
Reg Date	23-Jun-2016	
	(7yrs 8mths 18days COE left)	
Manufactured	2015	
Mileage	25,000 km (11k /yr)	
Transmission	Auto	
Engine Cap	1,496 cc	
Road Tax	\$682 /yr	
Power	96.0 kW (128 bhp)	
	View specs of the Honda Vezel (2014)	
Curb Weight	1,190 kg	
Features	1.5L I-VTEC Engine Producing 128bhp, Earth-Dream Technology, Keyless Entry/Start/Auto-Brake Hold, CTBA, Electric Park Brake.	
Accessories	DVD Player, USB, Bluetooth, Reverse Sensors And Camera, 16" Rims With Headlights/LED DRL Fog Lamps, Folding Mirrors, Audio Steering Control.	
Description	We Provide Door Step Viewing, High ARF. Almost Brand New Condition, Whole Car Is Cover With Beautiful Scruff Plate. Extremely Well Maintained. Most Popular Mid Size Family SUV, Super Low Mileage Done! Perfect Car For Driving With Its Low Fuel Consumption! V Kool Solar Film, Spacious With Big Boot Space And Knockdown Rear Seats, High Loan Available.	
COE	\$47,300	
OMV	\$20,481	
ARF	\$10,674	
Dereg Value	\$44,524 as of today (change)	
No. of Owners	2	
Type of Veh	SUV	
Category	PARF Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 04-Oct-2018 | Last Updated on: 04-Oct-2018

Tags: Honda Vezel, honda vezel, 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, vezel, Used Honda



Seller Information

Company	Avil Motors Pte Ltd	
	» dealer's pricelist	
	» 17 vehs sold 21 vehs available	
Address	60 Jalan Lam Huat #03-46	
	Search cars nearby this location	
Location	Carros Centre	
Office No	64756698	
Contact Person(s)	Mr Lim	85896789
	Eric	93848636
	Henry	90675508

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Upfront Payment

» more Financial info

Transfer Fee

\$25

Compare [1]

Down Payment	\$19,890 (change)	Maximum 70% Loan ?
1st Instalment	\$668	?
Total Upfront Payment	\$20,583 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Honda Vezel

[View All](#)


LED Scuff Plate
\$129



Cargo Tray
From \$45



Scuff Plate
From \$85



LED Scuff Plate for
Honda Vezel
\$120



Freepower S Drive
Throttle Control...
\$250



Bidded Carplate
For Sale
\$38,888

Showing 6 out of 255 suitable items for Honda Vezel [View All](#)

Pro-Jex V2D Auto Pte Ltd is a specialist workshop for Honda cars.

Recommended for you

1-6 of 18



20 narrowest car parks
in Singapore



10 facts about
renewing your COE



A tussle of two iconic
family sedans



Turbo Toyota Harrier
meets its matches



BMW specialist WS



Vios returns to BM in
2018

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or station wagons. You can also buy from a car auction and look up car loans, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2018-00008958 (Comprehensive - Classic Plan)

Car plate number: SLE1994G

Your name (As the policyholder): Mahmud Bin Mohd Aris

Coverage start date: 12/07/2018

Coverage end date: 11/07/2019

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

☐ You; and

☐ (b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Hong Leong Finance Limited

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 05/07/2018

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

Our ref. : UAM18.07.19-AK-MTP-TAP-SLE1994G
Date : 31 Jul 2018

Mahmud Bin Mohd Aris

WITHOUT PREJUDICE

Dear Sir,

Re : Third Party Claim For Vehicle Registration No. SLE1994G

We refer to your instruction to appraise the above-mentioned vehicle on 23 July 2018

A static inspection was carried out and our report is enclosed for your perusal. The estimated cost of repair submitted by Messrs. Team AutoPro Pte Ltd for SGD 17,346.70 as per our attached schedule has been inspected thoroughly by us against the actual damages sustained on the above-mentioned vehicle and we recommend the replacement and rectification accordingly.

Our revised quotation for the repair is SGD 12,614.96 which in our opinion, it is fair and reasonable. The repairer has agreed to undertake the repairs to your requirement at our adjusted revision. However, we have not given any instruction and authorisation to the repairer to proceed with the repairs.

Under normal circumstances, the entire repair of the damaged vehicle should be completed within a reasonable period of 6 (Six) days.

We are reverting the matter to you for a decision, and enclosed is our vehicle inspection report, appraisal schedule and invoice for services rendered.

Please do not hesitate to contact us if you have any queries on this matter.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

Encls. :

The information contained in these document may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you received this document by error, please contact us immediately to arrange for its return.

UNITED Appraisal And Management Pte Ltd

Motor Vehicle Appraiser and Insurance Loss Adjuster
No. 8 Kaki Bukit Ave 4 #06-21 Premier @ Kaki Bukit Singapore 415875
Handphone No. : +65 9146 1186 Email : united.appraisal@live.com.sg
Business Registration Nos. : 200817301N

VEHICLE INSPECTION REPORT

To : Mahmud Bin Mohd Aris

Our ref. : UAM18.07.19-AK-MTP-TAP-SLE1994G

Date : 31 Jul 2018

REFERENCE

Assign by	: Mahmud Bin Mohd Aris	Insured	: To be advice
Assign on	: 23 Jul 2018	Policy no.	: To be advice
Inspection on	: 23 Jul 2018	Claim no.	: To be advice
Accident on	: 22 Jul 2018	Sum insured	: To be advice
Workshop name	: Team AutoPro Pte Ltd	Excess	: Not applicable
Inspection at	: 8, Kaki Bukit Ave 4	3rd party Veh.	: To be advice
	#01-07 Premier@Kaki Bukit	3rd party ins.	: To be advice
	Singapore 415875		

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SLE1994G	Odometer	: 27898 Km
Make / Model	: Honda Vezel 1.5X CVT	Chassis no.	: RU11117610
Regn. date	: 12 Jul 2016	Engine no.	: L15B4037616
Body colour	: Blue	Engine cap.	: 1496 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	: In order	Paintwork	: Good
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Good

TYRE CONDITION ON VEHICLE

	Make	Size	Tread depth	Type of road wheel
Front N/S	: Dunlop	215/60R16	80%	Alloy
Front O/S	: Dunlop	215/60R16	80%	Alloy
Rear N/S	: Dunlop	215/60R16	80%	Alloy
Rear O/S	: Dunlop	215/60R16	80%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

* Denotes damaged component/s

POINT OF IMPACT

On the rear in the direction from rear to front.

**SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT**

The impact of the collision has damaged / affected the tailgate, taillamps, rear bumper, rear end panel, spare tyre panel, rear fender and etc...

Please refer to Annex A (Appraisal Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 25 Jul 2018 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Team AutoPro Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 12,614.96 to carry out the repairs. Please refer to Annex A (Appraisal Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would take approximately 6 (Six) working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,

United Appraisal & Management Pte Ltd



Ananda K. Biswas Marc
Motor Vehicle Appraiser

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLE1994G

Our reference : UAM18.07.19-AK-MTP-TAP-SLE1994G

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
<u>LIST ITEMS (1 of 2)</u>					
1	1	Tailgate	Dented	1620.00	^{1100.00} 1620.00 DD✓
2	1	Tailgate outer garnish	Cracked	385.00	385.00 CR✓
3	1set	Tailgate outer garnish clips	Necessary	40.00	^{20.00} 40.00 } NEC✓
4	1	Tailgate logo	Necessary	52.00	^{35.00} 52.00 } NEC✓
5	1	Tailgate emblem " VEZEL "	Necessary	56.20	^{35.00} 56.20 } NEC✓
6	1 2	Tailgate reflector @ SGD 395.00 264.60	O/S Cracked	790.00	^{264.60} 395.00 CR✓
7	1 2set	Tailgate reflector clip @ SGD 18.00	Necessary	36.00	^{18.00} 36.00 NEC✓
8	1	Tailgate inner lock	Jammed	245.00	245.00 NN X
9	1	Tailgate lock sensor	Not Affected	220.00	0.00
10	1	Tailgate trimboard	Cracked	295.00	295.00 CR✓
11	1set	Tailgate trimboard clips	Necessary	45.00	^{30.00} 45.00 NEC✓
12	1	Tailgate weatherstrip	Cut	145.00	145.00 NN X
13	1	Tailgate outer handle switch	Re-Used	180.00	0.00
14	2	Tailgate hydraulic damper @ SGD 210.00	Bend	420.00	420.00 NN X
15	1	Tailgate handle pocket garnish	Deformed	94.00	94.00 CUT✓
16	1set	Rear w/screen inner garnish top clip	Necessary	20.00	20.00
17	2set	Rear w/screen inner garnish side clip @ SGD 15.00	Necessary	30.00	30.00
18	2	Rear w/screen moulding side @ SGD 82.00	Necessary	164.00	164.00 } NEC✓
19	1	Rear w/screen moulding top	Necessary	104.00	104.00
20	1	Rear w/screen moulding bottom	Necessary	104.00	104.00
21	1	Rear bumper	Deformed	1185.00	^{780.00} 1185.00 DD✓
22	1set	Rear bumper clips	Necessary	50.00	50.00 NEC✓
23	2 1	Rear bumper side retainer @ SGD 72.00	O/S Distorted	144.00	72.00 CUT✓
24	2 1	Rear bumper bracket @ SGD 116.00	O/S Distorted	232.00	116.00 CUT✓
25	2 1	Rear bumper reflector @ SGD 167.00	O/S Cracked	334.00	^{56.00} 167.00 CR✓
26	2 1	Rear bumper side garnish @ SGD 210.00	O/S Deformed	420.00	210.00 SCR✓
27	2set	Rear bumper side garnish clip @ SGD 25.00	Necessary	50.00	50.00 NEC✓
28	1	Rear end panel	Dented	715.00	715.00 DD✓
29	1	Rear end panel top garnish	Deformed	184.00	184.00 CUT✓
30	1set	Rear end panel top garnish clips	Necessary	25.00	25.00 NEC✓
31	1	Spare tyre extension panel o/s	Buckled	232.00	232.00 R X
32	1	Spare tyre panel top board	Damaged	420.00	420.00 NN X
33	1	Rear fender o/s	Buckled	980.00	980.00 DD R
34	1	Rear fender arch garnish o/s	Deformed	210.00	210.00 DD✓
35	1set	Rear fender arch garnish clip o/s	Necessary	30.00	30.00 NEC✓
36	1	Rear fender air vent o/s	Deformed	65.00	65.00 NN X
37	1	Rear fender inner garnish o/s	Deformed	315.00	315.00 NN X
38	1set	Rear fender inner garnish clip o/s	Necessary	45.00	45.00 NN X
39	1	Rear fender inner shield o/s	Torn	155.50	155.50 CUT✓
40	1set	Rear fender inner shield clip o/s	Necessary	35.00	35.00 NEC✓
List Item Sub-Total				10871.70	9511.70

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLE1994G

Our reference : UAM18.07.19-AK-MTP-TAP-SLE1994G

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	10871.70	9511.70
<u>LIST ITEMS (2 of 2)</u>					
41	1	Taillamp o/s	Cracked	589.00	^{487.50} 589.00 CRAV
42	1	Taillamp base panel o/s	Serviceable	148.00	0.00
43	1set	Taillamp clips o/s	Necessary	18.00	18.00 NECV
				11626.70	10118.70
Less 0% / 20%				0.00	2023.74
				11626.70	8094.96
<u>SPECIAL NETT ITEMS</u>					
1	1	Sundries	Necessary	50.00	30.00 NNX
2	1	Tailgate windscreen primer & cleaner.	Necessary	80.00	60.00 NNX
3	1	Tailgate windscreen inner seal	Necessary	60.00	40.00 NECV
4	1	Tailgate windscreen sealant	Necessary	80.00	^{40.00} 60.00 NECV
5	2	Tailgate reflector seal @ SGD 50.00	Necessary	100.00	90.00
6	1	Tailgate sealant	Necessary	100.00	80.00
7	2	Taillamp seal @ SGD 60.00	Necessary	120.00	110.00
8	1	Taillamp base panel sealant o/s	Necessary	60.00	40.00
9	1	Rear fender sealant o/s	Necessary	100.00	80.00
10	1	Rear end panel sealant	Necessary	80.00	60.00
11	1	Reverse camera	Shorted	400.00	360.00
12	1	Reverse sensor c/w control module	Shorted	300.00	^{200.00} 280.00 CUT
				1530.00	1290.00
TOTAL				13156.70	9384.96

APPRAISEMENT SCHEDULE

Annex A

Registration no. : SLE1994G

Our reference : UAM18.07.19-AK-MTP-TAP-SLE1994G

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
			Balance C/F	13156.70	9384.96
<u>LABOUR & MISC CHARGES</u>					
1		To dismantle / renew the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts.		1800.00	^{600.00} 1400.00
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.		80.00	^{40.00} 60.00
3		To remove and refit interior upholstery to facilitate the repair.		200.00	180.00 NNX
4		To remove and refit tailgate component to replace tailgate, check and re-adjust the close gap and alignment and water seepage.		100.00	^{50.00} 80.00
5		To remove and refit tailgate windscreen to facilitate the repair.		150.00	^{80.00} 120.00
6		To remove and refit, straighten and readjust exhaust pipe.		180.00	150.00 NNX
7		To measure, drill holes on replaced rear bumper, position and install reverse sensor, check and test on the distance and functions.		80.00	60.00
8		To apply undercoating on the accident repair and replaced panel for rust protection.		200.00	^{60.00} 180.00
9		Supply spray paint material and necessary items to respray tailgate, rear end panel, rear fenders, spare tyre panel and other affected area / panel.		1400.00	^{400.00} 1000.00
TOTAL				4190.00	3230.00
Total Parts and Labour Cost of Repair				17346.70	12614.96
Less (Lumpsum repair adjustment)					0.00
Adjustment Parts and Labour Cost of Repair					12614.96

Repair days 5



Your Ref: 18/18/18/VP02/263932

Date: 19th October 2018

Our Ref: CS1/LPC18017750/Brbs2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLE 1994G INSURED VEHICLE: JQV 7798 ACCIDENT DATE: 22/07/2018**

We thank you for your instruction on 01/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLE 1994G from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicle SLE 1994G.
- c) Colour damaged vehicle photographs of SLE 1994G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLE 1994G
Make & Model	: Honda Vezel 1.5X CVT
Year of Registration	: 2016
Chassis Number	: RU11117610
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1994G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	1,620.00	1,100.00
1	TAILGATE OUTER GARNISH	CRACKED	385.00	385.00
1	SET TAILGATE OUTER GARNISH CLIPS	NECESSARY	40.00	20.00
1	TAILGATE LOGO	NECESSARY	52.00	35.00
1	TAILGATE EMBLEM "VEZEL"	NECESSARY	56.20	35.00
2	TAILGATE REFLECTOR @ \$395.00	O/S CRACKED	790.00	264.60
2	SET TAILGATE REFLECTOR CLIP @ \$18.00	NECESSARY 1SET ONLY	36.00	18.00
1	TAILGATE INNER LOCK	NOT NECESSARY	245.00	-
1	TAILGATE LOCK SENSOR	NOT AFFECTED	220.00	-
1	TAILGATE TRIMBOARD	CRACKED	295.00	295.00
1	SET TAILGATE TRIMBOARD CLIPS	NECESSARY	45.00	30.00
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	145.00	-
1	TAILGATE OUTER HANDLE SWITCH	RE-USED	180.00	-
2	TAILGATE HYDRAULIC DAMPER @ \$210.00	NOT NECESSARY	420.00	-
1	TAILGATE HANDLE POCKET GARNISH	CUT	94.00	94.00
1	SET REAR W/SCREEN INNER GARNISH TOP CLIP	NECESSARY	20.00	20.00
2	SET REAR W/SCREEN INNER GARNISH SIDE CLIP @ \$15.00	NECESSARY	30.00	30.00
2	REAR W/SCREEN MOULDING SIDE @ \$82.00	NECESSARY	164.00	164.00
1	REAR W/SCREEN MOULDING TOP	NECESSARY	104.00	104.00
1	REAR W/SCREEN MOULDING BOTTOM	NECESSARY	104.00	104.00
1	REAR BUMPER	DENTED	1,185.00	780.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER SIDE RETAINER @ \$72.00	O/S CUT	144.00	72.00
2	REAR BUMPER BRACKET @ \$116.00	O/S CUT	232.00	116.00
2	REAR BUMPER REFLECTOR @ \$167.00	O/S CRACKED	334.00	56.00
2	REAR BUMPER SIDE GARNISH @ \$210.00	O/S SCRATCHED	420.00	210.00
2	SET REAR BUMPER SIDE GARNISH CLIP @ \$25.00	NECESSARY	50.00	50.00
1	REAR END PANEL	DENTED	715.00	715.00
1	REAR END PANEL TOP GARNISH	CUT	184.00	184.00
1	SET REAR END PANEL TOP GARNISH CLIPS	NECESSARY	25.00	25.00
1	SPARE TYRE EXTENSION PANEL O/S	TO REPAIR SEE LABOUR	232.00	-
1	SPARE TYRE PANEL TOP BOARD	NOT NECESSARY	420.00	-

Report Ref No. CS1/LPC18017750/Brbs2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	980.00	-
1	REAR FENDER ARCH GARNISH O/S	DENTED	210.00	210.00
1	SET REAR FENDER ARCH GARNISH CLIP O/S	NECESSARY	30.00	30.00
1	REAR FENDER AIR VENT O/S	NOT NECESSARY	65.00	-
1	REAR FENDER INNER GARNISH O/S	NOT NECESSARY	315.00	-
1	SET REAR FENDER INNER GARNISH CLIP O/S	NOT NECESSARY	45.00	-
1	REAR FENDER INNER SHIELD O/S	CUT	155.50	155.50
1	SET REAR FENDER INNER SHIELD CLIP O/S	NECESSARY	35.00	35.00
1	TAILLAMP O/S	CRACKED	589.00	487.50
1	TAILLAMP BASE PANEL O/S	SERVICEABLE	148.00	-
1	SET TAILLAMP CLIPS O/S	NECESSARY	18.00	18.00
	LESS 20% DISCOUNT		-	-1,178.52
			11,626.70	4,714.08
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	TAILGATE WINDSCREEN PRIMER & CLEANER (SN)	NOT NECESSARY	80.00	-
1	TAILGATE WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	40.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
2	TAILGATE REFLECTOR SEAL @ \$50.00 (SN)	NOT NECESSARY	100.00	-
1	TAILGATE SEALANT (SN)	NOT NECESSARY	100.00	-
2	TAILLAMP SEAL @ \$60.00 (SN)	NOT NECESSARY	120.00	-
1	TAILLAMP BASE PANEL SEALANT O/S (SN)	NOT NECESSARY	60.00	-
1	REAR FENDER SEALANT O/S (SN)	NOT NECESSARY	100.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-
1	REVERSE CAMERA (SN)	NOT NECESSARY	400.00	-
1	REVERSE SENSOR C/W CONTROL MODULE (SN)	CUT	300.00	200.00
			1,530.00	280.00
	<u>LABOUR</u>			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF SPARE TYRE EXTENSION PANEL O/S AND REAR FENDER O/S.		1,800.00	600.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		80.00	40.00

Report Ref No. CS1/LPC18017750/Brbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.	NOT NECESSARY	200.00	-
	TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		100.00	50.00
	TO REMOVE AND REFIT TAILGATE WINDSCREEN TO FACILITATE THE REPAIR.		150.00	80.00
	TO REMOVE AND REFIT, STRAIGHTEN AND READJUST EXHAUST PIPE.	NOT NECESSARY	180.00	-
	TO MEASURE, DRILL HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS.		80.00	60.00
	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION.		200.00	60.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY TAILGATE, REAR END PANEL, REAR FENDERS, SPARE TYRE PANEL AND OTHER AFFECTED AREA / PANEL.		1,400.00	400.00
			4,190.00	1,290.00
GRAND TOTAL			17,346.70	6,284.08
RECOMMENDED COST OF REPAIRS				6,284.08

Report Ref No. CS1/LPC18017750/Brbs2

MARKET VALUE: \$65,000.00**LTA: \$49,102.00****NETT VALUE: 15,898.00****LIM TEOW GUAN****Asst. Automotive Assessor****K.K.LAU CPT(RET)****BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE****REGD Auto Consultant-SAE, Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.