

INSURANCE

INS. CASE OWNER:

CC6 /AIG1801 7810 A 16639

LKK:

IDAC:

Surveyor:

Adnan

DOE:

ASSIGNMENT

1/10/18

Date / Time:

1/10/18

Registered in Merimen:

1/10/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLS 7675P

Name of Insured:

KEWERN TJIN JEFFREY

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

1/10/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

BOH SHIAN YU 704 NWA

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

08194904956

Policy No.:

120031708

Make / Model:

MAZDA

Place of Accident:

SUP RN FROM TIA PHY. 1 TO PIE

OI GIA REPORT: YES/ NO

TP GIA REPORT: YES/ NO

Insured Liability:

% Final ? Yes/ No

SLS 7675L



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Chew motor



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

STAGE

DATE/ PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OE:

After call hr to OE:

Documentation Check List: Handler Typist

Notification hr (if non-pickup):

After call hr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/ GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

8/10/18  
vic

08/10/18

09/10/18

19/10/18

1/10/18 - 19/10/18

INTERVIEW TOWN

SPoke TO OI. OUI WILLY WITH. HE  
CONFIRMED ACCIDENT BEHIND 4 OUI  
ROAD. ENJOY TO. INFORMED TP CLAIM.  
WENT TO SETTING 4 AFTER NCD  
ISSUES.

SEND LETTER 4 MAIL TO OI.

MAIL UTILITY CLERK

FINISHED.

TP LOG IN BY RECEIVED 20/10/18

SEND 8/10 OFFER TO TP.

TP ACCEPTED OFFER.

ALL BOOK IN ORDER.

TO CLOSE.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 4,300.00 (5 days) Reduction:

69 %

FINAL SETTLEMENT

Date/Time:

Confirm with:

Confirm by:

Final Liability:

% (Agreed / Assessed) BOLA S/N No.:

24

Repair Cost:

SS 4,300.00

Loss of Rental (LOR):

SS 1 (days)

Loss of Use (LOU):

SS 500.00/560 x 5 (days)

Loss of Income (LOI):

SS 1 (5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/TA Search

SS 7.40

Medical:

SS -

Disbursement:

SS -

Legal Cost:

SS -

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 4,607.43

Global Sum SS:

4,600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Confirm by:

Payee 1:

SS 4,600.00

Name 1:

CHOW MOTOR PTE LTD

Payee 2: (Strike if N.A.)

SS -

Name 2:

-

Payee 3: (Strike if N.A.)

SS -

Name 3:

-

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claims No \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res: Yes or No  
 Lum Sum: 10 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLD7651L Yr Regn: 2016 June  
 Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Vezel c.c. 1496  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp Reading: 11179 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 Cr/No: Ru11117578  
 Gen. Cond: Good Fair / Poor / Burnt  
 Steering: Inorder Jammed / Leaked / Burnt or  
 Brake: Inorder Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim STD A/Rim or  
 Tyre Size: F: 215/60R16  
 R: 215/60R16  
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 06 mm R/Bal: 06 mm  
 L/Bal: 06 mm L/Bal: 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 01/10/18  
 Survey held at: Chew Motor  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TIP ALG.

U/S \$4,300.00  
 CASH: \$9,763.00 (69%)

Date/Time: File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

I \$ + RS \$

Photos

Others

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18017810/Ahb3

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 02-10-2018



Code : AIG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLS 7675P	Veh. Inspected	SLD 7651L
Policy No		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/10/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	01/10/2018	Inspection Date	01/10/2018
Survey held at	CHEW MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company  
 Owner ID: 8614Z

Vehicle Details

Vehicle No.: SLD7651L  
 Vehicle to be Exported: Yes  
 Intended Deregistration Date: 01 Oct 2018  
 Vehicle Make: HONDA  
 Vehicle Model: VEZEL 1.5X CVT  
 Primary Colour: Black  
 Manufacturing Year: 2016  
 Engine No.: L15B4037583  
 Chassis No.: RU11117578  
 Maximum Power Output: 96.0 kW (128 bhp)  
 Open Market Value: \$19,968.00  
 Original Registration Date: 28 Jun 2016  
 First Registration Date: 28 Jun 2016  
 Transfer Count: 0  
 Actual ARF Paid: \$9,968.00

Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 27 Jun 2026  
 PARF Rebate Amount: \$7,476.00

Intended COE Rebate Details

COE Expiry Date: 27 Jun 2026  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): 10  
 QP Paid: \$55,200.00  
 COE Rebate Amount: \$42,718.00  
**Total Rebate Amount: \$50,194.00**

The information contained herein is correct as at 01 Oct 2018

OK

Adnan Lkt - AIG



# CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545 Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

Blk 1 Kaki Bukit Ave 6  
# 01-43  
Singapore 417883

TRAFFIC

VIC

04/10/2018

Accident date: 01/10/2018

Estimated repair cost for vehicle no: SLD7651L HONDA VEZEL 1.5 X A '16

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$953.00 ✓
2	2	Rear Boot Lid Hinge <i>2nd</i>	\$68.10	\$136.20 +
3	2	Rear Boot Lid Shock Absorber <i>2nd</i>	\$180.90	\$361.80 +
4	2	Rear Boot Lid Side Reflector <i>not new</i>	\$284.60	\$569.20 +
5	1	Rear Boot Lid Emblem Logo <i>new</i>		\$45.10 ✓
6	1	Rear Boot Lid Inner Lock <i>not new</i>		\$185.60 +
7	1	Rear Boot Lid Inner Rubber <i>not new</i>		\$135.25 +
8	1	Rear Boot Lid Inner Trim Board <i>included</i>		\$333.75 ✓
9	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$95.00 ✓
10	1	Rear Boot Lid Windscreen Moulding <i>new</i>		\$151.70 ✓
11	1	Rear Boot Lid Camera (Special Nett) <i>2nd</i>		\$680.00 +
12	1	Rear Number Plate (Special Nett) <i>new</i>		\$80.00 +
13	2	Rear Tail Lamp <i>not new</i>	\$460.50	\$921.00 +
14	1	Rear Bumper <i>Reformed</i>		\$863.70 ✓
15	8	Rear Bumper Clip <i>new</i>	\$6.50	\$52.00 -30
16	2	Rear Bumper Side <i>Repair</i>	\$198.70	\$397.40 +
17	2	Rear Bumper Side Retainer <i>new</i>	\$38.00	\$76.00 ✓
18	2	Rear Bumper Side Reflector <i>Reformed</i>	\$148.40	\$296.80 148.40
19	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00 200/20
20	1	Rear End Panel <i>Repair</i>		\$595.60 +
21	1	Rear End Panel Top Garnish <i>Reformed</i>		\$132.30 ✓
22	2	Rear Fender Inner Trim Board <i>Reformed</i>	\$325.25	\$650.50 325.25
23	1	Rear Spare Tyre Panel Under Lower Cover <i>Reformed</i>		\$190.90 +
24	8	Rear Spare Tyre Panel Under Lower Cover Clip <i>new</i>	\$6.50	\$52.00 -30
25	1	Rear Exhaust <i>Best</i>		\$828.00 ✓
26	1	Rear Exhaust Chrome Pipe <i>Best</i>		\$135.00 80/20
27	1	Rear Centre Exhaust <i>not new</i>		\$956.00 X

420310  
336248

Subtotal :-

\$10,253.80

### Labour charges

To remove & refit rear windscreen	\$120.00	1W
Gum	\$50.00	✓
To remove & refit rear video camera & boot lid camera	\$380.00	50
To remove & refit reverse sensor	\$100.00	50
To remove & refit cushion & trim board	\$280.00	60
To remove & refit rear & centre exhaust	\$380.00	80
To check wiring	\$100.00	30
Tuff kote	\$150.00	X
Panel beating	\$1,400.00	70
Spray painting	\$1,400.00	650

Subtotal :- \$3,810.00

Total:- \$14,063.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices --- subject to confirmation
- Third party claim is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 541248

h/s. 43K

050m/s

43K

## Vic (LKKAUTO)

---

**From:** Chew Motor Pte. Ltd. <claims@chewmotor.com>  
**Sent:** Monday, 19 November, 2018 12:41 PM  
**To:** Vic (LKKAUTO)  
**Cc:** Admin A; Chew Motor  
**Subject:** Re: FW: SLD7651L CLAIMING SLS7675P DOA 01.10.18 CPL LKK REF CC6/AIG18017810/Ahb3  
**Attachments:** image001.jpg; SLD7651L DV.pdf

Without Prejudice

Hi Vic

Enclosed signed discharge voucher for your reference.

Hope to receive your payment soon.

**\*\*\*\*Please highlight to AIG, payment under "Chew Motor Pte Ltd" \*\*\***

Regards,

Sukyi Chong



CHEW MOTOR PTE. LTD.

On Mon, Nov 19, 2018 at 12:12 PM Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)> wrote:

Without Prejudice

Dear Sukyi,

We refer to your below email.

On a without prejudice basis and purely for an amicable settlement and without admission of any liability to our Insured's part, we offer a global sum of **\$4,600.00** (all in) to settle your client's claim.

If agreeable, kindly chop and sign the attached DV and forward back a copy to us for payment processing.

The above amount is to be made payable to **CHEW MOTOR PTE LTD.**

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

**From:** Chew Motor Pte. Ltd. [<mailto:claims@chewmotor.com>]  
**Sent:** Monday, 19 November, 2018 11:34 AM  
**To:** Shu Pei (LKKAuto)  
**Cc:** Admin A; Chew Motor; Vic (LKKAuto)  
**Subject:** Re: FW: SLD7651L CLAIMING SLS7675P DOA 01.10.18 CPL

Without Prejudice

Hi Vic

Please advice your offer and revert for close case,thanks.

Regards,

Sukyi Chong



CHEW MOTOR PTE. LTD.

On Wed, Nov 7, 2018 at 5:45 PM Shu Pei (LKKAuto) <[shupeil@lkkauto.com](mailto:shupeil@lkkauto.com)> wrote:

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC6/AIG18017810/Ahb3	Vic

*To check availability of the case handler, you may contact the undersigned.*

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Chew Motor Pte. Ltd. <[claims@chewmotor.com](mailto:claims@chewmotor.com)>

**Sent:** Wednesday, 7 November 2018 12:58 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Chew Motor <[admin@chewmotor.com](mailto:admin@chewmotor.com)>

**Subject:** SLD7651L CLAIMING SLS7675P DOA 01.10.18 CPL

\*Without Prejudice\*

Dear Motor Claims Department,

Enclosed LOD and supporting documents for your reference.

Please kindly advise officer in charge and hope to receive offer soon.

Thank you.

Regards,

Chloe



CHEW MOTOR PTE. LTD.

Our Reference : CM1811-0122 / SLD7651L  
Your Reference : SLS7675P

07<sup>th</sup> November 2018

**AIG Asia Pacific Insurance Pte. Ltd**  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120



**CHEW MOTOR PTE. LTD**

WITHOUT PREJUDICE

Dear Sir/Madam

**ACCIDENT INVOLVING SLD7651L & SLS7675P ON 01.10.2018 ALONG TOA PAYOH LOR 6 SLIP ROAD TO PIE(CHANGI) AT 16:03HRS**

We are instructed by **AUTO FLEETLEASE PTE LTD** to claim damages and losses against you in connection with the above-captioned road traffic accident which our client's vehicle **SLD7651L** damaged by vehicle **SLS7675P** driven by your insured at the material time.

We are informed that the said accident was caused by your insured's negligence. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows: -

➤ Repair Costs	\$ 4,300.00
➤ Loss of Use for 05 days (Rental Vehicle)	\$ 600.00
➤ LTA Fees	\$ 7.45
➤ Total	<u>\$ 4,907.45</u>

A copy of each supporting documents are enclosed for your perusal.

- GIA Report
- Invoice
- LTA Search Receipt

Please let us have your cheque for the sum of **\$4,907.45** made payable to us, **CHEW MOTOR PTE. LTD.**, within the next 14 days.

Yours Sincerely,



**CHEW MOTOR PTE. LTD.**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

09 OCTOBER 2018

KEE WERN TJIN JEFFREY  
16 HILLCREST ROAD  
SINGAPORE 288901

By Post & By Email

Dear Sir/Madam,

OUR REF : CC6/AIG18017810/Ahb3

YOUR REF : SLS 7675P

ACCIDENT INVOLVING SLS 7675P AND SLD 7651L ALONG SLIP ROAD FROM TOA  
PAYOH TO PIE (CHANGI) ON 01.10.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLD 7651L against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLD 7651L. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

  
Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

[Jeffkee91@gmail.com](mailto:Jeffkee91@gmail.com)  
(Email)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 9 October, 2018 1:14 PM  
**To:** Jeffkee91@gmail.com  
**Cc:** Admin A; Vic (LKKAUTO)  
**Subject:** YOUR REF: SLS 7675P\_ACCIDENT INVOLVING SLS 7675P AND SLD 7651L ALONG SLIP ROAD FROM TOA PAYOH TO PIE (CHANGI) ON 01.10.2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

09 OCTOBER 2018

**KEE WERN TJIN JEFFREY**  
**16 HILLCREST ROAD**  
**SINGAPORE 288901**

**By Post & By Email**

Dear Sir/Madam,

**OUR REF : CC6/AIG18017810/Ahb3**

**YOUR REF : SLS 7675P**

**ACCIDENT INVOLVING SLS 7675P AND SLD 7651L ALONG SLIP ROAD FROM TOA PAYOH TO PIE (CHANGI) ON 01.10.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of SLD 7651L against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle SLD 7651L. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD – if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 10 days from the date of this letter **if not provided at AIG's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK  
Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

# LETTER OF AUTHORISATION

**Chew Motor Pte Ltd**

Kaki Bukit Avenue 6

Blk 1 #01-11

Singapore 417883

Dear Sir,

**Accident on**

01/10/2018, 16:03

**Involving Vehicles**

SLO7651L, SLS7675P

**Along**

Tan Pagarh Lor 6 SLP Rd to PIE (Changi)

I/We, the registered owner/driver of vehicle registration no: \_\_\_\_\_  
have involved in the above accident.

SLO7651L

I/We hereby authorize **Chew Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, \_\_\_\_\_, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,





Owner's Signature

(Company's stamp if applicable)

Name: \_\_\_\_\_

NRIC No.: \_\_\_\_\_

Date: \_\_\_\_\_

**Assignment**

To: Chew Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SLD76SIL and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 01 day of 10 2018.

Signature	:	<u>[Signature]</u>
Name	:	<u>Lo Jiarui, Benjamin</u>
ID No.	:	<u>S8531945J</u>
Address	:	<u></u>
Witness Signature	:	<u>[Signature]</u>
Witness Name	:	<u>Chew Yue Yin</u>
Witness ID	:	<u>S8826618H</u>
Witness Address	:	<u></u>



**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **CHEW MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$ 4,600.00** (Global Sum – all in) for vehicle no. **SLD 7651L** that was damaged pursuant to the accident which occurred on **01/10/2018** (date) along **SLIP ROAD FROM LOR 6 TOA PAYOH TO PIE** (location) involving vehicle no/s **SLS 7675P**. This is pursuant to the inspection conducted on **01/10/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **AUTO FLEETLEASE PTE LTD** ("the third party claimant") of vehicle no. **SLD 7651L** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLD 7651L** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19 (day) of 11 (month) **2018** (year)

  
LKK

Signed by appointed surveyor

  
CHEW MOTOR PTE LTD

*sukyi chong*

Signed by "the workshop" (with chop)



## CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Bldg A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545 Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

# TAX INVOICE

**AIG ASIA Pacific Insurance Pte Ltd**  
78 Shenton Way,  
AIG Building, #09-16  
Singapore 079120

Invoice No : CPI1811-0122  
Date : 07-Nov-18

Date of Accident : 01-Oct-18  
Vehicle No. : SLD 7651L  
Model Type : Honda Vezel

Client: AUTO FLEETLEASE PTE LTD

Descriptions		Amount
Lump Sum Repair Cost		4,300.00
Total		4,300.00

(SGD) Dollars: FOUR THOUSAND AND THREE HUNDRED ONLY





Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 01 Oct 2018 / 16:34:18

Receipt Date/Time : 01 Oct 2018 / 16:34:18

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-181001-001905

Previous Receipt No. :

**S/N Item Description/  
Business Transaction Reference  
No.**

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - SLS7675P

As at 01 Oct 2018/16:03:00

Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.

1 Insurance Enquiry - SLS7675P  
Enquiry Fee  
20181001163330011643

7.00	0.49	7.49
------	------	------

<b>Sub-Total</b>	7.00	0.49	7.49
------------------	------	------	------

<b>Total Before Rounding</b>	7.00	0.49	7.49
------------------------------	------	------	------

<b>Rounding Difference</b>			0.04
----------------------------	--	--	------

<b>Total Amount Payable</b>			7.45
-----------------------------	--	--	------

Paid By

20181001163340551	Direct Debit: eNETS Debit (Internet Banking)	7.45
-------------------	---	------

<b>Total</b>		7.45
--------------	--	------

<b>Cash Change</b>		0.00
--------------------	--	------

<b>Tendered Amount</b>		7.45
------------------------	--	------

<b>Excess Refundable Amount</b>		0.00
---------------------------------	--	------

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

#### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018 <a href="#">Edit Reg</a>		01 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>KEE WERN TJIN JEFFREY</b> , ID: S9132208J									
Main Claimant: <b>AUTO FLEETLEASE PTE LTD</b> , Co. Reg. No.: 201608614Z									
Vehicle Reg. No.:	<b>SLD7651L</b>	Date of Loss:	01/10/2018 16:00 - :59 [27 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 0809590497SG</b>	Policy/Cover Note No.:	1700070208 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SL57675P</b>	Policy No. (Claimant):	999994676						
		Excess:							
Repairer: <b>Chew Motor Pte Ltd (HQ)</b> BLOCK 1 KAKI BUKIT AVE 6, #01-43, 417883 Kaki Bukit - Tel: 67479241									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com									
Claimant's Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 11/10/2018]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLD7651L (0809590497SG)  
[SLS7675P]  
TP  
AUTO FLEETLEASE PTE LTD  
Oct 1 2018 4:00PM  
[KEE WERN TJIN JEFFREY]  
Chew Motor Pte Ltd











































Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <span style="float: right;">View in Browser</span>	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	---	--

Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown							Edit		

Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
2	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
3	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
4	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
5	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
6	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
7	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
8	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
9	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
10	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
11	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
12	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
13	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
14	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
15	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
16	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
17	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
18	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
19	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
20	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
21	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
22	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
23	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
24	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
25	30/10/18 10:03	General View							Load JPG <input checked="" type="checkbox"/>		
26	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
27	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
28	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
29	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
30	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
31	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
32	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
33	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		
34	30/10/18 10:03	Reinspection Photo							Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/10/18 10:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/10/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/18 14:42	TP GIA REPORT	 Load PDF	
2	09/10/18 13:17	EMAIL TO OI	 Load PDF	
3	09/10/18 13:17	LETTER TO OI	 Load PDF	
4	30/10/18 11:42	TP ESTIMATE - MARKED	 Load PDF	
5	26/11/18 10:16	WORKSHOP INVOICE	 Load PDF	
6	26/11/18 10:16	AUTHORISATION TO ACT FORM	 Load PDF	
7	26/11/18 10:16	Release Voucher	 Load PDF	
8	26/11/18 10:16	LTA SEARCH	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/10/18 13:27	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SLS7675P (Insd veh)	Model:	HONDA VEZEL 1.5 (A)
	SLD7651L (TP veh)		
Date of Accident:	01/10/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	14,613.80
Final Repair Cost	:	\$	4,600.00
Loss of Use	:	\$	5.00 days at \$60.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	4,600.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability ____ 100 ____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Chew Motor Pte Ltd	: \$	4,600.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

26 Nov

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18017810/AHB3Q2

Date: 26/11/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070208  
**Claimant Vehicle No :** SLD7651L **Insured Vehicle No :** SLS7675P  
**Date of Loss:** 01/10/2018 **Nature of Claim:** TP **Claim No:** 0809590497SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD7651L**  
 Make & Model: HONDA VEZEL, 1.5 (A) Engine No: L15B4037583  
 Reg. Date: 28/06/2016 (Man. Year: 2016) Chassis No: RU11117578  
 Colour: Black Odometer: 111179 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,253.80	3,642.48	6,611.32	64.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,770.00	2,590.00	59.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,613.80</b>	<b>5,412.48</b>	<b>9,201.32</b>	<b>62.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,613.80</b>	<b>4,300.00</b>	<b>10,313.80</b>	<b>70.58</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>4,607.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>4,600.00</b>		

### INSPECTION

Date of Assignment: 01/10/2018  
 Date Inspected: 01/10/2018 Inspected At: Chew Motor Pte Ltd (HQ)  
 BLOCK 1 KAKI BUKIT AVE 6, #01-43  
 Singapore 417883  
 Estimated Period of Repair: 5.0 days

---

**Adjuster:** ADRIAN LING**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOT LID	Dented	953.00 F	*953.00 FL
2	2	*REAR BOOT LID HINGE	Not Necessary	136.20 F	*- FL
3	2	*REAR BOOT LID SHOCK ABSORBER	Not Necessary	361.80 F	*- FL
4	2	*REAR BOOT LID SIDE REFLECTOR	Not Necessary	569.20 F	*- FL
5	1	*REAR BOOT LID EMBLEM LOGO	Necessary	45.10 F	*45.10 FL
6	1	*REAR BOOT LID INNER LOCK	Not Necessary	185.60 F	*- FL
7	1	*REAR BOOT LID INNER RUBBER	Not Necessary	135.25 F	*- FL
8	1	*REAR BOOT LID INNER TRIM BOARD	Cracked	333.75 F	*333.75 FL
9	1	*REAR BOOT LID WINDSCREEN SEAL	Necessary	95.00 F	*95.00 FL
10	1	*REAR BOOT LID WINDSCREEN MOULDING	Necessary	151.70 F	*151.70 FL
11	1	*REAR BOOT LID CAMERA	Not Necessary	680.00 FS	*- FS
12	1	*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
13	2	*REAR TAIL LAMP	Not Necessary	921.00 F	*- FL
14	1	*REAR BUMPER	Deformed	863.70 F	*863.70 FL
15	8	*REAR BUMPER CLIP	Necessary	52.00 F	*30.00 FL
16	2	*REAR BUMPER SIDE	Repair	397.40 F	*- FL
17	2	*REAR BUMPER SIDE RETAINER	Necessary	76.00 F	*76.00 FL
18	1	*REAR BUMPER SIDE REFLECTOR	O/S Cracked	296.80 F	*148.40 FL
19	1	*REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
20	1	*REAR END PANEL	Repair	595.60 F	*- FL
21	1	*REAR END PANEL TOP GARNISH	Deformed	132.30 F	*132.30 FL
22	1	*REAR FENDER INNER TRIM BOARD	O/S Cracked	650.50 F	*325.25 FL
23	1	*REAR SPARE TYRE PANEL UNDER LOWER COVER	Deformed	190.90 F	*190.90 FL
24	8	*REAR SPARE TYRE PANEL UNDER LOWER COVER CLIP	Necessary	52.00 F	*30.00 FL
25	1	*REAR EXHAUST	Bent	828.00 F	*828.00 FL
26	1	*REAR EXHAUST CHROME PIPE	Bent	135.00 FS	*80.00 FS
27	1	*REAR CENTRE EXHAUST	Not Necessary	956.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,253.80</b>	<b>4,483.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>840.62</b>
<b>Total Parts (\$\$)</b>	<b>10,253.80</b>	<b>3,642.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	100.00
2	GUM	New	50.00	50.00
3	TO REMOVE & REFIT REAR VIDEO CAMERA & BOOT LID CAMERA	New	380.00	50.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE & REFIT CUSHION & TRIM BOARD	New	280.00	60.00
6	TO REMOVE & REFIT REAR & CENTRE EXHAUST	New	380.00	80.00
7	TO CHECK WIRING	New	100.00	30.00
8	TUFF KOTE	New	150.00	0.00
9	PANEL BEATING	New	1,400.00	700.00
10	SPRAY PAINTING	New	1,400.00	650.00
<b>Gross Labour Cost (S\$)</b>			<b>4,360.00</b>	<b>1,770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >