

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 184/IC/TCAC/CCR/2018
DATE : 01-OCT-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR NG BOON MENG
ADDRESS : 59 PASIR RIS DRIVE 1
#17-17
S(519532)
TELEPHONE NO : 98421009

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100488302-01
VEHICLE NO : SDY207S
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20908593B
CHASSIS NO : JN1JANT32Z0002665
MILEAGE : 54722 KM
DATE IN : 01/10/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 30/09/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDY207S

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
2 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
3 ZZ/001	REPLACE FRONT LEFT DOOR, TAPES, MOULDINGS ETC REPAIR PANELS	500.00	
4 ZZ/002	TRANSFER FRONT LEFT DOOR COMPONENTS TO FACILITATE REPAIR	12.00	
5 ZZ/003	RESPRAY FRONT LEFT DOOR	200.00	
6 ZZ/004	QC, RETUNE & CONSULT CHECK		
7 ZZ/005	COMPLIMENTARY WASH & VACUUM		
	TOTAL LABOUR CHARGES	932.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDY207S

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	CENTRE MOULDING	80821-4CLOA	157.00			
2	TOP MOULDING	80283-4CA0A	100.70			
3	B-PILLAR TAPE	80819-4CA0B	18.00			
4	FRONT LEFT DOOR	H010A-4CBMA	1032.90			
SUB TOTAL			1308.60	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			261.72	0.00	0.00	
GRAND TOTAL			1046.88	0.00	0.00	
OVERALL TOTAL			1046.88			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDY207S

TOTAL LABOUR CHARGES	932.00
TOTAL SPARE PARTS CHARGES	1046.88

GRAND TOTAL	1978.88 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.