

Narrative:

Rahul

DOI:

ASSIGNMENT

3-10-18

Date / Time:

3-10-18

Registered in Meriment:

Pre-assign / CCU / FTE

SGK 1666 G



Insured Vehicle No.

Name of Insured

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

29/9/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLG 3168B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Anz Interp



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Confirm by: MCB

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

46 S\$4,350.00

( 5 days) Reduction:

67 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 20-04-19

Confirm with:

Email ☐ Call ☐

Final Liability:

% 00

(Agreed / Assessed) BOLA S/N No.:

27

IF NO or B 28, Ass. Lia:

Repair Cost:

S\$ 4,350.00

01 Repair Breakdown Form

Loss of Rental (LOR):

S\$ 500.00

( 5 days) x 100

Loss of Use (LOU):

S\$ -

(3 x days)

Loss of Income (LOI):

S\$ -

(3 x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 4,857.45

Global Sum S\$:

FINAL PAYMENT

Date/Time: 20-04-19

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 4,857.45

Name 1:

ASA MOTORSPORTS SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC. BY:

REF

CS3/LPC/8017848/

d3

Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person):

Ong Li Li

of

LPC

Date/Time:

2/10/18 @ 4:21pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 3168 B

Insured:

SGK 1666G

at Workshop m/s

Asia Motorsports

Tel:

67453811

of

15 kaki Bkt Rd 4 # 01-05/53

Policy No:

Claim No:

18/18/18 / VP05 / 020474

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/09/18

CA / REV / REP. / REV 24 HRS

(up)

03/10/18

H.O.D. Endorsement:

Date/Time:

5:29pm @ 2/10/18

Person Contacted:

Mr. Loo

Vehicle

IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLG 3168B - X

SGK 1666G - X



PHN = Edison 400  
Fax = 67465110

From: Simon

# Estimate Repair For Vehicle SLG 3168 B ( VOLKSWAGEN JETTA 1.4 TSI )

Item	Description Parts	Qty	Price list
1	Rear bumper	1	\$1,213.50 4,557.50 DD
2	Rear bumper side retainer L/R @ \$201.70	2	\$ 403.40 RH-DLS, LH-NN
3	Rear bumper side bracket L/R @ \$189.50	2	\$ 379.00 X NN
4	Rear bumper top bracket	1	\$ 315.00 X NN
5	Rear bumper reinforcement	1	\$ 712.60 X NN
6	Rear bumper under dust cover RH	1	\$ 198.00 X NN
7	Rear end panel	1	\$ 789.00 X R
8	Rear end panel garnish	1	\$ 289.90 CRA
9	Rear tail lamp L/R @ \$521.80	2	\$ 1,043.60 RH-CRA, LH-NN
10	Rear boot lid	1	\$ 1,685.00 BIC
11	Rear boot lid lock	1	\$ 288.00 BT
12	Rear boot lid lamp L/R @ \$340.80	2	\$ 681.60 X NN
13	Rear boot lid weather-strip	1	\$ 189.00 TN
14	Rear boot lid inner trim cover	1	\$ 387.40 CRA
15	Rear fender inner trim cover RH	1	\$ 597.00 X NN
LKK Auto Consultants hence notify the Repairer of the following:			
• To resurvey before/after spray painting			
• To display damaged part(s) during resurvey			
• Parts prices are subject to confirmation			
• Third party survey is on a "Without Prejudice" basis			
• No illegal modification(s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
Acknowledged by Repairer			
Signature:			\$ 9,516.00
Date:			\$ 951.60
Less 10%			\$ 8,564.40

## S/NETT ITEM

16	Rear bumper reflector lamp L/R @ \$114.60	2	\$ 229.20 RH-CRA, LH-NN
17	Rear bumper clips	1	\$ 60.00 NEC
18	Rear boot lid latch lock badge	1	\$ 89.20
19	Rear boot lid 'JETTA' emblem	1	\$ 89.20 } NEC
20	Rear boot lid 'TSI' emblem	1	\$ 49.80
21	Rear bumper reverse sensor @ \$200.00	2	\$ 400.00 short
22	Rear bumper lower diffuser	1	\$ 689.00 X NN
23	Rear number plate with casing	1 set	\$ 50.00 X NN
Parts Total :			\$ 10,220.80

## LABOUR CHARGES & MISC

24	Check wiring, lighting, & centre locking system	\$ 50.00 30
25	Lobour charges.	\$ 1,100.00 600
26	Spray painting	\$ 1,100.00 600
27	To diagnostic checks & reset.	\$ 280.00 120
28	Anti-rust proofing on affected panel & re-seal body panel joint.	\$ 150.00 50
29	To transfer boot lid mechanism & components.	\$ 80.00 60
30	To straighten & realign rear exhaust system	\$ 120.00 X
31	To reinstall rear bumper reverse sensor.	\$ 150.00 60
Labour Total :		\$ 3,030.00

LS \$4,350

WVWZZZ 16Z

Sub Total : \$ 13,250.80

Lump Sum Repair Adjustment

\$10,600

Estimated Time required for Repairs

8 days

5 days

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Tuesday, 2 October 2018 4:21 PM  
**To:** Asia Motorsports Solution Pte Ltd; assignments@lkkauto.com; 'Nivitha (LKK Auto)'  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 18/18/18/VP05/020974 RE: ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

Thank you for confirming the appointment of a Single Joint Expert - MOHAMMED RASUL.

Dear Nivitha/Catherine

Please assign MOHAMMED RASUL to conduct TP survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

---

**From:** Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]  
**Sent:** Tuesday, 2 October, 2018 4:11 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** Re: ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT

**Your Ref:**  
**Our Ref:** SLG 3168 B

2 October 2018

Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

**PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any Personal Injury  
Claims)**

Attn: Claims Department

Dear Sir/Mdm,

**ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT**

Thank you so much for your reply dated 2 October 2018. We are pleased to inform you that we are agreeable to your selection of **MOHAMMED RASUL** as the Single Joint Expert.

**ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT**

Thank you so much for your reply dated 2 October 2018. We are pleased to inform you that we are agreeable to your selection of **MOHAMMED RASUL** as the Single Joint Expert.

In compliance with the New State Courts Practice Directions, we shall await your kind office to instruct **MOHAMMED RASUL** (as the Single Joint Expert) to attend to the pre-repair survey of our client's damaged vehicle at our premise at **15 Kaki Bukit Road 4 #01-05/53 Bartley Biz Centre Singapore 417808**.

We seek your assistance in arranging for the pre-repair survey by **4 October 2018 (Thursday), 4.30 pm** so that we can commence repair on our client's damaged vehicle as soon as possible and expedite the return of the vehicle to our client.

Thank you and we hope to hear from you soonest.

Regards,  
Asia Motorsports Solution Pte Ltd  
6745 3811  
6746 5110 (fax)  
[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)

---

**From:** ONG LI LI <[llong@lonpac.com](mailto:llong@lonpac.com)>  
**Sent:** Tuesday, October 2, 2018 3:39 PM  
**To:** [asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)  
**Cc:** MT\_Claim\_SG  
**Subject:** Your Ref: SLG3168B Our Ref : To Be Advised Accident Inv SGK1666G & SLG3168B on 29/9/18

Without Prejudice  
Save as to Costs

Dear Sir/Mdm

We refer to your fax of 1 October 2018

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	



## ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: [www.asiamotorsports.com.sg](http://www.asiamotorsports.com.sg)

F & J LIMOUSINE SERVICES  
53362165L

INVOICE NO: 2017/C097

DATE: 22/11/2018

VEHICLE NO: SLG 3168 B

ENGINE CAPACITY : 1390 CC

ENGINE NO : CAV441594

MAKE : VOLKSWAGEN CHASSIS NO : WVWZZZ16ZDM010949

MODEL : JETTA 1.4 TSI AT YEAR : 2012  
1623Q5

---

DESCRIPTION	AMOUNT
-------------	--------

---

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$4,350.00

**Total amount payable**

**S\$4,350.00**



---

Asia Motorsports Solution Pte Ltd



## ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

Your Ref: 18/18/18/VP05/020974

Our Ref: SLG 3168 B

3<sup>RD</sup> June 2019

Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any **Personal Injury**  
Claims)

Attn: Motor Claims Department

### ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018

We refer to the above matter.

We enclose and return herewith your Discharge Voucher duly signed and completed by our client for your attention.

Please let us have your cheque for the settlement sum of \$4,857.49 issued in our favor in due course.

In the meantime, please note that **with effect from 1<sup>st</sup> June 2019**, we have shifted to and are now operating from the following address:

**37A Everitt Road  
Singapore 428586**

Please update your records accordingly and send all future correspondence to the new address above.


Yours faithfully,



Asia Motorsports Solution Pte Ltd  
37A Everitt Road Singapore 428586

6745 3811  
6746 5110 (fax)  
[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)

Dated the 1<sup>ST</sup> day of October 2018

  
Owner (Signature) **HP: 8128 4284**

**F&J LIMOUSINE SERVICES**  
Owner (Name)

**53362165L**  
NRIC NO.

Address: **661C Edgedale Plains**

  
Witness (signature)

**LOO CHENG CHUAN**  
Witness (Name)

**S1169633C**  
NRIC NO.

Address: **37A Everitt Road Singapore 428586**





# LONPAC INSURANCE BHD

CLAIM NO : 18/18/18/VP05/020974  
DATE : 20 APRIL 2019

WITHOUT PREJUDICE  
TO: ANY PERSONAL INJURY CLAIMS

## DISCHARGE VOUCHER

I/We, F & J LIMOUSINE SERVICES confirmed acceptance from M/s LONPAC INSURANCE BHD and/or the owner SGK 1666G the sum of Singapore Dollars FOUR THOUSAND EIGHT HUNDRED FIFTY SEVEN AND CENTS FORTY NINE ONLY. (\$4,857.49) in full and final satisfaction, liquidation and discharge of all property losses competent to me/us upon the said M/s LONPAC INSURANCE BHD in respect of all property losses sustained by me/us whether now or hereafter to become manifest, arising either directly or indirectly from an accident involving, SLG 3168B on 29/09/2018 along/at PUNGGOL ROAD.

I /We hereby agree to indemnify and keep indemnify (ONG BENG HUI /LONPAC INSURANCE BHD) against all claims and any claims whatsoever made by any person/persons on our behalf in respect of the said accident.

I/We further authorize you to pay the above settlement sum directly to M/s ASIA MOTORSPORTS SOLUTION PTE LTD.

I/We hereby acknowledge that this payment is made on a without admission of liability basis and without prejudice to all related claims and in respect of our insured's recovery action.

  
F & J Limousine Services  
HP: 8128 4284

8/5/19  
.....  
Signature of vehicle owner/Date

F&J Limousine Services 8/5/19  
.....  
Name of vehicle owner/Date



## ASIA MOTORSPORTS SOLUTION PTE LTD

Specialise in sales of new & reconditioned bikes

Co. Reg. No: 200507766N

No. 568, Geylang Road Singapore 389514 Tel: +65 6745 3811 Fax: +65 6746 5110 Website: [www.asiamotorsports.com.sg](http://www.asiamotorsports.com.sg)

F & J LIMOUSINE SERVICES  
53362165L

INVOICE NO: 2017/C097

DATE: 22/11/2018

VEHICLE NO: SLG 3168 B

ENGINE CAPACITY : 1390 CC

ENGINE NO : CAV441594

MAKE : VOLKSWAGEN CHASSIS NO : WVVZZZ16ZDM010949

MODEL : JETTA 1.4 TSI AT YEAR : 2012  
1623Q5

---

DESCRIPTION	AMOUNT
-------------	--------

---

Total lump sum repair including supply of parts and labour

Adjusted total lump sum repair costs

S\$4,350.00

**Total amount payable**

**S\$4,350.00**



Asia Motorsports Solution Pte Ltd

# **ZOOM CAR LEASING**

**Zoom Car Leasing**  
Registration No.: 5339410M  
e-mail : zoomcarleasing@gmail.com

## **RENTAL INVOICE**

**1st Auto Pte Ltd**  
Blk 15 Kaki Bukit Road 4  
Bartley Biz Centre  
#01-05 Singapore 417808

Invoice No. : **INV0000266**  
Date : 10/10/2018  
Ref : SLE 2179 L  
Your Ref :  
Terms : COD

#	Rental Period	Rate	Quantity	Amount
1	Rental Charges for SLE 2179 L (01/10/2018 to 06/10/2018)	\$250.00	5 Days	\$1,250.00

**C/O Fendy Ang Jun Kai**  
Blk 661C Edgedale Plains  
#11-634 Singapore 823661  
Contact: 8128 4264

---

<b>Total</b>	<b>:</b>	<b>\$1,250.00</b>
--------------	----------	-------------------

---

\_\_\_\_\_  
(Customer's Signature/Stamp)



\_\_\_\_\_  
(For Zoom Car Leasing)



> Back to OneMotoring



Land Transport Authority  
10 Sin Ming Drive  
Singapore 575701  
GST Registration No. : MM-0006529-2

Print Date/Time : 01 Oct 2018 / 12:08:38

Receipt Date/Time : 01 Oct 2018 / 12:08:38

### Tax Invoice/Receipt

Receipt No. : ITNET-00000-181001-001039

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SGK1666G As at 29 Sep 2018/23:30:00 Insurance Co: LONPAC INSURANCE BHD				
1	Insurance Enquiry - SGK1666G Enquiry Fee 20181001120750260800	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20181001120758931	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## Asher Sng (LKKAuto)

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Wednesday, 27 March 2019 9:30 AM  
**To:** Asher Sng (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: [MANDATE REQUEST] Our Ref: 18/18/18/VP05/020974 ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT [External General]


**Follow Up Flag:** Follow up  
**Flag Status:** Completed

### Lonpac External - General

Dear Asher

Please proceed.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]  
**Sent:** Monday, 25 March, 2019 4:36 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** [MANDATE REQUEST] RE: Our Ref: 18/18/18/VP05/020974 ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT [External General]

Dear Sirs,

We refer to the above matter.

We have highlighted to your good office on 09/10/2018 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **ASIA MOTORSPORTS SOLUTION PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 13,250.80	\$ 4,350.00

2. Loss of Rental (5days x \$250)	\$ 1,250.00	\$ 500.00 (5days x \$100)
3. LTA/GIA Search Fee	\$ 7.45	\$ 7.45
<b>Total</b>	<b>\$ 14,508.25</b>	<b>\$ 4,857.49</b>

\*\*5 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

**The above is for your approval please.**

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <[long@lonpac.com](mailto:long@lonpac.com)>

Sent: Tuesday, 19 February 2019 10:24 AM

To: Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Robert-ABLim ([robert@ablim.com.sg](mailto:robert@ablim.com.sg)) <[robert@ablim.com.sg](mailto:robert@ablim.com.sg)>

Cc: MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

Subject: RE: Our Ref: 18/18/18/VP05/020974 ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT [External General]

## Lonpac External - General

Dear Asher

Please proceed to settle the claim at lowest possible sum.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

From: ONG LI LI

Sent: Monday, 28 January, 2019 4:45 PM

To: 'Asher Sng (LKKAuto)'

Cc: MT\_Claim\_SG

Subject: RE: Our Ref: 18/18/18/VP05/020974 RE: ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT


Dear Asher

Fyi, according to the agent, he has returned call but no one answer.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



**From:** Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]

**Sent:** Tuesday, 22 January, 2019 10:32 AM

**To:** ONG LI LI

**Cc:** MT\_Claim\_SG

**Subject:** RE: Our Ref: 18/18/18/VP05/020974 RE: ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT

Hi LiLi,

We refer to the email below.

We have try calling a few times however there was no one answer the call non return call.

Please advise.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)





## Asher Sng (LKKAUTO)

**From:** Asia Motorsports Solution Pte Ltd <asiamotorsports@hotmail.com>  
**Sent:** Monday, 14 January 2019 11:47 AM  
**To:** Asher Sng (LKKAUTO)  
**Subject:** Re: ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - CALL FOR DIRECT SETTLEMENT  
**Attachments:** SLG3168B\_estimate\_finalization.pdf; SLG3168B\_invoice.pdf; SLG3168B\_report.pdf; SLG3168B\_rental\_invoice.pdf; SGK1666G\_ins\_search.pdf  
**Follow Up Flag:** Flag for follow up  
**Flag Status:** Completed

**Your Ref:**  
**Our Ref :** SLG 3168 B

14 January 2019

Lonpac Insurance Bhd  
100 Beach Road  
#19-00 Shaw Tower  
Singapore 189702

PROPERTY CLAIM  
(WITHOUT PREJUDICE  
TO: Any **Personal Injury**  
Claims)

LKK Auto Consultants Pte Ltd  
Blk 51, Paya Ubi Industrial Park,  
Ubi Avenue 1,  
#02-25  
Singapore 408933

Attn: Claims Department

Dear Sir/Mdm,

### **ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - CALL FOR DIRECT SETTLEMENT**

Kindly find attached the finalized report for SLG 3168 B. We are pleased to inform that we are agreeable to the amount proposed.

As such, we are writing to your kind office to call for a direct settlement, in relation to the accident involving SLG 3168 B & SGK 1666 G on 29 September 2018. We will like to know if your company is prepared to settle for the amount as stated below:

Cost of Repair	:\$ 4,350.00
Cost of Rental	:\$ 1,250.00
LTA Search	:\$ 7.45
<b>Total:</b>	<b>: \$ 5,607.45</b>

We seek your kindest assistance in letting us know whether your kind office is agreeable to the above within the next 7 days and we look forward to you forwarding us the DV (without prejudice to any personal injury claims), if required, so that we can expedite on its return for an amicable settlement to the matter.

## Asher Sng (LKKAuto)

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 25 March 2019 4:36 PM  
**To:** 'ONG LI LI'  
**Cc:** MT\_Claim\_SG  
**Subject:** [MANDATE REQUEST] RE: Our Ref: 18/18/18/VP05/020974 ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - APPOINTMENT OF MOHAMMED RASUL AS SINGLE JOINT EXPERT [External General]  
**Attachments:** TP LOD.pdf; LKK Inspection.pdf; LKK Adjustment.pdf; LKK Survey Photo.pdf; LKK Resurvey Photo.pdf

Dear Sirs,

We refer to the above matter.

We have highlighted to your good office on 09/10/2018 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **ASIA MOTORSPORTS SOLUTION PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 13,250.80	\$ 4,350.00
2. Loss of Rental (5days x \$250)	\$ 1,250.00	\$ 500.00 (5days x \$100)
3. LTA/GIA Search Fee	\$ 7.45	\$ 7.45
<b>Total</b>	<b>\$ 14,508.25</b>	<b>\$ 4,857.49</b>

\*\*5 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

**The above is for your approval please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI <[long@lonpac.com](mailto:long@lonpac.com)>

**Sent:** Tuesday, 19 February 2019 10:24 AM

**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Robert-ABLim ([robert@ablim.com.sg](mailto:robert@ablim.com.sg)) <[robert@ablim.com.sg](mailto:robert@ablim.com.sg)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Friday, 12 April 2019 12:20 PM  
**To:** Asia Motorsports Solution Pte Ltd  
**Subject:** RE: (Gentle Reminder) ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - CALL FOR DIRECT SETTLEMENT

**'WITHOUT PREJUDICE'**  
**SAVE AS TO COSTS**

Hi Sir,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 4,350.00
2. Loss of Rental (5days x \$100)	\$ 500.00
3. LTA/GIA search fee	\$ 7.45
<b>TOTAL</b>	<b><u>\$ 4,857.49</u></b>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Asia Motorsports Solution Pte Ltd <[asiamotorsports@hotmail.com](mailto:asiamotorsports@hotmail.com)>  
**Sent:** Friday, 22 February 2019 1:50 PM  
**To:** Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Subject:** Re: (Gentle Reminder) ACCIDENT INVOLVING SLG 3168 B & SGK 1666 G ON 29 SEPTEMBER 2018 - CALL FOR DIRECT SETTLEMENT

**PROPERTY CLAIM**  
**(WITHOUT PREJUDICE)**

TO: Any Personal Injury

Claims)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18017848/R1ea3q2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 29-07-2019	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGK 1666G	Veh. Inspected	SLG 3168B	
Policy No.	Z18VP05019868	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020974	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	02/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN JETTA 1.4 TSI	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WVWZZZ16ZDM010949	Colour	BLUE	
Odometer	130287	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40Z R18	PIRELLI	6 mm	
L/H Front Tyre	225/40Z R18	PIRELLI	6 mm	
R/H Rear Tyre	225/40Z R18	PIRELLI	6 mm	
L/H Rear Tyre	225/40Z R18	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/09/2018	Inspection Date	03/10/2018	
Survey held at	15 KAKI BUKIT ROAD 4# 01-53			
Repairer	ASIA MOTORSPORTS SOLUTION PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 3168B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DENTED	1,557.50	1,213.00
2	REAR BUMPER SIDE RETAINER L/R @\$201.70	O/S DISTORTED / N/S NOT NECESSARY	403.40	112.00
2	REAR BUMPER SIDE BRACKET L/R @\$189.50	NOT NECESSARY	379.00	-
1	REAR BUMPER TOP BRACKET	NOT NECESSARY	315.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	712.60	-
1	REAR BUMPER UNDER DUST COVER RH	NOT NECESSARY	198.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	789.00	-
1	REAR END PANEL GARNISH	CRACKED	289.90	193.00
2	REAR TAIL LAMP L/R @\$521.80	O/S CRACKED / N/S NOT NECESSARY	1,043.60	391.00
1	REAR BOOT LID	BUCKLED	1,685.00	1,450.00
1	REAR BOOT LID LOCK	BENT	288.00	175.00
2	REAR BOOT LID LAMP L/R @\$340.80	NOT NECESSARY	681.60	-
1	REAR BOOT LID WEATHER-STRIP	TORN	189.00	189.00
1	REAR BOOT LID INNER TRIM COVER	CRACKED	387.40	238.00
1	REAR FENDER INNER TRIM COVER RH	NOT NECESSARY	597.00	-
	LESS 10% DISCOUNT		-951.60	-396.10
			8,564.40	3,564.90
<b><u>NETT ITEMS</u></b>				
2	REAR BUMPER REFLECTOR LAMP L/R @\$114.60 (N)	O/S CRACKED / N/S NOT NECESSARY	229.20	81.00
1	REAR BUMPER CLIPS (N)	NECESSARY	60.00	40.00
1	REAR BOOT LID LATCH LOCK BADGE (N)	NECESSARY	89.20	89.20
1	REAR BOOT LID 'JETTA' EMBLEM (N)	NECESSARY	89.20	89.20
1	REAR BOOT LID 'TSI' EMBLEM (N)	NECESSARY	49.80	49.80
	LESS 10% DISCOUNT		-	-34.92
			517.40	314.28
<b><u>SPECIAL NETT ITEMS</u></b>				
2	REAR BUMPER REVERSE SENSOR @\$200.00 (SN)	SHORTED	400.00	200.00

Report Ref No. CC4/LPC18017848/R1ea3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER LOWER DIFFUSER (SN)	NOT NECESSARY	689.00	-
1	SET REAR NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
			1,139.00	200.00
	<b>LABOUR</b>			
	CHECK WIRING, LIGHTING & CENTRE LOCKING SYSTEM.		50.00	30.00
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR REAR END PANEL.		1,100.00	600.00
	SPRAY PAINTING.		1,100.00	600.00
	TO DIAGNOSTIC CHECKS & RESET.	NOT NECESSARY	280.00	-
	ANTI-RUST PROOFING ON AFFECTED PANEL & RE-SEAL BODY PANEL JOINT.		150.00	50.00
	TO TRANSFER BOOT LID MECHANISM & COMPONENTS.		80.00	60.00
	TO STRAIGHTEN & REALIGN REAR EXHAUST SYSTEM.	NOT NECESSARY	120.00	-
	TO REINSTALL REAR BUMPER REVERSE SENSOR.		150.00	60.00
			3,030.00	1,400.00
<b>GRAND TOTAL</b>			<b>13,250.80</b>	<b>5,479.18</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,350.00</b>

Report Ref No. CC4/LPC18017848/R1ea3q2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.