

INS CASE OWNER: **KM**

CC 6, 180 18846, Hpas

IDAC:

Surveyor: **UMP**DOI: **1-10-18**Date / Time: **1-10-18**Registered in Merimen: **3-10-18**

Pre-assign / CCU / FTE

Insured Vehicle No. **SFW 111K**

Name of Insured

Insured Tel No.

HP:

Excess Sec II : \$5

D.O.A: **1-10-18**

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

**or**

INSRS:

WSP:

Tel:

Liability:

RMKS:

**TP**

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

**URGENT**

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(\$

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: **10/4/19**Confirm with: **Leary**

Email

Call

Final Liability:

%

**100**(Agreed / Assessed) BOLA S/N No.: **28C 3veh cc. Old 1stH)**

If NO or B 23, Ass. Lia:

Repair Cost:

\$5

**7500**

Loss of Rental (LOR):

\$5

**700**

(\$

( 7 days)

**X\$ 100.00**

Loss of Use (LOU):

\$5

**-**

(\$

x days)

Loss of Income (LOI):

\$5

**-**

(\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$5

**29.00**

Medical:

\$5

Disbursement:

\$5

Legal Cost

\$5

Total:

\$5

**8229**Global Sum \$5: **8200.00**

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5

**8200**

Name 1:

**Leary Automotive**

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

**\$ 320.00**

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 9 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 56F6696M Yr Regn: 2016 March  
 Type: M/Car M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Honda Vezel CC: 1496  
 Colour: White A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp Reading: 144262 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: RU11107262

Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16

BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 01/10/18Survey held at Leamy Auto.Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

US \$7500 (Red ~~10832.70~~ / 5991)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee

2)

Transportation

Add Fee: ☐ : Site Insp (\$

) \$ + RE \$

☐ : Interview (\$

) Photos

☐ : Tech. Invs (\$

) Others

☐ : Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TPA 16  
Xmas Tree

S6F6686M

Honda Vezel

R411107262

Front Number Plate	30(SW) x
Front Number Plate Holder	30(SW) x
Front Bumper	727.50 ✓
Front Bumper Clips	30 ✓
Front Bumper Side Holder x 02	23 x 2 = 46 ✓
Front Bumper Lower Grille	150 x
Front Bumper Reinforcement	32770 ✓
Headlamp x 02	1759 x 2 = 3518.80
Headlamp Lower Bracket x 02	35 x 2 = 70 35
Front Grille	250 ✓
Front Grille Logo	28.20 ✓
Front Grille Chrome Moulding x 02	46.2 x 2 = 92.40 46.20

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey vehicle after body painting
- To declare & label part(s) during resurvey
- Parts price is subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S6F6696M

Rear Bumper	Distorted	880 ✓
Rear Bumper Clips	new	30 ✓
Rear Bumper Side Holder x 02	new	32x2=64 ✓
Rear Bumper Reflector x 02	RH cracked	151x2=302 <del>151</del>
Rear Side Bumper x 02	RH torn	155x2=310 <del>195</del>
Rear End Panel	Dented	580 ✓
Rear End Panel Top Garnish	Delint	101.40 ✓
Rear End Panel Sealant	new	60(SN) ✓
Reverse Sensor	Damaged	<del>280(SN)</del> 200(SN)
Tailgate	Distorted	1100 ✓
Tailgate Lock	Damaged	185.40 ✓
Tailgate Weatherstripe	let	165 ✓
Tailgate Inner Trimboard	cracked	225.10 ✓
Tailgate Inner Trimboard Clips	new	30 ✓
Tailgate Reflector x 02	RH cracked	355x1=355 <del>210</del> 355
Tailgate Glass Moulding	2 per	120 ✓
Tailgate Glass Sealant	per	60(SN) ✓
Vezeal Moulding	new	5670 ✓
Rear Camera	new	480(SN) x

S6F6696M

489

Tailamp x 02

2H mald

489 x 2 = 978

Rees Fender Inner Trim Board x 02

RH mald

285 x 2 = 570 285

Rees Fender Inner Trim Board Clips

NEE

60 30

Rees Exhaust Pipe

855

Rees Exhaust Mounting

25

Spere Tyre Panel Undercover

215

Spere Tyre Panel Undercover Clips

30

list 8252.10

ven 20%: 6633.68

2.11 320

Labour: 2460

total: 9413.68

09 days

4/5: 7.5K ✓

Panel Beating

~~1800~~ 1100

Spring Painting

~~1600~~ 900

Wiring

~~100~~ 60

To underseal

~~150~~ 40

To remove reverse sensor

~~100~~ 50

To remove rear camera

~~100~~ 50

To remove upholstery

~~150~~ 60

To transfer tailgate settings

~~150~~ 80

To remove tailgate g/4s

~~180~~ 120

To remove exhaust pipe

150. X

13852.70  
4400  
18252.70

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Thursday, 1 November 2018 4:41 PM  
**To:** 'Kianmeng.Chan1@aig.com'  
**Subject:** <Request for OI Video> Your Ref: 9912469863SG Our Ref: CC6/AIG18017896/Apa3  
[ACCIDENT INVOLVING SFW 1121K(AIG) / SGF 6696M / OTHERS ON 01/10/2018]

Your Ref: **9912469863SG**  
Our Ref: CC6/AIG18017896/Apa3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SFW 1121K(AIG) / SGF 6696M / OTHERS ON 01/10/2018**

We refer to the above matter.

Kindly assist to upload OI's video in Merimen for our viewing.

Thank you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAuto)

---

**From:** Hsiao Tong (LKKAuto)  
**Sent:** Sunday, 6 January 2019 12:34 PM  
**To:** 'Chan, Kian-Meng'  
**Subject:** <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3  
[ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Your Ref: **9912469863SG**  
Our Ref: CC6/AIG18017896/Apa3

**Without Prejudice**

Dear Sirs,

### **ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018**

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.  
We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **Leang Automotive** is as follows: -

	Amount <u>Claimed</u>	Amount <u>Revised</u>
1. Cost of Repair	\$18,332.70	\$ 7,500.00
2. Loss of Rental (7days x \$200.00)	\$ 1,400.00	\$ 700.00 (7days x \$100.00)
3. LTA/ GIA Search Fee	\$ 29.00	\$ 29.00
<b>TOTAL</b>	<b>\$19,761.70</b>	<b>\$ 8,229.00</b>
Total amount of claim ( <b>Liability 100%</b> )		<b>\$ 8,229.00</b>

**For your approval in Merimen please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Hsiao Tong (LKKAuto)

---

**From:** Chan, Kian-Meng <Kianmeng.Chan1@aig.com>  
**Sent:** Tuesday, 9 April 2019 4:33 PM  
**To:** Hsiao Tong (LKKAuto)  
**Cc:** Admin A; Adrian Ling (LKKAuto)  
**Subject:** RE: <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3  
[ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Dear Hsiao Tong / Adrian,

Appreciate the clarifications & thank you.  
Mandate approved; Kindly settled at best.

Best regards,  
**Chan Kian Meng**  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120  
Tel +(65) 6419 1678  
[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Hsiao Tong (LKKAuto) [mailto:[chewht@lkkauto.com](mailto:chewht@lkkauto.com)]  
**Sent:** Tuesday, April 09, 2019 3:08 PM  
**To:** Chan, Kian-Meng  
**Cc:** Admin A; Adrian Ling (LKKAuto)  
**Subject:** [EXTERNAL] RE: <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3  
[ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

### Caution: External Email

Hi Kian Meng,

Kindly refer to the below for your perusal: -

No.	Particulars
8	Headlamp – Photo 56 – 58 in Merimen
25	Tailgate inner trim board – Photo 91 – 94 in Merimen
26	Tailgate inner trim board clips – It is necessary items while replace tailgate inner trim board
27	Tailgate Reflector – Photo 69 – 70 in Merimen
32	Tail lamp – Photo – 71 – 74 in Merimen
33	Rear fender inner trim board – Photo 79 – 83 in Merimen
34	Rear fender inner trim board clips - It is necessary items while replace Rear fender inner trim board

Kindly let us have your further mandate after reviewing the case.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chan, Kian-Meng <[Kianmeng.Chan1@aig.com](mailto:Kianmeng.Chan1@aig.com)>

**Sent:** Monday, 8 April 2019 11:21 AM

**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** <Seek Mandate> Your Ref: 99124698635G \*Our Ref: CC6/AIG18017896/Apa3 [ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Good day Hsiao Tong,

May I check on the updates on the aforementioned parts?

Best regards,

**Chan Kian Meng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1678

[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

Follow us:



**AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.**  
**[Click here to find out more.](#)**

IMPORTANT NOTICE:

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

---

**From:** Chan, Kian-Meng

**Sent:** Monday, March 11, 2019 3:51 PM

**To:** 'Hsiao Tong (LKKAuto)'

**Cc:** Admin A; Adrian Ling (LKKAuto)

**Subject:** RE: <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3 [ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Good day Hsiao Tong,

May I check on the updates on the aforementioned parts?

Best regards,

**Chan Kian Meng**

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1678

[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Hsiao Tong (LKKAuto) [<mailto:chewht@lkkauto.com>]

**Sent:** Monday, February 11, 2019 2:19 PM

**To:** Chan, Kian-Meng

**Cc:** Admin A; Adrian Ling (LKKAuto)

**Subject:** RE: <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3 [ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Hi Kian Meng,

Noted. We will check and get back to you.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chan, Kian-Meng <[Kianmeng.Chan1@aig.com](mailto:Kianmeng.Chan1@aig.com)>

**Sent:** Friday, 8 February 2019 2:58 PM

**To:** Hsiao Tong (LKKAuto) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>

**Subject:** RE: <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3 [ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Dear Hsiao Tong,

Kindly assist to check on the following items, appreciate if you can furnish additional clarification / photo(s) if any:

No.	Particulars
8	Headlamp

- 25 Tailgate inner trim board
- 26 Tailgate inner trim board clips
- 27 Tailgate Reflector
- 32 Tail lamp
- 33 Rear fender inner trim board
- 34 Rear fender inner trim board clips

Best regards,

**Chan Kian Meng**

**AIG**

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1678

[KianMeng.Chan1@aig.com](mailto:KianMeng.Chan1@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Hsiao Tong (LKKAUTO) [<mailto:chewht@lkkauto.com>]

**Sent:** Sunday, January 06, 2019 12:34 PM

**To:** Chan, Kian-Meng

**Subject:** <Seek Mandate> Your Ref: 9912469863SG \*Our Ref: CC6/AIG18017896/Apa3 [ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018]

Your Ref: **9912469863SG**

Our Ref: CC6/AIG18017896/Apa3

**Without Prejudice**

Dear Sirs,

**ACCIDENT INVOLVING SFW 1121K(OI) / SGF 6696M(TP) / OTHERS ON 01/10/2018**

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he is aware that NCD (if any) would be affected.

We seek your approval to offer to Third Party repairer, **Leang Automotive** is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair	\$18,332.70	\$ 7,500.00
2. Loss of Rental (7days x \$200.00)	\$ 1,400.00	\$ 700.00 (7days x \$100.00)
3. LTA/ GIA Search Fee	\$ 29.00	\$ 29.00
<b>TOTAL</b>	<b>\$19,761.70</b>	<b>\$ 8,229.00</b>

Total amount of claim (Liability 100%) **\$ 8,229.00**

**For your approval in Merimen please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Print Received Message

This mail is associated with :

**\*SGF6696M (9912469863SG)**  
**[SFW1121K]**  
TP  
WONG POH FATT  
Oct 1 2018 7:00AM  
[LEE BOON CHIANG JIMMY]  
Leang Automotive

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 09/04/2019 16:32 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$8229.00) - SGF6696M - Claim Handler: Chan, Kian-Meng

Approved:8229.00:Kindly settle at best.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG18017896/Apa3

02 NOV 2018

**LEE BOON CHIANG JIMMY**  
55 WEST COAST WAY  
#07-07  
SINGAPORE 127017

Dear Sir/Madam,

**ACCIDENT INVOLVING SFW 1121K / SGF 6696M/ OTHERS ON 01/10/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SGF 6696M against your motor insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
Email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

Date: 01/10-18

To: M/s Leang Automotive  
No. 1 Kaki Bukit Avenue 6  
#01-68  
Singapore 417883

**LETTER OF AUTHORITY & INDEMNITY**


I/we WONG POH FATT NRIC No./ Co Registration No.  
S2751320D of (address) Blk 705 Jurong West St 71 #08-78 (s) 640705  
the registered owner (or his/her/their/agent) of motor vehicle registration no. S6F6696M  
hereby authorise M/s Leang Automotive ("the Repairer") to commence repairs to my/our  
vehicle and to forward the claim for inter alia the costs of repairs to the owner/insured of the  
Third Party responsible for the said accident on (date) 1-10-2018 involving motor vehicle  
nos SFW1121K along Jurong West St 63. I further authorise M/s  
Leang Automotive to sign and execute all documents in my name including but not limited to  
the Discharge Voucher in connection with the claim against the Third Party

However, if the third party rejects liability for whatever reasons and/or if the claim is  
reverted to my/our insurers and my/our insurers do not settle the repair costs and  
disbursements under my/our own insurance policy, I/we will be fully responsible for the  
repair costs and disbursements.

I also agree that if I do not fully co-operate in the Third Party claim, I will be  
responsible for any losses incurred by my Repairer.

My/our vehicle is repaired by the Repairer on my/our own free will and without any  
threat, inducement and/or promise.

In the event that the Repairer is compelled to enforce this undertaking, I/we agree that  
I/we shall pay for the legal costs incurred by the Repairer on a solicitor and client full  
indemnity basis.

  
\_\_\_\_\_  
Signature/ Co. Stamp

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **LEANG AUTOMOTIVE** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$8,200.00** (Global Sum) for vehicle no. **SGF 6696M** that was damaged pursuant to the accident which occurred on **01/10/2018** (date) along **JURONG WEST ST63 TO PIONEER ROAD NORTH** involving vehicle no/s **SFW 1121K**.

This is pursuant to the inspection conducted on **01/10/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **WONG POH FATT** ("the third party claimant") of vehicle no. **SGF 6696M** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SGF 6696M** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of April (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

This Discharge Voucher applies only to the claimant's claim for property damage and will not affect the personal injuries claim and/or uninsured losses claim on a later date.

Further, the settlement terms herein shall not be used as evidence to prejudice the claimant's personal injuries claim and/or other uninsured losses claim arising out of the subject matter in this action.

No. 1282

Auto Bay @ Kaki Bukit 1 Kaki Bukit Ave 6 #01-68 Singapore 417883  
Tel: 6909 3048 Fax: 6909 3046

**M/s** AIIG Asia Pacific Insurance Pte Ltd

Vehicle No: S4F6696M

**Vehicle Model:** Honda vezei

**Date:** 39-10-2018

[illegible]

Authorised Signature

For LEANG AUTOMOTIVE



# DAWN ENTERPRISES

21 Seletar West Farmway 1

Singapore 798125

Tel: 63832651 Fax: 64842836

Reg No.430058/00D

Leung Auto

Nº 36077

## RENTAL AGREEMENT

DATE 1/10/18

### HIRER'S PARTICULARS

Name Wong Poh Fatt  
 Address 705 Jurong West St. 71  
#08-78  
S 640705  
27515200  
 I/C or Passport No. 27515200 Country \_\_\_\_\_  
 Occupation \_\_\_\_\_  
 Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
 Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
 Tel: (HP) 81582966 (Residence) \_\_\_\_\_

### DRIVER'S PARTICULARS

Name \_\_\_\_\_  
 Address \_\_\_\_\_  
 I/C or Passport No. \_\_\_\_\_ Country \_\_\_\_\_  
 Occupation \_\_\_\_\_  
 Date of Birth \_\_\_\_\_ Age \_\_\_\_\_  
 Driving Licence No. \_\_\_\_\_ Date Passed \_\_\_\_\_  
 Tel: (Office) \_\_\_\_\_ (Residence) \_\_\_\_\_

### IMPORTANT NOTES:

1. No insurance coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licensed to carry passengers only.
3. Hirer is liable to pay first \$ 2800 as excess all claims any accident plus cost of earning while damaged vehicle is under repair.
4. For usage in Malaysia subject to higher excess all claims of \$35,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

### SCHEDULE

SLD 14734

### MODEL

2000 cc  
7/10/18

Date	Time	Mileage
<u>1/10/18</u>	<u>11.40</u>	
<u>8/10/18</u>		

### CHARGES

Day at \$ <u>200.00</u> per days	\$ <u>1400.00</u>
Day at \$ _____ per week	
Day at \$ _____ per month	
TOTAL AMOUNT	\$ <u>1400.00</u>
AMOUNT PAID	\$ <u>1400.00</u>
BALANCE DUE	
Days Extension From _____ To _____	
Amount Deposit (refundable) \$	

FROM

1/10/18

TO

8/10/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Wong Poh Fatt

Hirer's Signature

Driver/Guarantor's Signature

[Signature]

DAWN ENTERPRISES

**DAWN ENTERPRISE**21 SELETAR WEST FARMWAY 1  
SINGAPORE 798125

TEL: 6383 2661 FAX: 6484 2836

REG. NO. 430058/0003

**OFFICIAL RECEIPT**

Received from

Wong Poh Katt

the sum of Dollars

One thousand four hundred

being Payment Of

S\$D 14724

C1/10/18

\$

1400/-

Cash/Cheque No.

## TAX INVOICE

Our Ref No: GR-18-152681  
Date of Request: 03/10/2018

Your Ref No: WALK IN NG KL

LEANG AUTOMOTIVE - KAKI BUKIT  
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 8 #01-68  
SINGAPORE 417883

Dear Sir/Madam,

Your Vehicle No: SGF6696M  
Date of Accident: 01/10/2018  
Place of Accident: JURONG WEST ST 63  
Involving Vehicle No: SFW1121K, SKL1218P

DESCRIPTION	AMOUNT (\$\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-152882  
Date of Request: 03/10/2018

Your Ref No: WALK IN NG KL

LEANG AUTOMOTIVE - KAKI BUKIT  
AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 8 #01-68  
SINGAPORE 417883

Dear Sir/Madam,

Date of Accident: 01/10/2018  
Vehicle No: SGF6696M  
Place of Accident: JURONG WEST ST 63  
Involving Vehicle No: SFW1121K

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SFW1121K	JURONG WEST ST 63	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☐ GIRO ☒ Cash ☐ Cheque

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

## CLAIM SUBFOLDER TRACKING



















































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018 <a href="#">Edit Reg</a>		01 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$57,500.00</b> <a href="#">Edit Estimates</a>	<b>\$57,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>











































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	LEE BOON CHIANG JIMMY, ID: S70399208								
Main Claimant:	WONG POH FATT, ID: S2751320D								
Vehicle Reg. No.:	SGF6696M	Date of Loss:	01/10/2018 07:00 - :59 [30 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9912469863SG	Policy/Cover Note No.:	1800078526 (Comprehensive) Coverage: 13/06/2018 - 12/06/2020						
Vehicle Reg. No. (Insured):	SFW1121K	Policy No. (Claimant):	5098761682						
		Excess:							
Repairer:	Leang Automotive (Kaki Bukit) AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 #01-68, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (09/04/2019): Alert - Adj Mandate Approved (\$58229.00) - SGF6696M - Claim Handler: Chan, Kian-...</li> <li>AIG_SG (04/10/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGF6696M (9912469863SG)  
[SFW1121K]  
TP  
WONG POH FATT  
Oct 1 2018 7:00AM  
[LEE BOON CHIANG JIMMY]  
Leang Automotive

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Video												1 per page		<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)										Thumbnail		Print
1	01/11/18 16:44	Video - Accident From:DD - Reg. No: SFW1121K, Claimant: LEE BOON CHIANG JIMMY											Load AVI	
Letters/Correspondences												1 per page		<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit	
Photos/Images												3 per page		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print
1	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
2	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
3	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
4	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
5	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
6	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
7	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
8	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
9	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
10	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
11	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
12	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
13	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
14	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
15	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
16	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
17	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
18	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
19	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
20	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
21	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
22	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
23	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
24	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
25	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
26	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
27	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
28	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
29	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>
30	29/10/18 19:42	General View											Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
31	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
32	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
33	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
34	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
35	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
36	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
37	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
38	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
39	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
40	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
41	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
42	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
43	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
44	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
45	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
46	29/10/18 19:42	General View		<input checked="" type="checkbox"/>
47	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
48	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
49	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
50	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
51	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
52	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
53	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
54	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
55	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
56	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
57	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
58	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
59	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
60	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
61	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
62	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
63	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
64	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
65	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
66	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
67	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
68	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
69	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
70	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
71	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
72	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
73	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
74	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
75	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
76	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
77	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
78	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
79	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>
80	29/10/18 19:42	Reinspection Photo		<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
81	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	29/10/18 19:42	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/10/18 12:02	TP GIA REPORT	 Load PDF	
2	01/11/18 16:10	TP ESTIMATE_MARKED	 Load PDF	
3	02/01/19 16:52	RENTAL RECEIPT	 Load PDF	
4	02/01/19 16:52	GIA SEARCH	 Load PDF	
5	02/01/19 16:52	LETTER TO OI	 Load PDF	
6	12/04/19 08:44	WORKSHOP INVOICE	 Load PDF	
7	12/04/19 08:44	AUTHORISATION TO ACT FORM	 Load PDF	
8	12/04/19 08:44	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/10/18 11:30	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer	
<small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFW1121K (Insd veh)	Model:	HONDA VEZEL 1.5 X (A)
	SGF6696M (TP veh)		
Date of Accident:	01/10/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	:	\$		18,332.70
Final Repair Cost	:	\$		8,200.00
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		7 days
LTA / GIA Search Fee	:	\$		
Others:	:	\$		
	:	\$		
Final Settlement Sum (Global Sum)	:	\$		8,200.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_\_ 100 \_\_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

BOLA Liability: \_\_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_\_ 100 \_\_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Leang Automotive	:	8,200.00
2)		:	
3)		:	

JOANNE LEE KHANG MIN

12 Apr  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18017896/APA3Q2

Date: 12/04/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800078526  
**Claimant Vehicle No :** SGF6696M **Insured Vehicle No :** SFW1121K  
 Date of Loss: 01/10/2018 Nature of Claim: TP Claim No: 9912469863SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF6696M**  
 Make & Model: HONDA VEZEL, 1.5 X (A) Engine No: L15B4027266  
 Reg. Date: 21/03/2016 (Man. Year: 2015) Chassis No: RU11107262  
 Colour: White Odometer: 144262 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,852.70	6,953.68	6,899.02	49.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	2,460.00	2,020.00	45.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,332.70</b>	<b>9,413.68</b>	<b>8,919.02</b>	<b>48.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,332.70</b>	<b>7,500.00</b>	<b>10,832.70</b>	<b>59.09</b>
<b>+ Car Rental (7.0 x S\$100.00/day) (S\$)</b>		700.00		
<b>+ Doc/Search Fee (S\$)</b>		29.00		
<b>Nett Liability (S\$)</b>		<b>8,229.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>8,200.00</b>		

### INSPECTION

Date of Assignment: 01/10/2018  
 Date Inspected: 01/10/2018 Inspected At: Leang Automotive (Kaki Bukit)  
 AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT  
 AVE 6 #01-68  
 Singapore 417883

Estimated Period of Repair: 9.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
2	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
3	1		*FRONT BUMPER	Deformed	727.50 F	*727.50 FL
4	1		*FRONT BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
5	2		*FRONT BUMPER SIDE HOLDER	Necessary	46.00 F	*46.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	150.00 F	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	327.70 F	*327.70 FL
8	1		*HEADLAMP	O/S Cracked	3,518.80 F	*1,759.40 FL
9	1		*HEADLAMP LOWER BRACKET	O/S Cracked	70.00 F	*35.00 FL
10	1		*FRONT GRILLE	Cut	250.00 F	*250.00 FL
11	1		*FRONT GRILLE LOGO	Necessary	28.20 F	*28.20 FL
12	1		*FRONT GRILLE CHROME MOULDING	O/S Cut	92.40 F	*46.20 FL
13	1		*REAR BUMPER	Distorted	880.00 F	*880.00 FL
14	1		*REAR BUMPER CLIPS	Necessary	30.00 F	*30.00 FL
15	2		*REAR BUMPER SIDE HOLDER	Necessary	64.00 F	*64.00 FL
16	1		*REAR BUMPER REFLECTOR	O/S Cracked	302.00 F	*151.00 FL
17	1		*REAR SIDE BUMPER	O/S Torn	390.00 F	*195.00 FL
18	1		*REAR END PANEL	Dented	580.00 F	*580.00 FL
19	1		*REAR END PANEL TOP GARNISH	Deformed	101.40 F	*101.40 FL
20	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
21	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
22	1		*TAILGATE	Distorted	1,100.00 F	*1,100.00 FL
23	1		*TAILGATE LOCK	Damaged	185.40 F	*185.40 FL
24	1		*TAILGATE WEATHERSTRIPE	Cut	165.00 F	*165.00 FL
25	1		*TAILGATE INNER TRIMBOARD	Cracked	225.10 F	*225.10 FL
26	1		*TAILGATE INNER TRIMBOARD CLIPS	Necessary	30.00 F	*30.00 FL
27	1		*TAILGATE REFLECTOR	O/S Cracked	710.00 F	*355.00 FL
28	1		*TAILGATE GLASS MOULDING	Necessary	120.00 F	*120.00 FL
29	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*VEZEL WORDING	Necessary	56.20 F	*56.20 FL
31	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
32	1		*TAILLAMP	O/S Cracked	978.00 F	*489.00 FL
33	1		*REAR FENDER INNER TRIM BOARD	O/S Cracked	570.00 F	*285.00 FL
34	1		*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	60.00 F	*30.00 FL
35	1		*REAR EXHAUST PIPE	Not Necessary	855.00 F	*- FL
36	1		*REAR EXHAUST MOUNTING	Not Necessary	25.00 F	*- FL
37	1		*SPARE TYRE PANEL UNDERCOVER	Not Necessary	215.00 F	*- FL
38	1		*SPARE TYRE PANEL UNDERCOVER CLIPS	Not Necessary	30.00 F	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc

<b>Sub Total (S\$)</b>	<b>13,852.70</b>	<b>8,612.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	<b>0.00</b>	<b>1,658.42</b>
<b>Total Parts (S\$)</b>	<b>13,852.70</b>	<b>6,953.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,800.00	1,100.00
2	SPRAY PAINTING	New	1,600.00	900.00
3	WIRING	New	100.00	60.00
4	TO UNDERSEAL	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE EXHAUST PIPE	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,480.00</b>	<b>2,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >