

INSTR

Binnite

CC 3, 116 180 18401, H 1843 1/2

IDAC

14

Wup

ASSIGNMENT

DOI

9-10-18

Date / Time

3-10-18

Registered in Merimen

3-10-18

FTE

Vehicle No.

SL57316

Claim No.

:

6x

Name of Insured

Sheng Jiy Jey

Policy No.

:

Insured Tel No.

HP:

Make / Model

:

Excess Sec II : \$

D.O.A:

29-9-18

Place of Accident

:

Is driver the owner?

(YES / NO)

Nature of Accident

:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability

%

Final? Yes / No

SKS 314P



INSRS:
WSP:
Tel:
Liability:
RMKS:

Premium



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

16/10
Mx

SKS 314P - X

SL57316 - X

Non-Reporting ltr (1st)
Non-Reporting ltr (2nd)
Non-Reporting ltr (Final)
Notification ltr (if non-pickup)

12/10/18

Spoke to OI's husband and he confirmed the accident details. Informed TP claim and he agree to settle.

Call OI: 7 THIN by Email.
After call ltr to OI: 3/11

7/2/19

FIG - Advan.

Documentation Check List: Handler Typist
Notification ltr (if non-pickup)
After call ltr to OI:
Authorisation To Act
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD

27/3/19

Recommended LOR = \$4776.39 (w/ GST) email to TP

8/4/19

TP finalised amt of \$5078.39 - Pending acceptance

27/5

Revised \$45078.39 DV pend - Pending DV int.

6/6

DV int - FW PMS CHT

12/6

File PMS Advan to close

PRELIMINARY ADVICE

Date/Time:

Sent By:

Post-Repair Photos:

Others:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

27/5/19 1:05pm

Confirm with

Mastura

Email

Call

Final Liability:

%

(

Agreed / Assessed)

BOLA S/N No.:

23

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ GST)

\$

4776.39

Loss of Rental (LOR):

\$

(

days)

Loss of Use (LOU):

\$

300.00

(

60 x 5

days)

Loss of Income (LOI):

\$

(

3 x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$

2.00

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$4776.00

Total:

\$

5078.39

Global Sum \$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

4778.39

Name 1:

Premium Automobiles Pte Ltd.

Payee 2: (Strike if N.A.)

\$

300.00

Name 2:

Kan Suet Hoon

Payee 3: (Strike if N.A.)

\$

Name 3:

:

:

wh 12/6

17957/Anob

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKS3147 Yr Regn: 2015 March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan cc 1395

Colour: White A/C Insured / Std / NI / NA

Sp. Reading: 70795 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V7F1084525

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 2 Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 205/55 R16

BS: DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Survey held at

Premium

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 09/10/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

PIP #4463 to with 5 repair days/Red = \$3244.08 / 43%.

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RE - \$

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL

SKS19017

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1339/2018/PH
Date	:	4-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Koh Suat Hoon
Address	:	Blk 470 Jurong West St 41 #14-425 Singapore 640470
Telephone	:	(HP) 91130042
Type of Claim	:	Third Party Claims
Policy No.	:	PNPV 2018-00003606
Vehicle No	:	SKS 314 P
Model Code	:	Audi A3 Sedan 1.4 TFSI
Model / Year	:	Mar-15
Engine No	:	CZC 232967
Chassis No	:	WAUZZZ8V7F1094525
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	29-Sep-18
Place of Accident	:	Bukit Batok MSCP

Premium Automobiles

S5 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 314 P.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00	<i>L</i>
2	To dismantle lhs front door panel trim. To remove and transfer lhs wing mirror assy.	S/N \$ 300.00	<i>check in Admin + 3W + * Can't give</i>
3	To dismantle and renew lhs front door. To repair lhs side member. Reinstall all parts removed.	\$ 1,200.00	<i>750 = L</i>
4	To respray lhs front door, lhs wing mirror cover, lhs door handle and lhs side member.	\$ 1,900.00	<i>1300 Door, side member: 1100 Mirror 120 Handle 80</i>
5	To carry out diagnostic check	S/N \$ 192.00	<i>L</i>
TOTAL LABOUR CHARGES - FRONT		: \$ 3,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 314 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH <i>Revised</i>	\$ 2,190.00	✓ 1752.00 P
2	ATTACHMENT PARTS FOR DOOR <i>Revised</i>	\$ 206.00	✓
3	SOUND ABSORBER <i>Revised</i>	\$ 42.00	✓
4	OUTER DOOR SEAL - LH <i>Revised</i>	\$ 139.00	✓ 111.00 P
5	BONDING AGENT <i>Revised</i>	\$ 43.00	✓
6	CLEANING SOLUTION <i>Revised</i>	\$ 64.00	✓
7	DOOR CATCH <i>Revised</i>	\$ 92.00	X
8	COVER FOR DOOR CATCH <i>Revised</i>	\$ 13.00	X
9	DOOR SEAL, INNER <i>Revised</i>	\$ 139.00	X
10	POWER WINDOW REGULATOR W/O MOTOR <i>Revised</i>	\$ 232.00	✓
11	DOOR HANDLE, EXTERIOR - LH <i>Revised</i>	\$ 207.00	✓
12	HOUSING - FRONT LH <i>Revised</i>	\$ 26.00	✓
13	MOUNTING BAR <i>Revised</i>	\$ 143.00	X
14	SUNDRIES <i>Revised</i>	\$ 300.00	X 78.72 P
TOTAL SPARE PARTS CHARGES		\$ 3,836.00	
TOTAL LABOUR CHARGES		\$ 3,872.00	
GRAND TOTAL		\$ 7,708.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved. Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1339/2018/PH
Date : 4-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - /b -26 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Koh Suat Hoon
Address : Blk 470 Jurong West St 41
#14-425
Singapore 640470
Telephone : (HP) 91130042
Type of Claim : Third Party Claims
Policy No. : PNPV 2018-00003606
Vehicle No : **SKS 314 P**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Mar-15
Engine No : CZC 232967
Chassis No : WAUZZZ8V7F1094525
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Sep-18
Place of Accident : Bukit Batok MSCP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKS 314 P.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N	\$ 280.00	\$ 280.00 ✓
2	To dismantle lhs front door panel trim. To remove and transfer lhs wing mirror assy.	S/N	\$ 300.00	\$ 300.00 ✓
3	To dismantle and renew lhs front door. To repair lhs side member. Reinstall all parts removed.		\$ 1,200.00	\$ 750.00 ✓
4	To respray lhs front door, lhs wing mirror cover, lhs door handle and lhs side member.		\$ 1,900.00	\$ 1,300.00 ✓
5	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00 ✓
TOTAL LABOUR CHARGES - FRONT		:	<u>\$ 3,872.00</u>	<u>\$ 2,822.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 314 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH	\$ 2,190.00	\$ 1,752.00
2	ATTACHMENT PARTS FOR DOOR	\$ 206.00	
3	SOUND ABSORBER	\$ 42.00	
4	OUTER DOOR SEAL - LH	\$ 139.00	\$ 111.20
5	BONDING AGENT	\$ 43.00	
6	CLEANING SOLUTION	\$ 64.00	
7	DOOR CATCH	\$ 92.00	
8	COVER FOR DOOR CATCH	\$ 13.00	
9	DOOR SEAL , INNER	\$ 139.00	
10	POWER WINDOW REGULATOR W/O MOTOR	\$ 232.00	
11	DOOR HANDLE , EXTERIOR - LH	\$ 207.00	
12	HOUSING - FRONT LH	\$ 26.00	
13	MOUNTING BAR	\$ 143.00	
14	SUNDRIES	\$ 300.00	\$ 78.72
TOTAL SPARE PARTS CHARGES :		\$ 3,836.00	\$ 1,941.92
TOTAL LABOUR CHARGES		\$ 3,872.00	\$ 2,822.00
GRAND TOTAL		\$ 7,708.00	\$ 4,763.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/1339/2018/PH 23-Oct-18 Kee Siang 23-Oct SKS 314 P Audi A3 Sedan 1.4 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Window Slot -Chrome	\$ 268.00	
		\$ 268.00	
	TOTAL	\$ 268.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Hsiao Tong (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 26 November 2018 11:02 AM
To: Adrian Ling (LKKAUTO); Thin Thin (LKKAUTO); CS A Team; Admin A; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SKS314P - TP AIG - SURVEYED 9 OCT 18
Attachments: PA13392018 - SKS 314 P - A3 SEDAN 1.4 TFSI - AIG TP (PH).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$4763.92 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 09/10/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 0\$ Pays

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/1339/2018/PH

23-Oct-18

Kee Siang

23-Oct

SKS 314 P

Audi A3 Sedan 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Window Slot -Chrome	\$ 268.00	<i>act / MIN</i>
TOTAL		\$ 268.00	

For Premium Automobiles Pte Ltd



Authorised Signature

23/10/18
[Handwritten signature]

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 314 P.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT DOOR - LH <i>perked</i>	\$ 2,190.00	✓
2	ATTACHMENT PARTS FOR DOOR <i>?</i>	\$ 206.00	?
3	SOUND ABSORBER <i>?</i>	\$ 42.00	?
4	OUTER DOOR SEAL - LH <i>per</i>	\$ 139.00	✓
5	BONDING AGENT <i>?</i>	\$ 43.00	?
6	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
7	DOOR CATCH <i>new it ✓</i>	\$ 92.00	X
8	COVER FOR DOOR CATCH <i>new</i>	\$ 13.00	X
9	DOOR SEAL, INNER <i>new</i>	\$ 139.00	X
10	POWER WINDOW REGULATOR W/O MOTOR <i>new</i>	\$ 232.00	X
11	DOOR HANDLE, EXTERIOR - LH <i>Repr</i>	\$ 207.00	X
12	HOUSING - FRONT LH <i>Repr</i>	\$ 26.00	X
13	MOUNTING BAR <i>new</i>	\$ 143.00	X
14	SUNDRIES <i>?</i>	\$ 300.00	X
TOTAL SPARE PARTS CHARGES		\$ 3,836.00	
TOTAL LABOUR CHARGES		\$ 3,872.00	
GRAND TOTAL		\$ 7,708.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 27 March 2019 4:52 PM
To: 'Carrine Leong'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: FINAL REVISION - SKS314P - TP AIG - SURVEYED 9 OCT 18

Without Prejudice

Dear Sirs/Mdm,

For cost of repair, recommended amount at P/P **\$4,776.39(w/gst) with 05 repair days.**

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Please note that all finalisation subject insurer's approval.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cecilia Chong (LKK Auto)
Sent: Friday, 22 March 2019 4:13 PM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: FINAL REVISION - SKS314P - TP AIG - SURVEYED 9 OCT 18

Without Prejudice

Dear Sirs/Mdm,

For cost of repair, recommended amount at P/P **\$5,063.15(w/gst) with 05 repair days.**

*** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Thank you.

Please note that all finalisation subject insurer's approval.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>

Sent: Thursday, 21 February 2019 4:48 PM

To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SKS314P - TP AIG - SURVEYED 9 OCT 18

Hi Adrian,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you on 26 Nov 2018.

We sincerely appreciate your early closure.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

x

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [<mailto:boojohnny@gmail.com>]

Sent: Monday, 26 November, 2018 11:02 AM

To: Adrian Ling <adrianling@lkkauto.com>; Thin Thin (LKK Auto) <thinthin@lkkauto.com>; cs-a@lkkauto.com; admin-a@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SKS314P - TP AIG - SURVEYED 9 OCT 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$4763.92 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18017907/ua3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/1339/2018/MAS

3 Apr 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SKS 314 P, Audi A3 Sedan 1.4 TFSI

With reference to the above-mentioned vehicle, no. **SKS 314 P**, claimant, **Ms. Koh Suat Hoon** please find the related document as per attached.

1. A copy of the Original invoice no. 85013641 – S\$4,776.39
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$300.00 (S\$60.00 x 5 working days)
6. A copy of GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKS 314 P

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

BREAKDOWN OF PAYMENT



Vehicle No: SKS314P

Accident on 29/09/2018 at BUKIT BATOK MSCP

Involving vehicle/s SLS731G

1) Repair cost \$ 4,776.39 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 300.00 Payable to: KOH SUAT HOON

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Thin Thin (LKKAUTO)

From: Thin Thin (LKKAUTO)
Sent: Thursday, 8 November 2018 3:23 PM
To: 'caobin_it@hotmail.com'
Cc: Vic (LKKAUTO)
Subject: ACCIDENT INVOLVING SLS 731G & SKS 314P ON 29/09/2018



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18017907/Aua3

08 NOVEMBER 2018

SHENG JINGJIN

56 BUKIT BATOK EAST AVE 5

#19-01

SINGAPORE 659804

Dear Sir/Madam,

ACCIDENT INVOLVING SLS 731G & SKS 314P ON 29/09/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING

Case Handler

DID: 6841 2360

FAX: 6741 4108

Email: thinthin@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd

(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, KOH SUAT HOON (the third party claimant) of Bik 470 Jurong West St 41
#14-425, Singapore 640470 (address), owner of SKS314P (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SKS314P that was damaged pursuant to the accident which occurred on 29/09/2018
(date) along BUKIT BATOK MSCP (location) involving vehicle no/s
SLS731G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 26 (day) of OCT (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, Premium Automobiles PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4776.39 (Repair Cost), S\$300.00 (Loss of Use/Rental), S\$ 2.00 (Disbursement) for vehicle no. SKS 314P that was damaged pursuant to the accident which occurred on 29/09/2018 (date) along BUKIT BATOK MSCP (location) involving vehicle no/s SLS 731G. This is pursuant to the inspection conducted on 09/10/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner KOH SUAT HOON ("the third party claimant") of vehicle no. SKS 314P make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SKS 314P (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 (day) of 06 (month) 2019 (year)

Wp
Signed by appointed surveyor


Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2222
Main Telefax: 6471 8283

Alexandre Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2222
Telefax: 6471 8283

UBI Service Centre
55 Ubi Road 1
Singapore 408863
Telephone: 6386 2222
Telefax: 6471 8283

Customer Service
Service Appointment
24 Hour Breakdown Service
Tel: 6386 2222
customer.care@premiumauto.com.sg

INSURANCE INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 10:42

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: BSR1364 Date: 29/03/2015 Order: BKS03140 Term: 30	Account: ANNS 17 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
-------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------

Regn No.: BKS03140 (V 256171) Regn Dates: 23/03/2015 Mileage: 71529 WIP No.: 27168	Model: A3 SEDAN 1.4 TFSI (AMBIENTE) 8 Chassis: WAUZZZ8V7F1894525 Engine: CTD 252967 Dept: U
VSB No.:	
You have been assisted by: UB-Jiayee 1.33	

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES	280.00	1.00	280.00
S	BODYWORK	TO DISMANTLE AND RENEW LHS FRONT DOOR, TO REPAIR LHS SIDE MEMBER, REINSTALL ALL PARTS REMOVE	750.00	1.00	750.00
S	BODYWORK	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, LHS DOOR HANDLE AND LHS SIDE MEMBER	1300.00	1.00	1,300.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	88V58318518	DOOR Less 020%	1.00	2190.00	1,752.00
X	88V5837311C	SERL Less 020%	1.00	139.00	111.20
X	88V5837249	CHECK ROD Less 020%	1.00	91.40	73.12
X	88V5837237	BOLT Less 020%	4.00	1.00	1.20
X	88V5837237	BOLT Less 020%	2.00	1.00	2.40

Parts 1,941.20	Sub-Total	4,463.92
Labour 0.00	7% GST	312.47
Sublet 2,522.00	Grand Total	4,776.39
Menus 0.00		
Lubricant 0.00		



28/3

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-152440

Date of Request: 02/10/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 02/10/2018
Enquiry By Tony Foong Chin Fong
TP Vehicle No. SLS731G
Accident Date 29/09/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLS731G	AIG Asia Pacific Insurance Pte. Ltd.	06/09/2018-05/09/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-152440

Date of Request: 02/10/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 02/10/2018
Enquiry By Tony Foong Chin Fong
TP Vehicle No. SLS731G
Accident Date 29/09/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2018 Edit Reg		09 Oct 2018 00:00 Edit Adj Rpt	S\$4,463.92 Edit Estimates	S\$4,463.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	SHENG JINGJING , ID: S8187732G								
Main Claimant:	KOH SUAT HOON , ID: S7202398F								
Vehicle Reg. No.:	SKS314P	Date of Loss:	29/09/2018 10:00 - :59 [42 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2206195514SG	Policy/Cover Note No.:	1700047524 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLS731G	Policy No. (Claimant):	PNPV2018-00003606						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS314P (2206195514SG)
[SL5731G]**

TP








KOH SUAT HOON

Sep 29 2018 10:00AM

[SHENG JINGJING]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Letters/Correspondences						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown				Edit	
Photos/Images						3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
2	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
3	07/02/19 16:58	Chassis Number				<input checked="" type="checkbox"/>	
4	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
5	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
6	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
7	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
8	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
9	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
10	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
11	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
12	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
13	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
14	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
15	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
16	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
17	07/02/19 16:58	General View				<input checked="" type="checkbox"/>	
18	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
19	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
20	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
21	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
22	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
23	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
24	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
25	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
26	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
27	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
28	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
29	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
30	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
31	07/02/19 16:58	Reinspection Photo				<input checked="" type="checkbox"/>	
Documentation						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 15:12	TP GIA REPORT	 Load PDF	
2	13/10/18 20:21	TP ESTIMATE-MARKED	 Load PDF	
3	26/10/18 09:52	TP ESTIMATE + SUPP	 Load PDF	
4	17/06/19 10:08	WORKSHOP INVOICE	 Load PDF	
5	17/06/19 10:08	AUTHORISATION TO ACT FORM	 Load PDF	
6	17/06/19 10:08	Release Voucher	 Load PDF	
7	17/06/19 10:08	GIA SEARCH	 Load PDF	
8	17/06/19 10:08	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/10/18 11:07	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLS731G (Insd veh)	Model:	AUDI A3 1.4 TFSI AMBIENTE
	SKS314P (TP veh)		MY 15 (A)
Date of Accident:	29/09/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	8,534.32	
Final Repair Cost	: \$	4,776.39	
Loss of Use	: \$	300.00	5.00 days at \$60.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	5,078.39	

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	4,778.39
2)	Koh Suat Hoon	: \$	300.00
3)		: \$	

JOANNE LEE KHANG MIN

17 Jun
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18017907/AGA3Q2

Date: 17/06/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700047524
Claimant Vehicle No : SKS314P **Insured Vehicle No :** SLS731G
 Date of Loss: 29/09/2018 Nature of Claim: TP Claim No: 2206195514SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS314P**
 Make & Model: AUDI A3, 1.4 TFSI AMBIENTE MY 15 (A) Engine No: CZC232967
 Reg. Date: 23/03/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V7F1094525
 Colour: White Odometer: 70795 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,104.00	1,941.92	2,162.08	52.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	2,522.00	1,350.00	34.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,976.00	4,463.92	3,512.08	44.03
+ GST 7.00/7.00% (S\$)	558.32	312.47	245.85	44.03
Nett Amount (S\$)	8,534.32	4,776.39	3,757.93	44.03
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,078.39		

INSPECTION

Date of Assignment: 09/10/2018
 Date Inspected: 09/10/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Dented	2,190.00 FS	*1,752.00 FS
2	1		*ATTACHMENT PARTS FOR DOOR	Not Necessary	206.00 FS	*- FS
3	1		*SOUND ABSORBER	Not Necessary	42.00 FS	*- FS
4	1		*OUTER DOOR SEAL -LH	Necessary	139.00 FS	*111.20 FS
5	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
7	1		*DOOR CATCH	Not Necessary	92.00 FS	*- FS
8	1		*COVER FOR DOOR CATCH	Not Necessary	13.00 FS	*- FS
9	1		*DOOR SEAL ,INNER	Not Necessary	139.00 FS	*- FS
10	1		*POWER WINDOW REGULATOR W/O MOTOR	Not Necessary	232.00 FS	*- FS
11	1		*DOOR HANDLE ,EXTERIOR -LH	Repair	207.00 FS	*- FS
12	1		*HOUSING -FRONT LH	Repair	26.00 FS	*- FS
13	1		*MOUNTING BAR	Not Necessary	143.00 FS	*- FS
14	1		*SUNDRIES	Necessary	300.00 FS	*78.72 FS
15	1		*WINDOW SLOT-CHROME	Not Necessary	268.00 FS	*- FS
Total Parts (\$\$)					4,104.00	1,941.92

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND TRANSFER LHS WING MIRROR ASSY	New	300.00	0.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR .TO REPAIR LHS SIDE MEMBER .REINSTALL ALL PARTS REMOVED	New	1,200.00	750.00
4	TO RESPRAY LHS FRONT DOOR ,LHS WING MIRROR COVER ,LHS DOOR HANDLE AND LHS SIDE MEMBER	New	1,900.00	1,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,872.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >