

1552/10

INS. CASE OWNER:

CC 4 ASM
AXA1801

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLW 5939X

SHC 710K

JEL 3736

SEH 8516D



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

8/10/18
THSHC 710K - 15/01/18 07:18
SLW 5939X - 1

OK 5 minutes claim

28-11-18

TRANSFER THIN² TO JOY

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

28-11-18 JOY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28. Ass. Lia:

Repair Cost:

SS

3,263.50

Loss of Rental (LOR):

SS

334.41

(3 days)

111.47

Loss of Use (LOU):

SS

150

(50 x 3 days)

Loss of Income (LOI):

SS

150

(50 x 3 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

2. x x

LOR + LOU

LOR + LOU

(Tick only one)

GIA/LTA Search

SS

2. x x

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

3,749.91

Global Sum SS:

3,745

Total:

SS

3,745. x x

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3,745. x x

Name 1:

DING AUTOMATIVE

Payee 2: (Strike if N.A.)

SS

x

Name 2:

x

Payee 3: (Strike if N.A.)

SS

x

Name 3:

x

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT

8/11/18

01 LAST 4VC.

SYNOPSIS

Tangher

REF: ASM (AXA)

U

3

ASSIGNMENT

From: Date: 04-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 7101K
at Workshop m/s Ding Automotive
of 31 Corporation Rd

Insured:

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

After 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHC 7101K Yr Regn: 2016 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 C.C. 1685

Colour: yellow A/C: Insured / Std / NI / NA

Sp.Reading: 370576 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM H 454 / 4 M 64 092480

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60-K11
R: 4 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Triangle

Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 5/10/180112

Survey held at Ding Auto Corporation Rd.

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TOTAL \$ 3,071.07

L/S \$ 3,050.00

R (\$ 9,339.81/75%)

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2)

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

Report Format:

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017915/ub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 03-10-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 5939X	Veh. Inspected	SHC 7101K	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/09/2018	Inspection Date		
Survey held at	DING AUTO PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C
#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

04/10/2018 10:51

JOB-NO: 50111003

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7101K

TRANS: AUTO

CHASSIS: KMHLB41UMGU092440

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU661313

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00		Y	500
2 SUNDRIES	1.00	80.00	0.00	80.00		Y	30
3 RUST PROOFING	1.00	120.00	0.00	120.00		Y	X an
4 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	150.00	0.00	150.00		Y	40
5 ALIGNMENT BOOTLID	1.00	100.00	0.00	100.00		Y	X an
6 R&R RADIATOR & TURBO INTERCOOLER	1.00	150.00	0.00	150.00		Y	X an
7 R&R AIR-COND CONDENSER & TOP UP GAS (R134A)	1.00	150.00	0.00	150.00		Y	X an
8 R&R FRONT SUPPORT PANEL	1.00	200.00	0.00	200.00		Y	X an
9 TO RESETTING AND RECODING HEAD LAMP & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	180.00	0.00	180.00		Y	X an
10 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
11 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	300
12 RESPRAY REAR BUMPER DIFFUSER	1.00	200.00	0.00	200.00		Y	100
13 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00		Y	X an
14 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
15 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200
TOTAL:		3,800.00	0.00	3,800.00			

MATERIALS

1 REAR BUMPER	1.00	559.90	111.98	447.92	L	Y	de
2 REAR BUMPER DIFFUSER	1.00	218.40	43.68	174.72	L	Y	cut
3 REAR BUMPER RETAINER LH	1.00	48.63	9.73	38.90	L	Y	2x
4 REAR BUMPER RETAINER RH	1.00	48.63	9.73	38.90	L	Y	2x
5 REAR BUMPER REINFORCEMENT	1.00	488.40	97.68	390.72	L	Y	2x
6 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	85.63	17.13	68.50	L	Y	2x
7 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	85.63	17.13	68.50	L	Y	2x
8 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.63	17.93	71.70	L	Y	de
9 REAR END PANEL	1.00	629.95	125.99	503.96	L	Y	X an
10 FRONT BUMPER	1.00	599.68	119.94	479.74	L	Y	Ry
11 FRONT BUMPER RETAINER LH	1.00	42.32	8.46	33.86	L	Y	2x an
12 FRONT BUMPER RETAINER RH	1.00	42.32	8.46	33.86	L	Y	2x an
13 FRONT BUMPER RADIATOR GRILLE	1.00	1,110.10	222.02	888.08	L	Y	cut
14 FRONT BUMPER RADIATOR GRILLE LOGO	1.00	142.84	28.57	114.27	L	Y	de
15 FRONT BUMPER RADIATOR GRILLE CHROME	1.00	121.77	24.35	97.42	L	Y	Cnr

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 FRONT BUMPER REINFORCEMENT SPONGE	1.00	99.66	19.93	79.73	L	Y	7/12
17 FRONT BUMPER REINFORCEMENT	1.00	432.21	86.44	345.77	L	Y	2/14
18 FRONT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	2/14
19 HEADLAMP LH	1.00	1,808.10	361.62	1,446.48	L	Y	X 14
20 HEADLAMP RH	1.00	1,808.10	361.62	1,446.48	L	Y	X 14
21 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	12/14
22 REAR BUMPER ADS STICKER	1.00	150.00	0.00	150.00	S	Y	12/14
23 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	200/14 Xun
24 REAR BUMPER RUBBER PROTECTOR PAD	1.00	150.00	0.00	150.00	S	Y	12/14
25 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X 14
26 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	12/14
27 FRONT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	12/14
28 REAR FENDER ADS STICKER LH	1.00	180.00	0.00	180.00	S	Y	12/14
29 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	12/14
TOTAL:		10,474.77	884.96	8,589.81			

TOTAL PARTS & LABOUR : 14,274.77 1,884.96 12,389.81

EXCESS/LOADING:SS 0.00

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SS

DATE OF SURVEY: 5/10/18

SURVEYED BY: Taylor 9744544

CONTACT NO:

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Service Request Details

Claim

S8M00XV2

Reference

None

Loss Date

September 29, 2018

Request Date

October 3, 2018

Due Date

October 10, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

03/10/2018 @ 1013am
Alex veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHC7101K

Make

TPVD HYUNDAI

Model

I4-1.7 D CRDI (A)

Service Address

Primary Contact/Insured

CHOO HUAT AIK

33 MAYFLOWER ROAD, 568622, Singapore

98268040

huataik@gmail.com

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

SHC7101K - Finalize Amount & After Repair Photo & Question Mark Item Photo .

Taxis Customer Service to: taufikh, sur

Mon 08 Oct 2018 04:19 PM

Cc: ACCOUNTS, ADMIN, Carlor.chan, thinthin, vivianlau,
AsherSng, cs-a, admin-a

Bcc "kelly.ding@dingauto.sg"

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you.]

[We encourage everyone to do his / her part in helping to preserve the environment. Kindly refrain from printing this email unless it is absolutely necessary.]

Dear Taufikh ,

Please see below for the finalize according to our conversion to finalize for SHC7101K
AFTER PAINT PHOTO & Question Mark Item In Estimate NO.8&16 .

Finalize Amount
Total Repair - 05 Days

Lump Sum

Labour - \$1230
Special Netts - \$735
Parts after 20% discount = \$1873.84
Total L+P+S = \$3838.84- 20% Lump sum
Final Amount = \$3071.07

Please help to close this case ASAP

Thanks

Best Regards
Ding Automotive Pte Ltd
Alex Khong
Hp : 62657130 / 83039588

NOTE !!!

All mailed letter & cheque payment is to be mailed to our main
office address :

BLOCK 10 #01-20

SIN MING INDUSTRIAL EST. SEC C

SINGAPORE 575645

        
AF 3.JPG AF 1.JPG AF 2.JPG AF 6.JPG AF 4.JPG AF 5.JPG RQ 7.JPG RQ 6.JPG RQ 5.JPG

   
RQ 4.JPG RQ 3.JPG RQ 2.JPG RQ 1.JPG

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please

12/24/2018

Ding Auto Mail - 50111003/SHC7101K ON 29/09/2018-FINALIZE CONFIRMATION REMINDER



ESTIMATE SHC7101K.pdf
62K

Mon, Dec 10, 2018 at 11:18 AM

Dd hashim <dd.hashim@dingauto.sg>

To: shupeil@lkkauto.com

Cc: Taufikh@lkkauto.com, Joylrene@lkkauto.com, admin-a@lkkauto.com, SUR <sur@lkkauto.com>, CS A Team <cs-a@lkkauto.com>, Kenneth Ding <kenneth.ding@dingauto.sg>, Kelly Ding <kelly.ding@dingauto.sg>, Ding Ding Auto <ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, taxiscs@stengg.com

Dear Shupeil,

Noted on your reply.

HAVE A GREAT DAY TO YOU AHEAD.

SINCERELY

DD HASHIM

+6581160811

(Quoted text hidden)

Wed, Dec 19, 2018 at 5:33 PM

Admin@Ding Automotive <admin@dingautomotive.com.sg>

To: Dd hashim <dd.hashim@dingauto.sg>, shupeil@lkkauto.com

Cc: Taufikh@lkkauto.com, Joylrene@lkkauto.com, admin-a@lkkauto.com, SUR <sur@lkkauto.com>, CS A Team <cs-a@lkkauto.com>, Kelly Ding <kelly.ding@dingauto.sg>, Ding Ding Auto <ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, taxiscs@stengg.com

Dear Shu Pei,

Good day to you.

Please let us have your finalize amount for this case as soon as possible.

Thank you.

Best Regards,

Kenneth Ding

HP: 92313123

Fax: 6452 0614

From: Dd hashim [mailto:dd.hashim@dingauto.sg]

Sent: Monday, December 10, 2018 11:19 AM

To: shupeil@lkkauto.com

Cc: Admin A <admin-a@lkkauto.com>, Joylrene@lkkauto.com; admin-a@lkkauto.com; SUR; CS A Team; Kenneth Ding; Kelly Ding; Ding Ding Auto; Accounts Ding Auto; taxiscs@stengg.com

Subject: Re: FW: 50111003/SHC7101K ON 29/09/2018-FINALIZE CONFIRMATION REMINDER

(Quoted text hidden)

Virus-free. www.avast.com

Fri, Dec 21, 2018 at 2:44 PM

Dd hashim <dd.hashim@dingauto.sg>

To: Taufikh@lkkauto.com

Cc: Admin A <admin-a@lkkauto.com>, SUR <sur@lkkauto.com>, CS A Team <cs-a@lkkauto.com>, Kenneth Ding <kenneth.ding@dingauto.sg>, Kelly Ding <kelly.ding@dingauto.sg>, Ding Ding Auto <ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, taxiscs@stengg.com

DING AUTOMOTIVE PTE LTD

Dear Taufikh,

As spoken please look for this finalize and confirm the amount as soon as possible.

We are unable to submit our claim as finalize amount still pending on your side.

HAVE A GREAT DAY TO YOU AHEAD.

SINCERELY

DD HASHIM

+6581160811

Virus-free. www.avast.com

(Quoted text hidden)

Mon, Dec 24, 2018 at 10:26 AM

Taufikh (LKKAuto) <Taufikh@lkkauto.com>

To: Dd hashim <dd.hashim@dingauto.sg>

Cc: Admin A <admin-a@lkkauto.com>, SUR <sur@lkkauto.com>, CS A Team <cs-a@lkkauto.com>, Kenneth Ding <kenneth.ding@dingauto.sg>, Kelly Ding <kelly.ding@dingauto.sg>, Ding Ding Auto <ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, taxiscs@stengg.com <taxiscs@stengg.com>, Joy Irene (LKKAuto) <Joylrene@lkkauto.com>

Hi Dd,

https://mail.google.com/mail/u/0?ik=6c54d92244&view=pt&search=all&permthid=thread-a%3Ar-6439177539649817162&simpl=msg-a%3Ar3705... 2/3

12/24/2018

Ding Auto Mail - 50111003/SHC7101K ON 29/09/2018-FINALIZE CONFIRMATION REMINDER

COR lumpsum \$3050 , 5 days.

Regards

Taufikh

Lkk Auto

From: Dd hashim [mailto:dd.hashim@dingauto.sg]
Sent: Friday, 21 December 2018 2:44 PM
To: Taufikh@lkkauto.com
Cc: Admin A; SUR; CS A Team; Kenneth Ding; Kelly Ding; Ding Ding Auto; taxiscs@stengg.com
Subject: Re: 50111003/SHC7101K ON 29/09/2018-FINALIZE CONFIRMATION REMINDER

[Quoted text hidden]

Mon, Dec 24, 2018 at 10:40 AM

Dd hashim <dd.hashim@dingauto.sg>
To: "Taufikh (LKKAuto)" <Taufikh@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>, SUR <sur@lkkauto.com>, CS A Team <cs-a@lkkauto.com>, Kenneth Ding <kenneth.ding@dingauto.sg>, Kelly Ding <kelly.ding@dingauto.sg>, Ding Ding Auto <ding@dingauto.sg>, Accounts Ding Auto <accounts@dingauto.sg>, "taxiscs@stengg.com" <taxiscs@stengg.com>, "Joy Irene (LKKAuto)" <JoyIrene@lkkauto.com>

Good Morning.

Dear Taufikh,

We are agreed with the finalize amount at \$3050 with 5 day repair.

Please close on your side and we will submit our claim to the officer.

Thanks.
HAVE A GREAT DAY TO YOU AHEAD.
SINCERELY
DD HASHIM
+6581168811

[Quoted text hidden]

Date Issued : 12/10/2017

CERTIFICATE REF.: MZ400A

CERTIFICATE OF INSURANCE (MASTER)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE NO.	D-18088937MFSH
Index Mark and Registration Number of Vehicle	All CityCab taxis operating in the Republic of Singapore.
Name of Insured	CityCab Pte Ltd
Coverage	Third Party Fire and Theft
Effective date of the Commencement of Insurance for the purpose of the Act	01/01/2018
Date of Expiry of Insurance	31/12/2020

Persons or Classes of Persons entitled to drive

- a) Any licensed taxi driver driving on the Insured's order or with their permission.
- b) Any person provided he is in the Insured's employ and is driving on their order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use:

- Use as a taxi.
- Use for social, domestic and pleasure purposes.

The Policy does not cover


- (1) Use for racing, pace-making, reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

Excess: All Claims \$2,000.00 each and every accident

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

First Capital Insurance Limited
(Approved Insurers)


Authorised Signature

A/C NO.: B0101

DING AUTOMOTIVE PTE LTD**Blk 10 Sin Ming Industrial Estate Sector C****#01-20****Singapore 575645****Tel: 6452 1208 Fax: 6452 0614**

TO :

FAX NO:

ESTIMATE REPORT

1ST Quotation

04/10/2018 10:51

JOB-NO: 50111003

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7101K

TRANS: AUTO

CHASSIS: KMHLB41UMGU092440

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDGU661313

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00	Y		500
2 SUNDRIES	1.00	80.00	0.00	80.00	Y		30
3 RUST PROOFING	1.00	120.00	0.00	120.00	Y		X
4 R&R SPARE TYRE BOARD/ CARPET/ TRIM	1.00	150.00	0.00	150.00	Y		40
5 ALIGNMENT BOOTLID	1.00	100.00	0.00	100.00	Y		X
6 R&R RADIATOR & TURBO INTERCOOLER	1.00	150.00	0.00	150.00	Y		X
7 R&R AIR-COND CONDENSER & TOP UP GAS (R134A)	1.00	150.00	0.00	150.00	Y		X
8 R&R FRONT SUPPORT PANEL	1.00	200.00	0.00	200.00	Y		X
9 TO RESETTING AND RECODING HEAD LAMP & DIAGNOSTIC (CLEAR FAULT CODE)	1.00	180.00	0.00	180.00	Y		X
10 R&R REVERSE SENSOR	1.00	60.00	0.00	60.00	Y		30
11 RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	Y		300
12 RESPRAY REAR BUMPER DIFFUSER	1.00	200.00	0.00	200.00	Y		100
13 RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	Y		X
14 RESPRAY REVERSE SENSOR	1.00	60.00	0.00	60.00	Y		30
15 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00	Y		200
TOTAL:		3,800.00	0.00	3,800.00			

MATERIALS

1 REAR BUMPER	1.00	559.90	111.98	447.92	L	Y	10
2 REAR BUMPER DIFFUSER	1.00	218.40	43.68	174.72	L	Y	unt
3 REAR BUMPER RETAINER LH	1.00	48.63	9.73	38.90	L	Y	?
4 REAR BUMPER RETAINER RH	1.00	48.63	9.73	38.90	L	Y	?
5 REAR BUMPER REINFORCEMENT	1.00	488.40	97.68	390.72	L	Y	?
6 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	85.63	17.13	68.50	L	Y	?
7 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	85.63	17.13	68.50	L	Y	?
8 REAR BUMPER REINFORCEMENT SPONGE	1.00	89.63	17.93	71.70	L	Y	?
9 REAR END PANEL	1.00	629.95	125.99	503.96	L	Y	X
10 FRONT BUMPER	1.00	599.88	119.94	479.74	L	Y	Ry
11 FRONT BUMPER RETAINER LH	1.00	42.32	8.46	33.86	L	Y	?
12 FRONT BUMPER RETAINER RH	1.00	42.32	8.46	33.86	L	Y	?
13 FRONT BUMPER RADIATOR GRILLE	1.00	1,110.10	222.02	888.08	L	Y	col
14 FRONT BUMPER RADIATOR GRILLE LOGO	1.00	142.84	28.57	114.27	L	Y	100
15 FRONT BUMPER RADIATOR GRILLE CHROME	1.00	121.77	24.35	97.42	L	Y	Cns

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 FRONT BUMPER REINFORCEMENT SPONGE	1.00	99.66	19.93	79.73	L	Y	?
17 FRONT BUMPER REINFORCEMENT	1.00	432.21	86.44	345.77	L	Y	?
18 FRONT SUPPORT PANEL	1.00	962.87	192.57	770.30	L	Y	X
19 HEADLAMP LH	1.00	1,808.10	361.62	1,446.48	L	Y	X
20 HEADLAMP RH	1.00	1,808.10	361.62	1,446.48	L	Y	X
21 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	no
22 REAR BUMPER ADS STICKER	1.00	150.00	0.00	150.00	S	Y	no
23 REAR BUMPER REVERSE SENSOR SET	1.00	230.00	0.00	230.00	S	Y	200?
24 REAR BUMPER RUBBER PROTECTOR PAD	1.00	150.00	0.00	150.00	S	Y	no
25 REAR END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X
26 FRONT BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	no X
27 FRONT NUMBER PLATE	1.00	40.00	0.00	40.00	S	Y	at
28 REAR FENDER ADS STICKER LH	1.00	180.00	0.00	180.00	S	Y	no
29 REAR FENDER ADS STICKER RH	1.00	180.00	0.00	180.00	S	Y	no
TOTAL:		10,474.77	884.96	8,589.81			

TOTAL PARTS & LABOUR:

14,274.77 1,884.96 12,389.81

EXCESS/LOADING:\$ 0.00

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 5 / 10 / 18

SURVEYED BY: Taylor 97495449

for
sur @ (Kalamo) com.

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

Labor \$ 1230
 SIN \$ 735
 Parts \$ 1873.84
 HSTP \$ 3838.84 - 20% lump sum
 total \$ 3071.07 #



redefining / insurance

Without Prejudice
to our driver's Injury Claim

CLAIM REF : S8M00XV2
INSURED : CHPP HUAT AIK

DISCHARGE VOUCHER

We/I CITYCAB PTE LTD CO REG NO. 199502839G hereby agree to accept the sum of dollars [THREE THOUSAND SEVEN HUNDRED FORTY FIVE ONLY.] (\$\$ 3,745.00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SLW 5939X] as a result of an accident along [THOMSON ROAD] on [29/09/2018] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SHC 7101K]

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SLW 5939X] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SLW 5939X]

Dated this 05 day of 03 2019

Claimant's Signature : CITYCAB PTE LTD

NRIC no./ Company Stamp : CO REG NO. 199502839G

Occupation/ Business :

Address :

Telephone No. :

Witness's Name :

Witness's Signature :

Witness's NRIC No. :



DD HASHIM

[Signature]

G8537451L

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)
8 Shenton Way, #24-01 AXA Tower, Singapore 068811
Customer Centre #B1-01
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg



Pls proceed DS with quantum as proposed

Type

🔔 Question

Message

No suspicious element between OI & TP veh.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 08/10/2018

Survey Details:

Date of loss	29-Sep-18
Date of appointment	3-Oct-18
Date of survey	5-Oct-18
Location of survey	DING AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 7101K
Make and Model	HYUNDAI I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Date of registration	21/7/2016
Excess	
Market Value	\$0
Part Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 12,389.81
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,608.84
Check items (estimate)	
Labour	\$ 1,230.00
Total	\$ 3,838.84
Lump Sum(if applicable)	\$ 3,050.00

Number of days for repair	5
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs. Malaysian vehicle involved 2nd in line (chain collision) TP 3RD IN LINE. OI LAST VEHICLE.

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	3,263.50	
Loss of use	\$	-	
Loss of rental	\$	557.35	5 x \$111.47
Loss of income	\$	250.00	5 x \$50
LTA search fees	\$	-	
Others	\$	-	
Proposed Total	\$	4,070.85	

6 OCT '18 13:19

Satisfaction Voucher

Date: 06/10/2018

MS First Capital Insurance Limited

Attention: MOTOR CLAIMS DEPT

Dear Sir/Madam

IG HOCK LYE

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHC7101K

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number D-18088937MFSH

reference claim number 50111003 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 29/09/2018

at ALONG THOMSON ROAD TOWARDS

Dated this day of _____, 201 _____

Signature: IG

NRIC No: S1655722F

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0

Company Stamp if applicable

DING AUTOMOTIVE PTE LTD

Business Reg. No : 201619222G
BLK 10, #01-20 SIN MING IND EST. SEC C, SINGAPORE 575645
Tel: 6452 1208 Fax: 6452 0614

TAX INVOICE

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01, AXA TOWER
SINGAPORE 068811

ATTN : MOTOR CLAIMS DEPARTMENT
TEL : FAX :

INVOICE : I-000562
DATE : 05/03/2019
GST REG NO : 201619222G
TERMS : C.O.D.
PO NO : SLW5939X
OUR REF : SHC7101K
PAGE : 1 of 1

ITEM NO.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1.	COST OF CLAIM-ALL IN COR,LOR,LOI&3RD PARTY SEARCH FEE	1	3,500.00	3,500.00
REMARKS : 50111003 TP CLAIMS AGAINST SLW5939X UNDER AXA INSURANCE OIC:MS JOY D.O.A:29.09.2018		SUB TOTAL	:	3,500.00
		GST	:	245.00
		TOTAL SGD	:	3,745.00
		DEPOSIT	:	
		O/S BALANCE	:	

FOR DING AUTOMOTIVE PTE LTD

Authorised Signature

Customer Signature

I have inspected and hereby confirmed that
the job done and the amount due herein
are entire to my satisfaction

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLW 5939X (Insd veh)	Model:	HYUNDAI I40
	SHC 7101K (TP veh)		
Date of Accident:	29/09/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	13,257.10
Final Repair Cost	:	\$	3,263.50
Loss of Token Sum	:	\$	150.00
Rental (if any)	:	\$	334.41
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	3,745.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability ____ 100 ____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: ____
BOLA Liability: ____ (%)	Assessed Liability (*): ____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	DING AUTOMOTIVE PTE LTD	:	\$ 3,745.00

NUR SHAQILAH BTE ABDOL
WAHAB

12/03/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18017915/T1jb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 12-03-2019



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLW 5939X	Veh. Inspected	SHC 7101K
Policy No.	VPA/P2090692	Coverage (\$)	0.00
Claim No.	S8M00XV2	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	03/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU092440	Colour	YELLOW
Odometer	370576	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	TRIANGLE	6 mm
L/H Front Tyre	205/60R16	TRIANGLE	6 mm
R/H Rear Tyre	205/60R16	TRIANGLE	6 mm
L/H Rear Tyre	205/60R16	TRIANGLE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/09/2018	Inspection Date	05/10/2018
Survey held at	31 CORPORATION RD		
Repairer	DING AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7101K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	559.90	559.90
1	REAR BUMPER DIFFUSER (CONSISTENT)	CUT	218.40	218.40
1	REAR BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	48.63	-
1	REAR BUMPER RETAINER RH (CONSISTENT)	NOT NECESSARY	48.63	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	488.40	-
1	REAR BUMPER REINFORCEMENT BRACKET LH (CONSISTENT)	NOT NECESSARY	85.63	-
1	REAR BUMPER REINFORCEMENT BRACKET RH (CONSISTENT)	NOT NECESSARY	85.63	-
1	REAR BUMPER REINFORCEMENT SPONGE (CONSISTENT)	DEFORMED	89.63	89.63
1	REAR END PANEL (CONSISTENT)	NOT NECESSARY	629.95	-
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	599.68	-
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NOT NECESSARY	42.32	-
1	FRONT BUMPER RETAINER RH (CONSISTENT)	NOT NECESSARY	42.32	-
1	FRONT BUMPER RADIATOR GRILLE (CONSISTENT)	CRACKED	1,110.10	1,110.10
1	FRONT BUMPER RADIATOR GRILLE LOGO (CONSISTENT)	NECESSARY	142.84	142.84
1	FRONT BUMPER RADIATOR GRILLE CHROME (CONSISTENT)	CRACKED	121.77	121.77
1	FRONT BUMPER REINFORCEMENT SPONGE (CONSISTENT)	DEFORMED	99.66	99.66
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	432.21	-
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	962.87	-
1	HEADLAMP LH (CONSISTENT)	NOT NECESSARY	1,808.10	-
1	HEADLAMP RH (CONSISTENT)	NOT NECESSARY	1,808.10	-
	LESS 20% DISCOUNT		-1,884.96	-468.46
			7,539.81	1,873.84
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	REAR BUMPER ADS STICKER (SN) (CONSISTENT)	NECESSARY	150.00	150.00

Report Ref No. CC4/ASM18017915/T1jb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	230.00	-
1	REAR BUMPER RUBBER PROTECTOR PAD (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CUT	40.00	40.00
1	REAR FENDER ADS STICKER LH (SN) (CONSISTENT)	NECESSARY	180.00	180.00
1	REAR FENDER ADS STICKER RH (SN) (CONSISTENT)	NECESSARY	180.00	180.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	80.00	30.00
			1,130.00	765.00
	LABOUR			
	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER. RUST PROOFING.		1,600.00	500.00
	R&R SPARE TYRE BOARD / CARPET / TRIM.	NOT NECESSARY	120.00	-
	ALIGNMENT BOOTLID.		150.00	40.00
	R&R RADIATOR & TURBO INTERCOOLER.	NOT NECESSARY	100.00	-
	R&R AIR-COND CONDENSER & TOP UP GAS (R134A).	NOT NECESSARY	150.00	-
	R&R FRONT SUPPORT PANEL.	NOT NECESSARY	150.00	-
	TO RESETTING AND RECODING HEAD LAMP & DIAGNOSTIC (CLEAR FAULT CODE)	NOT NECESSARY	200.00	-
	R&R REVERSE SENSOR.		180.00	-
	RESpray REAR BUMPER.		60.00	30.00
	RESpray REAR BUMPER DIFFUSER.		250.00	300.00
	RESpray REAR END PANEL.	NOT NECESSARY	200.00	100.00
	RESpray REVERSE SENSOR.		250.00	-
	RESpray FRONT BUMPER.		60.00	30.00
			250.00	200.00
			-	-
			-	-
			-	-
			3,720.00	1,200.00
	GRAND TOTAL		12,389.81	3,838.84

Report Ref No. CC4/ASM18017915/T1jb3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,050.00
---	--	--	----------

Report Ref No. CC4/ASM18017915/T1jb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.