



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CRAWFORD & COMPANY INTERNATIONAL PL

Ref : CS/CWF18017982/R1sbs2

NO.8 SHENTON WAY
#03-01 AXA TOWERS SINGAPORE 068811

Date : 18-01-2019



Code : CWF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	UNKNOWN VEHICLE	Veh. Inspected	SKZ 3A
Policy No.		Coverage (\$)	0.00
Claim No.	1089965/SSK	Excess (\$)	0.00
Assign From	SOH SOON KIAT	Assign Date	03/10/2018

2. Vehicle Particulars & Condition

Make & Model	LAMBORGHINI HURACAN	c.c	5204
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZHWEC1ZF2GLA04127	Colour	ORANGE
Odometer	016000	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/30ZR20	PIRELLI	6 mm
L/H Front Tyre	245/30ZR20	PIRELLI	6 mm
R/H Rear Tyre	245/30ZR20	PIRELLI	6 mm
L/H Rear Tyre	245/30ZR20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	Inspection Date	19/10/2018
Survey held at	24 LENG KEE RD #01-03	
Repairer	EUROSPORTS AUTO PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------