



Repair Estimate

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
AIG Building
#07-16
Singapore (079120)

Client,
LEE KENG MENG

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East
#05-155, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.carcrafters.sg

Date : 4-Oct-2018

Vehicle Num : SLL5243C

Make/Model : AUDI A5 2.0 SPORTBACK

Chassis No : WAUZZZ8T5AA071042

S/N	PARTS	QTY	PRICE	TOTAL
1	FRONT BUMPER	1 PC	\$ 1,115.00	\$ 1,115.00
2	FRONT BUMPER GUIDE PIECE RH	1 PC	\$ 25.00	\$ 25.00
3	COOLING AIR GRILLE WITH CHROME RH	1 PC	\$ 135.00	\$ 135.00
4	HEADLAMP RH	1 PC	\$ 1,475.00	\$ 1,475.00
5	HEADLAMP MOUNTING RH	1 PC	\$ 80.00	\$ 80.00
6	FRONT FENDER RH	1 PC	\$ 650.00	\$ 650.00
7	HEADLAMP WASHER COVER	1 PC	\$ 35.00	\$ 35.00
8	HEADLAMP FLAT BRACKET RH	1 PC	\$ 50.00	\$ 50.00
	TOTAL PARTS			\$ 3,565.00
	LABOUR			
1	To remove/ replace/ refit & panel beat of front portion of front bumper, front fender RH, headlamp RH & other affected area			\$ 1,000.00
2	To putty & respray front bumper, front fender RH & other affected area			\$ 800.00
3	To check accident affected wiring system & recover.			\$ 50.00
4	To recode & decode engine management system & fault code clearing after repair works.			\$ 100.00
	TOTAL			\$ 5,515.00
	GST 7%			\$ 386.05
	GRAND TOTAL			\$ 5,901.05