

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Joel Goh

Date: 10 Oct 2018

## Preliminary Advice

Vehicle No	: SKT9575M	Accident Date	: 01/10/2018
Make	: AUDI A6	Policy No.	: DMPPHQ18-001013
Assignment Date	: 05/10/2018	Excess	: S\$0.00
Date of Inspection	: 05/10/2018	Est. Duration of Repair	: 5 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road Singapore 609286		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,099.55
Revised Amount	:S\$	5,873.65
Check Items (Estimated)	:S\$	723.35
Total	:S\$	6,597.00
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	67,000.00
COE / PARF Rebate	:S\$	53,368.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,632.00

### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.  
Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE AUTHORISED REPAIR.