

RS AUTOMOTIVE PTE LTD

Workshop : Blk 3006 Ubi Road 1 #01-394 Singapore 408700
Mailing : 109 Pasir Ris Grove, #09-23 The Palette Singapore 518199
Tel No. : 67483032 Fax No. : 67499469
E-Mail : rsautomotive@yahoo.com.sg
Website : www.rsautomotive.com.sg
Tax Reg. No. : 201230654Z Buss. Reg. No. : 201230654Z

TRINA TAN

Works Order : WO002372

Contact : 96181893

Date Printed : 10/10/2018
Vehicle Num. : SJN 5681 J
Make/Model : TOYOTA CAMRY
Mileage(Km) :
P.O./R.O No. :
Ref./Remark :

S/N	Quantity	Particular	Unit Price	Amount S\$
				<i>Rsc 25%</i>
1.	1PC	FRONT BUMPER <i>At</i>	496.12	496.12 <i>✓</i>
2.	1PC	FENDER RH <i>Bue</i>	520.05	520.05 <i>✓</i>
3.	1PC	REAR RH WHEEL HOUSING GANISH	178.00	178.00
4.	2PCS	SPORT RIMS RH FRONT AND REAR <i>} Repair. x</i>	280.00	560.00
5.	1PC	REAR BUMPER	542.13	542.13
COMPUTERIZED FOUR WHEEL ALIGNMENT			<i>60</i>	120.00
LABOUR CHARGE TO REPLACE ABOVE ITEMS JOB			<i>300</i>	380.00
TO RESPRAY PAINT FRONT BUMPER, RH FRONT FENDER, RH REAR FENDER AND REAR BUMPER JOB			<i>700</i>	800.00

5 Days.

Impsum repair.

After repair photos.

*Guo Qiang - 8288 0282 20%: 1450
1500*

10/6.17

25%: 762.13

1872.13

10/10/18

SingDollars : Three Thousand Eight Hundred Forty-Eight & Cents Four Only

E. & O.E.

Total S\$: 3,596.30
GST @ 7% S\$: 251.74
Amount Due S\$: 3,848.04
=====

Terms : Cash

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Customer's Signature: _____
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

RS AUTOMOTIVE PTE LTD