

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

05 OCT 2018

E S T I M A T E

Estimate No. : b1 48678		Page No. : 1 of 5	
Date Estimated : 05/10/2018			
Prepared By : Gary Poh Chai Hoon			

- ESTIMATE REPAIR FOR - Chua Ngia Nghee (Cai Yayi) 47 West Coast Grove Singapore 127858	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1823D	0X01160	29/06/2017	X3 sDrive20	0

DESCRIPTION	VALUE
To replace rear bumper and attachment include knocking cause by the accident .	850 1,700.00
Painting rear bumper	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1:	2,995.00

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER CARRIER ECE	1	738.05	? 738.05
FLAP TOWING EYE REAR	1	35.95	X 35.95
RR LH BUMPER MIDDLE MOUNTING	1	137.75	? 137.75
RR RH BUMPER MIDDLE MOUNTING	1	137.75	? 137.75
RR BUMPER LH MOUNT	1	192.15	? 192.15
RR BUMPER RH MOUNT	1	192.15	? 192.15
COVER MIDDLE BOTTOM	1	68.70	? 68.70
CLADDING BUMPER REAR (PDC/SCHWARZ)	1	197.35	cut 197.35
REAR BUMPER PANEL PRIMED (PDC)	1	1,409.45	cut 1,409.45
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	? 20.20
BUMPER PDC SENSOR (SCHWARZ)	4	236.85	? 947.40
Total Parts :			4,076.90



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 48678**
Date Estimated : **05/10/2018**
Prepared By : **Gary Poh Chai Hoon**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1823D	0X01160	29/06/2017	X3 sDrive20	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/10/18 @ 1330 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 9006068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY Yes / No _____ BY SURVEYOR Yes / No _____ BY Yes / No _____

Surveyor's E-mail _____

No. of Working Days 3 days

Labour 1	:	2,995.00
Parts	:	4,076.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	495.03
Grand Total	:	7,566.93

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **