LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd To:

6 Temasek Boulevard 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park #18-01 Suntec Tower 4 Singapore 038986 Singapore 408933

Attn: Josey Loh Date: 11 Oct 2018

Preliminary Advice

Accident Date Vehicle No : SLJ9239A : 03/10/2018 : PNPV2018-Make : AUDI A3 Policy No.

00008681

Assignment Date : 10/10/2018 : S\$500.00 **Excess** Est. Duration of Repair Date of Inspection : 10/10/2018 : 3.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

> 55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,699.00
Revised Amount	:S\$	3,575.00
Check Items (Estimated)	:S\$	1,292.00
Total	:S\$	4,867.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 92.000.00 COE / PARF Rebate :S\$ 51,683.00

Salvage Value :S\$

Margin for Repair :S\$ 40,317.00

Remarks

()	()	let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :