

\* Surveyor:

WMH

DOI:

ASSIGNMENT

21/10/18

Date / Time:

9-10-18

Registered in Maritimes:

9-10-18

\* Pre-assign / CCU / FTE



Insured Vehicle No.:

SFJ 1680 G

Claim No.:

Name of Insured:

Tay Soo Leng

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II : \$5

D.O.A: 8/10/2018

Place of Accident:

Marine Parade Rd

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SGM 998 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

pm



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

12/10

WMH

SGM 998 U - 25/10/18 16:00 / 20/10/18 16:00 ; 20/10/18 16:00  
SFJ 1680 G. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 20-2-19

Confirm with: CAEDUNE

Confirm by: (M1)

Repair Cost:

PP \$5,108.05

( 5 days)

Reduction:

34 %

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 13-3-19

Confirm with: CAEDUNE

Email ☒Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

ML

If NO or B 28, Ass. Lia:

Repair Cost:

6/10/18 \$5,556.61

Loss of Rental (LOR):

\$5

( days)

Loss of Use (LOU):

\$5,000.00

(\$100 x 5 days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search:

\$50.00

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5,031.61

Global Sum \$5:

FINAL PAYMENT

Date/Time: 13-3-19

Confirm with: CAEDUNE

Email ☒Call ☐

Payee 1:

\$5,031.61

Name 1:

REPAIRMATE MOTOR LIMITED

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: T1

3) Survey fee: 9320 + 920

18/3/19

183371 11w 16w

The U/C / Chassis frame / Body Structure affected due to collision

Name and ID: \_\_\_\_\_

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. L97401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

118, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 OCT 2018

## ESTIMATE

Estimate No. : b1 48706  
Date Estimated : 08/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Selvan S/O Sothandara Kumaran  
19 Shelford Road  
#01-40

Singapore 288408

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM998U	D284965	26/03/2014	528iA	0

## DESCRIPTION

To replace front right side panel, front right wheelarch &  
all attachments cause by accident.  
To repair on front right door & bumper panel

Painting on front right side panel, front right door &  
front bumper

To check electrical wiring systems at the front section  
for proper function.

To carry out body cavity preservation.  
(Per panel). FRT RH side panel

Sundries. *NH*

## VALUE

*2425* 3,400.00  
*1700*

*2826* 2,808.00  
*1730*

*150* 177.00

*600* 118.00

*800* 150.00

Total Labour 1: 6,653.00

## DESCRIPTION

FRT RH 2 SIDE PANEL BRACKET  
FRT RH 3 SIDE PANEL BRACKET  
FRT RH 4 SIDE PANEL BRACKET  
FRT RH 1 SIDE PANEL BRACKET  
FRT RH FENDER  
SET MOUNTS PDC SENSOR FRT (PDC)  
FRT BUMPER RH SPACER  
FRT BUMPER PANEL PRIMED (PDC)  
FINISHER SIDE PANEL FRT RH  
FRT RH COVER F REAR WHEELHOUSE  
FRT RH WHEEL ARCH COVER

QTY	PRIC	VALUE
1	32.15	32.15
1	32.15	32.15
1	32.15	32.15
1	32.15	32.15
1	863.35	863.35
1	58.60	58.60
1	9.45	9.45
1	1,277.55	1,277.55
1	75.15	75.15
1	128.20	128.20
1	128.20	128.20

*3* 32.15  
*3* 32.15  
*3* 32.15  
*3* 32.15  
*1* 863.35  
*1* 58.60  
*1* 9.45  
*1* 1,277.55  
*1* 75.15  
*1* 128.20  
*1* 128.20

Total Parts : 2,669.10

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

285, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 48706  
Date Estimated : 08/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM998U	D284965	26/03/2014	528ia	0

29/10/18 EWS  
Tambin  
97195749  
05 day

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,653.00
Parts	:	2,669.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	652.55
Grand Total	:	9,974.65

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-1



## SUPPLEMENTARY

Estimate No. : b1 48706  
Date Estimated : 08/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Selvan S/O Sothandara Kumaran  
19 Shelford Road  
#01-40

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 288408

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SGM998U	D284965	26/03/2014	528iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BMW EMBLEM *	69.50	1.00		69.50

Total Labour :	
Total Parts :	69.50
Total Labour & Parts :	69.50

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 48706  
Date Estimated : 08/10/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -  
Selvan S/O Sothandara Kumaran  
19 Shelford Road  
#01-40  
  
Singapore 288408

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SGM998U	D284965	26/03/2014	5281A	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, front RH fender and attachments include knocking out dents caused by the accident	1700.00		1,700.00	
To spray paint front RH fender and front bumper	1730.00		1,730.00	
To check electrical wiring systems at the front section for proper function.	150.00		150.00	
To carry out body cavity preservation, (Per panel)	100.00		100.00	
Sundries,	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH FENDER	863.35	1.00		863.35
FRT BUMPER RH SPACER	9.45	1.00		9.45
FRT BUMPER PANEL PRIMED (PDC)	1,277.55	1.00		1,277.55
# BMW EMBLEM *	69.50	1.00		69.50
FRT RH COVER F REAR WHEELHOUSE	128.20	1.00		128.20

### # SUPPLEMENTARY ITEMS

Total Labour :	3,760.00
Total Parts :	2,348.05
Total Labour & Parts :	6,108.05
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,108.05
GST @7%:	427.56
Grand Total :	6,535.61

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**AIG THIRD PARTY EXPRESS SETTLEMENT  
FOR ACCIDENTS ON OR AFTER 1<sup>ST</sup> JUNE 2008  
(PAYMENT BREAKDOWN)**

Vehicle No:	SM 9984	Model:	BMW
Date of Accident:	8/10/2018		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	9974.65
Final Repair Cost	: \$	6535.61
Loss of Use	: \$	5000
Rental (if any)	: \$	
LTA / GIA Search Fee	: \$	200
Others	: \$	
	: \$	
Final Settlement Sum	: \$	7037.61
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)		
A) For Non GIA Registered Workshop: Agreed Liability _____ (%)		
B) For GIA Registered Workshop: BOLA Application: Yes / No		
BOLA Scenario No: _____		
BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks		

Payment Instruction: Payee's Breakdown			
1)	Performance Motor Limited	: \$	6535.61
2)	Performance Motors Ltd	: \$	200
3)	Selvan S/O Sothandaram Kumaran	: \$	5000

Signed by appointed surveyor

Date

Please attach all the supporting documents to the form.

Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;

Survey Report; Medical Report / Bill (if any)



## Acknowledgement

Accident Involving SGM998U and SFT1680G on 08/10/2018


I, SELVAN S/O SOTHNDARA KUMARAN the owner of Vehicle Registration Number SGM998U, have been advised by Customer Service Adviser and understand the content of my motor claim as specify herein:

1. Type of claim: ☐ Claiming own-policy only.  
☐ Claiming own-policy and uninsured losses.  
☒ Direct settlement with 3<sup>rd</sup>-Party Insurer [Any reversion to own-policy claim shall be submitted to my insurer within **14 days** from date of accident as required by my Policy].
2. Performance Motors Limited being an appointed Approved Reporting Centre is bound by GIA not to induce, instigate, encourage or procure any owner or driver of any motor vehicle to engage the services of any solicitors to make any third party claims.
3. The estimated repair costs shall be subjected to insurer surveyors' finalisation on completion of job and after considering additional parts and/or labours discovered in the course of repair.
4. A compulsory policy excess \_\_\_\_\_, stated in the Motor Policy taken up by you, is applicable for own-damage claim.
5. **Loss of Use** and **Cost of Rental** shall be computed in accordance to the number of days as recommended by the surveyor and the Benchmark Rates published in State Courts Practice Directions for Non-injury Motor Accident (NIMA) Claims.
6. I am fully aware that Performance Motors Limited is assisting me in my claim against the third-party insurer. I shall release Performance Motors Limited against any liability, loss claim or proceedings which may arise out of or in the course of or by reasons of execution of the services.
7. In the event that my insurer or third party insurer is not prepared to settle the claim due to breach of policy or other reasons, I shall pay Performance Motors Limited the full repair bill.
8. A towing charge of \$195.00, administration fee of \$300.00 and storage fee \$50.00 per day is chargeable to me if my vehicle is not repaired by Performance Motors Limited.
9. The average time span to settle a claim is **6 months** or longer for complex cases. Any correspondence or status enquiry of the mentioned claim shall be directed to the under-mentioned personnel:

Name: Ms Caroline Tan  
Tel: 6319 0174  
email: [pmi-pbsp@sime-darby.com.sg](mailto:pmi-pbsp@sime-darby.com.sg)

10. Special Instructions:

Signed by:

  
Name: Selvan Sothndara Kumaran  
NRIC No.: S7237286  
Date: 8 October 2018



Reprint

PRIVATE CARS  
THE SCHEDULE

Agency A0000079	Class of Policy	MOTOR POLICY - PRIVATE	Policy No.	MPC18A00069102
Account A0000079	Issued on	07/02/2018	Replacing Policy No.	MPC17A00111501
Client 10001606	Acceptance Date	11/01/2018		
		Singapore Head Quarters		
			Fund/Acct.No.Sfx	SIF/SD

Period of Insurance from 26/03/2018 to 25/03/2019, both dates inclusive

Insured's Name	SELVAN S/O SOTHANDARA KUMARAN
Address	19 SHELFORD ROAD #01-40 SINGAPORE 268408

Business/Occupation FUND MANAGER

Premium	BASIC PREMIUM.....	SGD 2,144.10
	LOYALTY DISCOUNT.....	SGD 214.41
	NO CLAIM DISCOUNT.....50.00%	SGD 964.85
	Total Annual Premium	SGD 964.84
	Premium Due	SGD 964.84
	Premium GST	SGD 67.54
	Total Due	SGD 1,032.38

Risk Group No. 01

Risk No. 00001	PRIVATE CARS
	YEAR OF REGISTRATION : 03/2014

Registration	SGM998U	Make/Model	BMW 528I AT D/AB DSC LED NAV
Type of Cover	COMPREHENSIVE	No. of seats	5
Engine No.	A6100668N20B20A	Capacity CC	1997
Chassis No.	WBA5A52080D284965	Yr of Manuf/Regn	2013/2014
Vehicle Usage	MOTOR CARS - PRIVATE	NCD%	50.00
		Certificate Ref.	M2300

Item 1.

SUM INSURED: MARKET VALUE AT THE TIME OF LOSS

EXCESS APPLICABLE

WINDSCREEN

SGD 100.00

SECTION I - INSURED/NAMED DRIVER

SGD 1,000.00

ADDITIONAL EXCESS OTHER THAN NAMED DRIVERS:

SECTION I - AGE &gt;70 OR DRIVING EXP &lt;2 YEARS OLD

SGD 3,000.00

Subject to the following clauses/warranties/endorsements/memo attached hereto :-

FREE ROADSIDE ASSISTANCE (APPLICABLE TO COMPREHENSIVE POLICIES ONLY)

IT IS HEREBY NOTED AND AGREED THAT THIS POLICY IS EXTENDED TO PROVIDE ACCESS TO ROADSIDE ASSISTANCE THROUGH OUR

24/7 AUTO ASSISTANCE HOTLINE AT (+65) 9101 2323

IN SINGAPORE, THE ROADSIDE ASSISTANCE SERVICES WILL INCLUDE JUMP START, PETROL TOP-UP, FLAT TYRE REPLACEMENT, BATTERY REPLACEMENT AND TOWING. THE COST OF PETROL, TYRES AND BATTERY SHALL BE BORNE BY THE INSURED. IN WEST MALAYSIA, ONLY TOWING SERVICES WILL BE PROVIDED UP TO A LIMIT OF S\$300 PER POLICY PERIOD. THE COMPANY SHALL ONLY BE LIABLE FOR THE SERVICE FEE FOR ONE ROADSIDE ASSISTANCE PER PERIOD OF INSURANCE.

TOWING OR REPAIR OF ANY MOTORCYCLES AND COMMERCIAL REGISTERED VEHICLES SUCH AS BUT NOT LIMITED TO LORRIES, TRUCKS, WAGONS, TAXIS ETC IS EXCLUDED.

SUBJECT OTHERWISE TO THE TERMS, CONDITIONS AND EXCEPTIONS OF THE POLICY.

YOUNG, ELDERLY AND INEXPERIENCED UNNAMED DRIVERS EXCESS

NOTWITHSTANDING ANYTHING HEREIN CONTAINED TO THE CONTRARY IT IS HEREBY UNDERSTOOD AND AGREED THAT IN THE EVENT OF EACH AND EVERY LOSS ARISING UNDER SECTION I OF THIS POLICY A FURTHER EXCESS OF S\$3000 SHALL APPLY, IN ADDITION TO THE AMOUNT OF EXCESS STATED IN THE SCHEDULE, WHEN AT THE

HQ/JTX/38/MR00022479/08-10-2018/10:59:40/DLW2

Issued On 07/02/2018  
Singapore Head Quarters

Policy No. MPC18A00069102  
Replacing Pol No. MPC17A00111501

TIME OF AN ACCIDENT THE MOTOR VEHICLE IS DRIVEN BY:

(A) ANY UNNAMED AUTHORISED DRIVER, WHO IS ABOVE 70 YEARS OLD (AGE AS AT DATE OF ACCIDENT),  
AND/OR

(B) ANY UNNAMED AUTHORISED DRIVER, PERSON WHO HOLDS A QUALIFIED DRIVING LICENCE FOR LESS THAN 24  
MONTHS (REGARDLESS OF AGE)

SUBJECT OTHERWISE TO THE TERMS AND CONDITIONS OF THIS POLICY.

THE FOLLOWING ENDORSEMENTS SHALL APPLY TO THIS POLICY :

V0003, V0009, V0012, V0014, V0017

SUBJECT OTHERWISE TO THE TERMS, EXCEPTIONS AND CONDITIONS OF THIS POLICY.

Authorized Drivers for vehicle(s) with Certificate Ref.: MZ300

- a) The Insured and all Named Drivers declared under the policy
- b) Any other person who is driving on the Insured's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use for vehicle(s) with Certificate Ref.: MZ300

Use for social, domestic and pleasure purposes and for the Insured's business. The policy does not cover use for hire or reward, tuition, driving test, race, pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Driver Details for Policy MPC18A00069102 and Risk No. 00001 as follows:

Named Drivers	SEX	M/S	AGE	EXP	DIP	NRIC
SELVAN S/O SOTHANDARA KUMARAN	M	M	46	23	0	S7235126B
WAHIDA BEGUM SEVATHAMARICAR	F	M	46	24	0	S7247667J

Signed for and on behalf of ECICS Limited



AUTHORISED SIGNATORY

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S7235128B



Name

SELVAN S/O SOTHANDARA  
KUMARAN

Race

INDIAN

Date of birth

24-09-1972

Country/Place of birth

SINGAPORE

Sex

M

S7235128B



NRIC No. S7235128B

5278310



Date of issue

10-03-2014

Address

19 SHELFORD ROAD  
#01-40  
SINGAPORE 288408

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7235128B

Name

SELVAN S/O SOTHANDARA  
KUMARAN

Birth Date: 24 Sep 1972

Issue Date: 21 Jul 2003



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of  
which unladen does not exceed 2500 kilograms

09 Jun 1993



Licence No. S7235128B

NP 428A



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18018337/wa3

25 October 2018

**Tay Soo Leng**  
69 Jalan Tua Kong  
#05-09  
Singapore 457264

Dear Sir/Madam,

**ACCIDENT INVOLVING SFJ 1680G AND SGM 998U ON 08/10/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau  
Case Handler  
DID: 6841 8625  
FAX: 6741 4108  
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)


**AUTHORISATION TO ACT**  
**(AIG Express Third Party Claim)**

I, Selvan S/o Sothindara Kumaran (the third party claimant) of 19 Shelford Rd  
#01-40 Singapore 288408 (address), owner of SGM 998U (vehicle no.)  
hereby authorize Performance Motors Limited ("the workshop") to act for me  
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle  
no. SGM 998U that was damaged pursuant to the accident which occurred on 8/10/18  
(date) along Marine Parade Rd/Still Rd South Junction (location) involving vehicle no/s  
SFJ1680G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit  
and the workshop is further authorized to receive payment further to settlement of my claim with  
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without  
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other  
vehicle/s is concerned.

Dated this 2 (day) of November (month) 2018 (year)



Signed by "the third party claimant"  
(with chop if applicable)

  
KEVIN LEONG WAI KIT  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Signed by "the workshop"  
(with chop)

**RELEASE VOUCHER**  
**(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)**

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 6535.61 (repair costs), S\$ 500.00 (loss of use/rental) S\$ 2.00 (search fees) for vehicle no. SGM 9984 that was damaged pursuant to the accident which occurred on 8-10-18 (date) along Marine Parade Rd / Still Rd South Junction (location) involving vehicle no/s SFJ 1680 G.

This is pursuant to the inspection conducted on 29-10-2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Selvan S/o Sothadara Kumaran ("third party claimant") of vehicle no. SGM 9984 to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGM 9984 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 13 day of 03 (month) 2019 (year)



Signed by AIG appointed surveyor

PERFORMANCE MOTORS LIMITED  
303 Alexandra Road  
Singapore 159941  
TEL: 63190100 (Sales)  
63190111 (Admin)

Chopped & Signed by "the workshop"

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63448773315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

## SERVICE TAX INVOICE

Repair Order No. : B1 1310643	Page No. : 1 of 2
Date IN : 29/10/2018	Invoice Number : 2068086 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 21/02/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

## - CUSTOMER INFORMATION -

Mr Selvan S/O Sothandara Kumaran  
19 Shelford Road  
#01-40

Singapore 288408

## - INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

REGN. NO. SGM998U	CHASSIS NO. D284965	REGN. DATE 26/03/2014	MODEL 528IA	MILEAGE 124219
----------------------	------------------------	--------------------------	----------------	-------------------

## - - - - LABOUR 1 - - - -

To replace front bumper and front right fender etc including to remove and install body parts in order to carry out painting job.	1,700.00
To respray front bumper and front right fender.	1,730.00
To check electrical wiring systems at the front section for proper function.	150.00
To carry out body cavity preservation.	100.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 8.10.2018. 3RD PARTY CAR : SFJ1680G.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 29.10.2018 AT 2.45 PM.	
AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 23.10.2018 VIA E-MAIL.	
PROPOSE LOSS OF USE = \$100X5. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
GIA SEARCH FEE = \$2.00.	0.00

Total Labour 1: 3,760.00

## - - - - PARTS - - - -

	Qty	Retail Price	NETT
FRT RH FENDER	1	863.35	863.35
FRT BUMPER PANEL PRIMED (PDC)	1	1,277.55	1,277.55
FRT BUMPER RH SPACER	1	9.45	9.45
FRT RH COVER F REAR WHEELHOUSE	1	128.20	128.20
BMW EMBLEM	1	69.50	69.50

Total Parts : 2,348.05



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438182  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

**SERVICE TAX INVOICE**

Repair Order No. : <b>B1 1310643</b>	Page No. : <b>2 of 2</b>
Date IN : <b>29/10/2018</b>	Invoice Number : <b>2068086 / WSB</b>
Cust. Svc. Advisor: <b>Kevin Leong Wai Kit</b>	Invoice Date : <b>21/02/2019</b>
	Payment Terms : <b>30 Days From Invoice</b>
	Invoice By : <b>Sharon Heng</b>

Labour Charges : <b>3,680.00</b>	Total Labour & Parts Charges : <b>S\$ 6,108.05</b>
Parts Charges : <b>2,348.05</b>	Less Insurance Excess : <b>S\$ 0.00</b>
Lubricant/Misc : <b>80.00</b>	Invoice Total Amount Exclude GST : <b>S\$ 6,108.05</b>
	GST @ 7% : <b>S\$ 427.56</b>
	Invoice Total Amount Include GST : <b>S\$ 6,535.61</b>

Computer generated invoice. No signature is required.	Amount Payable Include GST : <b>S\$ 6,535.61</b>
---	--

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.







RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-155429

Date of Request: 08/10/2018

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/10/2018  
Enquiry By Melanie Setiawati  
TP Vehicle No. SFJ1680G  
Accident Date 08/10/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFJ1680G	AIG Asia Pacific Insurance Pte. Ltd.	22/05/2018-21/05/2020	65-6419-3000

Thank You,

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-155429

Date of Request: 08/10/2018

Your Ref No:

Online Purchase

Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941

Dear Sir/Madam,

Enquiry Date 08/10/2018  
Enquiry By Melanie Setiawati  
TP Vehicle No. SFJ1680G  
Accident Date 08/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Oct 2018 <a href="#">Edit Reg</a>		29 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,108.05</b> <a href="#">Edit Estimates</a>	<b>S\$6,108.05</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>TAY SOO LENG</b> , ID: S74359151								
Main Claimant:	<b>SELVAN S/O SOTHNDARA KUMARAN</b> , ID: S72351288								
Vehicle Reg. No.:	<b>SGM998U</b>	Date of Loss:	08/10/2018 07:00 - :59 [54 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 7670093715SG</b>	Policy/Cover Note No.:	1800065407 (Comprehensive) Coverage: 22/05/2018 - 21/05/2020						
Vehicle Reg. No. (Insured):	<b>SFJ1680G</b>	Policy No. (Claimant):	MPC18A00069102						
		Excess:							
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Foo, Chit Yan</b> ] Chityan.Foo@aig.com								
Claimant's Insurer:	<b>ECICS Limited (HQ)</b> - Tel: 63374779 /6303 0178								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 18/10/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SGM998U (7670093715SG)  
[SFJ1680G]

TP

SELVAN S/O SOTHNDARA KUMARAN

Oct 8 2018 7:00AM

[TAY SOO LENG]

Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <div>View in Browser</div>		
Letters/Correspondences														1 per page		<div></div>	<div></div>
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown											1	Edit		
Photos/Images														3 per page		<div></div>	<div></div>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	13/03/19 17:02		Odometer Reading											1	Load JPG	<div></div>	
2	13/03/19 17:02		Chassis Number											1	Load JPG	<div></div>	
3	13/03/19 17:02		General View											1	Load JPG	<div></div>	
4	13/03/19 17:02		General View											1	Load JPG	<div></div>	
5	13/03/19 17:02		General View											1	Load JPG	<div></div>	
6	13/03/19 17:02		General View											1	Load JPG	<div></div>	
7	13/03/19 17:02		General View											1	Load JPG	<div></div>	
8	13/03/19 17:02		General View											1	Load JPG	<div></div>	
9	13/03/19 17:02		General View											1	Load JPG	<div></div>	
10	13/03/19 17:02		General View											1	Load JPG	<div></div>	
11	13/03/19 17:02		General View											1	Load JPG	<div></div>	
12	13/03/19 17:02		General View											1	Load JPG	<div></div>	
13	13/03/19 17:02		General View											1	Load JPG	<div></div>	
14	13/03/19 17:02		General View											1	Load JPG	<div></div>	
15	13/03/19 17:02		General View											1	Load JPG	<div></div>	
16	13/03/19 17:02		General View											1	Load JPG	<div></div>	
17	13/03/19 17:02		General View											1	Load JPG	<div></div>	
18	13/03/19 17:02		General View											1	Load JPG	<div></div>	
19	13/03/19 17:02		General View											1	Load JPG	<div></div>	
20	13/03/19 17:02		General View											1	Load JPG	<div></div>	
21	13/03/19 17:02		General View											1	Load JPG	<div></div>	
22	13/03/19 17:02		General View											1	Load JPG	<div></div>	
23	13/03/19 17:02		General View											1	Load JPG	<div></div>	
24	13/03/19 17:02		General View											1	Load JPG	<div></div>	
Documentation														1 per page		<div></div>	<div></div>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	09/10/18 19:16		TP ESTIMATE + TP GIA REPORT											1	Load PDF		
2	01/11/18 18:38		TP ESTIMATE - MARKED											1	Load PDF		
3	20/03/19 09:33		WORKSHOP INVOICE											1	Load PDF		
4	20/03/19 09:33		AUTHORISATION TO ACT FORM											1	Load PDF		
5	20/03/19 09:33		Release Voucher											1	Load PDF		
6	20/03/19 09:33		GIA SEARCH											1	Load PDF		
7	20/03/19 09:33		LETTER TO OI											1	Load PDF		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print	
1	10/10/18 09:22		OI GIA REPORT											1	Load PDF		

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SFJ1680G (Insd veh)	Model:	BMW 528i 2.0 (A)
	SGM998U (TP veh)		
Date of Accident:	08/10/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	10,049.01	
Final Repair Cost	:	\$	6,535.61	
Loss of Use	:	\$	500.00	5.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	7,037.61	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)		
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: <del>Yes</del> / No BOLA Scenario No: _____		
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Performance Motors Limited	:	\$	7,037.61
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

20 Mar  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18018337/T1EA3Q2  
Date: 20/03/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800065407  
Claimant Vehicle No: SGM998U Insured Vehicle No: SFJ1680G  
Date of Loss: 08/10/2018 Nature of Claim: TP Claim No: 7670093715SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGM998U  
Make & Model: BMW 528i, 2.0 (A) Engine No: A6100668N20B20A  
Reg. Date: 26/03/2014 (Man. Year: 2013) Chassis No: WBA5A52080D284965  
Colour: Grey Odometer: 124219 km  
Engine Capacity: 1997 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,888.60	2,428.05	460.55	15.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,503.00	3,680.00	2,823.00	43.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,391.60</b>	<b>6,108.05</b>	<b>3,283.55</b>	<b>34.96</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>657.41</b>	<b>427.56</b>	<b>229.85</b>	<b>34.96</b>
<b>Nett Amount (S\$)</b>	<b>10,049.01</b>	<b>6,535.61</b>	<b>3,513.40</b>	<b>34.96</b>
<b>+ Loss of Use (5.0 x S\$100.00/day) (S\$)</b>		<b>500.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>7,037.61</b>		

### INSPECTION

Date of Assignment: 29/10/2018  
Date Inspected: 29/10/2018 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941  
Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT RH 2 SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
3	1		*FRT RH 3 SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
4	1		*FRT RH 4 SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
5	1		*FRT RH 1 SIDE PANEL BRACKET	Not Necessary	32.15 FS	*- FS
6	1		*FRT RH FENDER	Bent	863.35 FS	*863.35 FS
7	1		*SET MOUNTS PDC SENSOR FRT (PDC)	Not Necessary	58.60 FS	*- FS
8	1		*FRT BUMPER RH SPACER	Necessary	9.45 FS	*9.45 FS
9	1		*FRT BUMPER PANEL PRIMED (PDC)	Deformed	1,277.55 FS	*1,277.55 FS
10	1		*FINISHER SIDE PANEL FRT RH	Not Necessary	75.15 FS	*- FS
11	1		*FRT RH COVER F REAR WHEELHOUSE	Cracked	128.20 FS	*128.20 FS
12	1		*FRT RH WHEEL ARCH COVER	Not Necessary	128.20 FS	*- FS
13	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
Total Parts (S\$)					2,888.60	2,428.05

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT RIGHT SIDE PANEL,FRONT RIGHT WHEELARCH & ALL ATTACHMENTS CAUSE BY ACCIDENT .TO REPAIR ON FRONT RIGHT DOOR & BUMPER PANEL	New	3,400.00	1,700.00
2	PAINTING ON FRONT RIGHT SIDE PANEL,FRONT RIGHT DOOR & FRONT BUMPER	New	2,808.00	1,730.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) .FRT RH SIDE PANEL	New	118.00	100.00
Gross Labour Cost (S\$)			6,503.00	3,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >