

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

08 OCT 2018

E S T I M A T E

Estimate No. : b1 48706
Date Estimated : 08/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Selvan S/O Sothandara Kumaran
19 Shelford Road
#01-40
Singapore 288408

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM998U	D284965	26/03/2014	528iA	0

DESCRIPTION

To replace front right side panel, front right wheelarch &
all attachments cause by accident.
To repair on front right door & bumper panel

VALUE
2125 3,400.00

Painting on front right side panel, front right door &
front bumper

2526 2,808.00

To check electrical wiring systems at the front section
for proper function.

150 177.00

To carry out body cavity preservation.
(Per panel). Frt RH side panel

600 118.00

Sundries.

? 150.00

Total Labour 1: **6,653.00**

DESCRIPTION

FRT RH 2 SIDE PANEL BRACKET
FRT RH 3 SIDE PANEL BRACKET
FRT RH 4 SIDE PANEL BRACKET
FRT RH 1 SIDE PANEL BRACKET
FRT RH FENDER
SET MOUNTS PDC SENSOR FRT (PDC)
FRT BUMPER RH SPACER
FRT BUMPER PANEL PRIMED (PDC)
FINISHER SIDE PANEL FRT RH
FRT RH COVER F REAR WHEELHOUSE
FRT RH WHEEL ARCH COVER

QTY	PRIC	VALUE
1	32.15	? 32.15
1	32.15	? 32.15
1	32.15	? 32.15
1	32.15	? 32.15
1	863.35	bf 863.35
1	58.60	na 58.60
1	9.45	ae 9.45
1	1,277.55	de 1,277.55
1	75.15	? 75.15
1	128.20	ce 128.20
1	128.20	? 128.20

Total Parts : **2,669.10**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 48706
Date Estimated : 08/10/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGM998U	D284965	26/03/2014	528iA	0

Claim: ☒ 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time: 09/10/18 Excess S\$ _____

Surveyor's Name: Tan Kim Sign: [Signature]

Surveyor's Tel: 97195719 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail: tan.kim@lkk.com.sg

No. of Working Days Recommend: 05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,653.00
Parts	:	2,669.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	652.55
Grand Total	:	<u>9,974.65</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **