

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

TP LCR
Joy.

09th OCTOBER 2018

2VW506100879

Accident date: 09th AUGUST 2018

Estimated repair cost for vehicle no: SLV4752D Toyota PRIUS '17

S/n	Qty	Items	U/price	Amount
1	1	Front head lamp -LH <i>crushed</i>		\$1,885.00 ✓ 1080
2	1	Front bumper <i>deformed</i>		\$1,050.00 ✓ 972
3	2	Front bumper side bracket LH <i>Angd</i>	\$121.00	\$242.00 121
4	1	Front bumper clips <i>per</i>		\$30.00 ✓
5	1	Front bumper fog lamp -LH <i>crushed</i>		\$385.00 ✓
6	1	Front bumper fog lamp cover-LH <i>new</i>		\$155.00 +
7	1	Front bumper reinforcement <i>new</i>		\$635.00 +
8	1	Front Fender -LH <i>dentled</i>		\$752.25 ✓
9	1	front fender inner garnish-LH <i>deformed</i>		\$127.20 ✓
10	4	front fender inner garnish clips <i>new</i>	\$12.90	\$51.60 30.
11	1	Front L/H Lower Arm		\$287.72 +
12	1	Front L/H Knuckle Arm		\$281.85 +
13	1	Front L/H Knuckle Arm Bearing		\$161.40 +
14	1	Front L/H Shock Absorber		\$381.20 +
16	1	Front L/H Door Side Mirror <i>Repair</i>		\$421.50 X.
17	1	front sport rim -LH <i>at</i>		\$600.00 200/500.
18	1	front tyre -LH <i>new</i>		\$450.00 +.

Subtotal :- \$7,896.72

349745

S.N. 200

262308

Labour charges

To remove & install cushion

\$120.00 x

tuff Kote

\$120.00 x

To wheel alignment computer

~~\$120.00~~ 80

To remove & re-fix front undercarriage

\$280.00 x

To Check Wiring System

~~\$60.00~~ 30

Panel beating

~~\$600.00~~ 400

Spray painting

~~\$600.00~~ 400

subtotal:- \$1,900.00

Total:- \$9,796.72

total: 3733.08

4/5: 2.8K ✓

OSDmgs.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: