

COMFORTDELGRO ENGINEERING PTE LTD

Date: 09.10.2018

REPAIR ESTIMATE

Time: 16:14:14

Page: 1

China Tai ping

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305223764
 REGN NO : SH 9329B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 09.10.2018 14:35
 ACCIDENT DATE : 09.10.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	553.00	20.00	442.40	/	Phd
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	/	cup
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	/	nc
0004	04-01-0103-0577-G	BOOTLID	1	2,174.90	20.00	1,739.92	/	Phd
0005	04-01-0103-0789-G	BOOTLID EMBLEM-HYUNDAI	1	35.90	20.00	28.72	/	nc
0006	04-01-0103-0787-G	BOOTLID EMBLEM-I40	1	27.80	20.00	22.24	/	nc
0007	04-01-0103-0786-G	BOOTLID EMBLEM-CRDI	1	27.80	20.00	22.24	/	nc
0008	04-01-0103-0800-G	BOOTLID EMBLEM-H	1	28.70	20.00	22.96	/	nc
0009	28-01-0103-0005-A	BOOTLID COMFORTDELGRO	1	20.00	2.00	20.00	/	nc
0010	28-01-0103-0006-A	BOOTLID 65521111	1	10.00	0.20	10.00	/	nc
0011	04-01-0103-1150-A	REAR BUMPER CHROME PLATE	1	50.00	0.02	50.00	/	nc
0012	09-01-9999-0068-A	REVERSE SENSOR	1	135.70	0.00	135.70	X	nc

SUB-TOTAL : 2,694.18

JOB NATURE

China Taiping

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305223764
 REGN NO : SH 9329B
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 09.10.2018 14:35
 ACCIDENT DATE : 09.10.2018

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 20-05 Rear Fender Adv.Sticker RH/LH	200.00	✓			
0001 20-05 Rear Bumper Adv.Sticker	100.00	✓			
0002 L PANEL BEATING	440.00	✓	400		
0003 23-502 SPRAYPAINT ON AFFECTED AREA	440.00	✓	400		
0004 20-00 TUFF COAT ON AFFECTED PARTS.	40.00	✓	20		
0005 L R/I REVERSE SENSOR	120.00	✓	30		
0006 20-05 BootLid Adv.Sticker	100.00	✓			

SUB-TOTAL : 1,440.00

TOTAL : 4,134.18

MVA NAME & SIGNATURE
 DATE :

SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1625/16
 Acknowledged by Repairer
 Signature:
 Date:

Kahlan LKK

9/10/18

3 Days

P/P

Before part photo