

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :8112 0307 Fax: 6481 5727 e-mail : ngsmotorsportpteltd@gmail.com

Reg No: 201812604N

08/10/2018

AIG

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 27/09/2018

VEH NO.: SJT5916B & SLW5760T

CLAIMS AGAINST SLW5760T (AIG)

*Not Authorized
V/Lmp &?
Rerun After Paint
4-5 days*

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Hyundai Avante

1	Rear Boot Lid		Br	\$	985.90	✓
1	Rear Boot Inner Lock		n	\$	118.30	X
1	Rear Bumper		Bu	\$	489.10	✓
1	Rear Bumper Sponge			\$	47.60	?
2	Rear Bumper Retainer RH/LH		Sn	\$	38.70	\$ 77.40 X
1	Rear Bumper Beam		CM	\$	270.00	✓
1	End Panel			\$	493.80	?
1	Trunk Rubber		Sn	\$	79.30	X
1	Rear End Garnish			\$	65.10	?
2	Taillamp RH/LH		Sn	\$	288.40	\$ 576.80 X
2	Boot Lamp RH/LH		Sn	\$	163.60	\$ 327.20 X
					\$ 3,530.50	
					Less 20%	\$ 706.10
					\$ 2,824.40	
1	RR Boot 'Badge' 'H'	S.Nett	na	\$	23.30	✓
1	RR Boot Emblem 'AVANTE'	S.Nett	na	\$	31.20	✓
1	RR Boot Emblem 'S'	S.Nett	na	\$	17.00	✓
1	Reverse Sensor	S.Nett	Shen	\$	280.00	2 or sm
15	Clips Rear Compartment	S.Nett		\$3.50	\$ 52.50	?

To remove all damaged part with all necessary component/attachment

Straighten chassis member, repair/reshape dented body panel..

Replace damaged part. Refit into position.

To spray paint replace/repair body part.

Check wiring & light function

\$ 1,200.00 ?

Any other parts which necessitate repair or renewal will incur additional charged.
Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

NGS MOTORSPORT PTE LTD

EVELYN NG

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 800.00 60d
\$ 50.00 20d
\$ 5,278.40