

INS. CASE OWNER:

CC 4, Bal 180 18424, R passy

INS. IDAC:

Kenneth

ASSIGNMENT
DOE: 15/14/18

Date/Time: 9-10-18

Registered in Merimen:

CCU / FIE

SLA 3378 T



Insured Vehicle No.:
Name of Insured: Wong Tui May.
Insured Tel No.:
Excess Sec II :SS
Is driver the owner? (YES / NO)

Claim No.:
Policy No.:
Make / Model:
Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; IF GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLK 7780K



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

12/10
CHH

SLK 7780K - X; SLA 33787 - X

STAGE DATE / PIC

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

27/14/18

OH OI came up from minor road.

Documentation Check List: Handler Typist

13/11/19
Khorchea

- sent off for to TR (S1,599.30)
Pending acceptance

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:

5/11/19
Khorchea

File pass to Mei Kuan to close file.

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: PIP SS 1,192.80 (2 days) Reduction: 2 %
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. 9.

Repair Cost: (w/loss) SS 1,276.30
Loss of Rental (LOR) (w/loss) SS 321.00 (2 days) x \$150

Loss of Use (LOU): SS - (\$ - x - days)
Loss of Income (LOI): SS - (\$ - x - days)

LOR only [checked] LOU only [] LOR + LOU [] LOR + LOI [] [Tick only one]

GIA/LTA Search SS 2.00
Medical: SS -
Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -
Total: SS 1,599.30 Global Sum SS:
1) Claim status: Normal/Reject/Private Settle
2) Report Format: TP
3) Survey fee: \$400

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: SS 1,599.30 Name 1: LAI HUAT (MENG KEE) MOTOR PTE LTD

Payee 2: SS - Name 2:

Handwritten signature/initials

REF: EDI

18420/14p - P

ASSIGNMENT

From: _____ Date: 15-10-2018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 7780K

at Workshop m/s: Lai Huet (Mary Kee)

of: Blk 160 Sin Ming Drive #04-01

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLK 7780K Yr Regn: 03, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Wagon

Make: Honda Odyssey C.C. 2356

Colour: M. White A/C: Insured / Std / NI / NA

Sp. Reading: 138412 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM RB 3850 PC 200 378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front: _____ Rear: _____

R/Bal: 8 mm R/Bal: 8 mm

L/Bal: 8 mm L/Bal: 8 mm

D.O.A: 3/10/18 D.O.I: 15/10/18

Survey held at: _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/10 File pass to Catherine

P/P \$1,192.80 (Road \$30/21)

Date/Time. File Pass to?

 : Preli. Report
 : Final Report

Date/Time. File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee

Transportation

) \$ + RE. \$

) Photo

) Other

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC4/EQ118018424/Kpa3

Date: 19/10/2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SLK 7780K


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.10.2018 at the premises of M/s Lai Huat (Meng Kee) Motor Pte Ltd - Sin Ming have the following to report:-

Workshop Estimate Amount	: S\$	<u>1,222.80</u>
Revised Estimate Amount	: S\$	<u>1,192.80</u>
"Check" Items Amount	: S\$	<u>-</u>
Total (Including Check Items)	: S\$	<u>1,192.80</u>
Market Value	: S\$	<u>-</u>
LTA Reimbursement Value	: S\$	<u>-</u>
Nett Value	: S\$	<u>-</u>

Description of Damage:

The vehicle sustained damages at the Rear O/S portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

来發 (明) 呖,) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST No EST0020415
Sodexo Kim Yew Pte Ltd

Page 1 of 1
Your ref TP-SLA 3376T EQ
Job No 69895
Our ref 18.10.08
Payment
Date 9/10/2018

Attn

Vehicle No SLK 7780K
Vehicle Model Honda Odyssey
Accident on 3/10/2018

Not Notwork
Resurvey B&paint
2 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts					
1.00	Pc	Rear bumper	440.00		440.00 ✓
1.00	Pc	Rear bumper reflector LH	32.00		32.00 ✓
Total amount of parts supplied - S\$472.00					
1.00		15% of parts supplied	70.80		70.80
Special nett item					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓
Labour & Misc					
1.00		To remove and renew above parts	200.00		200.00 ✓
1.00		To spray paint (Pearl paint)	280.00		280.00 250/ ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Sub Total 1,222.80
GST 7.00% 85.80
Total S\$ 1,308.40

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和快捷修理。此外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Hsiao Tong (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 29 October 2018 8:50 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: Finalisation - SLK 7780K / Honda Odyssey
Attachments: SLK 7780K-Est.pdf; IMG_9587.jpg; IMG_9588.jpg; IMG_9589.jpg; IMG_9590.jpg

Dear Hsiao Tong,

[CC4/EQI18018424/Kpa3](#)

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Sunday, 28 October 2018 9:51 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalisation - SLK 7780K / Honda Odyssey

Dear Sir

For your confirmation, please:

- Parts: \$ 472.00
 - 15%: \$ 70.80
 - SN: \$ 200.00
 - L&P: \$ 450.00
- Total: \$1,192.80 / 2 days**

Supporting document and photographs are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0020415
Sodexo Kim Yew Pte Ltd

Page: 1 of 1
Your ref.: TP-SLA 3378T EQ
Job No: 69895
Our ref: 18.10.08
Payment:
Date: 9/10/2018

Attn

Vehicle No SLK 7780K
Vehicle Model Honda Odyssey
Accident on 3/10/2018

Not Authorized
Respray B4 paint
2 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts.					
1.00	Pc	Rear bumper	440.00		440.00 ✓
1.00	Pc	Rear bumper reflector LH	32.00		32.00 ✓
Total amount of parts supplied - S\$472.00 ✓					
1.00		15% of parts supplied:	70.80		70.80 ✓
Special nett item.					
1.00	Set	Rear reversing sensor with installation	200.00		200.00 ✓
Labour & Misc.					
1.00		To remove and renew above parts	200.00		200.00 ✓
1.00		To spray paint (Pearl paint)	280.00		280.00 ^{25%}
					450
Sub-Total					1,222.80
GST 7.00%					85.60
Total					S\$ 1,308.40

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-153910
Date of Request: 04/10/2018

Your Ref No: Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 04/10/2018
Enquiry By Jenny Lim Lai Foong
TP Vehicle No. SLA3378T
Accident Date 03/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLA3378T	EQ Insurance Company Ltd	26/08/2018-25/08/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Niviṭha (LKK Auto)

From: Shu Pei (LKKAuto) <shupe@lkkauto.com>
Sent: Tuesday, 9 October 2018 2:08 PM
To: assignments
Subject: FW: Request for Survey (TP) - Your Ref: SLA3378T (EQ) / Our Ref: SLK 7780K (Date of Accident: 03.10.18)
Attachments: 09102018092529.pdf

2.30pm @ 9110 118
vehicle not in
person @ Jenny

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Tuesday, 9 October 2018 2:08 PM
To: Jenny Lim <jenny.lim@laihuat.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Request for Survey (TP) - Your Ref: SLA3378T (EQ) / Our Ref: SLK 7780K (Date of Accident: 03.10.18)

Without Prejudice

Dear Jenny

We will appoint LKK to handle this direct settlement.

Dear LKK

Please assist on the following.

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify

From: Jenny Lim [mailto:jenny.lim@laihuat.com.sg]

Sent: Tuesday, October 9, 2018 9:27 AM

To: EQI PRS

Subject: Request for Survey (TP) - Your Ref: SLA 3378T / Our Ref: SLK 7780K (Date of Accident: 03.10.18)

Dear Sir

We refer to the above matter.

Please can you arrange for survey of our client's vehicle no. SLK 7780K?

Supporting documents are enclosed for your reference.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 13 May 2019 4:14 PM
To: jenny.lim@laihuat.com.sg
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: SLK7780K & SLA3378T on 03/10/18 //LKK REF: CC4/EQ18018424/Kpa3

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 1,276.30
2. Loss of Rental (2days x \$150.00)(w/GST)	\$ 321.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 1,599.30

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity
160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722
Tel: 64538110 Fax: 64596267
UEN: 199407592C

Your Ref: SLA 3378T
Our Ref: SLK 7780K – 2018/JL

29 April 2019

EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110
Attention: Motor Claims

WITHOUT PREJUDICE

Dear Sir

ACCIDENT INVOLVING VEHICLE NOS. SLK 7780K AND SLA 3378T ON 03/10/2018 AT TAGORE ROAD

We refer to the above matter wherein your insured's vehicle no. SLA 3378T was involved in an accident with our client's vehicle no. SLK 7780K.

As the accident was caused by your insured's negligence, our client is now claiming for the following losses:

- Repair cost: \$1,276.30 (include GST)
- Rental cost: \$ 642.00 (3 days x \$200 per day + GST)
- GIA search fee: \$ 2.00
- Total: \$1,920.30**


Relevant documents in support of our client's claim are enclosed for your reference.

Please do not hesitate to contact Jenny Lim at telephone 64533757 or email jenny.lim@laihuat.com.sg should you need any additional information.

Meanwhile, we look forward to receiving your affirmative response soon enough.

Thank you.

Yours faithfully



LAI HUAT (MENG KEE) MOTOR PTE LTD

encs

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 30 October 2018 8:26 AM
To: 'DWSG167@YAHOO.COM.SG'
Subject: ACCIDENT INVOLVING SLA 3378T(EQ) AND SLK 7780K ON 03/10/2018

30 Oct 2018

Our Ref: CC4/EQ/18018424/Kpa3

MR WONG FUT MENG

ACCIDENT INVOLVING SLA 3378T(EQ) AND SLK 7780K ON 03/10/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from SLK 7780K against your insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as your vehicle turned out from minor road and collided with third party who was driving along the main road. Under Motor Accident Guide, vehicle turning into main road should exercise greater caution, We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORITY

To: Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722

Dear Sirs

ACCIDENT INVOLVING VEHICLE NOS: SLK 7780K & SLA 3378T ON 03/10/2018
AT TAGORE ROAD

This is to confirm that on 04/10/2018, I / We gave you instructions to repair my / our vehicle no. SLK 7780K which was damaged in the above accident.

In consideration of your agreement to repair my vehicle no. SLK 7780K, pay for my other expenses and to defer demanding for payment of the costs of repair which was damaged as a result of the above accident, I / We hereby authorise you and/or your solicitors as my / our representative to write, negotiate and settle the accident claim on my / our behalf against any party involved in the abovementioned accident.

I / We hereby undertake to co-operate with you and render you all the assistance (including having my / our vehicle re-inspected and being a witness at trial) that may be necessary for you to recover the cost of repairs and the loss of use to my / our vehicle. I / We further undertake to keep you informed at all times of any communication received from any party involved in the abovementioned accident.

I / We hereby confirm that by signing this Letter of Authority, I / We are not entitled in law to receive any payment. If a cheque is sent to me, I / We shall return the same to the sender as I am precluded in law from accepting any payment.

In the event of my / our claim against any party involved in the abovementioned accident being unsuccessful for any reason whatsoever, I / We shall bear the repair / excess cost payable to Lai Huat (Meng Kee) Motor Pte Ltd either by cash / cheque or claim against my / our insurance policy.

I / We hereby authorise the payment of my / our claim (including any or all medical related invoices / receipts) to be made directly to my / our representative, Lai Huat (Meng Kee) Motor Pte Ltd accordingly.

In relation to the personal and vehicle information collected or otherwise provided during the course of the claim process (including by way of recordings), I agree and consent that Lai Huat (Meng Kee) Motor Pte Ltd may use, disclose and process my personal data for the purpose of responding and administering all activities related to my insurance claim.

Yours faithfully

Signature:

A handwritten signature in black ink is written over a horizontal line. To the right of the signature is a circular stamp. The stamp contains the text 'SODEXO KIM YEW PTE LTD' around the perimeter and '199606507M' in the center.

Name: Sodexo Kim Yew Pte Ltd

NRIC No: UEN: 199606507M

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
 GST No: M2-0128609-3
 UEN: 199407592C

TAX INVOICE

EST No.: EST0020415
 Sodexo Kim Yew Pte Ltd

GST Reg No: M2-0128609-3
 Page: 1 of 1
 Number: INV0020790
 Your ref.: TP-SLA 3378T EQ
 Job No.: 69895
 Our ref: 18.10.08
 Payment:
 Date: 29/12/2018

Attn

Vehicle No: SLK 7780K
 Vehicle Model : Honda Odyssey
 Accident on ...: 3/10/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear bumper	440.00		440.00
1.00	Pc	Rear bumper reflector LH	32.00		32.00
Total amount of parts supplied - S\$472.00					
1.00		15% of parts supplied.	70.80		70.80
Special nett item:					
1.00	Set	Rear reversing sensor with installation	200.00		200.00
Labour & Misc:					
1.00		To remove and renew above parts	200.00		200.00
1.00		To spray paint (Pearl paint)	250.00		250.00
Sub-Total					1,192.80
GST 7.00%					83.50
Total					S\$ 1,276.30

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

POPULAR RENT A CAR PTE LTD
501 Gullermard Road Singapore 399840
Tel: 6742 8888 | Fax: 6743 3003
Co Reg No: 199608195Z
GST Reg No: 19-9608195-Z



Tax Invoice

Mr TING BOON HIN

BLK 603 HOUGANG AVE 4
#07-221
Singapore 530603

Attn: TING BOON HIN

Invoice No. : INV18100304
Invoice Date : 17/10/2018
Due Date : 17/10/2018
VHA No : R18100089
Sales ID : S002 ANNIE
Referral ID : LHMENGKEE

Description	Amount(S\$)
Rental for 3 Days @ S\$200.00 per day	600.00

Vehicle No : SJR8586K
Vehicle Description : HONDA ODYSSEY 2.4L AT SR
Rental Period : 15/10/2018 09:30 to 17/10/2018 16:30

Subtotal : S\$ 600.00
GST 7.0% : S\$ 42.00

Total amount payable : S\$ 642.00

IMPORTANT

- Please remit payment within 7 days from the due date.
- An interest of 1.5% per month will be levied on all overdue amounts.
- All Cheques must be made payable to **POPULAR RENT A CAR PTE LTD.**
- Please write the **vehicle** and **invoice** number on the reverse of your cheque.

This is a computer generated document. No signature is required.

POPULAR RENT A CAR PTE LTD
501 Guillemard Road Singapore 399840
Tel: 6742 8888 | Fax: 6743 3003
Co Reg No: 199608195Z
GST Reg No: 19-9608195-Z



VEHICLE RENTAL AGREEMENT

No. R18100089

Date: 13 Oct 2018

HIRER'S PARTICULARS

Name (as in I/C) : TING BOON HIN
NRIC/Passport No : S1806456A
Gender : Male
Address (Res) : BLK 603 HOUGANG AVE 4
#07-221
Singapore 530603
Driving Lic. No : S1806456A
Passing Date : 15/07/1988
Date of Birth : 05/09/1967
Res / Office Tel : 64664211 (OFFICE)
Mobile : +6597897662
Hirer is driver : Yes

DRIVER'S PARTICULARS

Name (as in I/C) : -
NRIC/Passport No : -
Gender : -
Address (Res) : -
Driving Lic. No : -
Passing Date : -
Date of Birth : -
Res / Office Tel : -
Mobile : -

ADDITIONAL DRIVER'S PARTICULARS

Name (as in I/C) : -
NRIC/Passport No : -
Gender : -
Address (Res) : -
Driving Lic. No : -
Passing Date : -
Date of Birth : -
Res / Office Tel : -
Mobile : -

VEHICLE PARTICULARS

Vehicle No : SJR8586K
Make & Model : HONDA ODYSSEY 2.4L AT
SR
Date & Time Out : 15 Oct 2018 | 09:30
Hire Period Expiry : 17 Oct 2018 | 16:30
CDW (Collision Damage Waiver) : No
Malaysia Usage : No
Excess : 4280 | M'sia -

PAYMENT

Daily: 3 days x 200.00

Weekly

Monthly

CDW

Delivery/Collection Service

Others

SUB TOTAL

GST

NETT AMOUNT

SECURITY DEPOSIT

Payment Mode : Cash

Bank : -

Expiry : -

I.D. : -

Rented out by : ANNIE LOH

Sales ID : 5002

AMOUNT

600.00

0.00

0.00

0.00

0.00

0.00

600.00

42.00

642.00

0.00

IMPORTANT

1. Only persons above 23 & below 60 years of age with more than 2 years driving experience, authorised, licensed and signing this agreement may drive the vehicle.
2. The hirer shall be liable for excess charges for any late return at the rate shown per hour or per day, inclusive of CDW and/or PAI where applicable.
3. Vehicle is strictly for singapore use only, and may not be driven out of Singapore without prior written consent of the company Popular Rent A Car Pte Ltd.
4. In case of accident, the hirer shall report to rental office IMMEDIATELY. If there is any bodily injury, a police report must be made within 24 hours.

24-HOUR ROAD SIDE ASSISTANCE 67415828

Acknowledgement

I have read and agree to the terms and conditions of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given Popular Rent A Car Pte Ltd in connection with this agreement is true.


Hirer's Signature

Main Driver's
Signature


Rented out by
Staff Name: ANNIE
LOH

Third Party Insurer Enquiry

Our Ref No: GR-18-153910
Date of Request: 04/10/2018

Your Ref No: Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 04/10/2018
Enquiry By Jenny Lim Lai Foong
TP Vehicle No. SLA3378T
Accident Date 03/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLA3378T	EQ Insurance Company Ltd	26/08/2018-25/08/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL
INSURANCE
ASSOCIATION**

RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-153910

Date of Request: 04/10/2018

Your Ref No:

Online Purchase

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive #04-01
Sin Ming AutoCity
Singapore 575722

Dear Sir/Madam,

Enquiry Date 04/10/2018

Enquiry By Jenny Lim Lai Foong

TP Vehicle No. SLA3378T

Accident Date 03/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

GIRO Cash Cheque



To : M/s EQ INSURANCE COMPANY LTD

Date: 20/08/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SLA 3378T (Insd Veh)	Your Ref. No. : DMPPHQ18-004537
	SLK 7780K (TP Veh)	Our Ref. No. : CC4/EQI18018424/Kpa3q2
Date of Accident	3/10/2018	

Liability	100%	
Final Repair Cost	: \$ 1,276.30	
Loss of Use	: \$	days
Rental (If any)	: \$ 321.00	2 days
Others:	: \$ 2.00	
	: \$	
	1,599.30	
Final Settlement Sum	: \$ 1,599.30	
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	LAI HUAT (MENG KEE) MOTOR PTE LTD	: \$ 1,599.30
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18018424/Kpa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 20-08-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLA 3378T	Veh. Inspected	SLK 7780K
Policy No.	DMPPHQ18-004537	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOEL	Assign Date	09/10/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY (A)	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMRB38509C200378	Colour	METALLIC WHITE
Odometer	138412	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	MAXXIS	8 mm
L/H Front Tyre	215/55 R17	MAXXIS	8 mm
R/H Rear Tyre	215/55 R17	MAXXIS	8 mm
L/H Rear Tyre	215/55 R17	MAXXIS	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/10/2018	Inspection Date	15/10/2018
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 7780K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (WCP)	BUCKLED	440.00	440.00
1	REAR BUMPER REFLECTOR LH (WCP)	CRACKED	32.00	32.00
	COST PLUS 15%		70.80	70.80
			542.80	542.80
SPECIAL NETT ITEMS				
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	DENTED	200.00	200.00
			200.00	200.00
LABOUR				
	TO REMOVE AND RENEW ABOVE PARTS.		200.00	200.00
	TO SPRAY PAINT (PEARL PAINT).		280.00	250.00
			480.00	450.00
GRAND TOTAL			1,222.80	1,192.80
RECOMMENDED COST OF REPAIRS				1,192.80

Report Ref No. CC4/EQ118018424/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Tuesday, 20 August 2019 4:04 PM
To: 'Joel Goh'
Cc: 'chewht@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving SLA 3378T (OI) and SLK 7780K (TP) on 03/10/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933