MS. CASE OWNER	WILLIAM	c 4 / Am 180	1847/	AJON 5 9 LXX	74310
Sarveyor	Adrun	DOI: ASSIGNA	TENT	Date/Time	10-10-18.
Pre-assign / CCU Insured Vehicle No Name of Insured Insured Tel No. Excess See II :SS Is driver the owner	SLQ 170  LW JIAM  HP.  D.O.	9 T work Jacob e: 9-10-18 e of Accident:	Claim No. Policy No. Make / Model Place of Accide		00 Ym1
If NO, Driver Ner Driver Tell	No. :	(V/L: (ES)/NÖ)	Of GIA REPOR	rt: ES/NO; TP GIA RI y: % Final	EPORT (FE) NO
5774946	<u></u>				
INSRS: WSP Tel: Liability: RMKS:	INSRS: WSP. Tel Liability: RMKS:		TNSRS: WSP: Tel: Liability: RMKS:		NSRS: VSP: Cd: Jability: UMKS:
Date/ Time	Cast at all A	1.015487	Y	STAGE	DATE/PIC
my	31110100	Marked F.		Non-Reporting ltr (1st): Non-Reporting ltr (2nd):	MILITA
12/10/16	Called, OD, My Lin Setails inform TP Hery to Rear, TP OS 901 photo. ewa	reported 3 web	dwy aa-kol	Non-Reporting ltr (Final): Notification ltr (if non-pickus Call Of: After call ltr to OI: Documentation Check List	COLY DUAL     COLO     Bandler Typist
6/2/19 -	DS-Pun cer	111 (CHO- 40 02		Notification ltr (if non-picker After call ltr to CII: Authorisation To Act:	
8/2/10 -	fle-SMK to	dok.		Release Voucher: Fmal Repair Bill: Car Rental Invoice:	
	6			Towing Invoice  LTA / GIA :  Medical Bill	
				Mandate/Reject Instruction	
PRELIMINARY ADVICE	Date/Time:	Sent By:		Payment Breakdown Form Post-Repair Photos: Others:	
FINALIZATION Repair Cost:	10111	Confirm with: sys) Reduction:	%	Confirm by	Call
FINAL SETTLEMENT Final Liability: Repair Cost. UGH Loss of Rental (LOR):	\$ 20517 - 2 8	m with Nova >8 and BOLA S/N No. : >8		IFRO or B 28, Ass. Lin:  OND INVOLVED IN	
Loss of Use (LOU): Loss of Income (LOI): LOR only LOU only	SS-12-0. 00 (3 &0 xq d	ays) ays)		1012	19
GIA/LTA Search Medical:	58 2.00			1) Claim status: Nem 1/R.	tiect/Private Settle
Disbursement: Legal Cost	SS —	(e.g. Tow/ Independent	)	2) Report Format:	757-4
Total:		al Sum SS:		1	
FINAL PAYMENT		irm with:		Email Pall	
Payee 1: Payee 2: (Strike if N.A.)	55 21299.38 Name		1 stiding on	PHE UTO	
Payer 3 (Sinke if N.A.)	\$\$ Pus				
The second second second					

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

## Estimated Labour Charges for Accident Vehicle. SJY 4646 K

S/n	Nature of Jobs			Charges Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	/
2	To dismantle and renew front bumper. Re- organise front crash management components. Reinstall all parts removed.		\$	900,000	· 1ºRO
3	To respray front bumper.		s	800,00 15 5/	P00
	TOTAL LABOUR CHARGES - FRONT	:	\$	2,060.00	

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

## Estimated Labour Charges for Accident Vehicle. SJY 4646 k.

S/N	Nature of Jobs			Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N	s	280.00 🗸
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	S	280.00 🥕
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	s	480.00 M 489
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panelling.re-organize rear crash management components. Reinstall all parts removed.		Š	3,600.00 1250
5	To respray rear bumper, rear lid and end panelling . To carry out joint sealant work and stone chip treatment.		\$	2,500.00 /650
6	To carry out diagnostic check.	S/N	S	192.00
	TOTAL LABOUR CHARGES - REAR		\$	7,332.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

### Material List for Accident Vehicle Regn No. SJY 4646 K

S/N	Parts Description			Damage Parts & Prices S/Nett
1	REAR BUMPER Vistanted		\$	1,621.00 / 1621
2	REAR BUMPER FIXING PARTS My		\$	195.00 2 563
3	REAR BUMPER CARRIER BLAT		5	
4	REAR BUMPER HOLDER BRACKET-LH/RH	2	\$	382.00 383.00
5	REAR BUMPER SPOILER Sel-d		5	333.00 - 3,37.50
6	REAR BUMPER GUIDE SECTION-LH/RH	2	\$	75.00 A
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2	Ś	39.00 -
8	REAR BUMPER TRIM Delad		\$	222.00 - 37/.3
9	REAR BUMPER SECURING STRIP New New		\$	11.00
10	REAR LID Per Briefeld.		\$	1,923.00
11	REAR LID ATTACHMENT PARTS AND MA		\$	133.00 🚽
12	REAR LID HINGE-LH/RH 7	2	\$	496.00 A
13	REAR LID GASKET FLAP Me Com		\$	176.00 +
14	REAR LID TOP BUFFER	5	\$	57.00 A
15	REAR LID LOCK		Ś	190.00+
16	REAR LID LOCK COVER		\$	17.00,4
17	REAR LID LOCK STRIKER		\$	44.00 %
18	REAR LID PUSH BUTTON FOR ELECTRIC		\$	159.00 ₹
19	REAR LID STOP BUFFER, ADJUSTABLE	2	\$	48.00 *
20	REAR LID STOP BUFFER CAP	2	\$	13.00 ⊀.
	SUB-TOTAL PARTS CHARGES - REAR		\$	6,697.00

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

## Material List for Accident Vehicle Regn No. SJY 4646 K .

S/N	Parts Description		Damage Parts & S/Nett	Prices
21 22	PACKING ADHESIVE MAL	s s	29.00	58-40 107-50
23 24	REAR CROSS PANEL TRIM	s	344.00 + 160.00 +	
25 26	LUGGAGE COMPARTMENT, FLOOR COVERING And on	\$	618.00 ± 321.00	321-00
27 28	REAR CROSS PANEL-OUTER 7 DEACH	s	9.00 +	765-00
29 30	REAR BUMPER REINFORCEMENT BEAT	s	765.00 ×	180-00
31	CAVITY WAX THOUSE NEW S/N	s	180.00	1800.00
33 34	FRONT NO. PLATE AND SINCE STATE AND	\$	180.00 / 25.00 -	22.00
35 36	SUNDRIES THE SAME SON	5	500.00	D.cc
	Materials frt/rr : Labour charges frt/rr :	\$	9,392.00	
	Total frt/rr :	\$	25,379.00	

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

**Authorised Date** 

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after agray painting
- To display dismaged part(s) during resurvey
- . Parts prices are subject to confirmation
- \* Third party survey is on a "Without Philipudice" basis
- \* No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

: we Anthorised, 08 Days.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

#### Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

#### Supplementary Estimate 1

SST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept Tel: 6880 4602 - Fax 6880 4838 Estimate No.

PA/TP/1160/2018/GW

Date

6-Dec-18 Jeffery Tan Service Advisor

Pages

Regn No Model No SJY 4646 K Audi A4 1.8 TFSI

101, 0000 4	002 - 1 8x 0000 4030					1
Quantity	Description		8	A	mount	
<u>Parts</u>						
1	REINFORCEMENT BEAM BOLT	s	38.00		450.50	1
3	REAR CROSS PANEL TRIM DE -	5	160.00	2	159.50	
3	REAR PARKING AID SENSOR	\$	392.00	\$	392.00	-
4	TEMP. SENSOR BRACKET Cruled	\$	16.00	\$	15.60	
	TOTAL		606.00	s	567.10	ŀ
	TOTAL	- 3	000.00	2	307.10	£ .

For Premium Automobiles Pte Ltd

Authorised Signature

#### > Back to OneMotoring

#### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company Owner ID: 7503W

Vehicle Details

Vehicle No.: 5JY4646K Vehicle to be Exported: Na Intended Deregistration Date: 30 Nov 2018

Vehicle Make: AUDI

A4 1.8T FSI MU S-LINE CVT ABS D/AB HID Vehicle Model: Primary Colour:

White Manufacturing Year: 2008 CDH026741 Engine No.:

WAUZZZ8K99A128135 Chassis No: Maximum Power Output: 118.0 kW (158 bhp) Open Market Value: \$38,931.00

Original Registration Date: 25 Nov 2008 25 Nav 2008 First Registration Date: Transfer Count: 2

Actual ARF Paid: \$38,931.00

Intended PARF Rebate Details

PARF Eligibility: Yes PARF Eligibility Expiry Date: 24 Nov 2018 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 24 Nov 2023 / COE Category: E-Open Category COE Period[Years]: \$16,061.00 POP Paid:

COE Rebate Amount: \$16,007.00 \$16,007.00 Total Rebate Amount:

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Nov 2018

Message

OK

1/1

MV HOK ALS-PV:16K ALS-30K not more than 2ft

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email. Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate

: Accident Repairs

Workshop

: Ubi Road 1

Contact No

: 6386 2323

Fax No

: 6841 1183

Reference

: PA/TP/1160/2018/GW

Date

11-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SLQ 6709 T

AXA Insurance Singapore Pte Ltd

B Shenton Way #27-01 AXA Tower Singapore 068811

Hi Adrian 8 days - ok - jb - 28 Jan 19

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name

Alatas Singapore Pte Ltd

Address

1 International Business Park

#03-01E, Synergy

Singapore 609917

Telephone

: HP +65 997360225

Type of Claim

Third Party Claims

Policy No.

5077402437-02

Vehicle No

SJY 4646 K

Model Code

: Audi A4 1.8 TFSI

Model / Year

: Nov-08

Engine No

: CDH026741

Chassis No.

WAUZZZ8K99A128135

Mileage

Date In

Liability

Excess Cost

Estimated By

: Johnny Boo / Allan Wu

Accident Date

: 9-Oct-18

Place of Accident

: Along Road 1 Pan Island Expressway

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

#### Estimated Labour Charges for Accident Vehicle. SJY 4646 K

S/n	Nature of Jobs			Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	s	360.00	\$ 360.00
2	To dismantle and renew front bumper. Re- organise front crash management components. Reinstall all parts removed.		\$	900.00	\$ 600.00
3	To respray front bumper.		s	800.00	\$ 600.00
	TOTAL LABOUR CHARGES - FRONT	:	\$	2,060.00	\$ 1,560.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

#### Material List for Accident Vehicle Regn No. SJY 4646 K

S/N	Parts Description			Damaged P S/Nett	arts &	Prices
-1	FRONT BUMPER		s	2,394.00	s	2,394.00
2	FRONT BUMPER FIXING PARTS		\$	222.00		
3	FRONT BUMPER GUIDE SECTION-LH/RH	2	\$	74.00		
4	FRONT BUMPER SECURING STRIP	2	\$	60.00		
5	FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE		\$	167.00		
6	FRONT BUMPER PULL STRAP-LOWER		\$	44.00		
7	FRONT BUMPER SPOILER-LOWER		\$	292.00	\$	291.50
8	FOAM FILLER PIECE		5	107.00		
9	FRONT BUMPER SIDE REINFORCEMENT		\$	770.00		
10	FRONT BUMPER SUPPORT-LH/RH	2	s	48.00		
11	FRONT BUMPER VENT GRILLE-LH/RH	2	\$	236.00		
12	FRONT BUMPER COVER		\$	84.00		
13	RADIAOTOR GRILLE		\$	595.00	\$	595.00
14	RADIAOTOR GRILLE COVER		\$	50.00		
	TOTAL PARTS CHARGES - FRONT		\$	5,143.00	\$	3,280.50
	TOTAL LABOUR CHARGES - FRONT		\$	2,060.00	\$	1,560.00
	GRAND TOTAL PARTS AND LABOUR - FRONT	9	\$	7,203.00	\$	4,840.50

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

## Premium Automobiles 55 Ubi Road 1, Singapore 408899

Tel: 6366 2323 Fax: 6841 1183

#### Telefax

#### Estimated Labour Charges for Accident Vehicle. SJY 4646 k.

S/N	Nature of Jobs		Estimated Charges		
	labour front c/f			s	1,560.00
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	\$	280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N	\$ 280.00	s	280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$ 480.00	s	480.00
4	To dismantle and renew rear bumper and rear lid. To cut out and reweld end panelling.re-organize rear crash management components. Reinstall all parts removed. (Rear lid, rear panel inner/outer repalced)  Axa rate - \$600.00 per day		\$ 3,600.00	\$	3,000.00
5	To respray rear bumper, rear lid and end panelling . To carry out joint sealant work and stone chip treatment.		\$ 2,500.00	\$	2,000.00
6	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES - REAR	:	\$ 7,332.00	\$	7,792.00

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

#### Material List for Accident Vehicle Regn No. SJY 4646 K

S/N	Parts Description		Damage Pa	rts &	Prices
City	Materials front	c/f	S. M. S.	\$	3,280.50
1	REAR BUMPER		\$ 1,621.00	\$	1,621.00
2	REAR BUMPER FIXING PARTS		\$ 195.00		
3	REAR BUMPER CARRIER		\$ 563.00	\$	563.00
:4	REAR BUMPER HOLDER BRACKET-LH/RH	2	\$ 382.00	5	382.00
5	REAR BUMPER SPOILER		\$ 333.00	\$	332.50
6	REAR BUMPER GUIDE SECTION-LH/RH	2	\$ 75.00		
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2	\$ 39.00		
8	REAR BUMPER TRIM		\$ 222.00	\$	221.50
9	REAR BUMPER SECURING STRIP		\$ 11.00	\$	11.00
10	REAR LID		\$ 1,923.00	\$	1,923.00
11	REAR LID ATTACHMENT PARTS		\$ 133.00		
12	REAR LID HINGE-LH/RH	2	\$ 496.00		
13	REAR LID GASKET FLAP		\$ 176.00		
14	REAR LID TOP BUFFER	5	\$ 57.00		
15	REAR LID LOCK		\$ 190.00		
16	REAR LID LOCK COVER		\$ 17.00		
17	REAR LID LOCK STRIKER		\$ 44.00		
18	REAR LID PUSH BUTTON FOR ELECTRIC		\$ 159.00		
19	REAR LID STOP BUFFER, ADJUSTABLE	2	\$ 48.00		
20	REAR LID STOP BUFFER CAP	2	\$ 13.00		
	SUB-TOTAL PARTS CHARGES - REAR	3	\$ 6,697.00	\$	8,334.50

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

#### Material List for Accident Vehicle Regn No. SJY 4646 K.

S/N	Parts Description		Damage Pa S/Nett	rts 8	Prices
		c/f		s	8,334.50
21	PACKING ADHESIVE		\$ 29.00	\$	28.90
22	AUDI EMBLEM		\$ 108.00	\$	107.50
23	REAR LID TRIM PANEL		\$ 344.00		
24	REAR CROSS PANEL TRIM		\$ 160.00		
25	LUGGAGE COMPARTMENT, FLOOR COVERING		\$ 618.00		
26	TAILIGHT-LH		\$ 321.00	\$	321.00
27	TAILIGHT BULB-LH	2	\$ 9.00		
28	REAR CROSS PANEL-OUTER		\$ 275.00	S	275.00
29	REAR CROSS PANEL-LOWER		\$ 765.00	\$	765.00
30	REAR BUMPER REINFORCEMENT		\$ 468.00	S	467.50
31	ACYLIC SEALANT	S/N	\$ 180.00	\$	180.00
32	CAVITY WAX	S/N	\$ 140.00	\$	140.00
33	STONE CHIP	S/N	\$ 180.00	\$	180.00
34	FRONT NO. PLATE	S/N	\$ 25.00	\$	25.00
35	REAR NO. PLATE	S/N	\$ 25.00	\$	25.00
36	Added parts - see attached		\$ 606.00	\$	567.10
37	SUNDRIES		\$ 500.00	5	22.60
	Materials frt/rr	8	\$ 16,593.00	\$	11,439.10
	Labour charges frt/rr	18	\$ 9,392.00	\$	7,792.00
	Total frt/rr	10	\$ 25,985.00	\$	19,231.10

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

#### Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

#### Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

#### Supplementary Estimate 1

GST Reg No. 19-9902271-W

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Estimate No.	PA/TP/1160/2018/GW
Date	6-Dec-18
Service Advisor	Jeffery Tan
Pages	1
Regn No	SJY 4646 K
Model No	Audi A4 1.8 TFSI

Quantity	Description		8	Amount
Parts 1	REINFORCEMENT BEAM BOLT	s	38.00	_
2 REAR PARKING AID SENSOR TEMP. SENSOR BRACKET		\$	392.00 16.00	
	TOTAL	s	446.00	

For Premium Automobiles Pte Ltd

Lâ

Authorised Signature

#### Hsiao Tong (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Monday, 7 January 2019 11:05 AM

To:

CS A Team; Admin A; Hsiao Tong (LKKAuto); glory.tan@premiumauto.com.sg

Cc:

SUR

Subject:

FW: Check item photos for SJY 4646 K

Attachments:

WhatsApp Image 2018-12-05 at 11.28.19 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.21 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.21 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.22 AM. (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.22 AM. (2).jpeg; WhatsApp Image 2018-12-05 at 11.28.22 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.23 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.24 AM. (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.25 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.24 AM. (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.24 AM. (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.25 AM.jpeg; WhatsApp Image 2018-12-05 AM.jpeg; WhatsApp Imag

11.28.23 AM (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.23 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.24 AM (1).jpeg; WhatsApp Image 2018-12-05 at 11.28.25 AM.jpeg; WhatsApp Image 2018-12-05 at 11.28.25 AM.jpeg; WhatsApp Image 2018-12-05 at 11.30.51 AM.jpeg; WhatsApp Image 2018-12-05 at 11.30.51 AM.jpeg; WhatsApp Image 2018-12-05 at 11.48.05 AM.jpeg; WhatsApp Image 2018-12-05 at 12.04.57 PM (1).jpeg; WhatsApp Image 2018-12-05 at 12.04.57 PM.jpeg; WhatsApp Image 2018-12-06 at 10.22.59 AM.jpeg; WhatsApp Image 2018-12-06 at 10.23.00 AM.jpeg; WhatsApp Image 2018-12-06 AM.jpeg; WhatsApp Im

WhatsApp Image 2018-12-06 at 10.23.01 AM.jpeg; WhatsApp Image 2018-12-06 at

10.23.02 AM (1).jpeg; WhatsApp Image 2018-12-06 at 10.23.02 AM.jpeg

Dear Hsiao Tong,

Kindly assist.-CC4/ASM18018427/Awa3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>

Sent: Monday, 7 January 2019 10:51 AM

To: SUR <sur@lkkauto.com>

Cc: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>
Subject: FW: Check item photos for SJY 4646 K

Hi all,

Regarding this vehicle SJY4646K, this car was repaired at 6/12/2018. This case was handled by Jeffrey Tan who is already resigned. We would like to get an approval letter for the renewal of the rear lid. It's a check item, photos all send to Adrian by Jeffrey, and Adrian already approved it.

Best Regards, Glory Tan. From: glory.tan@premiumauto.com.sg <glory.tan@premiumauto.com.sg>

Sent: Friday, 7 December 2018 4:48 PM

To: SUR <sur@lkkauto.com>

Cc: 'adrianling@lkkauto.com' <adrianling@lkkauto.com>; 'Claims' <claims@premiumauto.com.sg>

Subject: Check item photos for SJY 4646 K

Hi all,

Please refer attached for check item photos. Thank you.

#### Item number

- 3. Rear bumper carrier.
- Rear bumper holder bracket RH/LH.
- 9. Rear bumper securing strip.
- 10. Rear lid.
- 24. Rear cross panel trim.
- 28. Rear cross panel outer.
- Rear cross panel lower.
- 30. Rear bumper reinforcement.
- Acrylic sealant.
- Cavity wax.
- 33. Stone chip.
- 35. Rear No. Plate.

Best Regards, Glory Tan. **Used Cars** 

Sell My Car

Directory


Products

Insurance

Articles

Forum

Resources






Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD! \$99.8% Only. 1 Owner. Fully Maintained By PML. 5 Neg

Asking Slightly Higher Than Paper Value + Export Body, PML Unit With Records







Car Search

THE THE TANK 2255 THE 2008 AND ALL 2008 BOD OF AUGUST AND ALL DAY OF AUGUST.

### > Back to OneMotoring

## Enquire FARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	7503W
Vehicle District	
Vehicle No.:	SJY4646K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Oct 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8T FSI MU S-LINE CVT ABS D/AB HID
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	CDH026741
Chassis No.:	WAUZZZ8K99A128135
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$38,931.00
Original Registration Date:	25 Nov 2008
First Registration Date:	25 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$38.931.00
Intended PARE Repart Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Nov 2018
PARF Rebate Amount:	\$19,465.00
Intended GO   Religite Digitalis	
COE Expiry Date:	24 Nov 2018
COE Category:	E - Open Category
COE Period(Years):	10
QP Pald:	\$10,490.00
COE Rebate Amount:	\$87.00
Total Rebate Amount:	\$19,552.00

The information contained herein is correct as at 16 Oct 2018

st Selling Continental Sedan That Packs A Punch With 11's Turbo Charged Engine, Spacious Cabin And Boot Space! Renowned For It's Superb

09-Mar-2009

1.798 cc

140,000 km

Available

(CONTRACTO)

Lunury

\$5,980 /yr

\$59,800

Audi A4 1.8A TFSI MU (New

10-yr COE)

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/1160/2018/GW

Date : 11-Oct-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SLQ 6709 T

#### **AXA Insurance Singapore Pte Ltd**

8 Shenton Way #27-01 AXA Tower Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Alatas Singapore Pte Ltd

Address : 1 International Business Park

#03-01E, Synergy Singapore 609917

 Telephone
 : HP +65 997360225

 Type of Claim
 : Third Party Claims

 Policy No.
 : 5077402437-02

 Vehicle No
 : SJY 4646 K

Model Code : Audi A4 1.8 TFSI

Model / Year : Nov-08
Engine No : CDH026741

Chassis No : WAUZZZ8K99A128135

Mileage : Date In :

Liability : Excess Cost :

Estimated By : Johnny Boo / Allan Wu

Accident Date : 9-0ct-18

Place of Accident : Along Road 1 Pan Island Expressway

#### Hsiao Tong (LKKAuto)

From:

Nora Khai PA <nora.khai@premiumauto.com.sg>

Sent:

Saturday, 15 June 2019 1:29 PM

To:

Vivian Lau (LKKAuto)

Cc:

'Claims'

Subject:

RE: FINAL REVISION - SJY4646K - TP AXA - SURVEYED 16 OCT 18, LOD

Attachments:

[Untitled].pdf

Dear Vivian,

Attached is the LOD. Please process and facilitate for AXA payments to our good office. Thank you.

#### Kind Regards, Norah Khai

Claims Manager

#### Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6366 2323 d. +65 6768 9827 f. +65 6841 1183

e. claims@@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



#### **Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Vivian Lau (LKKAuto) [mailto:vivianlau@lkkauto.com]

Sent: Tuesday, May 28, 2019 4:13 PM

To: Carrine Leong <carrine.leong@premiumauto.com.sg>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SJY4646K - TP AXA - SURVEYED 16 OCT 18

#### 'WITHOUT PREJUDICE' SAVE AS TO COSTS

1

Dear Sir/Madam.

#### Accident involving Vehicle SJY 4646K & SLQ 6709T on 09/10/2018

We refer to the above matter

Our surveyor have finalise COR at \$ 19,231.10( exclude gst) 8 days. ( Subject to insurance approval )

In order to expedite the claim process, please forward all relevant documents for us to proceed on negotiate settlement.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <u>Vivianlau@lkkauto.com</u> fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong [mailto:carrine.leong@premiumauto.com.sg]

Sent: Tuesday, 19 March, 2019 4:26 PM

<cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>

Subject: RE: FINAL REVISION - SJY4646K - TP AXA - SURVEYED 16 OCT 18

Hi Adrian,

#### Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle. Revised estimate was mailed to you on 28 Jan & 20 Feb 2019. We sincerely appreciate your early closure.

Thanks & Best Regard Carrine Leong Claims Administrator

Premium Automobiles Pte Ltd (Neg No 199902271W)

Email Disclaimer	
This email, including any attachment, is confidential and may also be privileged. If you have received it in error, please notify us immediately by reply email and then delete thi	is message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to an	
From: Carrine Leong [mailto:carrine.leong@premiumauto.com.s	sgl
Sent: Wednesday, 20 February, 2019 5:18 PM	
To: 'Adrian Ling' <a drianling@lkkauto.com'="">; 'Vivian Lau' &lt; vivianl</a>	au@lkkauto.com>: 'cs-a@lkkauto.com' <c< th=""></c<>
a@lkkauto.com>; 'admin-a@lkkauto.com' <admin-a@lkkauto.co< th=""><th></th></admin-a@lkkauto.co<>	
Cc: 'Jiayee.yap@premiumauto.com.sg' < <u>Jiayee.yap@premiumau</u>	
	to.com.sg>, chang thee sing
< <u>claims@premiumauto.com.sg</u> >	257.12
Subject: RE: FINAL REVISION - SJY4646K - TP AXA - SURVEYED 16	OCT 18
Hi Adrian,	
Reminder	
We have yet receive your confirmation of repair cost and days of	f repair for above vehicle.
Revised estimate was mailed to you on 28 Jan 2019.	
We sincerely appreciate your early closure.	
Thanks & Best Regard	
Carrine Leong	
Claims Administrator	
Premium Automobiles Pte Ltd (Heg 5to 1989022771W)	
55 Ubi Road 1 Road Singapore 408699	
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183	
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65	6836 2223
	0030 2223
×	

**Email Disclaimer** 

55 Ubi Road 1 Road Singapore 408699

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 28 January, 2019 5:16 PM

To: Adrian Ling <adrianling@lkkauto.com>; Vivian Lau <<u>vivianlau@lkkauto.com</u>>; <u>cs-a@lkkauto.com</u>; <u>admin-a@lkkauto.com</u>; <u>Carrine Leong <a href="mailto:com.sg">carrine Leong <a href=</u>

Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SJY4646K - TP AXA - SURVEYED 16 OCT 18

Hi Adrian and all,

Revised estimate and B4 paint photographs is attached.

Please confirm repair cost of \$19,231.10 @ 8 days of repairs excluding weekend.

Your early closure is well appreciated.

Best regards - jb

Date

Norah Khai From AXA Insurance Singapore Pte Ltd Telephone +65-6768 9828 8 Shenton Way 6841 1183 Telefax -td. #27-01 AXA Tower Our department Body Repair Singapore 068811 Your Claim Ref Attn: Motor Claims Dept PA/TP/1160/2018/JW Ow Ref Your ref: CC4/ASM18018427/wa3 12-Dec-18 Date Premium Automobiles Pte Lid RE: CLAIM-OWNER'S SATISFACTION/DISCHARGE VOUCHER V Long Kee Road Singapore 159090 Audi A4 1.8 TFS1 Make & Model Telephone (65) 6566 1111 Telefas (85) 6471 3733 WAUZZZ8K99A128135 Vehicle Chassis No Service & Parts Centres SJY 4646 K Vehicle Regn No. scoscillust I Singapore 408/109 194833 KM Vehicle Mileage Telephone (IIII) 6366 2325 Telefan: (63) 6841 1583 Alatas Singapore Pte Ltd 1 Vehicle Owner 5077402437-02 . Certificate No Direct Setlement by Vivian of LKK via email Liability Dated 20/11/2018 with LOU/LOR 9 October, 2018 Accident Date Along Road 1 Pan Island Expressway Location S\$ 20,577.28 Repair Cost 28176 WIP No. Premium Automobiles Pte Ltd Repairer's Name I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claims singlatione in the repairer's charges that are claims singlatione in 36 Ton Guan Road East full and final settlement of my claim. #01-41 Enterprise Hub Singapore 608580 Tel: 65-6316 6316 Fax: 65-6310 7618 Owner/Insured Signature Time



#### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RIS	KS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RIS	KS AND COMPENSATION) RULES, 1960
ROAD THANSPORT ACT, 1987 (MALA	

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5077402437-02

Cover : drive CLASSIC

: SJY4646K

1. Index mark and Registration Number of Vehicle Chassis Number

2. Name of Policyholder

: WAUZZZ8K99A128135 : ALATAS SINGAPORE PTE LTD

3. Effective Date of Insurance

: 25 May 2018

4. Expiry Date of Insurance

: 24 May 2019

5. Persons or Classes of Persons entitled to driver

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

#### This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use for the carriage of goods (other than samples) in connection with any trade or business.

(d) Use for any purpose in connection with the Motor Trade.

# Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$600
EXCESS (SECTION 2)	: N/A
WINDSCREEN EXCESS	: 5\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: ND
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	2 NO
EXCESS WAIVER	ż NO
PRIMARY DRIVER	1 N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

: CONVINCE AUTO PTE. LTD. (00000572583)

Date of Issue

: 18 Apr 2018 14:35 hrs

FOR NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Menu



## <TP - Mandate IA> - S8M00YMI [ACCIDENT INVOLVING SLQ 6709T(OI) & SJY 4646K(TP) ON 09/10/2018]

#### Type

Question

#### Message

Liability: 100%. 3 vehicles chain collision whereby our insured was the last car. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$21,299.28(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong -17 June 2019

Reply



51 UBLAVE 1, #02-25 PAVA UIII INDUSTRIAL PARK, SINGAPORE 400933 TEL; (065) 62563861 FAX; (065) 62564318

Remarks:

#### Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 20,577.28	
Loss of use	\$ 720.00	(9days x \$80.00)
Loss of rental	NIL	
Loss of income	NIL	
LTA search fees	\$ 2.00	
Others	NIL	
Proposed Total	\$ 21,299.28	



\$1 UBLAYE 1, 402-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 400933 TEL: (005) 62563561 FAX: (065) 62564315

#### Immediate Advice

To: AXA Insurance Pte Ltd

Date: 17/6/2019

#### Survey Details:

Date of loss	9-Oct-18
Date of appointment	10-Oct-18
Date of survey	16-Oct-18
Location of survey	PREMIUM AUTOMOBILES PTE LTD

#### Vehicle Details:

Claim Type:	THIRD PARTY CLAIM	
Vehicle number	SJY4646K	
Make and Model	AUDI A4 1:81 F31 CV I AB3 D/AB	
Date of registration	25-Nov-08	
Excess		
Market Value	\$	46,000.00
Parf Rebate	\$	16,007.00
Nett Loss	\$	29,993.00

#### Repair details:

Initial Estimate	25,946.10

#### Proposed/Revised repair cost:

Parts	\$ 10,872.00
Check items (estimate)	NIL
Labour	\$ 7,792.00
Supplementary	\$ 567.10
Total	\$ 19,231.10
Lump Sum(if applicable)	\$

Number of days for repair	8 days	
1101110111		

#### Hsiao Tong (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Monday, 1 July 2019 7:28 PM

To:

Hsiao Tong (LKKAuto)

Subject:

FW: New message for service request 74310, vehicle number SJY4646K

1/7/19 4:34 PM\*\*\* Proceed with proposed quantum. Thanks - KHONG Lynn

——Original Message—— From: Admin-D (LKKAuto)

Sent: Monday, 1 July, 2019 4:40 PM To: Admin A <admin-a@lkkauto.com>

Subject: FW: New message for service request 74310, vehicle number SJY4646K

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi

Avenue 1, #02-25 | S(408933)

—Original Message—

From: lynn.khong@axa.com.sg [mailto:lynn.khong@axa.com.sg]

Sent: Monday, 1 July, 2019 4:35 PM

To: admin-d@lkkauto.com

Subject: New message for service request 74310, vehicle number SJY4646K

AXA Insurance has sent you a message for claim number S8M00YMI.

Please click here https://vp.smartclaims.axa.com.sg/claim-portal/ to view the message in Vendor Portal. This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Menu



# Re:<TP - Mandate IA> - \$8M00YMI [ACCIDENT INVOLVING SLQ 6709T(OI) & \$JY 4646K(TP) ON 09/10/2018]

Type

Question

Message

Proceed with proposed quantum. Thanks

Reply



#### Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: 5077402437-02

Cover : drivo CLASSIC

: WAUZZZ8K99A128135

: ALATAS SINGAPORE PTE LTD

1. Index mark and Registration Number of Vehicle

Chassis Number

2. Name of Policyholder

2. Name of Policyholder

3. Effective Date of Insurance

4. Expiry Date of Insurance

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

: 5JY4646K

25 May 2018

: 24 May 2019

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

#### This Policy does not cover

- (a) Use for hire or reward.
- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.
  - # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation)
    Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	; SS600
EXCESS (SECTION 2)	; N/A
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: NO
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

; CONVINCE AUTO PTE. LTD. (00000572583)

Date of Issue

: 18 Apr 2018 14:35 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

**Authorised Officer** 

Chief Executive

AXA Insurance Pte Ltd No 8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept Yr Ref: CC4/ASM18018427/wa3 Norah Khai 6768 9911 6841 1183 Nora.khai@premiumauto.com.sg Body & Paint Dept PA/TP/1160/2018/NK

12 Dec 2019

from
Telephone +65Telefax +65EMail
Our department
Our Ref
Your Ref
Date

Dear Sir.

RE: INSURANCE CLAIM FOR SJY 4646 K, Audi A4 Sedan 1.8 TFSI.

With reference to the above-mentioned vehicle, no. SJY 4646 K, claimant, M/s Alatas Singapore Pte Ltd, please find the related document as per attached.

- A copy of the Original invoice no. 85013858 S\$20,577.28.
- 2. A copy of Authorization to Act duly signed by client
- 3. A copy of the Release Voucher attached
- Loss of Use S\$720.00 (S\$80.00 x 9 days).
- 5. A copy of GIA Search fee S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encls AXA – SJY 4646 K total pages

Premium Automobiles Pte Ltd Showroom 9 Leng Kee Road Singapore 159090 Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

## **Premium Automobiles**

Date

Norah Khai From AXA Insurance Singapore Pte Ltd 6768 9828 Interhone +65-8 Shenton Way 6841 1183 Telefas -65-#27-01 AXA Tower Our department Body Repair Singapore 068811 Your Claim Ref. Attn: Motor Claims Dept PA/TP/1160/2018/JW Our Ref Your ref: CC4/ASM18018427/wa3 12-Dec-18 Distr total pages Premium Automobiles Pie Lid RE: CLAIM-OWNER'S SATISFACTION/DISCHARGE VOUCHER 9 Long Kee Bond Singapore 159090 Audi A4 1.8 TFSI Make & Model Telephone (65) 6566 [11] Telefin (6d) 6471 3733 WAUZZZ8K99A128135 Vehicle Chassis No Service & Parts Centres SJY 4646 K Vehicle Regn No. . 55 Uhi Road I Singapore 408699 194833 KM Vehicle Mileage Telephote (65) 6366-2323 Telefax: 165) 6841 1183 Alatas Singapore Pte Ltd Vehicle Owner 5077402437-02 Certificate No Direct Setlement by Vivian of LKK via email Liability Dated 20/11/2018 with LOU/LOR 9 October, 2018 Accident Date Along Road 1 Pan Island Expressway Location SS 20,577.28 Repair Cost 28176 WIP No. Premium Automobiles Pte Ltd Repairer's Name I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claims being a porter it to deemed in 36 Tot: Guan Road East full and final settlement of my claim. #01-41 Enterprise Hub Singapore 608580 Owner/Insured Signature Tel: 65-6316 6318 Fax: 65-6316 7618 Time

#### Vivian Lau (LKKAuto)

From:

Vivian Lau (LKKAuto)

Sent:

Wednesday, 17 October, 2018 10:18 AM

To:

'jianronglim@yahoo.com.sg'

Subject:

ACCIDENT INVOLVING SLO 6709T & SJY 4646K ALONG PIE ON 09/10/2018

Attachments:

Pictures for Accident from SJY 4646K.pdf

Dear Mr Lim

OUR REF

: CC4/ASM18018427/wa3

YOUR REF : SLO 6709T

#### ACCIDENT INVOLVING SLQ 6709T & SJY 4646K ALONG PIE ON 09/10/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer. AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Premium Automobiles Pte Ltd acting on behalf of the owner of SJY 4646K against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. You intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Thank you

Best Regards,

Vivian Lau | Case Handler

#### LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: <u>Vivianlau@lkkauto.com</u>] fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Letter of Authorization

Your ref: CC4/ASM18018427/wa3

Our ref: PA/TP/1160/2018/JW

12 December, 2018

#### Alatas Singapore Pte Ltd

1 International Business Park #03-01E, Synergy Singapore 609917

#### **AXA Insurance Singapore Pte Ltd**

8 Shenton Way #27-01 AXA Tower Singapore 068811 Attn: Motor Claims Dept

Dear Sir/ Mdm,

Accident involving SJY 4646 K / SLQ 6709 T Along Road 1 Pan Island Expressway On 09 October 2018.

I am the registered owner of SJY 4646 K

I confirm that I will be claiming for Rental Charges / Loss of Use and hearby authorize your esteemed company to settle Rental Charges / Loss of Use and repair bill directly with Premium Automobiles Pte Ltd.

June

Your kind attention will be greatly appreciated.

Yours faithful PORE PTE LTD

36 Tori Guan Road East #114 A Enterprise Hub Singapore 608580 Tel: 65-6316 6318 Fax: 65-6316 7618

Alatas Singapore Pte Ltd

Copy to Norah Khai, Premium Automobiles Pte Ltd



#### AXA THIRD PARTY DIRECT SETTLEMENT

Vehide No:		SLO STOOT (Insd veh)	To other			
		SJY 4646K (TP veh)	Model: Audi A4 (17)	9800	0)	
Date of Accident/ Time:		09/10/2018				
Repair Estimate	:5	27,807.99				
Final Repair Cost (w/GST)	: \$	20,577.28				
Loss of Use	15	720.00		8	days at \$ 80	
Rental (if any)	:5				days at \$	per day
LTA / GIA Search Fee	::5	2.00				
Others	:5					
	- 5					
Final Settlement Sum	±\$	21,299.28				
Payee Name : PREMIUM AUTON	MOBILES PTE	LTD -				
Is Third Party Workshop GIA Reg			(Kindly indicate below)			

A)	For Non GIA Registered Workshop:	Agreed Liability(%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/Mo BOLA Scenario No: 28
	BOLA LIBBRITY: 100 (96)	Assessed Liability (*) (%)
	* Assessed Liability to be filled only for chair	collisions and for cases where BOLA does not apply.

#### NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- 2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSDEVER.
- 3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

Name of Witness;

Date:

Signature of Witness / Workshop stamp (if applicable)

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

Name of Representative

Date:

Signature of AXA's surveyor/res yor /Representative: Name of AXA's surv

AXA Insurance Pte Ltd (Company Reg. No.: 199903512M) 8 Shenton Way #24-01 AXA Tower Singapore 068811

AXA Customer Centre #01-21/22 Telephone: +65 6880 4888 - axa.com.sg

 $\mathfrak{M}$ 

Audi Centre Singapore 281 Alexandra fixed Singapore 15938 Mein Talephone 6816 2223 Main Talephone 6871 2733

Page 1 15:23

MOTOR CLAIM DEPT

#27-81 AXA TOWER,

8 SHENTON WAY,

Allecandra Service Cer 201 Alecandra Board Triliganore 159005 Triliganore 6306 2223

Telefax 5475 1023

Util Service Centre 55 Util Road 1 Customer Service

( 9360-252) Jervice 9678-1231

INS TAX INVOICE Company Reg. No. 199902271W 6ST Reg. No. 199902271W

Inveice: 85813858

Account: A0008

(T:

Date : 07/06/2019

Order : SJY4646K

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPT

8 SHENTON WAY,

#27-01 AXA TOWER,

SINGAPORE 068811 068811

AXA INSURANCE PTE LTD

Term : 30

SINGAPORE 068811

Regn No.: SJY4646K (V

8864)

Regn Date: 25/11/2008

Mileage: 194833

WIP No.: 28176

Model: A4 1.8T FSI MU 8K202H

Chassis: WAUZZZ8K99A128135

Engine: CDH026741

Dept: U

VSB No. 1

You have been assisted by :- UB-Jiayee

(11)

		Details	Qty	Unit Price	Amount
6	SUBLET	TO CHOOL & HITHER C WHITE OF OTE (COOKE)	25.00	1.00	25.00
5	SUBLET	TO SUPPLY VEHICLE NUMBER PLATE (FRONT)  N:  TO SUPPLY VEHICLE NUMBER PLATE (REAR)	25.00	1.00	25, 88
S	BODYWORK	TO REMOVE AND TRANSFER FRONT WIRE HARNESS	368.00	1.00	368,88
5	BODYWORK	FOR HEADLIGHT, HORNS, DUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY M: TO DISMANTLE AND REMEW FRONT BUMPER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
8	BODYWORK	TO RESPRAY FRONT BUMPER	688.88	1.00	600.00
6	BODYWORK	TO REMOVE AND TRANSFER REAR PARKING AID.  CHECK FUNCTION	280.00	1,00	290.00
8	BODYWORK	Ma	288, 88	1.00	288, 88

Sub-Total

7% GST

Grand Total

Customer

Audi Cantro Singapore 201 Alexandra Road Singapore USES Main Telephone 1824 7222

8 SHENTON WAY,

#27-01 AXA TOWER,

JRE/Kerondra Road Singapore 159936. Trigotory 5788 2223

Seeba 8425 1923

55 l/hi Road 1

10(41,132) ANZE 1251

Main Soleton 9471-2733 Page 2 16:23

AXA INSURANCE PTE LTD MOTOR CLAIM DEPT

INS TAX INVOICE Company Reg. New 199902271W GST Reg. No. 1999W2271W

Invoice: 85013858

Date : 07/06/2019

Account: A0008 (T

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPT

8 SHENTON MAY.

Order : SJY4646K #27-81 AXA TOMER,

SINGAPORE 068811 068811

Term : 30

SINGAPORE 068811

Regn No.: SJY4646K (V

8864)

Mileage: 194833

WIP No. 1 28176

Model: A4 1.87 FSI MU 8K202H

Chassis: WAUZZZ8K99A128135

Regn Date: 25/11/2008

Engine: CDH026741

Dept: U

USB No. :

You have been assisted by :- UB-Jiayee

(11)

		Details	Qty	Unit Price	Amount
		TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT			400.00
(A)	BODYHORK	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHT, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS.	480.00	1.00	480.00
S	BODYWORK	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND REWELD END PANELLING. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	3000.00	1.00	3, 000. 00
G)	BODYWORK	TO RESPRAY REAR BUMPER, REAR LID AND END PANELLING TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT	2888.88	1.00	2,000.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00

	Tal	

795 GST

Grand Total

Customer

261 Alexandra Road Simpapore 158638 Main Telephores 6838-2223.

Main Telefac 8421 8135

Page 3

Alexandra Servica Centre 281 Alexandra Road Singapore 114938 Temphone 6389 2223 2666e 5475.1025

55 Utol Round 1

E306 1111 9828 1331

INS TAX INVOICE Company Reg. New 199902271W GST Reg. No. 199902271W

AXA INSURANCE PTE LTD

16:23

Invoice: 85013858

Order : SJY4646K

Account: A0008

AXA INSURANCE PTE LTD

(T

81

MOTOR CLAIM DEPT 8 SHENTON WAY,

Date : 07/06/2019

MOTOR CLAIM DEPT

B SHENTON WAY,

#27-01 AXA TOMER,

SINGAPORE 068811 068811

Term : 38

SINGAPORE 068811

Regn No.: SJY4646K (V 8864)

027-01 AXA TOWER,

Regn Date: 25/11/2008

Mileage: 194833

WIP No. 1 28176

Model: A4 1.87 FSI MU 8K202H

Chassis: WAUZZZ8K99A128135

Engine: CDH026741

Dept: U

VSB No. 1

You have been assisted by :- UB-Jiayee

(11)

		Details	Qty	Unit Price	Amount
6	BODYWORK	TO SUPPLY ACRYLIC SEALANT, CAVITY WAX AND STONE CHIP	588, 88	1.00	588, 88
1	A8K0853651 10P	GRILLE	1.00	595.00	595.00
X.	A8K5945095D	TAILLIGHT	1.00	321.00	321, 00
(	A8K5827823RE	LID	1.00	1923.00	1,923.00
X	A8K5813331A	REINFORCE	1.00	467.50	467,50
1	A8K5813307	PEAR APRON	1.00	275,00	275, 98
X	A8K8814339	END PLATE	1.00	765.00	765, 00
1	A8T0807313	BRACKET	1.00	563.00	563, 00
X	ABK0807105E GRU	BUMPER H/HH S-LINE	1.00	2394.00	2,394.00
X.	A8K5807303C GRU	BUMPER W/PA S-LINE	1,00	1621.00	1,621.00
X	A6H0807521C 1RR	SPOILER S-LINE	1.00	332.50	332, 50
X	ABT0853742B 22I	AUDI SIGN	1.00	107.50	107.50
X	A8K0807331E	HOLDER	1.00	191.00	191.00
Ý.	ABK0807332A	HOLDER	1.00	191.00	191.00
X	A8K8828536D	BRACKET	1.00	15.60	15.60
X	A8K58@7861	STRIP	1.00	11.00	11.00

Sub-Total

7% GST

Grand Total

Customer



281 Alexandra Read Tingapore 178608 Main Trieghorn 6836 2223

Main Telefax 6471.3135

281 Alexandra Road Singapore T10938 Selignory 6189 2221 Seigher 8475 1929

55 Util Road 1

£566,2111 9828 123

INS TAX INVOICE Cospany Reg. No. 199982271W GST Reg. No. 199902271W

Page 4

16:23

Inveice: 85013858

Date : 07/05/2019

Account: A0008

Ø1)

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPT

8 SHENTON WAY.

#27-01 AXA TOWER,

Order : SJY4646K

SINBAPORE 058811 068811

AXA INSURANCE PTE LTD

MOTOR CLAIM DEPT 8 SHENTON WAY.

#27-81 AXA TOMER,

Term : 30

SINSAPORE 068811

Regn No.: SJY4646K (V

88541

Regn Date: 25/11/2008

Mileage: 194833

WIP No. 1 28176

Model: A4 1.8T FSI MU 8K202H

Chassis: WAUZZZ8K99A128135

Engine: CDH026741

Dept: U

VSB No. :

You have been assisted by :- UB-Jiayee

(11)

	Details	Qty	Unit Price	Amount
X A8D0853419D X A8T0827310A X A8K0820536 X A150919275D X A1T0919133C 704 X A0K5863471 4PM X A8K0807833 01C X A8K0007110 1RR	PACKING CLIP BRACKET SENSOR WASHER TRIM PANEL TRIM S-LINE SPOILER	1.80 2.88 1.80 2.80 4.80 1.00 1.00	28.90 1.30 15.60 196.00 1.10 159.50 221.50 291.50	28, 98 2, 68 15, 68 392, 88 4, 48 159, 58 221, 58 291, 58

Parts 10,889.10 Labour 0.00 Sublet 8,342.00 0.00 Menus 0.00 Lubricant

Sub-Total

7% GST

1,346,18

19,231.10

Grand Total 20,577.28

Received by

For & on behalf of Premium Automobiles Pte Ltd



#### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No:

GR-18-156444

Date of Request:

09/10/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

**Enquiry Date** 

09/10/2018

Enquiry By

Jeffrey Tan Eng Su

TP Vehicle No.

SLQ6709T

Accident Date

09/10/2018

**Enquiry Result** 

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLQ6709T	AXA Insurance Pte Ltd	19/07/2017-18/07/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



#### GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

#### TAX INVOICE

Our Ref No:

GR-18-156444

Date of Request:

09/10/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd

55 Ubi Road 1 Singapore 408699

Dear Sir/Madam,

**Enquiry Date** 

09/10/2018

Enquiry By

Jeffrey Tan Eng Su

TP Vehicle No.

SLQ6709T

Accident Date

09/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature,

For GIARMC Official use:

[X] GIRO [] Cash [] Cheque



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

1000	Affiliated to Federation Interna	tionale Des Experts En Autom	oblie
AXA INSURANCE PTE	LTD	Ref : CC4/ASM18018	3427/Apa3q2
B SHENTON WAY #24 AXA TOWERSINGAPO ATTN:LYNN		Date: 25-07-2019 Code: ASM	
1.	Policy Particular	s :- THIRD PARTY CLAIR	M
Insured Veh.	SLQ 6709T	Veh. Inspected	SJY 4646K
Policy No.	VPA/P1955486	Coverage (\$)	0.00
Claim No.	S8M00YMI	Excess (\$)	0.00
Assign From		Assign Date	10/10/2018
2.	Vehicle Par	ticulars & Condition	
Make & Model	AUDI A4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WAUZZZ8K99A128135	Colour	WHITE
Odometer	190914	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3,	Cond	itions of Tyres	
	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
L/H Rear Tyre	245/40 R18	PIREĹLI	6 mm
	Descrip	tion of Damages	
THE VEHICLE SU DAMAGES SEE D	STAINED DAMAGES AT THE R ETAILS.	REAR PORTION.	
5.	Gener	ral Information	THE RESERVE OF THE PARTY OF
Accident Date	09/10/2018	Inspection Date	16/10/2018
Survey held at	PREMIUM AUTOMOBILES PT	TE LTD	
	55 UBI ROAD 1 . SINGAPORE 408699		
ia.		Remarks	
A)THE INSPECTION B)IN ACCORDANG	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	ITHOUT PREJUDICE" BASI WE HAVE NOT AUTHORISE	S. ED REPAIRS.
ib.	Estimat	e Days of Repair	
ESTIMATED NOR	MAL PERIOD FOR REPAIR:	8 Working Days	1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

		ationale Des Experts En Auton	
AXA INSURANCE PTI	ELTD	Ref : CC4/ASM1801	8427/Apa3q2
8 SHENTON WAY #24 AXA TOWERSINGAP		Date: 25-07-2019	
ATTN:LYNN		Code: ASM	
1.		ars :- THIRD PARTY CLA	IM
Insured Veh.	SLQ 6709T	Veh. Inspected	SJY 4646K
Policy No.	VPA/P1955486	Coverage (\$)	0.00
Claim No.	S8M00YMI	Excess (\$)	0.00
Assign From		Assign Date	10/10/2018
2.	Vehicle Pa	articulars & Condition	
Make & Model	AUDI A4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	WAUZZZ8K99A128135	Colour	WHITE
Odometer	190914	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	245/40 R18	PIRELLI	6 mm
L/H Front Tyre	245/40 R18	PIRELLI	6 mm
R/H Rear Tyre	245/40 R18	PIRELLI	6 mm
L/H Rear Tyre	245/40 R18	PIRELLI	6 mm
4.	Descri	ption of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
5.		eral Information	- J. J. Santal Block
Accident Date	09/10/2018	Inspection Date	16/10/2018
Survey held at	PREMIUM AUTOMOBILES F	Committee Commit	Hermonian (Carlo
	55 UBI ROAD 1 . SINGAPORE 408699	1003/57/1036	
5a.		Remarks	
	ON WAS CONDUCTED ON A" CE TO YOUR INSTRUCTIONS		
5b.	Estima	ate Days of Repair	
ESTIMATED NOR	MAL PERIOD FOR REPAIR:	8 Working Day	S



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 4646K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN) (CONSISTENT)	DEFORMED	2,394.00	2,394.00
1	FRONT BUMPER FIXING PARTS (SN) (CONSISTENT)	NOT NECESSARY	222.00	
2	FRONT BUMPER GUIDE SECTION -LH /RH (SN) (CONSISTENT)	NOT NECESSARY	74.00	ā.
2	FRONT BUMPER SECURING STRIP (SN) (CONSISTENT)	NOT NECESSARY	60.00	=
1	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE (SN) (CONSISTENT)	NOT NECESSARY	467.00	
4	FRONT BUMPER PULL STRAP-LOWER (SN) (CONSISTENT)	NOT NECESSARY	44.00	3
1	FRONT BUMPER SPOILER -LOWER (SN) (CONSISTENT)	CUT	292.00	291.50
1	FOAM FILLER PIECE (SN) (CONSISTENT)	NOT NECESSARY	107.00	
1	FRONT BUMPER SIDE REINFORCEMENT (SN) (CONSISTENT)	NOT NECESSARY	,770.00	3
2	FRONT BUMPER SUPPORT -LH/RH (SN) (CONSISTENT)	NOT NECESSARY	<b>48.00</b>	
2	FRONT BUMPER VENT GRILLE -LH/RH (SN) (CONSISTENT)	NOT NECESSARY	236.00	:
1	FRONT BUMPER COVER (SN) (CONSISTENT)	NOT NECESSARY	84.00	1
1	RADIATOR GRILLE (SN) (CONSISTENT)	CUT	595.00	595.0
1	RADIATOR GRILLE COVER (SN) (CONSISTENT)	NOT NECESSARY	50.00	
1	REAR BUMPER (SN) (CONSISTENT)	DISTORTED	1,621.00	1,621.0
1	REAR BUMPER FIXING PARTS (SN) (CONSISTENT)	NOT NECESSARY	195.00	
1	REAR BUMPER CARRIER (SN) (CONSISTENT)	BENT	563.00	563.00
2	REAR BUMPER HOLDER BRACKET -LH/RH (SN) (CONSISTENT)	DAMAGED	J382.00	382.00
1	REAR BUMPER SPOILER (SN) (CONSISTENT)	DEFORMED	333.00	332.50
2	REAR BUMPER GUIDE SECTION -LH/RH (SN) (CONSISTENT)	NOT NECESSARY	√75.00	i i
2	REAR BUMPER UPPER GUIDE SECTION -LH/RH (SN) (CONSISTENT)	NOT NECESSARY	39.00	
1	REAR BUMPER TRIM (SN) (CONSISTENT)	DEFORMED	222.00	221.50
1	REAR BUMPER SECURING STRIP (SN) (CONSISTENT)	NECESSARY	11.00	11.00
1	REAR LID (SN) (CONSISTENT)	BUCKLED	1,923.00	1,923.00
1	REAR LID ATTACHMENT PARTS (SN) (CONSISTENT)	NOT NECESSARY	133.00	

Report Ref No. CC4/ASM18018427/Apa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	REAR LID HINGE-LH/RH(SN) (CONSISTENT)	NOT NECESSARY	496.00	
1	REAR LID GASKET FLAP (SN) (CONSISTENT)	NOT NECESSARY	176.00	
5	REAR LID TOP BUFFER (SN) (CONSISTENT)	NOT NECESSARY	- 57.00	
1	REAR LID LOCK (SN) (CONSISTENT)	NOT NECESSARY	<b>190.00</b>	
1	REAR LID LOCK COVER (SN) (CONSISTENT)	NOT NECESSARY	17.00	
1	REAR LID LOCK STRIKER (SN) (CONSISTENT)	NOT NECESSARY	44.00	
1	REAR LID PUSH BUTTON FOR ELECTRIC (SN) (CONSISTENT)	NOT NECESSARY	159.00	
2	REAR LID STOP BUFFER ,ADJUSTABLE (SN) (CONSISTENT)	NOT NECESSARY	48.00	1
2	REAR LID STOP BUFFER CAP (SN) (CONSISTENT)	NOT NECESSARY	13.00	
1	PACKING ADHESIVE (SN) (CONSISTENT)	NECESSARY	29.00	28.90
1	AUDI EMBLEM (SN) (CONSISTENT)	NECESSARY	× 108.00	107.50
1	REAR LID TRIM PANEL (SN) (CONSISTENT)	NOT NECESSARY	344.00	
1	REAR CROSS PANEL TRIM (SN) (CONSISTENT)	NOT NECESSARY	- 160.00	
1	LUGGAGE COMPARTMENT ,FLOOR COVERING (SN) (CONSISTENT)	NOT NECESSARY	618.00	,
1	TAILIGHT-LH (SN) (CONSISTENT)	CRACKED	321.00	321.00
2	TAILIGHT BULB -LH (SN) (CONSISTENT)	NOT NECESSARY	9.00	
1	REAR CROSS PANEL -OUTER (SN) (CONSISTENT)	DENTED	275.00	275.00
1	REAR CROSS PANEL -LOWER (SN) (CONSISTENT)	DENTED	765.00	765.00
1	REAR BUMPER REINFORCEMENT (SN) (CONSISTENT)	BENT	×468.00	467.50
1	ACLIC SEALANT (SN) (CONSISTENT)	NECESSARY	180.00	180.00
1	CAVITY WAX (SN) (CONSISTENT)	NECESSARY	140.00	140.00
1	STONE CHIP (SN) (CONSISTENT)	NECESSARY	180.00	180.00
1	FRONT NO PLATE (SN) (CONSISTENT)	NECESSARY	25.00	25.00
1	REAR NO.PLATE (SN) (CONSISTENT)	NECESSARY	/ 25.00	25.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	- 500.00	22.60
1	REINFORCEMENT BEAM BOLT (SN) (CONSISTENT) (ADDITIONAL)	NOT NECESSARY	38.00	
1	REAR CROSS PANEL TRIM (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	_159.50	159.50
1	REAR PARKING AID SENSOR (SN) (CONSISTENT) (ADDITIONAL)	DAMAGED	392.00	392.00

Report Ref No. CC4/ASM18018427/Apa3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

19,231.10

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	TEMP .SENSOR BRACKET (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	15.60	15.60
			16,592.10	11,439.10
	LABOUR			
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		360.00	360.00
	TO DISMANTLE AND RENEW FRONT BUMPER .RE- ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		900.00	600.00
	TO RESPRAY FRONT BUMPER.		800.00	
	TO REMOVE AND TRANSFER REAR PARKING AID .CHECK FUNCTION.		280.00	280.00
	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.		280.00	280.00
	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS.		480.00	480.00
	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO CUT OUT AND REWELD END PANELLING .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED.		3,600.00	3,000.00
	TO RESPRAY REAR BUMPER ,REAR LID AND END PANELLING .TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.		2,500.00	2,000.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			9,392.00	7,792.00
	GRAND TOTAL		25,984.10	19,231.10

Report Ref No. CC4/ASM18018427/Apa3q2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

RECOMMENDED COST OF REPAIRS

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk.

SERVICE REQUESTS

31 July 2019

LICK AUTO CONSULTANTS PTE \( \text{TD} \( (\text{TP} \) \)

Surveyor/ Assessor expense

BIVOICE

DOGWOOD 19300

DATE

AUTHOR

MARTYPE.

MM

HAME

# Service Request Details

Helevenice CCGAASM18018427/AquiNo2 Amount National Interview CCCGAASM18018427/AquiNo2 Amount National Interview CCCGAASM18018427/AquiNo2 Amount Na	Claim	SAMODYMI	Arthons	Vehicle Information	tion
Cet 2018 9:00:00 AM  May 2019  K ALTO CONSULTANTS PTI  D (TP)  Int Durity Vehicle Damage  Int Durity Vehicle Damage  Assessment  Character  Discurrent Subftype   Discurrent Subftype   Oct 2018  Assessment  Asse	Reference	CC4/ASM18018427/Aga3q2		Incident Vehicle Registration #	SIYA644K
Oct 2018 9:00:00 AM  KANTO CONSULTANTS PTIT  O TTP!  Andrew verification - Direct  themsent  Dazument Sublitype  Dazument Sublitype  ***  ***  ***  ***  ***  ***  ***	Lints Date	9 October 2018	Add Tools	Make	TPVD AUDI
May 2019  K ALTO CONSLATANTS PTE  D (TP)  Ind Party Vehicle Damage  Indication - Direct  Assessment  Dacument Suddinge  Dacument Suddinge  This PTE  Description - Direct  This PTE  This	Report Date	15 Oct 2018 9:00:00 AM		Model	A4 1.8 TP31 MU
of TP    Interest   Discussion    Discussion   Discussion    Discussion	Response Date	3D May 2019		Service: Address	
MATO CONSULTANTS PTII  O [TP]  Ind Party Vehicle Damage  Assessment  Chacament Subtype  Dacament Subtype   Decoment Subtype  The Subtyp	Disc Date			S1 Ubi Avenue 1,	401-25,., 408933
ind Party Vehicle Dannage infinite Dannage  Shistory Discounseld Assessment Metrics Notes  Datament Subtype	Windor Name	LKK AUTO CONSULTANTS PTE. UTD (TP)		Primary Contac	/Justined
Absorbert  Charactert Subtype  Discurrent Subtype	Type of Lass	Thirt Party Vehicle Damage		LIM JANRONG J BLK 546A SEGAR	ASON (LIN JIANHONG JASON) 180AD, #07-65, 671546.
Shizory Discussion Assessment Metrics Notes  Discussent Sulfigue	Services	Pending verification - Direct Settlement		93201182 JANBONGLIMER	WHOOLOMSG
S History Disconnecti Assessment Metrics Notes  Disconnect Subtype				Claim Handler	
Dacument Subtype				KHONG Lynn 68804892 fyrn Mongggaas	Avuo
Restricts, History Documenti Assessment Netroca	Additional Institu				
Discussion Sufficient		Helbery Documents	Metrics		
	Document Type				
		Ī			

128
ĕ
- 5
ž
1
4
27
2
3
74
11
- 8
. E
3
量
\$
ē
å
第
ž
Œ
2
17.
E S
Ē
¥
ā
.9
5
15
丑
E
4
100 100
Ŧ
Ē
£
ė
-
6
2
dp
-
\$
×
윤
- 5
F
差
君
E
ŏ
Ė
馬
10/0
DE
E
8
XB.(
×
105
-
100
5
2
95
=
- 6
复

17 Ame 2019	LICK ALTO CONSULTANTS PTE LTD (TP)	Assessment	Forms / Claim Documents	TH - Mandate M dd 170619 geff
17 June 2019	LION AUTO CONSULTANTS PTE LTD (TP)	Others	Reports & Statement	LKIK Resurvey Photos 3 pdf
17 June 2019	LIOX AUTO CONSULTANTS PTE LTD (TP)	Others	Reports & Statement	LKK Resurvey Photos 1 adf
17 June 2019	LEX AUTO CONSULTANTS PTE UD (TP)	Others	Reports & Statement	LKK Resurvey Photos 2 pdf
17 June 2019	LICK AUTO CONSULTANTS PTE LTD (TP)	Others	Reports & Statement	LAS Survey Photos.pdf
17 Ame 2019	LICK AUTO CONSULTANTS PTE LTD (TP)		Reports & Statement	PARE_COE REBATE_and
17 June 2019	LICK AUTO CONSULTANTS PTE LTD (TP)	Estimate / Quotation	Reports, & Statement	TP ESTIMATE + Supp Marked pdf
31 July 2019	LICK AUTO CONSULTANTS PTE LTD (TP)	Policy Hoklers / Insured	Letters and Correspondence	LETTER TO Olgoth
31 AAy 2019	DOK AUTO CONSULTANTS PTE (TD (TP)	Repairer	hvaier	WORSHOP INVOICE put
31 July 2019	LICK AUTO CONSULTANTS PTE LTD (TP)	POA / Authority Letter	Forms / Claim Documents	ALTHORISATION TO ACT FORM per
31 July 2019	UKK AUTO CONSULTANTS PTE (TD (TP)	Satisfaction / Discharge Voucher	Forms / Claim Documents	PAYMENT BREAKDOWN, EXPRESS SETTLEMENT PORM, pdf
31 July 2019	UKK AUTO CONSULTANTS PTE (TD (TP)	Others	Forms / Claim Documents	GIA SEARCH pdf
31 July 2019	LKK AUTO CONSULTANTS PTE LTD (TP)	Others	Forms / Claim Documents	LickAqustment La (5) petr
31 July 2019	LICK ALITO CONGLITANTS PTE LTD (TP)	Others	Figures / Claim Discuments	LKK/mspection (3) pdf
OF TAMERAL PARTY		200		

19 November 2016

WANG Peter

Photos

Evidence

Emult from OI - accident scene photos ma

10 October 2018

DHIWAR Namrata

Other

Other

■EMAIL FROM WORKSHOP WITH TP GIA REPORT, rive 10 October 2018

DHIWAR Namrata

GIA Report

Reports & Statement

SLQ6709T INSD GIA REPORT, PDF

27 October 2018

LKK ALITO CONSULTANTS PTE LTD (TP)

Estimate / Quotation

Reports & Statement

TH ESTINANTE-MAINCED pul

DATE

AUTHOR

SUBTYPE

THE

HAMM

44	
- 2	
č	
- 7	
- 3	
- E	
- 5	
- 35	
76	
-	
95	
C	
7	
- 25	
- 22	
111	
- 1	
- 4	
4	
- E	
- 2	
2	
77	
- 20	
2	
E	
- 6	
8	
-	
, C	
-5	
0	
- 5	
2	
1	
36	
12	
Œ	
- =	
~	
- 25	
3	
95	
-3	
- 5	
- 8	
. ut	
125	
- 12	
- 5	
Ξ	
-20	
alles	
9	
=	
- 26	
- 8	
å	
- 75	
-5	
-	
90	
er.	
ö	
- 50	
ĕ	
-	
5	
3	
25	
-	
2	
-	
=	
5	
E	
5	
(17)	
T.	
0	
÷.	
Ė	
.59	
U	
B	
100	
-	
E	
- 93	
9	
174	
8	
m,	
US.	
E	
青	
-	
- 0	
E	
12	
5	
6.5	
6	
200	
-	
=	
=	
tos://	
=	
=	