

Trans-cab Auto Services Pte L
 No. 2 Ang Mo Kio Street 63 Singapore
 Tel No. : 6287 6666 Fax No. : 6257
 CO/GST Reg. No. 201019626G
SHC 5216B

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

1,108.46 +
 768.84 +
 43.61 +
 777.52 +
 1,471.77 +
 404.56 +
 2,872.68 +
 225.36 +
 225.36 =
 7,898.16 *

7,898.16 x
 90. %
 7,108.344 *

660. +
 600. +
 60. +
 60. +
 60. +
 60. =

1,500. *

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR R
- 4 1 BUMPR BRACKET SIDE R
- 5 1 BUMPR RETAINER RH RE
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPR BRACKET SIDE LH
- 8 1 BUMPER RETAINER LH RE
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET L
- 12 1 BUMPER BEAM BRACKET R
- 13 1 OUTER PANEL REAR (End
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 TAILLAMP RH
- 16 1 TAILLAMP PANEL RH
- 17 1 TAILLAMP LH
- 18 1 TAILLAMP PANEL LH
- 19 1 BOOT REAR
- 20 1 BOOT FINISHER
- 21 1 BOOT WHEATERSTRIP
- 22 1 BOOT REFLECTOR LAMP LH
- 23 1 BOOT REFLECTOR LAMP RH
- 24 1 BOOT BADGE 'RENAULT'
- 25 1 BOOT BADGE
- 26 1 BOOT STRUT LH
- 27 1 BOOT STRUT RH
- 28 1 BOOT HINGE LH
- 29 1 BOOT HINGE RH

L/S → \$7,1000

7,108.34 +
 1,500. +
 165. =
 8,773.34 *
 8,773.34 x
 80. %
 7,018.672 *

AAD1810-103

Authorised
by Food

IC 5216B

1ABL15AUC276169

NAULT

TITUDE

0.2018

INA TAIPING

LIST

Buc 1,108.46 ✓
nd 768.84 ✓
Sn 113.47 X
Sn 135.97 X
Sn 44.99 X
cm 43.61 ✓
Sn 135.97 X
Sn 44.99 X
Sn 43.61 X
R 777.52 ✓
R 225.95 X
R 225.95 X
R 1,471.77 ✓
nd 404.56 ✓
Sn 552.55 X
R 986.70 X
Sn 552.55 X
R 986.70 X
R 2,872.68 ✓
Sn 470.06 X
Sn 323.05 X
Sn 493.35 X
Sn 493.35 X
R 225.36 ✓
R 225.36 ✓
Sn 276.08 X
Sn 276.08 X
R 367.84 X
R 367.84 X