



VIFI PTE LTD

REPAIRS WITH ETHICS

Your Ref: GBE9463M

Our Ref: SLG5149T

To: AXA INSURANCE PTE LTD

CC

Email

Fax

Date: 08-10-18

From: Ezuwan

Fax: 6659 0111

Contact: 8811 1110

Make / Model: FORD MUSTANG CONVERTIBLE 2.3

Chassis No.: 1FATP8UH1G5334967

Engine No.: G5334967

Year of Make: 2016

Accident Date: 02-10-18

ESTIMATE FOR VEHICLE NO. : SLG5149T

DESCRIPTION

- FRONT BUMPER
- FRONT BUMPER UPPER GRILL
- FRONT BUMPER LOWER GRILL
- FRONT RIGHT FOG LAMP COVER
- FRONT BUMPER LIP
- BUMPER CLIP

*Rasul*  
*Hp 90010068*  
*3 days*  
*4s*  
*12/10/18 @ 1600*  
*Resurvey after repair*

QTY		List Price
1	\$	<i>scr</i> 3,180.00
1	\$	<i>X</i> 980.00
1	\$	<i>?</i> 740.00
1	\$	<i>X</i> 560.00
1	\$	<i>scr</i> 840.00
10	\$	<i>u</i> 80.00

Total: \$ 6,380.00

LESS 10% \$ (638.00)

Parts Total: \$ 5,742.00

SPECIAL NETT

- ANTI RUST COATING
- BODY SEALANT

1	\$	<i>40</i> 150.00
1	\$	<i>X</i> 120.00

LABOUR

- TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
- TO CHECK & RECONNECT ALL NECESSARY WIRING
- TO SPRAY PAINTING ON THE AFFECTED AREA

	\$	<i>300</i> 600.00
	\$	<i>X</i> 150.00
	\$	<i>600</i> 1,800.00

Total: \$ 8,562.00

7% GST: \$ 599.34

Grand Total: \$ 9,161.34

Please survey the vehicle at :-

1 Bukit Batok Crescent  
#06-12, WCEGA PLAZA  
SINGAPORE 658064

(Kindly contact Ezuwan @ 8811 1110)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VIFI PTE LTD

1 BUKIT BATOK CRESCENT

#06-12, WCEGA PLAZA

t 67670011

Company Registration Number : 201315095D