

ASS. REC. BY:

REF: CS/CT118018493/ Urd3

Official Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

11/10/18 @ 4:20pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 6307K

Insured:

GY 2863Z

at Workshop m/s

Tan Him Motor

Tel:

6858 5151

of

51 Defu Lane 10

Policy No:

DMCVSN 3010021800

Claim No:

SNM18D04853C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/10/2018

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

4:26pm @ 11/10/18

Person Contacted:

william

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	Estimate
	SKB 6307K - 003/A1G16017027/Gybn2	Don: 17/8/2016
	GY 2863Z - CS/III71025292/KF/k3	Don: 3/12/2011

Workshop no/cus

REF:

CT1/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SKB6307K**
 at Workshop no/cus: **12/10/18**
 of: **G 4/2863+**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: **3** days Res: Yes or No

Lum Sum: **2** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

ATA 20330

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SKB6307K** Yr Reg: **3 10**
 Type: **CA** M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or **CA**
 Make: **Audi A3** C.C. **1798**
 Colour: **Grey** A/C: Insured / Std / NI / NA
 Sp. Reading: **122203** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 G/No: **WAUZZZ8P0NA116861**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brakes: **Good** / Jammed / Leaked / Burnt or
 Mod: **NI** / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: **225/45 R17**
 ES / JUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front **6** mm Rear **6** mm
 R/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **10/10/18** D.O.I. **11/10/18**
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

11/10/18 confirmed 4/5 @ 2600 with will. (Red. 4/13/18, G12)

RECEIVED 25 OCT 2018

Date/Time: File Pass to:

☐ : Prel. Report
☐ : Final Report

Date/Time: File Return to:

3

Days Of Repair: **3**

Resurvey No. of Trip: **-**

Survey Fee

Transportation

1. ___ 2. ___ 3. ___

4. ___ 5. ___

6. ___ 7. ___

TOTAL

Add Fee: ☐ Site Insp. 15

☐ Interview 15

☐ Tech. Insp. 15

☐ Weekend 15

Report Format: **TP**

Lump Sum / I.B.R. 2600

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submit Time	Dis Auth'd	Status
Main	11 Oct 2018		11 Oct 2018 16:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MS CHARMING TRADING , Co. Reg. No.: B530138/08-E		
Main Claimant:	ESTRELLITA P JAVIER , ID: S2205130Z		
Vehicle Reg. No.:	SKB6307K	Date of Loss:	10/10/2018 09:00 - :59
Claim Type:	TP / SNM18D04853C02	Policy/Cover Note No.:	DMCVSN3010021800 (Third Party Only)
Vehicle Reg. No. (Insured):	GY2863Z	Policy No. (Claimant):	5087411671-01
		Excess:	S\$0.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/10/2018]		
Driver/Custodian (Insured):	TAN KOON SENG (58 / Male), NRIC: S2195770D, Tel: +6596274517		
Adj Asg. Remarks:	EST \$6773, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5130Z

Vehicle Details

Vehicle No.: SKB6307K
Vehicle to be Exported: No
Intended Deregistration Date: 10 Oct 2018
Vehicle Make: AUDI
Vehicle Model: A3 SPORTBACK 1.8 TFSI AT ABS D/AB HID 5D
Primary Colour: Grey
Manufacturing Year: 2010
Engine No.: CDA091213
Chassis No.: WAUZZZ8P0AA116861
Maximum Power Output: 118.0 kW (158 bhp)
Open Market Value: \$30,590.00
Original Registration Date: 30 Mar 2010
First Registration Date: 30 Mar 2010
Transfer Count: 3
Actual ARF Paid: \$30,590.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Mar 2020
PARF Rebate Amount: \$16,824.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2020
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$24,229.00
COE Rebate Amount: \$3,506.00
Total Rebate Amount: \$20,330.00

The information contained herein is correct as at 10 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/10/2018 15:27
Date Of Accident	10/10/2018 09:50
Exact Location Of Accident	TPE BEFORE EXIT 12
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB6307K
Insured/Policyholder	
Name Of Registered Owner	ESTRELLITA P JAVIER
NRIC No	S2205130Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97832098
Alternative Phone No	OFFICE-97832098

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SPORTBACK 1.8 TFSI AT ABS D/AB HID 5D
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087411671-01
Cover Note Number	

Driver

Name of Driver	ESTRELLITA P JAVIER
NRIC No	S2205130Z
Date Of Birth	02/09/1950
Occupation	INDOOR
Date Of Driving Pass	29/08/1984
Driving Experience	34 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-97832098
Fax Number	
Contact Number	OFFICE-97832098
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

OCT 10 2018

3:36pm

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper	\$ 1,700.00
02	1 pc	rear bumper lower diffuser/garnish	\$ 250.00
03	1 pc	rear bumper reinforcement	\$ 750.00
04	1 pc	rear bumper absorber foam	\$ 380.00
05	1 pc	rear bumper inner frame	\$ 280.00
06	2 pc	rear bumper bracket @ \$100.00	\$ 200.00
07	2 pc	rear bumper side retainer @ \$50.00	\$ 100.00
08	1 pc	rear bumper lower splashshield cover	\$ 280.00
09	2 pc	rear bumper side holder @ \$125.00	\$ 250.00
10	1 pc	rear hatch door A3 badge	\$ 90.00
11	1 pc	rear hatch door 1.8T badge	\$ 90.00
			\$ 4,370.00
		Less 10 %	\$ 437.00
			\$ 3,933.00
		<u>SPECIAL NETT ITEMS</u>	
12	2 pc	rear bumper parking sensor @ \$450.00	\$ 900.00
			\$ 900.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 150.00
02		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 180.00
03		To check electrical lighting concerned.	\$ 60.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 750.00
05		Putty and spray painting of the affected portion.	\$ 800.00
			\$ 1,940.00
		Total	\$ 6,773.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Oct 2018		11 Oct 2018 16:20 Edit Adj Rpt	\$52,600.00 Edit Estimates	\$52,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	MS CHARMING TRADING , Co. Reg. No.: B530138/08-E								
Main Claimant:	ESTRELLITA P JAVIER , ID: S2205130Z								
Vehicle Reg. No.:	SKB6307K	Date of Loss:	10/10/2018 09:00 - :59 [102 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04853C02	Policy/Cover Note No.:	DMCVSN3010021800 (Third Party Only)						
Vehicle Reg. No. (Insured):	GY2863Z	Policy No. (Claimant):	5087411671-01						
		Excess:	S\$0.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/10/2018]								
Driver/Custodian (Insured):	TAN KOON SENG (58 / Male), NRIC: S2195770D, Tel: +6596274517								
Adj Asg. Remarks:	EST \$6773, ASSIGN MARCUS CHUA AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Claim Documents

*SKB6307K (SNM18D04853C02)
[GY2863Z]
TP
ESTRELLITA P JAVIER
Oct 10 2018 9:00AM
[MS CHARMING TRADING]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	10/10/18 15:50	Accident Statement							Load HTM		
Photos/Images											
									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	10/10/18 15:49	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	19/10/18 19:00	General View							Load PDF		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	11/10/18 16:19	EMAIL FM TAN LIM							Load PDF		
2	11/10/18 16:19	REPAIR EST							Load PDF		
3	11/10/18 16:19	OI GIA							Load PDF		
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	10/10/18 15:48	Sketch Plan [Linked Accident Report Documents]							Load TIF		

Linked Accident Report Documents

										View	View in Browser
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	10/10/18 15:50	Accident Statement							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)							Thumbnail	Print	
1	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	
2	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	
3	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	
4	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	
5	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	
6	10/10/18 15:49	Accident Photo							Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
7	10/10/18 15:49	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	10/10/18 15:48	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118018493/URD3Q2

Date: 26/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3010021800

Claimant Vehicle
No: SKB6307KInsured Vehicle
No: GY2863Z

Date of Loss: 10/10/2018

Nature of Claim: TP

Claim
No: SNM18D04853C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB6307K

Make & Model: AUDI A3, 1.8 TFSI (A)

Reg. Date: 30/03/2010 (Man. Year: 2010)

Colour: Grey

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: CDA091213

Chassis No: WAUZZZ8P0AA116861

Odometer: 122203 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,833.00	2,430.00	2,403.00	49.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	830.00	1,110.00	57.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,773.00	3,260.00	3,513.00	51.87
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	6,773.00	2,600.00	4,173.00	61.61
+ GST 7.00/7.00% (S\$)	474.11	182.00	292.11	61.61
Nett Amount (S\$)	7,247.11	2,782.00	4,465.11	61.61

INSPECTION

Date of Assignment: 11/10/2018

Date Inspected: 11/10/2018 Inspected At:

Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 25 Oct 2018)	
Parts:	N/A	AUDI A3 1.8 TFSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB6307K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,700.00 FL	*1,700.00 FL
2	1		*REAR BUMPER LOWER DIFFUSER /GARNISH	Grazed	250.00 FL	*250.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	750.00 FL	*750.00 FL
4	1		*REAR BUMPER ABSORBER FOAM	Not Necessary	380.00 FL	*- FL
5	1		*REAR BUMPER INNER FRAME	Not Necessary	280.00 FL	*- FL
6	2		*REAR BUMPER BRACKET	Not Necessary	200.00 FL	*- FL
7	2		*REAR BUMPER SIDE RETAINER	Not Necessary	100.00 FL	*- FL
8	1		*REAR BUMPER LOWER SPLASHIELD COVER	Not Necessary	280.00 FL	*- FL
9	2		*REAR BUMPER SIDE HOLDER	Not Necessary	250.00 FL	*- FL
10	1		*REAR HATCH DOOR A3 BADGE	Not Necessary	90.00 FL	*- FL
11	1		*REAR HATCH DOOR 1.8T BADGE	Not Necessary	90.00 FL	*- FL
12	2		*REAR BUMPER PARKING SENSOR	Serviceable	900.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,270.00	2,700.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	437.00	270.00
Total Parts (\$\$)	4,833.00	2,430.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	180.00	60.00
3	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	750.00	300.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	800.00	400.00
Gross Labour Cost (S\$)			1,940.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >