BMW Dealer

Performance Motors Limited a member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

09 OCT 2018

ESTIMATE

Estimate No. Page No. : 1 of 5 : b1 48717

: 09/10/2018 Date Estimated Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -- ACCOUNT -40000

SIMON TAN SEOW BOON 989 BUKIT TIMAH ROAD

#02-06

Cash Sales - Service

Singapore

SINGAPORE 589629

REGN. NO.	CHASSIS NO.	REGN. DATE 27/07/2018	MODEL 116d		MILEAGE
SMC9057H	V945593	27/07/2018	1100		0
	DESCRIPTION Replace rear boot lid,rear bumpetc include repairs on accident		ment		VALUE 3,400.00
	Spray painting rear boot lid, rear bumper and tail end panel				
	To replace rear windscreen glass.				
	To conduct water leak tests.				75.00
:	To remove and install boot com to facilitate repairs.	partment carpet and g	arnish		271.00
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	To check electrical wiring syste rear section for proper function.		•		177.00
	To carry out body cavity present (Per panel).	vation.			118.00
	To supply rear emboss number	plate.			83.00
	Sundries.				150.00
	To supply and install rear winds	creen solar film.			531.00
				Total Labour 1:	8,045.00
	DESCRIPTION			QTY PRIC	VALUE
	BOOTLID			1 1,108.45	1,108.45
	REAR BUMPER CARRIER			1 385.25	385.25
	REAR BUMPER CENTRE GUIL	• •		1 57.45	57.45 54.50
	REAR BUMPER TOWING EYE REAR BUMPER LH MOUNT	COVER PRIMED		1 54.50 1 142.55	54.50 142.55
	REAR BUMPER RH MOUNT			1 142.55	142.55
	(S/L) LH PROTECTION FOIL			1 8.40	8.40
	(S/L) RH PROTECTION FOIL			1 8.40	8.40

Estimate No.

Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)

Grand Total

15,243.33



Page No. : 2 of 5

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated Prepared By	: b1 4871 : 09/10/2013 : Chua Kee	3			Page No.	: 2 of 5	5
REGN. NO. SMC9057H	CHASSIS NO. V945593	REGN. DATE 27/07/2018	MODEL 116d			MILEA O	.GE
REAR I REAR I REAR I MICRO GAS PI TRUNK STRIKE EMBLE SUPPO REAR I BUMP : LOADIN PLAQU TRUNK DECOL PDC se (DG) CI (DG/SL (DG/SL (DG/SL Date& Time Surveyor's Tel Michobal Date Surveyor's Tel	NG SILL COVER E 82MM LID GASKET JPLING RING PDC TO INSOR LEANER R1 (100ML) W/SCREEN SEALA GLASS PRIMER 30 Brd Party / Uninsured in	G F TRUNK LID DRQUE CONVERTE NT (COLD 1 HOUR) ML (VP208) DSSés / Direct Settlemen: Claim No. Excess S\$ Sign Authorised Yes / No Time DK Yes / No PML (es / No.)		QTY	PRIC 947.35 23.10 88.40 115.20 155.70 55.75 103.40 35.55 595.25 3.25 77.20 69.50 66.95 5.05 368.80 26.15 131.55 27.85	:	947.35 23.10 88.40 230.40 155.70 55.75 103.40 35.55 595.25 32.50 77.20 69.50 66.95 20.20 1,475.20 26.15 263.10 27.85
				Labour 1 Parts Labour 2 Excess Total GST	י @ 7%	: : : : : : : : : : : : : : : : : : : :	8,045.00 6,201.10 0.00 0.00 997.23

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

10/9/2018 Invoice



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No:

GR-18-156012

Date of Request:

09/10/2018

Your Ref No:

Online Purchase

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Dear Sir/Madam,

Enquiry Date

09/10/2018

Enquiry By

Melanie Setiawati

TP Vehicle No.

SJN4274H

Accident Date

09/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJN4274H	EQ Insurance Company Ltd	28/05/2018-27/05/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

10/9/2018 Invoice



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580 Phone: +65 6224 0010 Fax: +65 6224 0030 Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No:

GR-18-156012

Date of Request:

09/10/2018

Your Ref No:

Online Purchase

Performance Motors Limited 303 Alexandra Road Sime Darby Performance Centre Singapore 159941

Dear Sir/Madam,

Enquiry Date

09/10/2018

Enquiry By

Melanie Setiawati

TP Vehicle No.

SJN4274H

Accident Date

09/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

[X] GIRO [] Cash [] Cheque

IDENTITY CARD NO. \$8563446A





YU YUANCAN









Date of birth 03-08-1985

S8562446A

Country/Place of birth

9461610



CHINESE Date of issue 02-10-2017

989 BUKIT TIMAH ROAD #02-06 SINGAPORE 589629





Insurance

www.libertyinsurance.com.sg

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Name of Policyholder:

SIMON TAN SEOW BOON

Effective Date of Commencement:

Date of Issue: 10 Aug 2018

27 Jul 2018 00:00

Registration No.:

Chassis No.:

SMC9057H

WBA1V72040V945593

Certificate No.:

SD18V08353/ VPC / R00

Date of Expiry:

26 Jul 2019 23:59

Type of Certificate:

Persons or Classes of Persons entitled to drive*:

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

> For and on behalf of LIBERTY INSURANCE PTE LTD

Approved Insurers

For Information Only:

Coverage(s): Comprehensive, Unlimited Windscreen

Sum Insured: 31 MARKET VALUE AT THE TIME OF LOSS

Excess: Section I S\$800,Additional Excess for Young & Inexperienced Drivers S\$2500,Windscreen Excess

Name of Finance Company: DBS BANK LTD

SD CONTEGO SERVICES (A1429-5) Name of Producer:

ROBO1/PLGG/SD18V08353/17-Aug-2018/MotorCJ/v1.0