

JW-HM

CC 61 804

180 18564

Upas y

ASSIGNMENT

Surveyor

Mafm

DOI

17/10/18

Date / Time

17/10/18

Registered in Merimen

Pre-assign / CCU / FTE

GP 5934U



Insured Vehicle No.

GP 5934U

Claim No.

Name of Insured

Policy No.

Insured Tel No.

HP

Make / Model

Excess Sec II :S\$

D.O.A

10/10/18

Place of Accident

Is driver the owner?

( YES / NO )

Nature of Accident

If NO, Driver Name / Age

Driver Tel No.

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

6u17064



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

7/10/18

6u17064, x; GP 5934U-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

24/10/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Tarun

Email

Call

Final Liability:

%

100/10/18

(Agreed / Assigned) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

5564.00

Loss of Rental (LOR):

S\$

640.00

(\$ 80 x 8 days)

Loss of Use (LOU):

S\$

640.00

(\$ 80 x 8 days)

Loss of Income (LOI):

S\$

640.00

(\$ 80 x 8 days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

2.00

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

(e.g. Tow/ Independent)

Total:

S\$

6206.00

Global Sum S\$:

6200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6200.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

19/10/18

av 20/10/18

Guarantee 120/125

REF:

54/

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: **GU 17064**  
 at Workshop no: **H.**  
 of \_\_\_\_\_  
 insured: **59959344**  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **22500**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: **7** days Res: Yes or No  
 Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

**30/4/2022**  
 Vehicle IN / OUT

Date \_\_\_\_\_ Person Contacted \_\_\_\_\_

Veh No: **GU17064** Yr Regn: **2 01**  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or **(M)**  
 Make: **Hyundai H100** C.C. **2476**  
 Color: **Silver** A/C: Insured / Std / NI / NA  
 Sp. Reading: **399048** T/Radio: Insured / Std / NI / NA  
 Engine: \_\_\_\_\_  
 C/Nr: **KMF6D27FP1K 484612**  
 Gen. Cond: **Good** Fair / Poor / Burnt  
 Steering: **Good** Jammed / Leaked / Burnt or  
 Brake: **Good** Jammed / Leaked / Burnt or  
 Mod: **Nil** SIRim / STD AIRim or  
 Tyre Size: F: \_\_\_\_\_ R: **175 215**  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or **FALKEN**  
 Front **6** Rear **6**  
 R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
 L/Bal. **6** mm L/Bal. **6** mm  
 D.O.A. **10/10/18** D.O.I. **12/10/18**  
 Survey held at: \_\_\_\_\_  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
**Rear N/S**  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction **Per 45600**

**3.15 pm. LTA 17043 net 5457**  
**have 6.9**

**30/10/18 4/5 5200 constant rate after.**

**(Red 9279.44/644)**

Date/Time File Pass to?

☐

: Preli. Report

Days Of Repair:

To:

☐

: Final Report

Resurvey No. of Trip:

Date/Time File Return to?

To:

Add Fee:

☐  
☐  
☐  
☐

Site Insp. 1\$  
 Interview 1\$  
 Tech. Insp. 1\$  
 Weekend 1\$

Survey Fee:

Transportation:

1. 3+75.00

2. Photo

3. News

4. Other

5. Other

Report Format:

Lump Sum / I.B. / 1\$

**FASTECH AUTO PTE LTD**  
**1 KAKI BUKIT AVENUE 6**  
**#01-46/48/50**  
**SINGAPORE 417883**

VEHICLE NO: GU 1706Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary cost(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Adhered*  
*12/10/18*  
*2/5 \$5200/-*  
*7 day.*

QTY	PARTICULAR		
1 PCS	TAILGATE	<i>Body 1285.20</i>	\$1,985.30 ✓
1 PCS	TAILGATE INNER LOCK	<i>10/15m 105</i>	\$288.20 ✓
1 PCS	TAILGATE INNER TRIM BOARD	<i>11</i>	\$311.30 x
1 SET	TAILGATE INNER TRIM BOARD CLIPS	<i>11</i>	\$50.00 x
1 PCS	TAILGATE WEATHERSTRIP	<i>1m/1m 145.00</i>	\$266.40 ✓
1 PCS	TAILGATE OUTER HANDLE	<i>11</i>	\$385.30 x
1 PCS	TAILGATE REAR WIPER MOTOR	<i>11</i>	\$685.00 x
1 PCS	REAR WINDSCREEN RUBBER	<i>1m</i>	\$229.30 <i>5025.20</i>
1 PCS	REAR BUMPER	<i>215 425.30</i>	\$822.10 ✓
1 PCS	REAR BUMPER BEAM	<i>210.50</i>	\$350.00 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @ \$85.00	<i>1m 45.50 x 2 = 91.00</i>	\$170.00 ✓
1 SET	REAR BUMPER CLIPS	<i>1pc</i>	\$50.00 ✓
1 PCS	REAR END PANEL	<i>306.50</i>	\$688.50 ✓
1 PCS	REAR END PANEL TOP PLATE	<i>11</i>	\$215.00 x
2 PCS	TAILLAMPS @ \$350.00	<i>1/3 1m 225.00</i>	\$700.00 <i>1pc</i>
1 PCS	REAR EXHAUST	<i>11</i>	\$988.50 x
2 PCS	REAR EXHAUST MOUNTINGS @ \$30.00	<i>11</i>	\$60.00 x
1 PCS	REAR FENDER N/S	<i>Body 100/3uc 1466.50</i>	\$1,885.00 ✓
1 PCS	REAR FENDER OUTER RUBBER N/S	<i>1m 225.00</i>	\$365.00 ✓
1 PCS	REAR '70KM/H' STICKER	<i>1m</i>	\$12.00 ✓
1 SET	REAR REVERSE SENSOR	<i>1m</i>	\$250.00 ✓
1 PCS	TAILLAMP HOUSING PANEL N/S	<i>Body 150 184.50</i>	\$322.50 ✓
			<b>\$11,079.40</b>

**LABOUR CHARGES:**

TO CHECK WIRING	\$80.00 <i>20</i>
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00 <i>50</i>
TO DISMANTLE & REFIX REAR WINDSCREEN GLASS	\$120.00 <i>60</i>
TO DISMANTLE & REFIX REAR EXHAUST	<i>11</i> \$120.00 x
TO TRANSFER TAILGATE MECHANISM	\$120.00 <i>60</i>
TO SPRAY RUST PROOFING	\$100.00 <i>80</i>
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS	\$1,280.00 <i>1200</i>
TO PUTTY & SPRAY PAINTING	\$1,500.00 <i>900</i>
<b>TOTAL</b>	<b>\$14,479.40</b>

*65269.7*

*5049.5*

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	8054B

**Vehicle Details**

Vehicle No.:	GU1706Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	11 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	GRACE H100 M
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	D4BFY033636
Chassis No.:	KMFGD27FP1K484612
Maximum Power Output:	-
Open Market Value:	\$18,026.00
Original Registration Date:	02 Feb 2001
First Registration Date:	02 Feb 2001
Transfer Count:	0
Actual ARF Paid:	\$902.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	30 Apr 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$24,005.00
COE Rebate Amount:	\$17,056.00
<b>Total Rebate Amount:</b>	<b>\$17,056.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Oct 2018

OK

## Hsiao Tong (LKKAUTO)

---

**From:** Jason Fastech Auto <jason@fastechauto.com.sg>  
**Sent:** Monday, 17 December 2018 10:02 AM  
**To:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: Your Ref: GU 1706Y \*Our Ref: CC6/EQI18018564/Upa3 [ACCIDENT INVOLVING SJP 5934U(EQ) & GU 1706Y ON 10/10/2018]

Without Prejudice

Dear Hsiao Tong,

We are pleased to accept your offer of global sum of \$6,200.00(all-in) for my client vehicle's property claim.

Thank you.

Best Regards

Jason Tang  
Fastech Auto Pte Ltd  
1 Kaki Bukit Ave 6  
#01-46/48/50 AutoBay  
Singapore 417883  
Tel: 67465405  
Hp: 98218445  
[jason@fastechauto.com.sg](mailto:jason@fastechauto.com.sg)

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** Saturday, December 15, 2018 1:35 PM  
**To:** Jason Fastech Auto (jason@fastechauto.com.sg) <jason@fastechauto.com.sg>  
**Subject:** Your Ref: GU 1706Y \*Our Ref: CC6/EQI18018564/Upa3 [ACCIDENT INVOLVING SJP 5934U(EQ) & GU 1706Y ON 10/10/2018]

Your Ref: **GU 1706Y** Without Prejudice  
Our Ref: CC6/EQI18018564/Upa3

Dear Sirs/Madam,

### **ACCIDENT INVOLVING SJP 5934U(EQ) & GU 1706Y ON 10/10/2018**

We refer to the above matter.

We propose settlement at a global sum of **\$6,200.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in

respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Mei Kwan (LKKAuto)

---

**From:** Justin Wong <justin.wong@eqinsurance.com.sg>  
**Sent:** Friday, 19 October, 2018 3:34 PM  
**To:** Mei Kwan (LKKAuto)  
**Cc:** Hsiao Tong (LKKAuto); Vic (LKKAuto); Admin A  
**Subject:** RE: Direct Settlement - Accident Involving SJP5934U (OI : EQI - TBA) AND GU1706Y (TP : LKK REF - CC6/EQI18018564/Upa3) on 10/10/2018  
**Attachments:** OI GIA - SJP5934U.PDF  
**Categories:** HMK


Dear Mei Kwan,

Please find our insured's GIA report and proceed with direct settlement.

Regards,  
**Justin Wong**  
Executive | Claims



**EQ Insurance Company Limited**  
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110  
did 65 6496 9115 | tel 65 6223 9433 ext 115 | fax 65 6223 4190  
[www.eqinsurance.com.sg](http://www.eqinsurance.com.sg)



*Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the*

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Friday, October 19, 2018 2:44 PM  
**To:** Justin Wong <justin.wong@eqinsurance.com.sg>  
**Cc:** Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>  
**Subject:** Direct Settlement - Accident Involving SJP5934U (OI : EQI - TBA) AND GU1706Y (TP : LKK REF - CC6/EQI18018564/Upa3) on 10/10/2018

**EQI ref: TBA**  
**LKK REF: CC6/EQI18018564/Upa3**

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle GU 1706Y at M/s Fastech Auto Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:  
- TP GIA report

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67465405 / 67465376 Fax No: 67458520

Tax Reg No: 200006262D

Date :05.11.2018

EQ Insurance Company Limited

5 Maxwell Road

#17-00 Tower Block MND Complex

Singapore 069110

Attn: Motor Claim Department

## **ACCIDENT INVOLVING VEHICLE: GU1706Y AND SJP5934U ON 10.10.2018**

---

We are the authorized repair workshop for the owner of motor vehicle no: **GU1706Y**, which was involved in the captioned accident with your insured vehicle no: **SJP5934U**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

1) Cost of Repair (inclusive of GST)	\$	5,564.00
2) Loss Of Use(7days + 1sun x \$150)	\$	1,200.00
3) GIA Search Fee	\$	2.00
	<b>\$</b>	<b>6,766.00</b>

We enclosed herewith the following documents to support the claims:

- |                                 |                                    |
|---------------------------------|------------------------------------|
| a) Final Repair Invoice         | b) Vehicle Registration Log Card   |
| c) GIA Report/GIA Search Result | d) I/C & Driving Licence           |
| e) Insurance Certificate        | f) Letter of Authorisation, etc... |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you.

Yours faithfully,

Allan Tang

For Fastech Auto Pte Ltd





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQI18018564/Upa3

25 OCT 2018

**CHAN CHER HUAT**  
BLK 812C CHOA CHU KANG AVE 7  
#02-631  
SINGAPORE 683812

Dear Sir/Madam,

**ACCIDENT INVOLVING SJP 5934U AND GU 1706Y ON 10/10/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, EQ Insurance Company Ltd to deal with the third party claim against your policy.

We have received a claim from GU 1706Y against your insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHEW HSIAO TONG  
Case Handler  
DID: 6742 3197  
FAX: 6741 4108  
EMAIL: chewht@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*  
*(Motor Claims Dept)*

DATE : 11th Oct 2018

TO : EQ Insurance Company Limited

RE : ACCIDENT INVOLVING VEHICLE NO. GU 1706Y & SJPS9344

ALONG PIE towards Changi

ON 10/10/2018

I/We, Lee Hong Jee

of (NRIC No./ROC No.) S1238054B

of 209 Teo Payoh North #05-1285 S 310209

owner of vehicle no. GU 1706Y in consideration of M/s FASTECH AUTO

PTE LTD repairing my/our vehicle GU 1706Y at my/our instruction and hereby

authorise M/s FASTECH AUTO PTE LTD to demand claim settlement whatever

amount settled/payable by the Insurance Company and/or third party or to commence legal proceedings, if necessary, under my name, for the cost of repairs, car rental and/or loss of use, etc. and to their appointing solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall belong to them absolutely.

I/We further agree and undertake to indemnify them against the above-mentioned claim cost which may arisen therewith.

Signature of Owner :



Name of Owner :

Lee Hong Jee

## TAX INVOICE

### **FASTECH AUTO PTE LTD**

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax.Reg No: 200006262D

EQ Insurance Company Limited  
5 Maxwell Road  
#17-00 Tower Block MND Complex  
Singapore 069110

Attn: Motor Claim Department

Tax Invoice : 20630

Date: 05.11.2018  
Vehicle No: GU1706Y  
Make/Model: HYUNDAI GRACE

Accident Date: 10.10.2018  
Claim No : 1018-20630  
Reference :  
Policy No :

---

		Amount
To proceed on lump sum repair	SS	5,200.00

E. & O. E.

Total : S\$	5,200.00
GST @ 7% : S\$	364.00
<b>Amount Due : S\$</b>	<b>5,564.00</b>

  
for FASTECH AUTO PTE LTD

All Invoices are subjected to GST

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-157991

Date of Request: 11/10/2018

Your Ref No:

Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 11/10/2018

Enquiry By Tang Kok Wee, Allan

TP Vehicle No. SJP5934U

Accident Date 10/10/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJP5934U	EQ Insurance Company Ltd	30/09/2018-29/09/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-157991

Date of Request: 11/10/2018

Your Ref No: Online Purchase

Kim Chwee Auto Pte Ltd  
1 Kaki Bukit Avenue 6 #01-48  
AutoBay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 11/10/2018  
Enquiry By Tang Kok Wee, Allan  
TP Vehicle No. SJP5934U  
Accident Date 10/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 27/12/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	SJP 5934U (Insd Veh)	Your Ref. No. : DMPPHQ18-006746
	GU 1706Y (TP Veh)	Our Ref. No. : CC6/EQI18018564/Upa3q2
Date of Accident	10/10/2018	

Liability	100%	
Final Repair Cost	: \$ 5,564.00	
Loss of Use	: \$ 640.00	8 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	6,206.00	
Final Settlement Sum	: \$ 6,200.00	GLOBAL SUM
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	FASTECH AUTO PTE LTD	: \$ 6,200.00
		: \$

JOANNE LEE  
LKK Auto Consultants Pte Ltd




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQI18018564/Upa3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 27-12-2018	
			Code : EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJP 5934U	Veh. Inspected	GU 1706Y	
Policy No.	DMPPHQ18-006746	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	12/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI H100 (M)	c.c	2476	
Engine No.	HIDDEN	Year of Reg.	2001	
Chassis No.	KMFGD27FP1K484612	Colour	SILVER	
Odometer	399048	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185 R15	FALKEN	6 mm	
L/H Front Tyre	185 R15	FALKEN	6 mm	
R/H Rear Tyre	185 R15	FALKEN	6 mm	
L/H Rear Tyre	185 R15	FALKEN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	10/10/2018	Inspection Date	12/10/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GU 1706Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BADLY DENTED	1,985.30	1,285.20
1	TAILGATE INNER LOCK	DENTED / JAMMED	288.20	105.00
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	311.30	-
1	SET TAILGATE INNER TRM BOARD CLIPS	NOT NECESSARY	50.00	-
1	TAILGATE WEATHERSTRIP	TWISTED / NECESSARY	266.40	145.00
1	TAILGATE OUTER HANDLE	NOT NECESSARY	385.30	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	685.00	-
1	REAR BUMPER	DISTORTED	822.10	425.30
1	REAR BUMPER BEAM	BENT	350.00	210.50
2	REAR BUMPER SIDE HOLDERS @\$85.00	CRACKED	170.00	91.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	688.50	366.50
1	REAR END PANEL TOP PLATE	NOT NECESSARY	215.00	-
2	TAILLAMPS @\$350.00	N/S CRACKED	700.00	225.00
1	REAR EXHAUST	NOT NECESSARY	988.50	-
2	REAR EXHAUST MOUNTINGS @\$30.00	NOT NECESSARY	60.00	-
1	REAR FENDER N/S	BADLY DENTED / BUCKLED	1,885.00	1,466.50
1	REAR FENDER OUTER RUBBER N/S	NECESSARY	365.00	225.00
1	REAR '70KM/H' STICKER	NECESSARY	12.00	12.00
1	SET REAR REVERSE SENSOR	CRACKED	250.00	250.00
1	TAILLAMP HOUSING PANEL N/S	BADLY DENTED	322.50	184.50
	LESS 20% DISCOUNT		-	-1,008.30
			10,850.10	4,033.20
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN RUBBER (50%) (SN)	NECESSARY	229.30	146.50
			229.30	146.50
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00

Report Ref No. CC6/EQ18018564/Upa3q2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	120.00	60.00
	TO DISMANTLE & REFIX REAR EXHAUST .		120.00	-
	TO TRANSFER TAILGATE MECHANISM .		120.00	60.00
	TO SURAP RUST PROOFING.		100.00	80.00
	LABOUR FOR PANEL BEATING ,CUT & REPLACING PARTS.		1,280.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,400.00	2,370.00
GRAND TOTAL			14,479.40	6,549.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CC6/EQ18018564/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.