

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@ymail.com

Invoice/Ref No: YP6237P181010

**Final Bill****Customer**Name: AXA Insurance Pte Ltd  
Motor Claims DepartmentDate: 12-01-19  
Vehicle No: YP6237P  
Model/Make: Mitsubishi Fuso  
FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Windscreen Glass	\$ 1,526.00	\$ 1,526.00
2	Windscreen Glass Weatherstrip	\$ 691.50	\$ 691.50
3	Wiper Panel	\$ 2,436.60	\$ -
4	Corner Panel	\$ 383.60	\$ 383.60
5	"FUSO" Mark	\$ 280.10	\$ 280.10
6	Grille	\$ 978.10	\$ 978.10
7	Grille "Motsubishi" Motif	\$ 155.30	\$ -
8	Panel	\$ 3,263.20	\$ -
	Total		\$ 3,859.30
	Parts Less 25%		\$ 964.83
	<b>Total Parts After Less 25%</b>		<b>\$ 2,894.47</b>
9	Front Rh "Corporate" Advertisement & Artwork	\$ 350.00	SN \$ 120.00
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	\$ 600.00
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	\$ 550.00
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 200.00	\$ 120.00
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	\$ -

**Total Parts & Labour of estimate for damaged vehicle****\$ 11,944.40****Total amount in Parts By Parts Basis for repaired vehicle****\$ 4,284.47**SDLS: Four Thousand Two Hundred Eighty-Four And Cents  
Forty-Seven Only.

M/s Liu's Brother Auto Engrg Wks