



EQ Insurance Company Ltd  
5 Maxwell Road  
#17-00 Tower Block  
MND Complex  
Singapore 069110

CarCrafters Singapore Pte Ltd

48 Toh Guan Road East  
#05-155, Enterprise Hub  
Singapore 608586

## Repair Estimate

Tel: 6267 9916  
Fax: 6267 9313  
www.carcrafters.sg

Date : 11-Oct-2018

Vehicle Num : SKG6852B

Make/Model : VW TIGUAN 2.0 TSI

Chassis No : WVGZZZ5NZDW000780

| S/N | PARTS                                                                                                                    | QTY | PRICE     | TOTAL       |
|-----|--------------------------------------------------------------------------------------------------------------------------|-----|-----------|-------------|
| 1   | LOWER SPOILER                                                                                                            | 1   | \$ 250.00 | \$ 250.00   |
| 2   | REAR BUMPER                                                                                                              | 1   | \$ 740.00 | \$ 740.00   |
| 4   | REINFORCEMENT                                                                                                            | 1   | \$ 390.00 | \$ 390.00   |
| 5   | BUMPER GUIDE PIECE LH                                                                                                    | 1   | \$ 28.00  | \$ 28.00    |
| 6   | BUMPER GUIDE PIECE RH                                                                                                    | 1   | \$ 34.00  | \$ 34.00    |
| 7   | END PANEL                                                                                                                | 1   | \$ 500.00 | \$ 500.00   |
| 8   | LICENSE PLATE LIGHT                                                                                                      | 1   | \$ 27.00  | \$ 27.00    |
| 10  | REFLECTOR LH                                                                                                             | 1   | \$ 38.00  | \$ 38.00    |
| 12  | REFLECTOR RH                                                                                                             | 1   | \$ 38.00  | \$ 38.00    |
| 13  | PARKING SENSOR                                                                                                           | 4   | \$ 160.00 | \$ 640.00   |
|     |                                                                                                                          |     |           |             |
|     | <b>TOTAL PARTS</b>                                                                                                       |     |           | \$ 2,685.00 |
|     | <b>LABOUR</b>                                                                                                            |     |           |             |
| 1   | To remove/ replace/ refit & panel rear portion of realigned rear bumper, end panel, lower spoiler & other affected area. |     |           | \$ 1,000.00 |
| 2   | To putty & respray rear bumper, tailgate, end panel, & other affected accident area.                                     |     |           | \$ 1,000.00 |
| 3   | To check accident affected wiring system & recover.                                                                      |     |           | \$ 50.00    |
| 4   | To remove, refix rear sensor.                                                                                            |     |           | \$ 50.00    |
| 5   | To recode & decode engine management system & fault code clearing after repair works.                                    |     |           | \$ 100.00   |
|     |                                                                                                                          |     |           |             |
|     | <b>TOTAL</b>                                                                                                             |     |           | \$ 4,885.00 |
|     | <b>GST 7%</b>                                                                                                            |     |           | \$ 341.95   |
|     | <b>GRAND TOTAL</b>                                                                                                       |     |           | \$ 5,226.95 |