



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

# ESTIMATE FOR SLH216K

## SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 27508  
Reg No/Reg Date SLH216K / 21/10/2016  
Date In/Mileage 22/10/2018/ 30876  
Chassis No WDD2050402R213607  
Engine No 27491030729140  
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A  
Colour/Trim 027 775 Iridium Sil/ 041 101 Black ARTIC

| Account No | Terms  | Date/Time Printed | CSE | Operator           |
|------------|--------|-------------------|-----|--------------------|
| WC000668   | Credit | 15/02/2019/ 17:25 |     | 395 / Yik Chan Hoe |

| Description of Goods / Services  | Qty  | Unit Price | Disc% | Amount |
|----------------------------------|------|------------|-------|--------|
| X FRONT SUPPORT PANEL CONSOLE    | 1.00 | 208.24     | 00.00 | 208.24 |
| X LEFT FRONT CROSSMEMBER BRACKET | 1.00 | 67.61      | 00.00 | 67.61  |
| X COVER ENGINE COMP. BM          | 1.00 | 187.61     | 00.00 | 187.61 |

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

**Yik Chan Hoe**  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272  
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

|                      |               |
|----------------------|---------------|
| Nett                 | 463.46        |
| 7% GST on            | 32.44         |
| <b>Total Payable</b> | <b>495.90</b> |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany