

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 15 Oct 2018

Preliminary Advice

Vehicle No	: SLW4999D	Accident Date	: 11/10/2018
Make	: TOYOTA PRIUS	Policy No.	: B29089136MCY
Assignment Date	: 12/10/2018	Excess	: S\$1,500.00
Date of Inspection	: 15/10/2018	Est. Duration of Repair	: 6.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	8,876.40
Revised Amount	:S\$	5,565.37
Check Items (Estimated)	:S\$	209.28
Total	:S\$	5,774.65

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	67,006.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,994.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.