

cc3, CTI 18627, Aha3n2

Surveyor:

ADMAN

DOI:

22/10/18

Date / Time:

15/10/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GV39R

Claim No.:

SNH18D04862002

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 8/10/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLV9311K



INSRS:

WSP:

Tel:

Liability:

RMKS:

C4

Full



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

Date/ Time	STAGE	DATE / PIC
19/10	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI: 26/10/2018	
	After call ltr to OI: 26/10/2018 - vic	
	Documentation Check List: Handler Typist	
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time: 20/10/18 Sent By: 23

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: PIP	S\$ 2,240.00 (3 days) Reduction: 81 %		Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 12/09/19	Confirm with: MARS LOR	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No.:	NIL	
Repair Cost: (w/ass)	S\$ 2,396.80		
Loss of Rental (LOR):	S\$ (days)		
Loss of Use (LOU):	S\$ 180.00 (\$60 x 3 days)		
Loss of Income (LOI):	S\$ (\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]		
GIA/LTA Search	S\$ 2.00		
Medical:	S\$		
Disbursement:	S\$		
Legal Cost	S\$	(e.g. Tow/ Independent)	
Total:	S\$ 2,578.80	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ 2,578.80	Name 1: CYCLE & CARRIAGE - PULCO MOTOR DEALER PUS LOR	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT 13/11/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D04862C02
Our ref: CC3/CTI18018627/Uha3

Date: 30/10/2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLV 9311K


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/10/2018 at the premises of M/s Cycle & Carriage Fulco Motor Dealer Pte Ltd - Ubi have the following to report:-

Workshop Estimate Amount	: S\$	12,217.00
Revised Estimate Amount	: S\$	2,240.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,240.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Portion



Comments/Present Status:





Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

FOR C&C USE ONLY





CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Siti Rosmawati Binte Mohamed Isnen
 Period of Insurance : 23 Jan 2018 To 22 Jan 2020
 Engine No. : 3A92UGN8819
 Chassis No. : MMBSTA13AJH000881

Vehicle No. : SLV9311K
 Policy No. : 1800005392
 Endorsement No. :
 Issued Date : 06 Feb 2018

ABOUT THE COVER

Make/Model : MITSUBISHI ATTRAGE 1.2 CVT

Engine Capacity/Tonnage : 1,193.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2018

Insuring with COE/PARE : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Siti Rosmawati Binte Mohamed Isnen - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Customer Service Centres (For windscreen claim only) Add: 20 Leng Kee Rd Singapore 156094 64700668

2. Cycle & Carriage Customer Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 406850 67461050

3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 608339 65864501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website: www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623211

FULCOMIP2 - SL

22 UBI ROAD 4 FULCO BUILDING

SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

520458



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	<table> <tr> <td>Cust No/Name</td><td>/Ms Siti Rosmawati Binte Mohamed</td></tr> <tr> <td>Reg No/Reg Date</td><td>SLV9311K / 23/01/2018</td></tr> <tr> <td>Date In/Mileage</td><td>11/10/2018/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH000881</td></tr> <tr> <td>Engine No</td><td>3A92UGN8819</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P57 / BK</td></tr> </table>	Cust No/Name	/Ms Siti Rosmawati Binte Mohamed	Reg No/Reg Date	SLV9311K / 23/01/2018	Date In/Mileage	11/10/2018/ 0	Chassis No	MMBSTA13AJH000881	Engine No	3A92UGN8819	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	P57 / BK
Cust No/Name	/Ms Siti Rosmawati Binte Mohamed														
Reg No/Reg Date	SLV9311K / 23/01/2018														
Date In/Mileage	11/10/2018/ 0														
Chassis No	MMBSTA13AJH000881														
Engine No	3A92UGN8819														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	P57 / BK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
F0000018	Credit	12/10/2018/ 19:17	DS	218 / MarsLer	11628					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
S	MIPNT88088									300 500.00
TO TRANSFER RHF & RHR DOOR COMPONENT AND MECHANISM PARTS									x 250.00	
S	MIPNT88088									x 1200.00
DIAGNOSTIC / SCANNING										
S	MIPNT88088									600 3000.00
TO REMOVE AND RE-INSTALL ROOF LINING & CAPERTING & SEAT										
TO GIVE WAY ACCESS REPAIR ON RH SIDE CENTER PILLAR (NETT)										
S	MIPNT88088									1W 200.00
TO REPLACE RHF & RHR DOOR PANEL,ETC										
-TO REPAIR ON RH SIDE CENTER PILLAR										
STRAIGHTEN,REFORM,ALIGN ON RH SIDE ACCIDENT-AFFECTED AREAS									+ 600.00	
S	MIPNT88088									420 2520.00
TO APPLT SEALANT KIT ON NEW PANEL										
S	MIPNT88088									
TO REPLACE RH SIDE SEAT BELT										
S	MIPNT98088									
SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS										
M	JJ5700B682	FR DOOR,RH PANEL ASS	3 new			1.00	986.00	0.00	+ 986.00	
M	JJ7410A940XA	TAPE,FR DR SASH,RH	new			1.00	29.00	0.00	+ 29.00	
M	JJ5730B792	RR DR,RH PANEL ASSY	revised			1.00	791.00	0.00	✓ 791.00	
M	JJ5702A161	HINGE,FR DOOR,UPR LH	3 new			1.00	54.00	0.00	+ 54.00	
M	JJ5732A110	RR DR,UPR RH HINGE				1.00	54.00	0.00	+ 54.00	
M	JJ5757A312	MOULDING, RR DOOR WI	3 new			1.00	66.00	0.00	+ 66.00	
M	JJ5755A280	WEATHERSTRIP,RR DR O				1.00	135.00	0.00	+ 135.00	
M	JJ5743A224	REGULATOR,RR DOOR WI	new			1.00	130.00	0.00	+ 130.00	
M	JJ5713A323	MOTOR,RR DOOR POWER	new			1.00	387.00	0.00	+ 387.00	
M	JJ5745A426	LATCH,RR DOOR,RH	new			1.00	318.00	0.00	+ 318.00	
M	JJ5732A101	CHECKER,RR DR	new			1.00	46.00	0.00	+ 46.00	
M	JJ7410A944XA	TAPE, RR DOOR SASH,	new			1.00	29.00	0.00	✓ 29.00	
M	JJ7000F740XA	SEAT BELT,FR SEAT PR				1.00	581.00	0.00	+ 581.00	
M	JJ7211A298HA	TRIM,CTR PILLAR,UPR				1.00	49.00	0.00	+ 49.00	
M	JJ7211A272XA	TRIM,CTR PILLAR,LWR				1.00	142.00	0.00	+ 142.00	
M	JJ7656A188XA	SCUFF PLATE,RR RH				1.00	50.00	0.00	+ 50.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name /Ms Siti Rosmawati Binte Mohamed Reg No/Reg Date SLV9311K / 23/01/2018 Date In/Mileage 11/10/2018/ 0 Chassis No MMBSTA13AJH000881 Engine No 3A92UGN8819 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000018	Credit	12/10/2018/ 19:17	DS	218 / MarsLer	11628

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z NOTES
 ACCIDENT ON 08/10/2018 ALONG CARPARK INFRONT OF TANJONG KATONG PRI
 OWNER CLAIMING THIRD PARTY
 REQUIRED REPLACEMENT CAR
 TP # GV39R TP INS : CHINA TAIPING

Estimate

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
 P/P 22/10/18
 03 days

Confirm & accepted by

Parts	3,847.00
Labour	0.00
Standard Menu	0.00
Specialist Job	8,370.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	12,217.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111	Cust No/Name	/Ms Siti Rosmawati Binte Mohamed
	Reg No/Reg Date	SLV9311K / 23/01/2018
	Date In/Mileage	11/10/2018/ 0
	Chassis No	MMBSTA13AJH000881
	Engine No	3A92UGN8819
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000018	Credit	22/11/2018/ 08:05	DS	323 / ChrisBulaclac	11628		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
S	MIPNT88088 TO TRANSFER RHF & RHR DOOR COMPONENT AND MECHANISM PARTS						300.00
S	MIPNT88088 TO REPLACE RHR DOOR PANEL,ETC -TO REPAIR ON RH SIDE CENTER PILLAR STRAIGHTEN,REFORM,ALIGN ON RH SIDE ACCIDENT AFFECTED AREAS						600.00
S	MIPNT88088 TO APPLT SEALANT KIT ON NEW PANEL						100.00
S	MIPNT98088 SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS						420.00
X	JJ5730B792	RR DR,RH PANEL ASSY	1.00	791.00	0.00	791.00	
X	JJ7410A944XA	TAPE, RR DOOR SASH	1.00	29.00	0.00	29.00	
Z	NOTES ACCIDENT ON 08/10/2018 ALONG CARPARK IN FRONT OF TANJONG KATONG PRI OWNER CLAIMING THIRD PARTY LOSS OF USE 03DAYS x S\$80.00 = S\$240.00 TP # GV39R TP INS : CHINA TAIPING						

Confirm & accepted by

Authorized signatory and company stamp

Parts	820.00
Labour	0.00
Standard Menu	0.00
Specialist Job	1,420.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	2,240.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 15 October, 2018 3:43 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GV39R (OI : CTI - SNM18D04862C02) and SLV9311K (TP : LKK REF - CC3/CTI18018627/Uha3) on 08/10/2018
Attachments: leeSZ_SNM18D04862C01-GV39R-LKKDirectSettlementAccidentLtr_CLCR95.815.pdf; MCCA18131489-GV39R.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Catherine Thia

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Monday, 15 October, 2018 1:54 PM
To: Claims Dept of CTI
Cc: Catherine Thia; Lucas Lee; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GV39R (OI : CTI - TBA) and SLV9311K (TP : LKK REF - CC3/CTI18018627/Uha3) on 08/10/2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D04862/C01/9**

Date : **15 OCTOBER 2018**

via Ordinary & Registered Mail

**SPAN AQUARIUM PTE LTD
BLK 7 KAKI BUKIT ROAD 1
#B1-08 EUNOS TECHNOLINK
SINGAPORE 415937**

Dear Sir / Madam

**ACCIDENT INVOLVING GV39R AND SLV9311K ON 08 OCTOBER 2018
ALONG BLK 65 UPPER CHANGI ROAD CARPARK**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SLV9311K**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : VIC

Ref : CC3/CT118018627/UHA3

Contact No : 68412096

via Email : VIC@LKKAUTO.COM

CC : Agent - (DR0510A) - SPAN AQUARIUM PTE LTD

F01/LKKDS-2013

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-157417
Date of Request: 11/10/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date: 11/10/2018
Enquiry By: Mars Ler Yeong Cherng
TP Vehicle No: GV39R
Accident Date: 08/10/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-157417

Date of Request: 11/10/2018

Your Ref No: Online Purchase

Cycle & Carriage Fulco Motor Dealer Pte Ltd
330 Ubi Road 3
Singapore 408650

Dear Sir/Madam,

Enquiry Date 11/10/2018

Enquiry By Mars Ler Yeong Cherng

TP Vehicle No. GV39R

Accident Date 08/10/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GV39R	China Taiping Insurance (Singapore) Pte. Ltd.	16/03/2018-15/03/2019	6389 6111

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

REPAIRER CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD - EUNOS LINK SERVICE CENTRE

MOTOR VEHICLE CLAIM DISCHARGE VOUCHER

ATTN: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
105 Cecil Street
#18-00/#19-00/#16-01/02
SINGAPORE 069428

OWNER	: <u>SITI ROSMAWATI BINTE MOHAMED</u> : <u>ISNEN</u>	VEHICLE NO	: <u>SLV9311K</u>
VEHICLE MODEL	: <u>MIT/ATTRAGE</u>	THIRD PARTY#	: <u>GV39R</u>
ACCIDENT DATE	: <u>08/10/2018</u>	WIP NO	: <u>11628</u>

I/WE CERTIFY THAT THE VEHICLE HAS BEEN FULLY REPAIRED TO MY ENTIRE SATISFACTION AND THE PAYMENT OF REPAIRER'S CHARGES ARE CLAIMABLE UNDER THE POLICY WILL BE DEEMED IN FULL AND THE FINAL SETTLEMENT OF MY CLAIMS.



OWNER/INSURED SIGNATURE

DATE : _____

TIME : _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18018627/Aha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 18-09-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GV 39R	Veh. Inspected	SLV 9311K
	Policy No.	DMCVSN8004451810	Coverage (\$)	0.00
	Claim No.	SNM18D04862/C02	Excess (\$)	0.00
	Assign From		Assign Date	22/10/2018
2. Vehicle Particulars & Condition				
	Make & Model	MITSUBISHI ATTRAGE	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MMBSTA13AJH000881	Colour	RED
	Odometer	3494	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/55 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/55 R15	BRIDGESTONE	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	08/10/2018	Inspection Date	22/10/2018
	Survey held at	CYCLE & CARRIAGE.FULCO MOTOR DEALER PL NO.330 UBI ROAD 3 SINGAPORE 408650		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 9311K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FR DOOR,RH PANEL ASS (SN)	NOT NECESSARY	986.00	-
1	TAPE,FR DR SASH,RH (SN)	NECESSARY	29.00	29.00
1	RR DR,RH PANEL ASSY (SN)	DENTED	791.00	791.00
1	HINGE,FR DOOR,UPR LH (SN)	NOT NECESSARY	54.00	-
1	RR DR,UPR RH HINGE (SN)	NOT NECESSARY	54.00	-
1	MOULDING,RR DOOR WI (SN)	NOT NECESSARY	66.00	-
1	WEATHERSTRIP,RR DR O (SN)	NOT NECESSARY	135.00	-
1	REGULATOR,RR DOOR WI (SN)	NOT NECESSARY	130.00	-
1	MOTOR,RR DOOR POWER (SN)	NOT NECESSARY	387.00	-
1	LATCH,RR DOOR,RH (SN)	NOT NECESSARY	318.00	-
1	CHECKER,RR DR (SN)	NOT NECESSARY	46.00	-
1	TAPE,RR DOOR SASH (SN)	NOT NECESSARY	29.00	-
1	SEAT BELT,FR SEAT PR (SN)	NOT NECESSARY	581.00	-
1	TRIM,CTR PILLAR,UPR (SN)	NOT NECESSARY	49.00	-
1	TRIM,CTR PILLAR,LWR (SN)	NOT NECESSARY	142.00	-
1	SCUFF PLATE,RR RH (SN)	NOT NECESSARY	50.00	-
			3,847.00	820.00
LABOUR				
TO TRANSFER RHF & RHR DOOR COMPONENT AND MECHANISM PARTS.			600.00	300.00
DIAGNOSTIC/SCANNING.			250.00	-
TO REMOVE AND RE-INSTALL ROOF LINING & CARPETING & SEAT TO GIVE WAY ACCESS REPAIR ON RH SIDE CENTER PILLAR.			1,200.00	-
TO REPLACE RHF & RHR DOOR PANEL,ETC-TO REPAIR ON RH SIDE CENTER PILLAR,STRAIGHTEN,REFORM,ALIGN ON RH SIDE ACCIDENT AFFECTED AREAS.			3,000.00	600.00
TO APPLY SEALANT KIT ON NEW PANEL.			200.00	100.00
TO REPLACE RH SIDE SEAT BELT.			600.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPRAY PAINTING ON RH SIDE ACCIDENT AFFECTED AREAS.		2,520.00	420.00
			8,370.00	1,420.00
GRAND TOTAL			12,217.00	2,240.00
RECOMMENDED COST OF REPAIRS				2,240.00

Report Ref No. CC3/CTI18018627/Aha3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.