



Rico 60 Auto Services Pte Ltd . Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875 , Email: claims@rico60.com
Tel: 6286 6060 , FAX: 6286 7060
VECHICLE NUM: SMC 5609 S
MAKE & MODEL: KIA CARENS
MILEAGE:
TYRE:
CHASSIS NUM:

not held
1/5/18
30/1/18
17/10/18

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
	FRONT BUMPER <i>Re-etch</i>		\$ 668.00
	FRONT BUMPER SIDE RETAINER RH <i>34</i>		\$ 38.00
	FORNT BUMPER BRACKET RH <i>11 X</i>		\$ 36.00
	FRONT BUMPER GRILLE <i>11 X</i>		\$ 357.00
	FRONT BUMPER LOWER GRILLE <i>11 X</i>		\$ 159.00
	FRONT BUMPER LOWER <i>11 X</i>		\$ 180.00
	FOG LAMP RH <i>11 X</i>		\$ 206.00
	FOG LAMP COVER RH <i>11 X</i>		\$ 130.00
	FRONT BUMPER TOWING CAP <i>11 X</i>		\$ 38.00
	FRONT BUMPER SPONGE <i>11 X</i>		\$ 68.00
	FRONT BUMPER REINFORCEMENT <i>11 X</i>		\$ 389.00
	FRONT SUPPORT PANEL <i>11 X</i>		\$ 575.00
	HEADLAMP RH <i>?</i>		\$ 1,558.00
	HEADLAMP BRACKET RH <i>11 X</i>		\$ 189.00
	FRONT FENDER RH <i>m/24</i>		\$ 310.00
	FRONT FENDER COWLING RH <i>70.00</i>		\$ 75.00
	FRONT QUARTER GLASS MOULDING <i>11 X</i>		\$ 190.00
	FRONT QUARTER GLASS CHROME MOULDING <i>11 X</i>		\$ 195.00
	FRONT DAMPER ASSY RH <i>11 X</i>		\$ 335.00
	FRONT WHEEL BEARING RH <i>11 X</i>		\$ 153.00
	FRONT BEARING HUB RH <i>11 X</i>		\$ 180.00
	FRONT LOWER ARM RH <i>11 X</i>		\$ 429.00
	FRONT KNUCKLE ARM RH <i>11 X</i>		\$ 344.00
	STEERING RACK AND PINION ASSY <i>11 X</i>		\$ 832.00
	SPORT RIM RH <i>600</i>		\$ 704.00
		SUBTOTAL	\$ 8,338.00
		LESS 10%	\$ 833.80
		PARTS TOTAL	\$ 7,504.20
	SPECIAL NETT	QTY	PRICE
	FRONT NUMBER PLATE <i>11 X</i>		\$ 80.00
	QUARTER GLASS SEALANT <i>11 X</i>		\$ 120.00
	TYRE 205/55/16 <i>500 X</i>		\$ 300.00
	FRONT BUMPER CLIPS <i>20 50</i>		\$ 80.00
	FRONT FENDER COWLING CLIPS <i>20 50</i>		\$ 80.00
		SPECIAL NETT TOTAL	\$ 660.00
	LABOUR	QTY	PRICE
	TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN <i>300</i>		\$ 1,600.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA <i>400</i>		\$ 1,400.00

