

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7699X

MAKE :

MODEL : HYUNDAI i40

DATE 15/10/2018 11:10

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (LH)			\$ 2,201.10
	Rear Wheel Hup-Cap (LH)			\$ 107.10
	<i>Re-bumper x 2</i>			
	SUB TOTAL			\$ 2,308.20
	LESS 20%			\$ 461.64
	DISCOUNTED TOTAL			\$ 1,846.56
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Rear Door Advertisement Logo (LH)			\$ 100.00
	Rear Door Comfortdelgro & Apps Sticker (LH)			\$ 80.00
				\$ 480.00
	Labour Charge			
	Panel Beating-Repair Fender			\$ 440.00 ⁴⁰⁰
	Spray Painting Charge			\$ 660.00 ⁶⁰⁰
	Tuff Kote			\$ 50.00 ²⁰
	Transfer of Door			\$ 80.00 ⁵⁰
	Rear Wheel Alignment			\$ 80.00 ^X
	TOTAL LABOUR			\$ 1,310.00
	ESTIMATE TOTAL			\$ 3,636.56

Kalm LKK

15/10/18 1130h

3 hrs

4/5

After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

(C7)

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.