

CASE OWNER:

4. CPC 180 18821, N 1/32

Surveyor:

NAE

DOI:

SIGNMENT

22/10/18

Date / Time:

Registered in Merit:

14/10/18

Pre-assign / CCU / FTE

GX 7427Y



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A: 17/10/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SLF 6314G



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kah mstr



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

14/10/18  
ucSLF 6314G - X;  
GX 7427Y - (6/10/17/14/29/6/14/29); 10/17/18Non-Reporting ltr (1st);  
Non-Reporting ltr (2nd);  
Non-Reporting ltr (Final);  
Notification ltr (if non-pickup);

14/10/18

- FILE PROHIBITED. OLD RATE - BUNDLED TP.  
- BUNDLED LIABILITY COVER.

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

30/10/18

Sent By:

CS

FINALIZATION

Date/Time:

Confirm with:

Confirm by: NAE

Repair Cost:

P/P

SS

11,259.40

(B days) Reduction:

38 %

Email

Call

FINAL SETTLEMENT

Date/Time: 08-01-19

Confirm with DESMOND

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

OLD RATE - BUNDLED TP

Repair Cost:

0/149

SS

12,047.55

Loss of Rental (LOR): 0/149

SS

823.90

(11 days) x + 10

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS

12,871.45

Global Sum S\$:

FINAL PAYMENT

Date/Time: 08-01-19

Confirm with: DESMOND

Email

Call

Payee 1:

SS

12,871.45

Name 1:

KAM MOTOR CO. SON. BHD.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

450





Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VC00/021022  
Our ref: CC4/LPC18018821/Nha3

Date: 30/10/2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLF 6314G**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.10.2018 at the premises of M/s Kah Motor Co Sdn Bhd have the following to report:-

|                               |       |           |
|-------------------------------|-------|-----------|
| Workshop Estimate Amount      | : S\$ | 17,831.35 |
| Revised Estimate Amount       | : S\$ | 9,528.00  |
| "Check" Items Amount          | : S\$ | 2,901.49  |
| Total (Including Check Items) | : S\$ | 12,429.49 |
| Market Value                  | : S\$ | - (est.)  |
| LTA Reimbursement Value       | : S\$ | - (est.)  |
| Nett Value                    | : S\$ | - (est.)  |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 5.0 days

Yours faithfully,

MUHAMMAD NAZRIL  
**Licensed Appraiser**



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                  |                                                                           |                    |                           |      |   |
|------------------|---------------------------------------------------------------------------|--------------------|---------------------------|------|---|
| Customer         | : SIM WEE SIANG<br>887A WOODLANDS DRIVE 50<br>#05-569<br>SINGAPORE 731887 | Document No.       | : SQT18004376             | Page | 1 |
| Registration No  | : SLF6314G                                                                | Date               | : 12. Oct 2018            |      |   |
| Chassis No       | : JHMRU1830GX200236                                                       | Customer No.       | : ****3165I               |      |   |
| Model            | : HRV LX-SIN CVT YM 2016                                                  | Svc Advisor        | : ANIKKA LAI SWEE KAM     |      |   |
| Owner's Name     | : SIM WEE SIANG                                                           | Engine No          | : L15B4530236             |      |   |
| Ins Policy No.   | :                                                                         | Date   Time        | : 12. Oct 2018 8:42:03 PM |      |   |
| Date of Accident | : 12/10/2018                                                              | Surveyor Name      | :                         |      |   |
|                  |                                                                           | Survey Date        | :                         |      |   |
|                  |                                                                           | Authorisation Date | :                         |      |   |

| Item            | Description                                                                                                                                                                          | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|--------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: SIM WEE SIANG<br>OWNER INSURER: LIBERTY<br>ACC DATE: 12/10/2018<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: LONPAC<br>TP VEH: GX7427Y |     |            |        |        |               |                  |
| 68100-T7A-J20ZZ | TAIL GATE COMP                                                                                                                                                                       | 1   | 838.90     | 25     | 629.17 | 44.04         | 673.21           |
| 68210-T5A-J03ZZ | HINGE COMPTAILGATE                                                                                                                                                                   | 2   | 30.20      | 25     | 45.30  | 3.17          | 48.47            |
| 74440-T5A-003   | WEATHERSTRIPTAILGATE                                                                                                                                                                 | 1   | 92.30      | 25     | 69.22  | 4.85          | 74.07            |
| 74800-T7A-J02   | LOCK ASSYTAILGATE                                                                                                                                                                    | 1   | 81.90      | 25     | 61.42  | 4.30          | 65.72            |
| 74810-T4N-H01   | SWITCH ASSYTAILGATE OPENER                                                                                                                                                           | 1   | 103.20     | 25     | 77.40  | 5.42          | 82.82            |
| 74813-T5A-003   | STRIKER ASSYTAILGATE                                                                                                                                                                 | 1   | 24.70      | 25     | 18.52  | 1.30          | 19.82            |
| 84521-T7A-J01ZA | BOARD ASSYTRUNK FLOOR                                                                                                                                                                | 1   | 186.00     | 25     | 139.50 | 9.77          | 149.27           |
| 84550-T7A-J00   | BOX ASSY,CARGO FLOOR                                                                                                                                                                 | 1   | 126.90     | 25     | 95.17  | 6.66          | 101.83           |
| 84431-T7A-J01ZA | LINING ASSYTAILGATE                                                                                                                                                                  | 1   | 133.40     | 25     | 100.05 | 7.00          | 107.05           |
| 84433-T7A-J01ZA | LINING ASSYTAILGATE UPPER                                                                                                                                                            | 1   | 58.10      | 25     | 43.57  | 3.05          | 46.62            |
| 75722-T7W-A01   | EMBLEMRR.                                                                                                                                                                            | 1   | 12.90      | 25     | 9.67   | 0.68          | 10.35            |
| 75725-T8N-T00   | EMBLEM,RR. I-VTEC                                                                                                                                                                    | 1   | 14.10      | 25     | 10.57  | 0.74          | 11.31            |
| 75701-T5A-000   | EMBLEMH                                                                                                                                                                              | 1   | 10.70      | 25     | 8.02   | 0.56          | 8.58             |
| 90301-ST0-003   | NUTPUSH 3MM                                                                                                                                                                          | 2   | 1.90       | 25     | 2.85   | 0.20          | 3.05             |
| 33502-T7A-J01   | LAMP UNITR.                                                                                                                                                                          | 1   | 428.70     | 25     | 321.52 | 22.51         | 344.03           |
| 33552-T7A-J01   | LAMP UNITL.                                                                                                                                                                          | 1   | 428.70     | 25     | 321.52 | 22.51         | 344.03           |
| 34150-T7A-J01   | LIGHT ASSY,R.LID                                                                                                                                                                     | 1   | 264.60     | 25     | 198.45 | 13.89         | 212.34           |
| 34155-T7A-J01   | LIGHT ASSYL.LID                                                                                                                                                                      | 1   | 264.60     | 25     | 198.45 | 13.89         | 212.34           |
| 04715-T7A-900ZZ | FACE,RR.BUMPER                                                                                                                                                                       | 1   | 463.70     | 25     | 347.77 | 24.34         | 372.11           |
| 71593-T7A-J00   | SPACER R,RR.BPR S                                                                                                                                                                    | 1   | 19.20      | 25     | 14.40  | 1.01          | 15.41            |
| 71598-T7A-J00   | SPACER,L,RR.BPR S                                                                                                                                                                    | 1   | 19.20      | 25     | 14.40  | 1.01          | 15.41            |



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

|                  |                                                                           |                    |                           |      |   |
|------------------|---------------------------------------------------------------------------|--------------------|---------------------------|------|---|
| Customer         | : SIM WEE SIANG<br>887A WOODLANDS DRIVE 50<br>#05-569<br>SINGAPORE 731887 | Document No.       | : SQT18004376             | Page | 2 |
| Registration No  | : SLF6314G                                                                | Date               | : 12. Oct 2018            |      |   |
| Chassis No       | : JHMRU1830GX200236                                                       | Customer No.       | : ****31651               |      |   |
| Model            | : HRV LX-SIN CVT YM 2016                                                  | Svc Advisor        | : ANIKKA LAI SWEE KAM     |      |   |
| Owner's Name     | : SIM WEE SIANG                                                           | Engine No          | : L15B4530236             |      |   |
| Ins Policy No.   | :                                                                         | Date   Time        | : 12. Oct 2018 8:42:03 PM |      |   |
| Date of Accident | : 12/10/2018                                                              | Surveyor Name      | :                         |      |   |
|                  |                                                                           | Survey Date        | :                         |      |   |
|                  |                                                                           | Authorisation Date | :                         |      |   |

| Item            | Description                               | Qty | Unit Price | Disc % | Amount   | 0% GST Amount | Amount incld GST |
|-----------------|-------------------------------------------|-----|------------|--------|----------|---------------|------------------|
| 91505-TM8-003   | CLIPBUMPER                                | 7   | 2.00       | 25     | 12.00    | 0.74          | 11.24            |
| 33505-T7A-J01   | REFLECTOR ASSYR.RR.                       | 1   | 151.80     | 25     | 113.85   | 7.97          | 121.82           |
| 33555-T7A-J01   | REFLECTOR ASSYL.RR.                       | 1   | 151.80     | 25     | 113.85   | 7.97          | 121.82           |
| 04717-T7A-000ZZ | FACER.RR.BUMPER CORNER                    | 1   | 92.30      | 25     | 69.22    | 4.85          | 74.07            |
| 04718-T7A-000ZZ | FACEL.RR.BUMPER CORNER                    | 1   | 92.30      | 25     | 69.22    | 4.85          | 74.07            |
| 66100-T7A-300ZZ | PANEL COMPRR.                             | 1   | 365.70     | 25     | 274.27   | 19.20         | 293.47           |
| 04655-T7A-310ZZ | PANEL SETRR.FLOOR                         | 1   | 662.20     | 25     | 496.65   | 34.77         | 531.42           |
| 65750-T5B-300ZZ | CROSSMEMBER COMPRR.FLOOR                  | 1   | 81.20      | 25     | 60.90    | 4.26          | 65.16            |
| 74890-T7A-J12ZS | GARNISH ASSYRR.LICENSE                    | 1   | 186.10     | 25     | 139.57   | 9.77          | 149.34           |
| 18307-T7A-901   | SILENCER COMPEXHUAUST                     | 1   | 528.00     | 25     | 396.00   | 27.72         | 423.72           |
| 74646-T7A-010   | COVERRR.FLOOR UN                          | 1   | 118.30     | 25     | 88.72    | 6.21          | 94.93            |
| 74410-T7A-J01ZN | PROTECTOR,R,RR.WHEEL ARCH                 | 1   | 165.40     | 25     | 124.05   | 8.68          | 132.73           |
| 74450-T7A-J01ZE | PROTECTORL,RR.WHEEL ARCH                  | 1   | 172.10     | 25     | 129.07   | 9.03          | 138.10           |
| 38387-TZ5-A01   | ANTENNA ASSYL.F.                          | 1   | 58.10      | 25     | 43.57    | 3.05          | 46.62            |
| 74940-TR0-003   | BUZZER ASSYSMART                          | 1   | 58.90      | 25     | 44.17    | 3.09          | 47.26            |
| 72841-SH3-315   | OILSHEET                                  | 1   | 39.90      | 25     | 29.92    | 2.09          | 32.01            |
| 73214-T7J-H01   | RUBBER CR.WINDSHIELD DAMPER               | 1   | 19.30      | 25     | 14.47    | 1.01          | 15.48            |
| 73226-SZW-000   | DAMPERSTD 5X5                             | 1   | 8.30       | 25     | 6.22     | 0.44          | 6.66             |
| 73254-T7J-H01   | RUBBER CL.WINDSHIELD DAMPER               | 1   | 19.30      | 25     | 14.47    | 1.01          | 15.48            |
| 76711-T6A-003   | CAPPIVOT                                  | 1   | 4.70       | 25     | 3.52     | 0.25          | 3.77             |
| 91501-S70-003   | FASTENER BW/SHIELD                        | 4   | 3.20       | 25     | 9.60     | 0.67          | 10.27            |
| 91502-S70-003   | FASTENER B                                | 2   | 4.90       | 25     | 7.35     | 0.51          | 7.86             |
| 91536-SS0-J01   | FASTENER AW/SHIELD                        | 2   | 3.50       | 25     | 5.25     | 0.37          | 5.62             |
| BO-WS-SEALANT   | WINDSCREEN SEALANT (N)                    | 2   | 60.00      |        | 120.00   | 8.40          | 128.40           |
|                 |                                           |     |            |        | Sum Item | 5111.35       | 357.81           |
|                 |                                           |     |            |        |          |               | 5,469.16         |
| BOSUN           | SUNDRIES                                  | 1   | 100.00     |        | 100.00   | 7.00          | 107.00           |
| BOJSE           | BODY JOINT SEALANT TAILGATE               | 1   | 100.00     |        | 100.00   | 7.00          | 107.00           |
| BOJSE           | BODY JOINT SEALANT END PANEL              | 1   | 100.00     |        | 100.00   | 7.00          | 107.00           |
| BOJSE           | BODY JOINT SEALANT FLOOR PANEL            | 1   | 100.00     |        | 100.00   | 7.00          | 107.00           |
| BOMISC1         | RESET & CALLIBRATE SMART ENTRY SYSTEM (N) | 1   | 200.00     |        | 200.00   | 14.00         | 214.00           |

Printed on 13/10/2018 12:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : SIM WEE SIANG  
887A WOODLANDS DRIVE 50  
#05-569  
SINGAPORE 731887  
Registration No : SLF6314G  
Chassis No : JHMRU1830GX200236  
Model : HRV LX-SIN CVT YM 2016  
Owner's Name : SIM WEE SIANG  
Ins Policy No. :  
Date of Accident : 12/10/2018

Document No. : SQT18004376  
Date : 12. Oct 2018  
Customer No. : \*\*\*\*3165I  
Svc Advisor : ANIKKA LAI SWEE KAM  
Engine No : L15B4530236  
Date | Time : 12. Oct 2018 8:42:03 PM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 3

| Item      | Description                                        | Qty | Unit Price | Disc % | Amount   | 0% GST Amount | Amount incld GST |
|-----------|----------------------------------------------------|-----|------------|--------|----------|---------------|------------------|
| BOMISC1   | REMOVE & INSTALL REAR VIEW CAMERA (N)              | 1   | 220.00     |        | 220.00   | 15.40         | 235.40           |
| BA02R     | REMOVE & RENEW REVERSE SENSORS-4 PGS (N)           | 1   | 140.00     |        | 140.00   | 9.80          | 149.80           |
| BMI03D    | REMOVE & INSTALL REAR COMPARTMENT LININGS          | 1   | 500.00     |        | 500.00   | 36.00         | 536.00           |
| BKTG02R   | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &  | 1   | 800.00     |        | 800.00   | 56.00         | 856.00           |
| BG02R     | REPLACE RR. WINDSCREEN (N)                         | 1   | 560.00     |        | 560.00   | 39.20         | 599.20           |
| BMU30R    | RMOVE & REPLACE EXHAUST SYSTEM (N)                 | 1   | 800.00     |        | 800.00   | 56.00         | 856.00           |
| BKRP21B   | CUT OFF & RENEW RR FLOOR PANEL & DAMAGE PARTS.     | 1   | 5600.00    |        | 5600.00  | 392.00        | 5992.00          |
| BP06R     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1   | 3500.00    |        | 3500.00  | 245.00        | 3745.00          |
| Sum Labor |                                                    |     |            |        | 12720.00 | 890.40        | 13,610.40        |

Survey By \_\_\_\_\_  
Date & Time \_\_\_\_\_  
Excess \_\_\_\_\_  
Status \_\_\_\_\_  
Signature \_\_\_\_\_

Total Amount 17,831.35 1,248.21 19,079.56  
Total (Inclusive of GST) 19,079.56

18,997.22

NA2 LKK  
22/10/18 1230  
P/P  
5 DAYS  
- CHECK ITEMS PHOTOS  
- BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 13/10/2018 12:19:36 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** S78131651 / SIM WEE SIANG  
**Chassis No:** JHMRU1830GX200236  
**License No:** SLF6314G  
**Mileage:** 48220  
**Engine No:** L15B4530236

**Document No:** SVO18062186  
**Printed By:** ANIKKALAI  
**Order Date:** 20. October 2018  
**Order Time:** 10:49:46 AM  
**Service Advisor:** ANIKKA LAI SWEE KAM

| ITEM            | DESCRIPTION         | QTY | UNIT  | DISC % | AMOUNT | 7% GST Amount | Amount incld GST |
|-----------------|---------------------|-----|-------|--------|--------|---------------|------------------|
| 65513-T7A-300ZZ | ADDITIONAL PART     |     |       |        |        |               |                  |
|                 | STIFFENERRR.JACK UP | 1   | 61.40 | 25     | 46.05  | 3.22          | 49.27            |
| 91505-T5A-003   | CLIPUNDER COVER     | 2   | 0.70  | 25     | 1.05   | 0.07          | 1.12             |
| SUM PARTS:      |                     |     |       |        | 47.10  | 3.29          | 50.39            |
| TOTAL SGD       |                     |     |       |        | 47.10  | 3.29          | 50.39            |

66100 TFA

Total Payable (SGD) 50.39

GST Amount is calculated from individual line(s)

(1) REPLACE RR. WINDSCREEN (N) 7360 ✓



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer:** WZN008 / NTUC INCOME INS  
**Chassis No:** JHMRU1830GX200236  
**License No:** SLF6314G  
**Mileage:** 48220  
**Engine No:** L15B4530236

**Document No:** SVO18062186  
**Printed By:** ANIKKALAI  
**Order Date:** 20. October 2018  
**Order Time:** 10:49:46 AM  
**Service Advisor:** ANIKKA LAI SWEE KAM

| ITEM            | DESCRIPTION                                                                                                                                                                                              | QTY | UNIT   | DISC % | AMOUNT          | 7% GST Amount | Amount Incl GST |
|-----------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|--------|--------|-----------------|---------------|-----------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: SIM WEE SIANG<br>OWNER INSURER: LIBERTY<br>ACC DATE: 12/10/2018<br>SURVEYED BY: NAZ /LKK<br>DATE: 22/10/2018<br>REF NO:<br>TP INSURER: LONPAC<br>TP VEH: GX7427Y |     |        |        |                 |               |                 |
| 68100-T7A-J20ZZ | TAIL GATE COMP                                                                                                                                                                                           | 1   | 855.70 |        | 855.70          | 59.90         | 915.60 /DEF     |
| 74440-T7A-003   | WEATHERSTRIPTAILGATE                                                                                                                                                                                     | 1   | 98.70  |        | 98.70           | 6.91          | 105.61 /DEF     |
| 74800-T7A-J02   | LOCK ASSYTAILGATE                                                                                                                                                                                        | 1   | 78.90  |        | 78.90           | 5.52          | 84.42 /JAM      |
| 84550-T7A-J00   | BOX ASSY,CARGO FLOOR                                                                                                                                                                                     | 1   | 129.50 |        | 129.50          | 9.07          | 138.57 /ORL     |
| 75722-T7W-A01   | EMBLEMRR.                                                                                                                                                                                                | 1   | 13.30  |        | 13.30           | 0.93          | 14.23 /NFC      |
| 75725-T8N-T00   | EMBLEM,RR. I-VTEC                                                                                                                                                                                        | 1   | 14.50  |        | 14.50           | 1.02          | 15.52 /NFC      |
| 75701-T5A-000   | EMBLEMH                                                                                                                                                                                                  | 1   | 10.70  |        | 10.70           | 0.75          | 11.45 /NFC      |
| 90301-ST0-003   | NUTPUSH 3MM                                                                                                                                                                                              | 2   | 2.10   |        | 4.20            | 0.29          | 4.49 /NFC       |
| 04715-T7A-900ZZ | FACE,RR.BUMPER                                                                                                                                                                                           | 1   | 463.70 |        | 463.70          | 32.46         | 496.16 /DEF     |
| 71593-T7A-J00   | SPACER R,RR.BPR S                                                                                                                                                                                        | 1   | 16.90  |        | 16.90           | 1.18          | 18.08 /NFC      |
| 71598-T7A-J00   | SPACER,L,RR.BPR S                                                                                                                                                                                        | 1   | 16.90  |        | 16.90           | 1.18          | 18.08 /NFC      |
| 91505-TM8-003   | CLIPBUMPER                                                                                                                                                                                               | 7   | 2.30   |        | 16.10           | 1.13          | 17.23 /NFC      |
| 33555-T7A-J01   | REFLECTOR ASSYL,RR.                                                                                                                                                                                      | 1   | 156.30 |        | 156.30          | 10.94         | 167.24 /CRK     |
| 04717-T7A-000ZZ | FACER,RR.BUMPER CORNER                                                                                                                                                                                   | 1   | 94.10  |        | 94.10           | 6.59          | 100.69 /NFC     |
| 04718-T7A-000ZZ | FACEL,RR.BUMPER CORNER                                                                                                                                                                                   | 1   | 94.10  |        | 94.10           | 6.59          | 100.69 /NFC     |
| 66100-T7A-300ZZ | PANEL COMPR.                                                                                                                                                                                             | 1   | 373.10 |        | 373.10          | 26.12         | 399.22 /DEF     |
| 04655-T7A-310ZZ | PANEL SETRR.FLOOR                                                                                                                                                                                        | 1   | 675.50 |        | 675.50          | 47.29         | 722.79 /DEF     |
| 18307-T7A-901   | SILENCER COMPEXHUAST                                                                                                                                                                                     | 1   | 538.60 |        | 538.60          | 37.70         | 576.30 /DEF     |
| 74646-T7A-010   | COVERRR.FLOOR UN                                                                                                                                                                                         | 1   | 120.70 |        | 120.70          | 8.45          | 129.15 /NFC     |
| 74940-TZ5-A01   | BUZZER ASSYSMART                                                                                                                                                                                         | 1   | 60.40  |        | 60.40           | 4.23          | 64.63 /CRK      |
| 73214-T7J-H01   | RUBBER CR.WINDSHIELD DAMPER                                                                                                                                                                              | 1   | 19.30  |        | 19.30           | 1.35          | 20.65 /NFC      |
| 73226-SZW-000   | DAMPERSTD 5X5                                                                                                                                                                                            | 1   | 8.50   |        | 8.50            | 0.60          | 9.10            |
| 73254-T7J-H01   | RUBBER CL.WINDSHIELD DAMPER                                                                                                                                                                              | 1   | 19.30  |        | 19.30           | 1.35          | 20.65 /NFC      |
| 76711-T6A-003   | CAPPIVOT                                                                                                                                                                                                 | 1   | 4.80   |        | 4.80            | 0.34          | 5.14            |
| 91501-S70-003   | FASTENER BW/SHIELD                                                                                                                                                                                       | 4   | 5.30   |        | 21.20           | 1.48          | 22.68           |
| 91502-S70-003   | FASTENER B                                                                                                                                                                                               | 2   | 5.30   |        | 10.60           | 0.74          | 11.34           |
| 91536-SS0-J01   | FASTENER AW/SHIELD                                                                                                                                                                                       | 2   | 3.80   |        | 7.60            | 0.53          | 8.13            |
| BO-WS-SEALANT   | WINDSCREEN SEALANT (N)                                                                                                                                                                                   | 2   | 60.00  |        | 120.00          | 8.40          | 128.40 /NFC     |
| 65513-T7A-300ZZ | STIFFENERRR.JACK UP                                                                                                                                                                                      | 1   | 61.40  | 25     | 46.05           | 3.22          | 49.27           |
| 91505-T5A-003   | CLIPUNDER COVER                                                                                                                                                                                          | 2   | 0.70   | 25     | 1.05            | 0.07          | 1.12 /NFC       |
|                 | <b>SUM PARTS:</b>                                                                                                                                                                                        |     |        |        | <b>4,090.30</b> | <b>286.33</b> | <b>4,376.63</b> |
| BOSUN           |                                                                                                                                                                                                          | 1   | 80.00  |        | 80.00           | 5.60          | 85.60           |
|                 | SUNDRIES                                                                                                                                                                                                 |     |        |        |                 |               |                 |
| BOJSE           | 1610                                                                                                                                                                                                     | 1   | 80.00  |        | 80.00           | 5.60          | 85.60           |
|                 | BODY JOINT SEALANT TAILGATE                                                                                                                                                                              |     |        |        |                 |               |                 |
| BOJSE           | 1610                                                                                                                                                                                                     | 1   | 80.00  |        | 80.00           | 5.60          | 85.60           |
|                 | BODY JOINT SEALANT END PANEL                                                                                                                                                                             |     |        |        |                 |               |                 |
| BOJSE           | 1610                                                                                                                                                                                                     | 1   | 80.00  |        | 80.00           | 5.60          | 85.60           |
|                 | BODY JOINT SEALANT FLOOR PANEL                                                                                                                                                                           |     |        |        |                 |               |                 |



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZN008 / NTUC INCOME INS  
Chassis No: JHMRU1830GX200236  
License No: SLF6314G  
Mileage: 48220  
Engine No: L15B4530236

Document No: SVO18062186  
Printed By: ANIKKALAI  
Order Date: 20. October 2018  
Order Time: 10:49:46 AM  
Service Advisor: ANIKKA LAI SWEE KAM

|         |                                                                                                                   |   |             |           |        |           |   |
|---------|-------------------------------------------------------------------------------------------------------------------|---|-------------|-----------|--------|-----------|---|
| BOMISC1 | 1757<br>RESET & CALLIBRATE SMART ENTRY<br>SYSTEM (N)                                                              | 1 | 200.00      | 200.00    | 14.00  | 214.00    | ✓ |
| BOMISC1 | 1757<br>REMOVE & INSTALL REAR VIEW<br>CAMERA (N)                                                                  | 1 | 220.00      | 220.00    | 15.40  | 235.40    | ✓ |
| BA02R   | 0671<br>REMOVE & RENEW REVERSE<br>SENSORS-4 PCS (N)                                                               | 1 | 140.00      | 140.00    | 9.80   | 149.80    | ✓ |
| BMI03D  | 0671<br>REMOVE & INSTALL REAR<br>COMPARTMENT LININGS<br>GARNISHES.(N)                                             | 1 | 360.00      | 360.00    | 25.20  | 385.20    | ✓ |
| BKTG02R | 0671<br>REMOVE & TRANSFER ITEMS TO NEW<br>TAILGATE. ADJUST &<br>ALIGN TAILGATE.(N)                                | 1 | 560.00      | 560.00    | 39.20  | 599.20    | ✓ |
| BG02R   | 1757<br>REPLACE RR. WINDSCREEN.(N)                                                                                | 1 | 560.00      | 560.00    | 39.20  | 599.20    | ✓ |
| BMU30R  | 0671<br>REMOVE & REPLACE EXHAUST SYSTEM.<br>(N)                                                                   | 1 | 560.00      | 560.00    | 39.20  | 599.20    | ✓ |
| BKRP21B | 0671<br>CUT OFF & RENEW RR FLOOR PANEL &<br>DAMAGE PARTS.<br>STRAIGHTEN ALIGN RR CHASSIS &<br>RENEW DAMAGE PARTS. | 1 | 1,960.00    | 1,960.00  | 137.20 | 2,097.20  | ✓ |
| BP06R   | 1610<br>SPRAY PAINTING ON REPAIRED OR<br>REPLACED AREAS. (6P)                                                     | 1 | 3,470.00    | 3,470.00  | 242.90 | 3,712.90  | ✓ |
|         |                                                                                                                   |   | SUM LABOUR: | 8,150.00  | 584.50 | 8,934.50  |   |
|         |                                                                                                                   |   | TOTAL SGD   | 12,440.30 | 870.83 | 13,311.13 |   |

Total Payable (SGD)

13,311.13

12,240.30

GST Amount is calculated from individual line(s)

PARTS \$4,090.30  
LABOUR \$8,150.00  
TOTAL \$12,240.30 / 5 DAYS

FINALIZED PART BY PART REPAIR \$12,240.30 / 5 DAYS

NAZUKK  
7/1



# Service Tax Invoice

**Kah Motor Co. Sdn. Bhd.**  
(A Member of Oriental Holdings Berhad)  
6A Mandal Estate, SINGAPORE 729903  
Mandal Parts Centre  
Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223  
Company Ref. No. S60FC1380G

LONPAC INSURANCE BHD  
MOTOR CLAIMS DEPT  
100 BEACH ROAD  
#19-00 SHAW TOWERS  
SINGAPORE, 189702

Customer No. : WZL009  
Payment Term : 30 Days

Invoice No. : SINV-BM19000468  
Invoice Date : 29/03/19  
Order No. : SVO18062186  
Reference :  
Job Card No. : 08001  
Date/Time Received : 12/10/18 / 8:42:03 PM  
Licence No. : SLF6314G  
Model : HRV LX-SIN CVT YM 2016  
Car Chassis No. : JHMRU1830GX200236  
Car Engine No. : L15B4530236  
Mileage : 48220  
Service Advisor : ANIKKA LAI SWEE KAM 1821  
Served By : ANIKKALAI  
Page : 1

| No.             | Description                                                               | Qty. | UoM   | U. Price | Disc % | Amount   | 7% GST Amount | Incl GST |
|-----------------|---------------------------------------------------------------------------|------|-------|----------|--------|----------|---------------|----------|
|                 | TP DIRECT SETTLEMENT (J/NO: )                                             |      |       |          |        |          |               |          |
|                 | OWNER: SIM WEE SIANG                                                      |      |       |          |        |          |               |          |
|                 | OWNER INSURER: LIBERTY                                                    |      |       |          |        |          |               |          |
|                 | ACC DATE: 12/10/2018                                                      |      |       |          |        |          |               |          |
|                 | SURVEYED BY: NAZ /LKK                                                     |      |       |          |        |          |               |          |
|                 | DATE: 22/10/2018                                                          |      |       |          |        |          |               |          |
|                 | REF NO:                                                                   |      |       |          |        |          |               |          |
|                 | TP INSURER: LONPAC                                                        |      |       |          |        |          |               |          |
|                 | TP VEH: GX7427Y                                                           |      |       |          |        |          |               |          |
| BOSUN           | 0701 SUNDRIES                                                             | 1    | Hours | 80.00    |        | 80.00    | 5.60          | 85.60    |
| BOJSE           | 1610 BODY JOINT SEALANT TAILGATE                                          | 1    | Hours | 80.00    |        | 80.00    | 5.60          | 85.60    |
| BOJSE           | 1610 BODY JOINT SEALANT END PANEL                                         | 1    | Hours | 80.00    |        | 80.00    | 5.60          | 85.60    |
| BOJSE           | 1610 BODY JOINT SEALANT FLOOR PANEL                                       | 1    | Hours | 80.00    |        | 80.00    | 5.60          | 85.60    |
| BOMISC1         | 1757 RESET & CALIBRATE SMART ENTRY SYSTEM (N)                             | 1    | Hours | 200.00   |        | 200.00   | 14.00         | 214.00   |
| BOMISC1         | 1757 REMOVE & INSTALL REAR VIEW CAMERA (N)                                | 1    | Hours | 220.00   |        | 220.00   | 15.40         | 235.40   |
| BA02R           | 0671 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)                             | 1    | Hours | 140.00   |        | 140.00   | 9.80          | 149.80   |
| BMI03D          | 0671 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)              | 1    | Hours | 360.00   |        | 360.00   | 25.20         | 385.20   |
| BKTG02R         | 0671 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N) | 1    | Hours | 560.00   |        | 560.00   | 39.20         | 599.20   |
| BMU30R          | 0671 RMOVE & REPLACE EXHAUST SYSTEM.(N)                                   | 1    | Hours | 560.00   |        | 560.00   | 39.20         | 599.20   |
| BKRP21B         | 0671 CUT OFF & RENEW RR FLOOR PANEL & DAMAGE PARTS.                       | 1    | Hours | 1,960.00 |        | 1,960.00 | 137.20        | 2,097.20 |
|                 | STRAIGHTEN ALIGN RR CHASSIS & RENEW DAMAGE PARTS.                         |      |       |          |        |          |               |          |
| BP06R           | 1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)                   | 1    | Hours | 3,470.00 |        | 3,470.00 | 242.90        | 3,712.90 |
| 68100-T7A-J20ZZ | TAIL GATE COMP                                                            | 1    | Each  | 855.70   | 25     | 641.77   | 44.92         | 686.69   |
| 74440-T7A-003   | WEATHERSTRIPTAILGATE                                                      | 1    | Each  | 98.70    | 25     | 74.02    | 5.18          | 79.20    |
| 74800-T7A-J02   | LOCK ASSYTAILGATE                                                         | 1    | Each  | 78.90    | 25     | 59.17    | 4.14          | 63.31    |
| 84550-T7A-J00   | BOX ASSY,CARGO FLOOR                                                      | 1    | Each  | 129.50   | 25     | 97.12    | 6.80          | 103.92   |
| 75722-T7W-A01   | EMBLEMRR.                                                                 | 1    | Each  | 13.30    | 25     | 9.97     | 0.70          | 10.67    |
| 75725-T8N-T00   | EMBLEM,RR. I-VTEC                                                         | 1    | Each  | 14.50    | 25     | 10.87    | 0.76          | 11.63    |
| 75701-T5A-000   | EMBLEMH                                                                   | 1    | Each  | 10.70    | 25     | 8.02     | 0.56          | 8.58     |
| 90301-ST0-003   | NUTPUSH 3MM                                                               | 2    | Each  | 2.10     | 25     | 3.15     | 0.22          | 3.37     |
| 04715-T7A-900ZZ | FACE,RR.BUMPER                                                            | 1    | Each  | 463.70   | 25     | 347.77   | 24.34         | 372.11   |
| 71593-T7A-J00   | SPACER R,RR.BPR S                                                         | 1    | Each  | 16.90    | 25     | 12.67    | 0.89          | 13.56    |
| 71598-T7A-J00   | SPACER,L.RR.BPR S                                                         | 1    | Each  | 16.90    | 25     | 12.67    | 0.89          | 13.56    |

Printed by ANIKKALAI on 29 Mar 2019 at 7:27:37 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.  
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.  
Interest will be charged at 2% per month on overdue amounts.

Please give us your feedback by scanning the QR Code using mobile device.



**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

**Service Tax Invoice**

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BM19000468  
 Invoice Date : 29/03/19  
 Order No. : SVO18062186  
 Reference :  
 Job Card No. : 08001  
 Date/Time Received : 12/10/18 / 8:42:03 PM  
 Licence No. : SLF6314G  
 Model : HRV LX-SIN CVT YM 2016  
 Car Chassis No. : JHMRU1830GX200236  
 Car Engine No. : L15B4530236  
 Mileage : 48220  
 Service Advisor : ANIKKA LAI SWEE KAM 1821  
 Served By : ANIKKALAI  
 Page : 2

LONPAC INSURANCE BHD  
 MOTOR CLAIMS DEPT  
 100 BEACH ROAD  
 #19-00 SHAW TOWERS  
 SINGAPORE, 189702

Customer No. : WZL009

Payment Term : 30 Days

| No.             | Description                     | Qty. | UoM   | U. Price | Disc % | 7% GST Amount incld |        |        |
|-----------------|---------------------------------|------|-------|----------|--------|---------------------|--------|--------|
|                 |                                 |      |       |          |        | Amount              | Amount | GST    |
| 91505-TM8-003   | CLIPBUMPER                      | 7    | Each  | 2.30     | 25     | 12.07               | 0.84   | 12.91  |
| 33555-T7A-J01   | REFLECTOR ASSYL.RR.             | 1    | Each  | 156.30   | 25     | 117.22              | 8.21   | 125.43 |
| 04717-T7A-000ZZ | FACER.RR.BUMPER CORNER          | 1    | Each  | 94.10    | 25     | 70.57               | 4.94   | 75.51  |
| 04718-T7A-000ZZ | FACEL.RR.BUMPER CORNER          | 1    | Each  | 94.10    | 25     | 70.57               | 4.94   | 75.51  |
| 66100-T7A-300ZZ | PANEL COMPRR.                   | 1    | Each  | 373.10   | 25     | 279.82              | 19.59  | 299.41 |
| 04655-T7A-310ZZ | PANEL SETRR.FLOOR               | 1    | Each  | 675.50   | 25     | 506.62              | 35.46  | 542.08 |
| 18307-T7A-901   | SILENCER COMPEXHUAUT            | 1    | Each  | 538.60   | 25     | 403.95              | 28.28  | 432.23 |
| 74646-T7A-010   | COVERRR.FLOOR UN                | 1    | Each  | 120.70   | 25     | 90.52               | 6.34   | 96.86  |
| 74940-TZ5-A01   | BUZZER ASSYSMART                | 1    | Each  | 60.40    | 25     | 45.30               | 3.17   | 48.47  |
| 65513-T7A-300ZZ | STIFFENERRR.JACK UP             | 1    | Each  | 61.40    | 25     | 46.05               | 3.22   | 49.27  |
| 91505-T5A-003   | CLIPUNDER COVER                 | 2    | Each  | 0.70     | 25     | 1.05                | 0.07   | 1.12   |
|                 |                                 |      |       |          |        | 1,643.74            |        |        |
| BG02R           | 1757 REPLACE RR. WINDSCREEN.(N) | 1    | Hours | 360.00   |        | 360.00              | 25.20  | 385.20 |
| 73214-T7J-H01   | RUBBER CR.WINDSHIELD DAMPER     | 1    | Each  | 19.30    | 25     | 14.47               | 1.01   | 15.48  |
| 73226-SZW-000   | DAMPERSTD 5X5                   | 1    | Each  | 8.50     | 25     | 6.37                | 0.45   | 6.82   |
| 73254-T7J-H01   | RUBBER CL.WINDSHIELD DAMPER     | 1    | Each  | 19.30    | 25     | 14.47               | 1.01   | 15.48  |
| 76711-T6A-003   | CAPPIVOT                        | 1    | Each  | 4.80     | 25     | 3.60                | 0.25   | 3.85   |
| 91501-S70-003   | FASTENER BW/SHIELD              | 4    | Each  | 5.30     | 25     | 15.90               | 1.11   | 17.01  |
| 91502-S70-003   | FASTENER B                      | 2    | Each  | 5.30     | 25     | 7.95                | 0.56   | 8.51   |
| 91536-SS0-J01   | FASTENER AW/SHIELD              | 2    | Each  | 3.80     | 25     | 5.70                | 0.40   | 6.10   |
| BO-WS-SEALANT   | WINDSCREEN SEALANT (N)          | 2    | Each  | 60.00    |        | 120.00              | 8.40   | 128.40 |
|                 |                                 |      |       |          |        | 188.46              |        |        |

|                     |           |        |           |
|---------------------|-----------|--------|-----------|
| Sum Labor           | 8,150.00  | 570.50 | 8,720.50  |
| Sum Item            | 3,109.40  | 217.65 | 3,327.05  |
| Total SGD           | 11,259.40 | 788.15 | 12,047.55 |
| Total Payable (SGD) |           |        | 12,047.55 |

Printed by ANIKKALAI on 29 Mar 2019 at 7:27:37 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.  
 Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).

Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.  
 Interest will be charged at 2% per month on overdue amounts.

Please give us your  
 feedback by scanning  
 the QR Code using  
 mobile device.



## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Monday, 15 October 2018 10:16 AM  
**To:** assignments@lkkauto.com; Catherine Chong (LKK Auto)  
**Cc:** MT\_Claim\_SG  
**Subject:** Our Ref: 18/18/18/VC00/021022 TP survey SLF6314G  
**Attachments:** 15102018101421.pdf

10.53am @ 15/10/2018  
person @ Anika  
vehicle not in

Dear Catherine/Nivitha

Please see attached and contact TP workshop for survey.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18018821/Nea3s2

300 BEACH ROAD  
#17-04/07 THE CONCOURSE SINGAPORE 199555

Date : 19-08-2019



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | GX 7427Y             | Veh. Inspected | SLF 6314G  |
| Policy No.   | Z/18/VC00/102430     | Coverage (\$)  | 0.00       |
| Claim No.    | 18/18/18/VC00/021022 | Excess (\$)    | 0.00       |
| Assign From  | ONG LI LI            | Assign Date    | 15/10/2018 |

### 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HONDA HRV LX CVT  | c.c          | 1496               |
| Engine No.   | HIDDEN            | Year of Reg. | 2016               |
| Chassis No.  | JHMRU1830GX200236 | Colour       | RED                |
| Odometer     | 048220            | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | FAIR              |              |                    |

### 3. Conditions of Tyres

|                | Size      | Make   | Balance |
|----------------|-----------|--------|---------|
| R/H Front Tyre | 215/60R16 | DUNLOP | 5 mm    |
| L/H Front Tyre | 215/60R16 | DUNLOP | 5 mm    |
| R/H Rear Tyre  | 215/60R16 | DUNLOP | 6 mm    |
| L/H Rear Tyre  | 215/60R16 | DUNLOP | 6 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                              |                 |            |
|----------------|--------------------------------------------------------------|-----------------|------------|
| Accident Date  | 12/10/2018                                                   | Inspection Date | 22/10/2018 |
| Survey held at | KAH MOTOR.CO.SDN.BHD<br>6A MANDAI ESTATE<br>SINGAPORE 729903 |                 |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 8 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 6314G

| Qty                         | Description of Parts            | Condition   | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------|-------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                 |             |                           |                   |
| 1                           | TAIL GATE COMP (SN)             | DEFORMED    | 641.17                    | 641.77            |
| 2                           | HINGE COMPTAILGATE (SN)         | SERVICEABLE | 45.30                     | -                 |
| 1                           | WEATHERSTRIPTAILGATE (SN)       | DEFORMED    | 74.02                     | 74.02             |
| 1                           | LOCK ASSYTAILGATE (SN)          | JAMMED      | 61.42                     | 59.17             |
| 1                           | SWITCH ASSYTAILGATE OPENER (SN) | SERVICEABLE | 77.40                     | -                 |
| 1                           | STRIKER ASSYTAILGATE (SN)       | SERVICEABLE | 18.52                     | -                 |
| 1                           | BOARD ASSYTRUNK FLOOR (SN)      | SERVICEABLE | 139.50                    | -                 |
| 1                           | BOX ASSY, CARGO FLOOR (SN)      | CRACKED     | 97.12                     | 97.12             |
| 1                           | LINING ASSYTAILGATE (SN)        | SERVICEABLE | 100.05                    | -                 |
| 1                           | LINING ASSYTAILGATE UPPER (SN)  | SERVICEABLE | 43.57                     | -                 |
| 1                           | EMBLEMRR. (SN)                  | NECESSARY   | 9.97                      | 9.97              |
| 1                           | EMBLEM,RR. I-VTEC (SN)          | NECESSARY   | 10.87                     | 10.87             |
| 1                           | EMBLEMH (SN)                    | NECESSARY   | 8.02                      | 8.02              |
| 2                           | NUTPUSH 3MM (SN)                | NECESSARY   | 3.15                      | 3.15              |
| 1                           | LAMP UNITR. (SN)                | SERVICEABLE | 321.52                    | -                 |
| 1                           | LAMP UNITL. (SN)                | SERVICEABLE | 321.52                    | -                 |
| 1                           | LIGHT ASSY,R.LID (SN)           | SERVICEABLE | 198.45                    | -                 |
| 1                           | LIGHT ASSYL.LID (SN)            | SERVICEABLE | 198.45                    | -                 |
| 1                           | FACE,RR.BUMPER (SN)             | DEFORMED    | 347.77                    | 347.77            |
| 1                           | SPACER R,RR.BPR S (SN)          | NECESSARY   | 14.40                     | 12.67             |
| 1                           | SPACER,L.RR.BPR S (SN)          | NECESSARY   | 14.40                     | 12.67             |
| 7                           | CLIPBUMPER (SN)                 | NECESSARY   | 12.07                     | 12.07             |
| 1                           | REFLECTOR ASSYR.RR. (SN)        | SERVICEABLE | 13.85                     | -                 |
| 1                           | REFLECTOR ASSYL.RR. (SN)        | CRACKED     | 117.22                    | 117.22            |
| 1                           | FACER.RR.BUMPER CORNER (SN)     | NECESSARY   | 70.57                     | 70.57             |
| 1                           | FACEL.RR.BUMPER CORNER (SN)     | NECESSARY   | 70.57                     | 70.57             |
| 1                           | PANEL COMPRR. (SN)              | DEFORMED    | 279.82                    | 279.82            |
| 1                           | PANEL SETRR.FLOOR (SN)          | DEFORMED    | 506.62                    | 506.62            |
| 1                           | CROSSMEMBER COMPRR.FLOOR (SN)   | SERVICEABLE | 60.90                     | -                 |
| 1                           | GARNISH ASSYRR.LICENCE (SN)     | SERVICEABLE | 139.57                    | -                 |
| 1                           | SILENCER COMPEXHAUST (SN)       | BENT        | 403.95                    | 403.95            |

Report Ref No. CC4/LPC18018821/Nea3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------|---------------|---------------------------|-------------------|
| 1   | COVERRR.FLOOR UN (SN)                              | TORN          | 90.52                     | 90.52             |
| 1   | PROTECTOR,R,RR.WHEEL ARCH (SN)                     | SERVICEABLE   | 124.05                    | -                 |
| 1   | PROTECTORL.RR.WHEEL ARCH (SN)                      | SERVICEABLE   | 129.07                    | -                 |
| 1   | ANTENNA ASSYL.F. (SN)                              | SERVICEABLE   | 43.57                     | -                 |
| 1   | BUZZER ASSYSMART (SN)                              | CRACKED       | 45.30                     | 45.30             |
| 1   | OILSHEET (SN)                                      | NOT NECESSARY | 29.92                     | -                 |
| 1   | RUBBER CR.WINDSHIELD DAMPER (SN)                   | NECESSARY     | 14.47                     | 14.47             |
| 1   | DAMPERSTD 5X5 (SN)                                 | NECESSARY     | 6.37                      | 6.37              |
| 1   | RUBBER CL.WINDSHIELD DAMPER (SN)                   | NECESSARY     | 14.47                     | 14.47             |
| 1   | CAPPIVOT (SN)                                      | NECESSARY     | 3.60                      | 3.60              |
| 4   | FASTENER BW/SHIELD (SN)                            | NECESSARY     | 15.90                     | 15.90             |
| 2   | FASTENER B (SN)                                    | NECESSARY     | 7.95                      | 7.95              |
| 2   | FASTENER AW/SHIELD (SN)                            | NECESSARY     | 5.70                      | 5.70              |
| 2   | WINDSCREEN SEALANT (SN)                            | NECESSARY     | 120.00                    | 120.00            |
| 1   | SUNDRIES (SN)                                      | NECESSARY     | 100.00                    | 80.00             |
| 1   | STIFFENERRR.JACK UP (SN) (ADDITIONAL)              | NECESSARY     | 46.05                     | 46.05             |
| 2   | CLIPUNDER COVER (SN) (ADDITIONAL)                  | NECESSARY     | 1.05                      | 1.05              |
|     |                                                    |               | 5,219.72                  | 3,189.40          |
|     | <b>LABOUR</b>                                      |               |                           |                   |
|     | BODY JOINT SEALANT TAILGATE.                       |               | 100.00                    | 80.00             |
|     | BODY JOINT SEALANT END PANEL.                      |               | 100.00                    | 80.00             |
|     | BODY JOINT SEALANT FLOOR PANEL.                    |               | 100.00                    | 80.00             |
|     | RESET & CALLIBRATE SMART ENTRY SYSTEM.             |               | 200.00                    | 200.00            |
|     | REMOVE & INSTALL REAR VIEW CAMERA.                 |               | 220.00                    | 220.00            |
|     | REMOVE & RENEW REVERSE SENSORS.                    |               | 140.00                    | 140.00            |
|     | REMOVE & INSTALL REAR COMPARTMENT LININGS.         |               | 500.00                    | 360.00            |
|     | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &. |               | 800.00                    | 560.00            |
|     | REPLACE RR. WINDSCREEN.                            | NOT NECESSARY | 560.00                    | -                 |
|     | REMOVE & REPLACE EXHAUST SYSTEM.                   |               | 800.00                    | 560.00            |
|     | CUT OFF & RENEW RR FLOR PANEL & DAMAGE PARTS.      |               | 5,600.00                  | 1,960.00          |
|     | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.      |               | 3,500.00                  | 3,470.00          |

Report Ref No. CC4/LPC18018821/Nea3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                         | Description of Parts                | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------|-----------|---------------------------|-------------------|
|                             | REPLACE RR WINDSCREEN. (ADDITIONAL) |           | 360.00                    | 360.00            |
|                             |                                     |           | 12,980.00                 | 8,070.00          |
| GRAND TOTAL                 |                                     |           | 18,199.72                 | 11,259.40         |
| RECOMMENDED COST OF REPAIRS |                                     |           |                           | 11,259.40         |

Report Ref No. CC4/LPC18018821/Nea3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.