

Vehicle No: SLL148C
Model : Toyota Sianta

No	List Items	Qty	Unit Price	List Price
1	Rear Bumper	1	\$495.90	de ✓ \$495.90
2	Rear Bumper (LH)	1	\$295.50	ny ✓ \$295.50
3	Rear Bumper Trim (Center)	1	\$235.80	de ✓ \$235.80
4	Rear Bumper Trim (LH)	1	\$198.50	de ✓ \$198.50
5	Rear Bumper Retainer	2	\$58.00	ne ✓ \$58.00
6	Rear Undercarriage Trim Cover	1	\$189.20	de ✓ \$189.20
7	Rear Bumper Clips	10	\$18.00	ne ✓ \$18.00
8	Rear Bootlid Cover	1	\$1,653.80	bt ✓ \$1,653.80
9	Rear Bootlid Chrom Trim	1	\$230.50	ny x \$230.50
10	Rear Bootlid Chrom Trim Clips	4	\$20.00	ny x \$20.00
11	Rear Bootlid Emblem	1	\$55.30	ne ✓ \$55.30
12	Sianta Emblem	1	\$58.00	ne ✓ \$58.00
13	G Emblem	1	\$42.70	ne ✓ \$42.70
14	Rear bootlid lamp (LH)	1	\$554.50	wt ✓ \$554.50
15	Rear Bootlid lock unit	1	\$185.20	BT ✓ \$185.20
16	Rear Bootlid lock connector	2	\$20.50	ny x \$20.50
17	Rear Bootlid Catch	1	\$35.30	RY ✓ \$35.30
18	Rear Boot weather strip (Inner)	1	\$185.20	ny x \$185.20
19	Rear Boot weather strip (outer)	1	\$163.40	de ✓ \$163.40
20	Rear Bootlid wiper motor	1	\$375.10	x ny \$375.10
21	Rear windscreen (with moulding)	1	\$1,453.50	ny x \$1,453.50
22	Rear Bootlid Trim	1	\$489.00	ny x \$489.00
23	Rear Bootlid Trim Clips	8	\$36.00	ny x \$36.00
24	Rear Boot floor Trim	1	\$132.60	ny x \$132.60
25	Rear Boot floor Trim Clips	4	\$36.00	ny x \$36.00
26	Rear Boot inner Trim (LH)	1	\$383.60	de ✓ \$383.60
27	Taillamp LH	1	\$898.50	ena ✓ \$898.50
28	Rear exhaust muffler	1	\$853.60	ny x \$853.60
29	Rear exhaust insulator	1	\$166.00	ny x \$166.00
30	Rear fender LH	1	\$898.90	bt ✓ \$898.90
31	Rear End Panel	1	\$495.00	bt ✓ \$495.00

Rear End Panel top Garish de ✓ \$230.00 List Price \$10,913.10
Rear Bumper LH Reflector Lamp ena ✓ \$115.00 -25% \$2,728.28
Total \$8,184.83

No	Special Nett Items	Qty	Unit Price	Nett Price
1	Revers Sensor	1 set	\$250.00	\$250.00
2	Windscreen Sealent	1Pc	\$80	\$80.00
3	Rear end panel sealent	2 Pcs	\$60	\$120.00
4	Rear number plate	1pc	\$30.00	\$30.00
5	Rear number plate casing	1pc	\$25.00	\$25.00
Total				\$505.00

Vehicle No: SLL148C
Model : Toyota Sianta

SUPPLEMENTARY

No	List Items	Oty	Unit Price	List Price
1	Taillamp panel	1		bt / \$0.00
2	Air vent duct	1		de / \$0.00
3	Rear fender upper garnish	1		ang / \$0.00
4	Spare tyre panel	1		Rx / \$0.00
5	End panel top garnish clips	1 set	\$38.00	nee / \$38.00

\$698.00 220
\$110.00
\$270.00
\$830.00

List Price ~~\$38.00~~
-25% ~~\$9.50~~
Total ~~\$28.50~~

Labour

To remove & refix fuel tank
To vaccum & clean interior cushion
To straighten rear chassis member

\$120.00 60
\$150.00 X n n
\$250.00 X n n

Total \$520.00

Special Nett lifting

spare tyre panel sealant
taillamp panel sealant

\$60 X n n
\$60 40 nee