



7 day.

12/12/18

Take into other regt -

21. grand result. Not attained

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
	LH FRONT DOOR	1 X	
	LH FRONT DOOR LOCK	1 X	
	LH FRONT DOOR INNER TRIM	1 X	
	LH FRONT DOOR WEATHERSTRIP	1 X	
	LH FRONT DOOR MOULDING	1 X	
	LH REAR DOOR	Dis	
	LH REAR DOOR LOCK	700/gm	
	LH REAR DOOR INNER TRIM	?	
	LH REAR DOOR WEATHERSTRIP	neu	
	LH REAR DOOR MOULDING	1 X	
	LH REAR DOOR OUTER HANDLE	1 X	
	LH REAR DOOR QUARTER COVER	1 X	
	LH REAR DOOR HINGE UPPER + LOWER	1 X	
	LH REAR DOOR CHECKER	1 X	
	LH REAR DOOR P/W WINDOW MOTOR	?	
	LH REAR DOOR P/W WINDOW REGULATOR	?	
	LH REAR DOOR GLASS CHANNEL	1 X	
	LH REAR DOOR SPEAKER	1 X	
	LH REAR DOOR WIRE HARNESS COMPLETE SET	1 X	
	LH REAR DOOR INNER SIDE GARNISH	De / 1.1	
	LH REAR DOOR SEAT GARNISH	De / 1.1	
	LH REAR FENDER	B. 1.300	
	LH REAR FENDER COWLING	?	
	LH REAR FENDER GLASS COMPLESET WITH MOLDING	neu	
	LH REAR FENDER INNER TRIM	1 X	
	REAR BUMPER	De 700	
	REAR BUMPER SIDE RETAINER	500	
	REAR BUMPER LOWER	1 X	
	REAR BUMPER REFLECTOR LH	1 X	
	REAR MUDFLAP LH	2 X	
	ROCKER PANEL LH	R. 1.300	
	SPORT RIM	700	
	LH REAR DAMPER	1 X	
	LH REAR WHEEL BEARING	?	
	LH REAR BEARING HUB	?	
	LH REAR KNUCKLE ARM	1 X	
	LH REAR LOWER ARM	1 X	
	SUBTOTAL		\$ -

		50% LESS 10%	\$ -
		PARTS TOTAL	\$ -
	SPECIAL NETT	QTY	PRICE
ROCKER PANEL SEALANT	11 X		\$ 100.00
FRONT BUMPER CLIPS	11 X		\$ 100.00
FRONT BONNET ISOLATOR CLIPS	11 X		\$ 100.00
FRONT FENDER COWLING CLIPS	11 X		\$ 100.00
REAR DOOR INNER TRIM CLIPS	11 50		\$ 100.00
FRONT DOOR INNER TRIM CLIPS	11 X		\$ 100.00
REAR FENDER GLASS SEALANT	11 30		\$ 100.00
	SPECIAL NETT TOTAL		\$ 700.00
	LABOUR	QTY	PRICE
TO RNR ACCIDENT DAMAGE PARTS,CUT/WELD ,KNOCK&REALIGN	1200		\$ 1,800.00
TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1100		\$ 1,600.00
TO RUST PROOF ACCIDENT AFFECTED AREA	90		\$ 160.00
TO RNR REAR QUARTER GLASS SEALANT	replaced X		\$ 150.00
TO RNR FRONT DOOR MECHANISM	11 X		\$ 200.00
TO RNR REAR DOOR MECHANISM	60		\$ 200.00
TO RNR UPHOSTERY,GARNISH AND ATTACHMENT PARTS	20		\$ 400.00
TO RNR UNDERCARRAIGE SYSTEM	?		\$ 300.00
TO CHECK WHEEL ALIGNMENT	60		\$ 150.00
TO RNR TYRE AND WHEEL BALANCING	11 X		\$ 100.00
TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE.	11 X		\$ 200.00
TO DO WATER LEAK TEST .	11 X		\$ 100.00
TO RNR FUEL TANK TO ASSIST WORK LOAD	60		\$ 300.00
	LABOUR TOTAL		\$ 5,660.00
	GRAND TOTAL COST		\$ 6,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: